

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO.201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
TEL: 64193000 **FAX:** 64153727
ATTN: Motor Claim Department
WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 10/05/2018
TP Veh Reg No: SLJ2854U

Estimate No: ES1890546/AMK
Date: 18 May 2018
Policy No: 5086598866-01
Veh Reg No: SJR7438L
Make/Model: HONDA FIT 1.3G A
Chassis No: GE61154400
Engine No: L13A4169086
Reg. Date: 10/07/2009

Estimate Repair Cost to Vehicle No :SJR7438L

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER / RE	474.10	1 PC	474.10	
2 REAR BUMPER LH SIDE RETAINER - MCL	16.50	1 PC	16.50	
3 REAR BUMPER CLIP / MCL	3.70	6 PC	22.20	
4 REAR TAILGATE / BUC	771.50	1 PC	771.50	
5 TAILGATE INNER RUBBER / Tm	98.50	1 PC	98.50	
6 TAILGATE INNER LOCK X NN	189.80	1 PC	189.80	
7 TAILGATE EMBLEM 'FIT' / MCL	35.00	1 PC	35.00	
8 TAILGATE WINDSCREEN GLASS MOULDING - MCL	85.10	1 PC	85.10	
9 TAILGATE INNER BOARD / RE	102.20	1 PC	102.20	
10 LH TAILLAMP / CRA	206.20	1 PC	206.20	
11 REAR END PANEL / BUC	276.50	1 PC	276.50	
12 REAR END PANEL INNER TOP GARNISH - RE	60.80	1 PC	60.80	
13 REAR LH FENDER INNER TRIM / CRA	195.00	1 PC	195.00	
14 REAR TOOL SPONGE / CRA	210.00	1 PC	210.00	
15 REAR LH FENDER X repair.	652.40	1 PC	652.40	
			3,395.80	
	Less 20%		679.16	2,716.64
Special Net				
16 REVERSE SENSOR ?	200.00	1 SET	200.00	
17 REAR WINDSCREEN GLASS SEALANT / MCL	40.00	1 PC	40.00	
18 REAR LH FENDER GLASS SEALANT / MCL	30.00	1 PC	30.00	
			270.00	270.00
Labour				
19 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	100
20 REMOVE & REFIX REAR BUMPER, REAR LH FENDER, TAILGATE & ATTACHMENTS, TAILLAMPS; TO CUT, WELD & RENEW REAR END PANEL; KNOCKING & REPAIR REAR SPARE TYRE PANEL & REALIGN THE SAME	1,300.00	1 LA	1,300.00	900.
21 PUTTY & RESPRAY REAR BUMPER, TAILGATE, REAR FENDERS, REAR END PANEL & ALL AFFECTED AREAS	1,000.00	1 LA	1,000.00	900
22 REMOVE & REFIX REAR LH FENDER GLASS	80.00	1 LA	80.00	X NN
23 REMOVE & REFIX TOP ROOF LINING, SEAT, CARPET ETC	100.00	1 LA	100.00	60
24 REMOVE & REFIX REVERSE CAMERA, RESET & REPOSITION	50.00	1 PC	50.00	40
25 RUSTPROOFING	90.00	1 LA	90.00	60
			2,740.00	2,740.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department
WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 10/05/2018
TP Veh Reg No: SLJ2854U

Estimate No: ES1890546/AMK
Date: 18 May 2018
Policy No: 5086598866-01
Veh Reg No: SJR7438L
Make/Model: HONDA FIT 1.3G A
Chassis No: GE61154400
Engine No: L13A4169086
Reg. Date: 10/07/2009

Estimate Repair Cost to Vehicle No :SJR7438L

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 5,726.64
			Add GST @ 7%	400.86
			Total Amount Payable	<u>S\$ 6,127.50</u>

VEHICLE LYING AT :
NO.10 ANG MO KIO INDUSTRIAL PARK 2A
#01-04 AMK AUTOPOINT
SINGAPORE 568047
TEL : 64812001

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

6 Days .
lump sum repair.
After repair photos.
Lmo Q:ay -82880282
18/5/18.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: