

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0578/2018/PH
Date : 16-May-18

Vehicle NOT in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Ng Hock Seng
Address : 1 Pearl Bank
#08-03
Singapore 169016
Telephone : (HP)90173847
Type of Claim : Third Party Claims
Policy No. : 2100355288-04
Vehicle No : **SBC 2800 E**
Model Code : Audi A6 2.0 TFSI
Model / Year : Oct-13
Engine No : CDN 378897
Chassis No : WAUZZZ4G4EN054255
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-May-18
Place of Accident : 31 BUKIT BATOK EAST AVE 6 (S)659763

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SBC 2800 E.

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓
2	To dismantle and renew front bumper, rhs front fender and both headlights. Inspect lock carrier for damage. Re-organise front crashmanagement components. Re-install all parts removed.	\$ 2,800.00 1250
3	To respray front bumper and rhs front fender.	\$ 1,600.00 1100
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 5,072.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBC 2800 E.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER / <i>Re</i>	\$	2,326.00
2	1 SET FIXING PARTS FOR BUMPER <i>Att.?</i>	\$	236.00
3	CLOSING ELEMENT ?	\$	163.00
4	RADIATOR GRILLE ?	\$	1,174.00
5	RADIATOR GRILLE COVER ?	\$	32.00
6	HEADLIGHT COVER CAP - LH / RH <i>Cut</i>	2 \$	98.00
7	GRILLE RH <i>Mts.</i>	\$	134.00
8	SENSOR ?	2 \$	421.00
9	SENSOR SUPPORT INNER LH / RH ?	2 \$	118.00
10	GUIDE PIECE LH / RH <i>ACC.</i>	2 \$	64.00
11	BRACE LH / RH <i>ACC.</i>	2 \$	50.00
12	FOAM FILLER PIECE ?	\$	85.00
13	SIDE REINFORCEMENT ?	\$	702.00
14	BUMPER COVER ?	\$	105.00
15	SIGN CAUTION ?	\$	12.00
16	STICKER FOR AIR CONDITIONER ?	\$	17.00
17	FENDER - RH <i>Bnc</i>	\$	1,220.00
18	FENDER ATTACHMENTS ?	\$	36.00
19	STONE GUARD FILM - RH <i>McL</i>	\$	105.00
20	FENDER BRACE - RH ?	\$	72.00
TOTAL SPARE PARTS		\$	7,170.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBC 2800 E.

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
21	WHEEL HOUSING LINER / <i>TN</i>	\$	246.00
22	WHEEL SPOILER - FRONT RH ?	\$	202.00
23	WHEEL HOUSING LINER ATTACHMENTS ?	\$	68.00
24	HEADLIGHT FOR GAS DISCHARGE LAMP - LH / RH <i>CH ?</i>	2 \$	5,806.00
25	HEADLIGHT WASHER LIFT CYLINDER - LH ?	\$	208.00
26	HEADLIGHT WASHER LIFT CYLINDER - RH ?	\$	208.00
27	ELBOW FITTING ?	2 \$	45.00
28	MOUNTING FOR MAIN BEAM HEADLIGHT - LH ?	\$	103.00
29	MOUNTING FOR MAIN BEAM HEADLIGHT - RH ?	\$	103.00
30	FRONT BUMPER & FENDER SUPPORT - FRONT LH & RH ?	2 \$	22.00
31	HORN - RH LOW TONE ?	\$	254.00
32	HORN SPRING SHACKLE BRACKET - RH ?	\$	38.00
33	FLAT CONNECTOR HOUSING WITH CONTACT LOCKING MECHANISM ?	\$	16.00
34	FRONT NUMBER PLATE ?	S/N \$	25.00
35	SUNDRIES ?	\$	500.00
TOTAL SPARE PARTS CHARGES		:	\$ 15,014.00
TOTAL LABOUR CHARGES		:	\$ 5,072.00
GRAND TOTAL		:	\$ 20,086.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Guo Qiang - 82880282
: before paint photos.
: 5 Days.
: 17/5/18.

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant