

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

15 MAY 2018

Estimate No. : b1 46919
Date Estimated : 14/05/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Leong Oi Choo
229 Tampines Street 23
#08-271

Singapore 521229

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLZ1511G	VB68535	24/04/2018	218i-C	0

DESCRIPTIONVALUE

To Replace right rear fender, right side skirt and rear bumper and attachment include knocking caude by the accident

5950. 6,800.00

Painting rear bumper, right rear fender, tail panel, trunk floor,

2749. 3,055.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To remove and replace convertible top including reset and conduct checks all control units for proper function.

photo.
? 2644 3,111.00

To remove and install fuel tank to facilitate repairs including conduct checks for leak.

* photo 451 531.00

To carry out body cavity preservation.
(For cut panel).

451 531.00

To replace right rear rim and tyre including balancing. (1x)

80 94.00

To check steering geometry and conduct wheel alignment according to BMW specification (1X)

451 531.00

To replace right rear tyre - bridgestone 225/45/17

X 268.75

Sundries.

? 150.00

Total Labour 1: 15,248.75

DESCRIPTIONQTY PRICVALUE

ALLOY RIM 7.5X17 V SPK 725
HUB CAP WITH CHROME EDGE (BMW)
REAR RH SIDE PANEL
RH SIDE GUIDE FOR BUMPER

1 899.25
1 24.30
1 1,295.95
1 47.85

cut 899.25
? 24.30
bt 1,295.95
? 47.85

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46919
Date Estimated : 14/05/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLZ1511G	VB68535	24/04/2018	218i-C	0

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER PANEL PRIMED (BASIS)	1	956.35	Rx 956.35
RH SILL STRIP PRIMED	1	270.55	? 270.55
Total Parts :			3,494.25

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date/Time: 22/5/18 @ 11am Excess \$: _____

Surveyor's Name: Taufik Sign: Taufik

Surveyor's Tel: 97495749 Authorised: Yes / No

Authorised Date: _____ Time: _____

REPAIR YES / NO: _____

Surveyor's Email: taufik@khank.com

No. of Working Days: 13-15 days

KKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- This 3rd party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Labour 1	:	15,248.75
Parts	:	3,494.25
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,312.01
Grand Total	:	20,055.01

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **