

M/S AIG ASIA PACIFIC INS PTE LTD
CHARTIS BUILDING
78 SHENTON WAY #08-16
SINGAPORE 079120

ESTIMATE

DATE : 11/05/2018
ACC DATE : 09/05/2018
REF NO. : VFIX-TP20180469
POLICY NO :

Attention: Motor Claim Department

RE : VEHICLE NO. PC3919A TOYOTA HIACE

DESCRIPTION	AMOUNT S\$
1 1 FRONT BUMPER <i>648.10</i>	<i>893.40</i>
2 1 FRONT BUMPER RETAINER <i>ALJ</i>	<i>120.10</i>
3 1 HEADLAMP <i>ALJ HTD</i>	<i>2,515.50</i>
	3,529.00
LESS 25%	882.25
	\$ 2,646.75

3283.7
2462.77

LABOUR & MISCELLANEOUS:	AMOUNT S\$
1 To remove damaged body parts with all necessary components/ attachment apply hot-works where necessary, straighten door pillar	<i>200</i> 800.00
2 To spray paint replaced/repainted body panels inclusive of preparatory works and painting materials	<i>280</i> 800.00
3 To conduct headlamp alignment	<i>20</i> 30.00
	\$ 1,630.00

LKKA Insurance hence notify
the Repairer the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Pants prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- For resurvey (if necessary) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

GRAND TOTAL : \$ 4,276.75

SINGAPORE DOLLARS : FOUR THOUSAND TWO HUNDRED SEVENTY SIX & CENTS
SEVENTY FIVE ONLY

Vfix Auto Service Pte Ltd



not done
photo after repair
18/5/18
2017
P/P 2962-77