

INS. POLICY OWNER:

cc 6, 01 1800 8859, 1003

LKK:

IDAC:

Surveyor:

DOI:

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

DATE / PIC

STAGE

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

EMAIL 7.6.18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: KSC

Repair Cost: 45 SS 3,100

(6 days) Reduction: 49 %

Email ☒ Call ☐

FINAL SETTLEMENT Date/Time: 12.04.19

Confirm with: HASE BOON

Email ☒ Call ☐

Final Liability: % 100

(Agreed / Assessed) BOLA S/N No.: 21

If NO or B 28, Ass. Lia:

Repair Cost: SS 3,100.00

OID REPAIR ENDED TP.

Loss of Rental (LOR): SS - (days)

Loss of Use (LOU): SS 600.00 (\$100 x 6 days)

Loss of Income (LOI): SS - (\$ x days)

LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search SS 145

Medical: SS -

Disbursement: SS - (e.g. Tow/Independent)

Legal Cost SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: 440

Total: SS 4,307.45

Global Sum SS:

FINAL PAYMENT

Date/Time: 12.04.19

Confirm with: HASE BOON

Email ☒ Call ☐

Payee 1: SS 4,307.45

Name 1: HASE SENG SPRAY PAINTING COMPANY

Payee 2: (Strike if N.A.) SS

Name 2:

Payee 3: (Strike if N.A.) SS

Name 3:

ASS. REC. BY:

REF: C72 /

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3-6 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SFE 988C

Yr Regn:

07, 0P

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Suz Grand Vitara c.c.

1995

Colour:

M. P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

113889

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JSAJTE54V00520116

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / A/Rlm or

Tyre Size:

F:

R:

225/65R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

12/5/18

Rear

R/Bal.

4

mm

L/Bal.

4

mm

D.O.I.

14/5/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

15/5

File sent to Catherine

4s: + 3,700 (RED: + 3,547.75 49%)

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI18008859/Kea3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 15-05-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GY 4938D	Veh. Inspected	SFE 988C	
Policy No.	DMCVSN3025471800	Coverage (\$)	0.00	
Claim No.	SNM18D02414C02	Excess (\$)	0.00	
Assign From		Assign Date	15/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/05/2018	Inspection Date	14/05/2018	
Survey held at	HWA SENG SPRAY PAINTING COMPANY 160 SIN MING DRIVE #05-11 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

HWA SENG SPRAY PAINTING CO

1 of 1

160 Sin Ming Drive

#05-11 Sin ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO. 09574400B)

TEL: 64533100

FAX: 62669932

*Not within
11 days 8?
Resurvey After Paint
5-6 days*

Estimate repair cost to SUZUKI VITARA reg no : SFE 988 C

1pc tailgate	S\$	Bu	858.80	✓
1pc emblem 'SUZUKI'		Ma	28.50	—
1pc emblem 'GRAND'		Ma	38.00	—
1pc emblem 'VITARA'		Ma	28.00	—
2pcs tailgate hinges	(S\$55.20/pc)	Ma	110.40	X
1pc tailgate weather strip		Ma	186.80	X
1pc tailgate lock		Ma	429.10	—
1pc tailgate catch		Ma	43.50	X
1pc tailgate inner trim			345.80	?
1pc rear bumper		Bu	759.00	—
2pcs rear bumper side retainer	(S\$39.30/pc)	Ma	78.60	X
1pc rear bumper side support			76.40	?
1pc rear bumper reinforcement			388.60	?
2pcs rear number plate lamp	(S\$74.40/pc)	Ma	148.80	X
1pc spare tyre cover		CM	798.80	—
1pc spare tyre cover base			364.20	?
1pc spare tyre bracket			185.80	?
1pc end panel			581.20	?
			5450.30	
	Lesss 15%		1396.55	
			4632.75	
<u>Labour & misc charges</u>				
1pc tailgate sealant		Ma	60.00	40sn
1 set moulding and clip		Ma	60.00	—
Labour to remove and install rear windscreen			150.00	120l
1 set number plate plus holder		Ma	65.00	45sn
Panel knocking			1000.00	?
Spray painting			1000.00	800l
1 set reverse sensor		Ma	230.00	X
Wire checking			50.00	20l
			7247.75	

HWA SENG SPRAY PAINTING COMPANY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

HWA SENG SPRAY PAINTING CO

160 Sin Ming Drive

#05-11 Sin ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO. 09574400B)

TEL: 64533100

FAX: 62669932

1 of 1

Not Authorised
 61 Sup 8370d
 Rekey After Paint
 5-6 days

Estimate repair cost to SUZUKI VITARA reg no : SFE 988 C

1pc tailgate	S\$	858.80	✓
1pc emblem 'SUZUKI'		28.50	✓
1pc emblem 'GRAND'		38.00	✓
1pc emblem 'VITARA'		28.00	✓
2pcs tailgate hinges	(S\$55.20/pc)	110.40	X
1pc tailgate weather strip		186.80	X
1pc tailgate lock		429.10	✓
1pc tailgate catch		43.50	X
1pc tailgate inner trim		345.80	✓
1pc rear bumper		759.00	✓
2pcs rear bumper side retainer	(S\$39.30/pc)	78.60	X
1pc rear bumper side support		76.40	✓
1pc rear bumper reinforcement		388.60	X
2pcs rear number plate lamp	(S\$74.40/pc)	148.80	X
1pc spare tyre cover		798.80	✓
1pc spare tyre cover base		364.20	✓
1pc spare tyre bracket		185.80	X
1pc end panel		581.20	X
		5450.30	
	Lesss 15%	1396.55	
		4632.75	
Labour & misc charges			
1pc tailgate sealant		60.00	40sn
1 set moulding and clip		60.00	✓
Labour to remove and install rear windscreen		150.00	2ol
1 set number plate plus holder		65.00	45sn
Panel knocking		1000.00	500
Spray painting		1000.00	800
1 set reverse sensor		230.00	X
Wire checking		50.00	2ol
		7247.75	

HWA SENG SPRAY PAINTING COMPANY

Mei Kwan (LKKAUTO)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Wednesday, 16 May, 2018 3:39 PM
To: Mei Kwan (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving GY4938D (OI : CAI - SNM18D02414C02) and SFE988C (TP : LKK REF - CC6/CTI18008859/Kea3) on 12.05.2018
Attachments: leeSZ_SNM18D02414C02-GY4938D-LKKDirectSettlementAccidentLtr_CLCR95.670.pdf; MSAT18062099-GY4938D.pdf
Categories: HMK

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Elaine Cheong

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Wednesday, 16 May, 2018 9:37 AM
To: Claims Dept of CTI
Cc: Elaine Cheong; Lucas Lee; Asher Sng (LKKAUTO); Joy Irene (LKKAUTO); Hsiao Tong (LKKAUTO); Admin A
Subject: Direct Settlement - Accident Involving GY4938D (OI : CAI - TBA) and SFE988C (TP : LKK REF - CC6/CTI18008859/Kea3) on 12.05.2018

WITHOUT PREJUDICE

Dear Sir /Madam,



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.cntaiping.com
Co. Reg. No. 200208384E

Our Reference: **SNM18D02414/C02/8**

Date : **16 MAY 2018**

via Ordinary & Registered Mail

**SAS M&E PTE LTD
1 TOH TUCK LINK
#03-00
SINGAPORE 596222**

Dear Sir / Madam

**ACCIDENT INVOLVING GY4938D AND SFE988C ON 12 MAY 2018
ALONG BISHAN ROAD**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SFE988C** , is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd
Attn : ASHER
Ref : CC6/CT118008859/KEA3
Contact No : 68416051
via Email : ASHER@LKKAUTO.COM

CC : Agent - (AN0435A) - YETTA INSURANCE AGENCY PTE LTD

F01/LKKDS-2013

Date: 06/06/2018

Lim Eng Lai
160 Sin Ming Drive
#05-07/11 Sin Ming Antecity
Singapore 575722

Attn : Motor Claim Department

Your Ref:

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Dear Sirs/Madam,

DIRECT SETTLEMENT

Accident on 12/5/2018 involving Vehicle No. SFE 988C & GY 4938D
At Bishan Road.

I/We refer to my/our letter date

Arising out of the above accident, as a assessment on the damaged to my/our Vehicle No. SFE 988C was being conducted by your appointed panel surveyor.

Due to the negligence/fault of your insured/driver of Vehicle No. GY 4938D. I/We am/are now claiming against you for the repair and other consequential suffered by me/us.

For the purpose of a amicable settlement. I/We quantified my/our claim as follows:-

a) Cost of repair at	SS 3,700.00
b) Loss of use for 6 days at rate of (\$60 per day)	SS 360.00
c) Police/ROV Fee	SS
d) Others LTA Search Fee	SS 7.45

Total Cost

SS 4,067.45

I/We enclose herewith copies of all relevant documents for your perusal.

Kindly also direct all correspondence or liase with my Repairer's Messrs Hwa Seng
Spray Painting Co relating to the said accident without any further
reference to me/us.

Thanking you and awaiting your favourable response.

Yours Faithfully




LETTER OF AUTHORIZATION

To Whom It May Concern

Accident on 12/05/2018 involving SFE 988C and GY4938D
along Bishan Road

I/We Lim Eng Lai NRIC No. S 711843F
of 700 Loring 1 Toa Payoh #15-11 Spore 319773
Owner of Motor Vehicle Registration No. SFE 988C insured by
of AIG Asia Pacific Insurance Pte Ltd under Policy No. 2100 153943-08000
do hereby authorize M/s Hwa Seng Spray Painting Co
as my/our representative with full authority to write, negotiate and settle claim
for damages on my/our behalf against the owner and/or driver of
Motor Vehicle No. GY4938D in regard to the abovementioned accident.

I/We also consent to the agreed settlement sum be made in favour of my/our
representative, M/s Hwa Seng Spray Painting Co and
the said payment be forwarded to them to be construed as full and final discharge of
my/our claim.



Owner Signature & Company Stamp

Date: 06/06/2018

HWA SENG SPRAY PAINTING CO.

160 Sin Ming Drive, #05-11, Sin Ming Autocity
Singapore 575722
Tel No. : 64533100 Fax No. : 62669932
Buss. Reg. No. : 095744/00B

LIM ENG LAI
700 LORONG 1 TOA PAYOH #15-11
319773

Attention : Motor Claim Department
Contact : 97553258

Final Repair Bill : H00024

Date : 06/06/2018
Vehicle Num. : SFE 988 C
Make/Model : SUZUKI VITARA
Chassis/Eng# :
Accident Date : 12/05/2018
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		3,700.00
		On lump sum basis repair inclusive of spare parts, panel knocking, spray paint and misc charges		
		Labour Total S\$:		3,700.00

E. & O.E.

Total S\$: 3,700.00
=====



for HWA SENG SPRAY PAINTING CO.



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 12 May 2018 / 14:12:26

Receipt Date/Time : 12 May 2018 / 14:12:26

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180512-000744

Previous Receipt No. :

**S/N Item Description/
Business Transaction Reference
No.**

Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - GY4938D

As at 12 May 2018/13:15:00

Insurance Co: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

1 Insurance Enquiry - GY4938D
Enquiry Fee
20180512141056666356

Sub-Total	7.00	0.49	7.49
Total Before Rounding	7.00	0.49	7.49
Rounding Difference			0.04
Total Amount Payable			7.45

Paid By

xxxxxxxxxxxx6419 Credit Card:
Visa/MasterCard

Total	7.45
Cash Change	0.00
Tendered Amount	7.45
Excess Refundable Amount	0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI18008859/Kea3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 18-04-2019



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GY 4938D	Veh. Inspected	SFE 988C
Policy No.	DMCVSN3025471800	Coverage (\$)	0.00
Claim No.	SNM18D02414/C02/8	Excess (\$)	0.00
Assign From		Assign Date	14/05/2018

2. Vehicle Particulars & Condition

Make & Model	SUZUKI GRAND VITARA (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JSAJTE54V00520116	Colour	METALLIC PEARL WHITE
Odometer	113889	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/65 R17	KUMHO	7 mm
L/H Front Tyre	225/65 R17	KUMHO	7 mm
R/H Rear Tyre	225/65 R17	KUMHO	4 mm
L/H Rear Tyre	225/65 R17	KUMHO	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/05/2018	Inspection Date	14/05/2018
Survey held at	HWA SENG SPRAY PAINTING COMPANY 160 SIN MING DRIVE #05-11 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFE 988C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE	BENT	858.80	858.80
1	EMBLEM 'SUZUKI'	NECESSARY	28.50	28.50
1	EMBLEM 'GRAND'	NECESSARY	38.00	38.00
1	EMBLEM 'VITARA'	NECESSARY	28.00	28.00
2	TAILGATE HINGES @\$55.20	TO REPAIR SEE LABOUR	110.40	-
1	TAILGATE WEATHER STRIP	SERVICEABLE	186.80	-
1	TAILGATE LOCK	DENTED	429.10	429.10
1	TAILGATE CATCH	TO REPAIR SEE LABOUR	43.50	-
1	TAILGATE INNER TRIM	MTG CRACKED	345.80	345.80
1	REAR BUMPER	BUCKLED	759.00	759.00
2	REAR BUMPER SIDE RETAINER @\$39.30	SERVICEABLE	78.60	-
1	REAR BUMPER SIDE SUPPORT	NOT NECESSARY	76.40	-
1	REAR BUMPER REINFORCEMENT	NO SUCH PARTS	388.60	-
2	REAR NUMBER PLATE LAMP @\$74.40	SERVICEABLE	148.80	-
1	SPARE TYRE COVER	CRACKED	798.80	798.80
1	SPARE TYRE COVER BASE	DENTED / CUT	364.20	364.20
1	SPARE TYRE BRACKET	TO REPAIR SEE LABOUR	185.80	-
1	END PANEL	TO REPAIR SEE LABOUR	581.20	-
	LESS 15% DISCOUNT		-817.55	-547.53
			4,632.75	3,102.67
<u>SPECIAL NETT ITEMS</u>				
1	TAILGATE SEALANT (SN)	NECESSARY	60.00	40.00
1	SET MOULDING AND CLIP (SN)	NECESSARY	60.00	60.00
1	SET NUMBER PLATE PLUS HOLDER (SN)	DENTED	65.00	45.00
1	SET REVERSE SENSOR (SN)	SERVICEABLE	230.00	-
			415.00	145.00

Report Ref No. CC6/CTI18008859/Kea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	LABOUR TO REMOVE AND INSTALL REAR WINDSCREEN.		150.00	120.00
	PANEL KNOCKING.INCLUSIVE OF THE REPAIR OF TAILGATE HINGES ,TAILGATE CATCH ,SPARE TYRE BRACKET AND END PANEL.		1,000.00	500.00
	SPRAY PAINTING.		1,000.00	800.00
	WIRE CHECKING.		50.00	20.00
			2,200.00	1,440.00
	GRAND TOTAL		7,247.75	4,687.67
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,700.00

Report Ref No. CC6/CT118008859/Kea3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.