

HWA SENG SPRAY PAINTING CO

160 Sin Ming Drive

#05-11 Sin ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO. 09574400B)

TEL: 64533100

FAX: 62669932

Not Withair
1 Day @?
Recovery After Repair
5-6 days

Estimate repair cost to SUZUKI VITARA reg no : SFE 988 C			
1pc tailgate	S\$	858.80	✓
1pc emblem 'SUZUKI'		28.50	—
1pc emblem 'GRAND'		38.00	—
1pc emblem 'VITARA'		28.00	—
2pcs tailgate hinges	(S\$55.20/pc)	110.40	X
1pc tailgate weather strip		186.80	X
1pc tailgate lock		429.10	—
1pc tailgate catch		43.50	X
1pc tailgate inner trim		345.80	?
1pc rear bumper		759.00	—
2pcs rear bumper side retainer	(S\$39.30/pc)	78.60	X
1pc rear bumper side support		76.40	?
1pc rear bumper reinforcement		388.60	?
2pcs rear number plate lamp	(S\$74.40/pc)	148.80	X
1pc spare tyre cover		798.80	—
1pc spare tyre cover base		364.20	?
1pc spare tyre bracket		185.80	?
1pc end panel		581.20	?
		5450.30	
	Lesss 15%	1396.55	
		4632.75	
<u>Labour & misc charges</u>			
1pc tailgate sealant		60.00	40sn
1 set moulding and clip		60.00	—
Labour to remove and install rear windscreen		150.00	120l
1 set number plate plus holder		65.00	45sn
Panel knocking		1000.00	?
Spray painting		1000.00	800l
1 set reverse sensor		230.00	X
Wire checking		50.00	20l
		7247.75	

HWA SENG SPRAY PAINTING COMPANY


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: