

From: PEK POH HONG [pekpoh_hong@hotmail.com]
Sent: Tuesday, 15 May, 2018 10:16 AM
To: GERALD POH WEE BIN
Subject: FW: Primer Mover Reg No XE 341E (Accident Reporting)
Attachments: image001.jpg

Dear Gerald,

Kindly advise.

Thank you.

Best Regards.

Miss Yeo
Sing Chew Insurance Agency Pte Ltd

From: Desmond Bok [desmond.bokck@hiapseng.com]
Sent: Tuesday, May 15, 2018 2:12 AM
To: 'PEK POH HONG'
Cc: belindakoh@hiapseng.com; 'Choong Yiu Gei'
Subject: Primer Mover Reg No XE 341E (Accident Reporting)

Dear M/s Yeo,
The above mentioned Primer mover is covered under LONPAC INSURANCE BHD .

Last Friday on 11/5/18, We sent the above mentioned vehicle in the morning to Gold Bell Engineering Pte Ltd for servicing. We were informed in the afternoon by Gold Bell Engineering Pte Ltd that while test driving our above mentioned outside, they had an accident. Gold Bell Service Advisor said that they will take responsibility for the accident and will do the necessary insurance reporting under Gold Bell Engineering Pte Ltd.

As per my tele –reporting for this accident on 11/5/18, you have requested for this email to be sent to you.

Thanks & Regards,
Desm0nd Bok
Assistant Manager
Mechanical/ Electrical Department
[cid:image001.jpg@01D3EB96.E8E2B630]
Hiap Seng Engineering Limited
28 Tuas Crescent
Singapore 638719
Tel : 6862 1144 Ext 305
Grid Phone No: 9080 5692