

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

14-May-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6212 E

1 pc	Bootlid cRdi	\$	29.00
1 pc	Bootlid lower garnish	\$	290.00
1 pc	Rear bumper	\$	696.00
1 pc	Rear bumper lower cover	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 ?	\$	58.00
1 pc	Rear bumper inner sponge	\$	114.00
1 pc	Rear bumper reinforcement ?	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 ?	\$	106.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 ?	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 ?	\$	36.00
1 pc	Rear bumper o/s reflector @ \$46.00 X	\$	46.00
			\$ 2,224.00
Less 10%			\$ 222.40
			\$ 2,001.60

S/NETT

1 set	Bootlid lower garnish clips	\$	60.00
1 set	Rear bumper clips	\$	48.00
1 set	Reverse sensor	\$	280.00 200
1 set	Bootlid stickers	\$	100.00
Sundry		\$	50.00 20
Towing Fee		\$	50.00
To dismantle / replace/test reverse sensor to new bumper and reset to the same		\$	120.00 20
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the bootlid lower garnish etc		\$	750.00 500
To putty and spray painting on rear bumper, bootlid lower garnish, bootlid		\$	600.00 500
To apply rustproofing on the repaired and replaced panels.		\$	150.00 X
			\$ 4,389.60

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Date:

Kahin (11/11/18)
18/5/18 10:00 hrs
3 Rep.
4/5 After Repair phh

CASH SALE/WORK ORDER No:AD 8284



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717

TEL : 6743 1987 (3 LINES) FAX : 6743 0013

Reg No: 200415052W

Date, 11/5/18

寶號

Messrs:

車號

Vehicle No:

車型

Model No:

由

From:

到

To:

其他

Remark:

時間

Time:

13:25:14:00:14:58

AMOUNT: \$

注意 本公司對所拖之車輛，在進行中如有任何損失或破壞，一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed

經手人

Authorised by:

收貨人

Received by: