

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 3082H

DATE 14/5/2018 10:07

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper <i>X Rep.</i>			\$ 603.60	
	Rear Door (RH) <i>X Rep.</i>			\$ 1,351.10	
	Rear Wheel Hup-Cap (RH) <i>✓</i>			\$ 150.70	
</					