

23/03/2002

ASS. REC. BY:

REF:

CS/FCI18008867/Kqd3⁷²

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

CWS

From (Person):

Eileen Lee

of

FCI

Date/Time: 15/5/18 @ 5.33pm

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PA 9146J

Insured:

SHC 1008 L

at Workshop m/s

City Auto

Tel:

64531235

of

Blk 8 Sin Ming Rd # 01-58

Policy No:

D-18088936 MFSH

Claim No:

D18003806 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 10/05/2018

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time:

5.38pm @ 15/5/18

Person Contacted:

Vronica

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

PA 9146J-X

SHC 1008 L - CS/FCI16005782 / M/vbc2

DOA: 26/3/16

16/5/18 @ 4.17pm Reused to Eileen Lee by email.

7/8 L1 Sup. @ 4000 Customer (Red @ 1652.79, 29%)

ASS. REC. BY:

REF: FCZ /

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____ City Ave

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 23%

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: PA 91467 Yr Regn: 11, 09

Type: M.Car / M.Cycle (Bus) / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace c.c. 2982Colour: White A/C: Insured / Std / NI / NASp. Reading: 406935 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFS722PX00007339Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm orTyre Size: F: 195R15X8
R: _____BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 3 mmL/Bal. 3 mmD.O.A. 10/5/18

Survey held at

Rear

R/Bal. 3 mmL/Bal. 3 mmD.O.I. 14/5/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

15/5 File pass to Customer

Date/Time, File Pass to?

1) 07/8 to customer

Date/Time, File Return to?

2) _____

☐ : Prell. Report☐ : Final ReportDays Of Repair: 6Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S - RS - St

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

TP4000

140
50
50+50
21
311



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18008867/Kqd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 16-05-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 1008L	Veh. Inspected	PA 9146J
Policy No.		Coverage (\$)	0.00
Claim No.	D18003806MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE	Assign Date	16/05/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	10/05/2018	Inspection Date	15/05/2018
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 SIN MING ROAD SINGAPORE 575643.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18003806MFSH

Date: 16 May 2018

Our Ref: CS/FCI18008867/Kqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. PA 9146J .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 14/05/2018 at the premises of M/s CITY AUTO, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,652.79</u> .
Revised Estimate Amount	: S\$ <u>3,074.80</u> .
"Check" Items Amount	: S\$ <u>1,944.28</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
at the o/s rear portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	11-05-2018	Our Ref No. D18003806MFSH
Accident Date	10-05-2018	Claim Type. Third Party
Insured Vehicle	SHC1008L	Third Party Vehicle. PA9146J
Survey Location	BLK 8 SIN MING ROAD #01-58/60/62 SIN MING IND EST	
Contact Person.	VRONICA LAW	
Contact No.	64531235/ 64531235	Fax No. 64537944
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CITY AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/240346)



PRI Documents



Close X

PRI Header Details

Claim No	D18003806MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & CITY AUTI
Workshop Name	CITY AUTO PTE LTD (Contact Person : VRONICA LAW)	Survey Location & Contact Details	BLK 8 SIN MING ROAD #01-58/60/62 SIN MING IND ES Mobile: 64531235 , Phone: 64531235 , Fax: 6453794 EmailId: CITYAUTO@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: LIABILITY UNCLEAR:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC1008L	TP Vehicle No	PA9146J
PRI Recieved Date	15-05-2018 06:54:03 PM	Surveyor Appointed Date	15-05-2018 05:32:47 PM	Surveyor Accept Date	16-05-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	16-05-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 16 May 2018 4:17 PM
To: 'Claim Workflow System'; assignments
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18003806MFSH/1
Attachments: CSFCI18008867Kqd3.pdf

Dear Eileen,

Enclosed herewith preliminary advice of PA 9146J.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 15 May 2018 5:57 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18003806MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 15 May 2018 5:33 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18003806MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

MS FIRST CAPITAL INSURANCE LTD

NO. 36

ROBINSON RD

CITY HOUSE

SINGAPORE 068877

Attention: SHIN KAIGAI TRAVEL SERVICE PTE LTD

Contact : 8298687

Fax No. : 6507 3849

Estimate : QUOT201805-000227(00)

Date : 11/05/2018

Vehicle No. : PA9146J

Make/Model : TOYOTA TOYOTA HIACE
HIGHROOF AUTO 14 SEATER

Mileage (km) : 0

Chassis No. : JTFST22PX00007339

Accident Date : 10/05/2018 00:00:00

Claim No. : SHC1008L

Reference : PA9146J

Policy No. : 5095374043

*Not Whatched part
L1 Lip 8 3900h
Runway After Paint*

S/No	Particular	Quantity	Unit Price	Amount S\$
LIST ITEMS :				
1	RH rear panel	1.0	1,849.70	1,849.70
2	RH rear mud flap	1.0	156.70	156.70
3	RH rear wheel bearing	1.0	156.40	156.40
4	RH rear axle	1.0	1,931.80	1,931.80
5	RH rear oil seal	1.0	37.50	37.50
6	RH rear rim <i>with hub cap</i>	1.0	311.60	311.60
List Total :				4,443.70
25% Discount S\$				1,110.91
				3,332.79
SPECIAL NET :				
1	Rear side glass sealant	1.0	40.00	40.00
SPECIAL NET Total S\$:				40.00
LABOUR :				
	*To remove and install side glass	1.0	120.00	120.00
	*Computerized wheel alignment	1.0	60.00	60.00
	*Labour charge to change axle bearing	1.0	350.00	350.00
	- To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1.0	950.00	950.00
	- Spray painting on affected & replace parts	1.0	800.00	800.00
				2,280.00

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total S\$: 5,652.79

GST 7% S\$: 395.70

Amount Due S\$: 6,048.49

77

HA

for CITY AUTO PTE LTD



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18008867/Kqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 13-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1008L	Veh. Inspected	PA 9146J	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18003806MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	15/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JTFST22PX00007339	Colour	WHITE	
Odometer	406935	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	MICHELIN	3 mm	
L/H Front Tyre	195 R15X8	MICHELIN	3 mm	
R/H Rear Tyre	195 R15X8	MICHELIN	3 mm	
L/H Rear Tyre	195 R15X8	MICHELIN	3 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/05/2018	Inspection Date	14/05/2018	
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 SIN MING ROAD SINGAPORE 575643.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PA 9146J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RH REAR PANEL	BENT	1,849.70	1,849.70
1	RH REAR MUD FLAP	CRACKED	156.70	156.70
1	RH REAR WHEEL BEARING	NECESSARY	156.40	156.40
1	RH REAR AXLE	BENT	1,931.80	1,931.80
1	RH REAR OIL SEAL	NECESSARY	37.50	37.50
	LESS 25% DISCOUNT		-1,033.03	-1,033.03
			3,099.07	3,099.07
1	RH REAR RIM WITH HUB CAP	CRACKED / DENTED	311.60	150.00
	LESS 25% DISCOUNT		-77.90	-
			233.70	150.00
SPECIAL NETT ITEMS				
1	REAR SIDE GLASS SEALANT (SN)	NECESSARY	40.00	40.00
			40.00	40.00
LABOUR				
	TO REMOVE AND INSTALL SIDE GLASS.		120.00	120.00
	COMPUTERIZED WHEEL ALIGNMENT.		60.00	60.00
	LABOUR CHARGE TO CHANGE AXLE BEARING.		350.00	220.00
	TO KNOCK JACKOUT DAMAGED PARTS,PANEL BEATING,WELDING ALIGN,REFIX AND TO RENEW ACCIDENT PARTS.		950.00	800.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		800.00	500.00
	-		-	-
	-		-	-
	-		-	-
			2,280.00	1,700.00
GRAND TOTAL			5,652.77	4,989.07
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,000.00

Report Ref No. CS/FCI18008867/Kqd3n2



Report Ref No. CS/FCI18008867/Kqd3n2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.