

ASS. REC. BY:

REF: CS/ICS18008876/09d362

Special Instruction:

Surveyor
Menmen

MA

ASSIGNMENT (Office)

From (Person):

Janice Goh

of

ECICS

Date/Time:

16/5/18 @ 10:39am

Estimated Cost:

Bill to:

☒ TP

/ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKS 14864

Insured:

at Workshop in/s

Falcon - Air Auto

Tel:

6452 0880

of

176 Sin Ming Drive # 01-06

Policy No:

MPC17A00431101

Claim No:

DMPC1800187H

Sum Insured:

Excess:

\$500.00

Make of Veh:

(Client's Record)

D.O.A:

12/05/2018

CA / ☒ EV

/ REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:58am @ 16/5/18

Person Contacted:

Lynn

Vehicle

☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SKS 14864 -X
18/5/18 @ 10:30am	then went to Janice Goh via Menmen.
18/5/18 @ 12:04pm	Janice informed c/a at 812860 via Menmen.
18/5/18 @ 2:05pm	Informed Joshua c/a not more than US \$12800 & EX: \$500.
18/5/18 @ 5:25pm	Confirmed with Florence US \$12800, 11 days by email.
	(Cred \$7850, 38%)

REF:

CS/ICS18008876/M19d3

ASSIGNMENT

From _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No. _____

at Workshop no. _____

of _____

Insured. _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$26K

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR. Scan: _____

Consistent? : Yes or No

Est. Repairs: _____

11

days

Res: _____

Yes or No

Lump Sum: _____

%

3 Val: _____

Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Van No: 211V KS1864Yr Regn: 03

2010

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 318iCC: 1995Colour: Black

A/C: _____

Insured / Std / NI / NA

Sp Reading: 195799

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: WBAFT72070472680Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: 235/35/19R: 265/30/19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or RY

Front

Rear

R/Bal: 6

mm

R/Bal: 6

mm

L/Bal: 6

mm

L/Bal: 6

mm

D.O.A. _____

D.O.I. 16/5/2018

Survey held at: _____

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

Date/Time File Pass to?



Prel. Report

11/06/18 typist

Final Report

Date/Time File Return to?

D.

Days Of Repair: 11Resurvey No. of Trip: 2Survey Fee: 450

Transportation: _____

1. S-RS: _____

1. Items: _____

1. Other: _____

1. Total: _____

1. Total: 460Add Fee: ☐Site Insp: ☐ \$Interview: ☐ \$Tech. Insp: ☐ \$Work end: ☐ \$Report Format: web-09Lump Sum / L.R. / \$ 12800

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ECICS LTD		Ref : CS/ICS18008876/M1qd3	
7 TEMASEK BOULEVARD #10-01 SUNTEC TOWER ONE SINGAPORE 038987 		Date : 16-05-2018	
		Code : ICS	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SKS 1486U
Policy No.	MPC17A00431101	Coverage (\$)	0.00
Claim No.	DMPC1800187H	Excess (\$)	500.00
Assign From	MERIMEN (JANICE GOH)	Assign Date	16/05/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	12/05/2018	Inspection Date	16/05/2018
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD (HQ) 176 SIN MING DRIVE #01-06/07/13, SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Dis Auth'd	Status
Main	15 May 2018 21:49 Sendback Est	16 May 2018 09:35 S\$18,086.00	16 May 2018 10:39 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	NOORMALA BINTE SUJUDDIN, ID: S1466679F, Email: mdzahil@yahoo.com		
Vehicle Reg. No.:	SKS1486U	Date of Loss:	12/05/2018 16:00 - :59 [97 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / DMPC1800187H	Policy/Cover Note No.:	MPC17A00431101 (Comprehensive) Coverage: 30/09/2017 - 29/09/2018
		Excess:	S\$500.00
Repairer:	Falcon-Air Auto Services Pte Ltd (Sin Ming) 176 Sin Ming Drive #01-06, Sin Ming Autocare, 575721 Sin Ming - Tel: 6452 0880		
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Janice Goh - 6303 0182]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/05/2018]		
Driver/Custodian:	MUHAMMAD ZAHIL FADZULI BIN ZAKARIA (28 / Male), NRIC: S9004068E, Tel: +6585001904		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 6 August 2018 5:25 PM
To: 'Florence Loh'
Cc: SUR; lynn; francine ng; Joshua
Subject: RE: Finalise_SKS 1486U (DOA: 12/05/2018)

Dear Florence,

WITHOUT PREJUDICE

Confirm Lump Sum \$12,800.00 before excess \$500.00 and 11 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Florence Loh <fa_autoservices@falconair.com.sg>
Sent: Thursday, 2 August 2018 5:45 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; lynn <lynn@falconair.com.sg>; francine ng <francine.gail@falconair.com.sg>; Joshua <joshua@falconair.com.sg>
Subject: Finalise_SKS 1486U (DOA: 12/05/2018)

Hi Shiau Chan,

Attach estimate, supplementary and photos for finalise.

Please confirm COR \$12,800.00.

Thank you.
florence

From: Joshua Ng
Sent: Friday, May 18, 2018 3:06 PM
To: Shiau Chan (LKKAUTO)
Cc: SUR ; florence ; lynn ; francine ng
Subject: Re: VEHICLE SKS 1486U (DOA: 12/05/2018)

Thanks Shiau Chan.

Regards
Joshua Ng
Falcon-Air Auto Services Pte Ltd
Tel : 6452 0880

From: Shiau Chan (LKKAUTO)
Sent: Friday, May 18, 2018 2:05 PM

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 18 May 2018 2:05 PM
To: joshua@falconair.com.sg
Cc: SUR
Subject: VEHICLE SKS 1486U (DOA: 12/05/2018)

Dear Joshua,

As instructed by our client, please proceed to repair the insured vehicle **SKS 1486U** at repair cost not more than **\$12,800.00 on Lump Sum basis (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	15 May 2018 17:42	Cim Veh Model Changed	(200080) BMW 318I 2.0 (A).	[R] Florence Loh Fui Fong
2	15 May 2018 17:42	Cim Created	Reg No: SKS1486U. Policy No: MPC17A00431101. Acct Date: 2018/05/12. Claim Type: OD. Insurer: ECICS Limited (HQ). Workshop: Falcon-Air Auto Services Pte Ltd (Sin Ming). Created from SAS:MFA118062903	[R] Florence Loh Fui Fong
3	16 May 2018 09:35	Cim Submitted	18086.00.	[R] Florence Loh Fui Fong
4	16 May 2018 10:39	Cim Registration Modified	Excess: -> 500.00.	[I] Janice Goh
5	16 May 2018 10:39	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[I] Janice Goh
6	16 May 2018 10:39	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/05/25	[I] Janice Goh
7	16 May 2018 10:39	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[I] Janice Goh
8	16 May 2018 10:56	Assignment 1st Accessed		[A] Nivitha Govindasamy
9	16 May 2018 11:57	Adj Adjuster Assigned	[None] -> MA CHIN FOOK	[A] Nivitha Govindasamy
10	17 May 2018 17:34	Adj Rpt Initiated		[A] SHIAU CHAN
11	18 May 2018 10:25	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/05/25	[A] SHIAU CHAN
12	18 May 2018 10:26	Adj Mandate Request	Cur.Req:15567.40:DAMAGES CONSISTENT. REPAIRER ASKING REPAIR COST AT \$13,000.00 ON LUMP SUM BASIS. (MARGIN OF REPAIR: \$12,859.00) WE HAVE NOT A UTHORISE REPAIR.	[A] SHIAU CHAN
13	18 May 2018 12:04	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/05/25	[I] Janice Goh
14	18 May 2018 12:04	Adj Mandate Set	Approved:12860.00.	[I] Janice Goh

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1805387	15/05/2018 17:42	Motor	Falcon-Air Auto Services Pte Ltd (HQ)	Falcon-Air Auto Services Pte Ltd (Sin Ming)	SKS1486U		xx.xx
1808051	17/05/2018 17:34	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKS1486U		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Janice Goh

Date: 17 May 2018

Preliminary Advice

Vehicle No	: SKS1486U	Accident Date	: 12/05/2018
Make	: BMW 318i	Policy No.	: MPC17A00431101
Assignment Date	: 16/05/2018	Excess	: S\$500.00
Date of Inspection	: 16/05/2018	Est. Duration of Repair	: 11.00
Inspection At	: FALCON-AIR AUTO SERVICES PTE LTD (SIN MING) 176 SIN MING DRIVE #01-06, SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,086.00
Revised Amount	:S\$	11,714.00
Check Items (Estimated)	:S\$	3,853.40
Total	:S\$	15,567.40

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	34,000.00
COE / PARF Rebate	:S\$	21,141.00
Salvage Value	:S\$	
Margin for Repair	:S\$	12,859.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER ASKING REPAIR COST AT \$13,000.00 ON LUMP SUM BASIS. (MARGIN OF REPAIR: \$12,859.00)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6679F
Vehicle Details	
Vehicle No.:	SKS1486U
Vehicle to be Exported:	No
Intended De-registration Date:	17 May 2018
Vehicle Make:	B.M.W.
Vehicle Model:	318i 2.0L A/T ABS D/AIRBAG 2WD 4DR SR
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	A172I664N46B20BZ
Chassis No.:	WBAPF72070A793680
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$30,338.00
Original Registration Date:	30 Mar 2010
First Registration Date:	30 Mar 2010
Transfer Count:	4
Actual ARF Paid:	\$30,338.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Mar 2020
PARF Rebate Amount:	\$16,685.00
Intended COE Rebate Details	
COE Expiry Date:	29 Mar 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$24,229.00
COE Rebate Amount:	\$4,456.00
Total Rebate Amount:	\$21,141.00

The information contained herein is correct as at 17 May 2018

OK

MV 34K

17/05/2018

**CHEAPEST CAR
INSURANCE RENEWAL**



Compare
10+ insurers

GET A CHEAPER QUOTE NOW!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Nov 2011 Volkswagen Passat 1.8A Tsi At \$50800



Best Deal On Line. Only \$4000
Above Paper Value. Cheapest In
The Market.
Privilege Group Pte. Stocked

HIN LUNG AUTO
Ho Bee Group
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars
30 years
of car sale

Browse by Category

Sort by Date Posted 20 results/page

13 vehicles

bmw 318

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	bmw 318	Any	Any	2010	Any	Any	Any	Available



BMW 3 Series 318i Sunroof

\$36,151

\$11,310 /yr

01-Apr-2010

1,995 cc

97,000 km

Luxury

Available

P.M. Maintained And Workshop Record. One Of The Best 3 Series Around, In Excellent Condition Inside/Out. Sporty Black With Sunroof. Great Driving Sense And Road Handling. Buy With Peace Of Mind With Ex...

Dosh Car

Posted: 14 May 2010 Tags: 2010 BMW 318i, BMW 318i, BMW, 318i, Used BMW



BMW 3 Series 318i

\$35,000

\$10,780 /yr

10-Feb-2010

1,995 cc

122,533 km

Luxury

Available

Super Well Maintained Exterior And Interior As Good As Brand New Car. Accident Free And Regularly Maintained. New Road Tax. Viewings And Test Drives Are Strictly By Appointment Only. Up To 80% Loan An...

Monster Motors Pte Ltd

Posted: 09 May 2010 Tags: 2010 BMW 318i, BMW 318i, BMW, 318i, Used BMW



BMW 3 Series 318i Sunroof

\$40,800

\$11,840 /yr

18-Aug-2010

1,995 cc

106,000 km

Luxury

Available

Lowest Price In The Market. No Further Discount. Serious Buyer Are Welcome!

Think One Automobile & Trading

Posted: 08 May 2010 Tags: 2010 BMW 318i, BMW 318i, BMW, 318i, Used BMW



BMW 3 Series 318i

\$34,900

\$10,180 /yr

08-Feb-2010

1,995 cc

138,997 km

Luxury

Available

All Our Quality Pre-Owned Cars Are Selling At The Most Reasonable Price And With A Peace Of Mind! STA/VICOM Evaluate Are Welcome. Easy Approval! Down Payment \$3900, Our Flexible Bank And In House Fina...

Posted: 08 May 2010 Tags: 2010 BMW 318i, BMW 318i, BMW, 318i, Used BMW

Car Buying

Car Selling

Car Ownership

Buying a pre-owned car, but
Unsure of its Condition?
Get, STA Car Evaluation

Car Aftermarket

On The Move

Lifestyle



BMW 3 Series 318i Sunroof

\$36,800

\$11,490 /yr

16-Apr-2010

1,995 cc

114,000 km

Luxury

Available

High Demand! Classy And Executive BMW With Sunroof Edition! No Repair Needed. Powerful And Great Driving Feel. View To Believe! Flexible Loan And High Trade In Are Available. Call Us Now For An Non Ob...

Car Search

Posted: 06 May 2010 Tags: 2010 BMW 318i, BMW 318i, BMW, 318i, Used BMW



BMW 3 Series 318i Sunroof

\$34,800

\$10,510 /yr

30-Mar-2010

1,995 cc

153,000 km

Luxury

Available

High Demand! Classy And Executive BMW With Sunroof Edition! Best For Short Terms Drive! Elegant White With Cozy Black Interior! Shelter Protected, No Repair Needed. Powerful And Great Driving Feel. VL...

Car Search

Posted: 06 May 2010 Tags: 2010 BMW 318i, BMW 318i, BMW, 318i, Used BMW



BMW 3 Series 318i Sunroof

\$39,800

\$12,800 /yr

27-Apr-2010

1,995 cc

132,000 km

Luxury

Available

Full Service Records, Major Parts Replaced, Maintained By Reputable Workshop, Accident Free, Evaluation Welcome, Car Is Always Parked Under Shelter, Sporty Midnight Black With Red Interior, High Loan ...

Posted: 05 May 2010 Tags: 2010 BMW 318i, BMW 318i, BMW, 318i, Used BMW



BMW 3 Series 318i Sunroof

\$38,000

\$12,150 /yr

09-Apr-2010

1,995 cc

120,000 km

Luxury

Available

1 Owner, Low Original Mileage, New Body Paint, Direct Seller Price With Trade In And Loan Support. Super Condition Well Taken Care By Owner. Don't Miss This Unit. Great For New Driver And 1st Time Buy...

Posted: 04 May 2010 Tags: 2010 BMW 318i, BMW 318i, BMW, 318i, Used BMW



BMW 3 Series 318i Sunroof **\$44,900** **\$11,720 /yr** **28-Dec-2010** **1,995 cc** **103,000 km** **Luxury** **Available**

\$7k Drive Away, 100% In House Loan Approval, Well Kept Regularly Service, Car In Very Good Condition, No Repair Needed, Flexible Loan & Warranty Packages To Cater All Needs, View To Appreciate, Call Us...

Posted: 10-Apr-2018 Tags: 2010 BMW 318i, BMW 318i, BMW, 318i, Used BMW



BMW 3 Series 318i Sunroof **\$37,800** **\$11,810 /yr** **14-Apr-2010** **1,995 cc** **87,000 km** **Luxury** **Available**

Super Low Mileage Of Only 87,000KM! Nice Bidded Number! Guaranteed Lowest Price And Best Condition In Market! Highest Trade In With Lowest In House Interest Easy Loan, \$3k Deposit, Low Down Payment! C...

Posted: 28-Apr-2018 Tags: 2010 BMW 318i, BMW 318i, BMW, 318i, Used BMW



Insurance renewal at cheaper price!

We'll find you the cheapest car insurance quotes from over 10 insurers. Make your choice on zero excess and own workshop. Everything done at the comfort of your own home. Roadside assistance & claims support completely free.

Find out more!



BMW 3 Series 318i Sunroof **\$35,800** **\$11,500 /yr** **16-Mar-2010** **1,995 cc** **78,314 km** **Luxury** **Available**

1 Owner, Low Mileage, High Demand! Classy Executive Sedan With Sunroof Edition! Best For Short Term Drive! Elegant White On Classy Beige Leather Upholstery. Tip Top Condition. Powerful And Great Drive...

Posted: 28-Apr-2018 Tags: 2010 BMW 318i, BMW 318i, BMW, 318i, Used BMW



BMW 3 Series 318i Sunroof **\$35,333** **\$10,300 /yr** **29-Jun-2010** **1,995 cc** **87,000 km** **Luxury** **Available**

No Admin Fees, Processing Fees Or Any Other Hidden Costs, Low Mileage, Good Condition, Well Maintained, Call Now To Arrange A Viewing For Further Discussion.

Posted: 14-Apr-2018 Tags: 2010 BMW 318i, BMW 318i, BMW, 318i, Used BMW



BMW 3 Series 318i Sunroof **\$40,800** **\$12,240 /yr** **30-Jul-2010** **1,995 cc** **78,188 km** **Luxury** **Available**

Beautifully Equipped And Stylish Looking Luxury Sedan.Nice And Comfortable For Long Journeys With Reliable BMW Performance. Owned By A Successful Businesswoman Who Has Upgraded To A SUV. Car Is Mainta...

Car House Pte Ltd

Posted: 28-Apr-2018 Tags: 2010 BMW 318i, BMW 318i, BMW, 318i, Used BMW

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to CCE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used bmw 318, bmw 318 Singapore, used bmw 318 Singapore, used bmw 318, used vehicles Singapore or even buy used bmw 318 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, motor, car performance parts, car discussion, forum discussion, commercial vehicle leasing & CCE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement
©2004-2018 sgCarMart. All rights reserved.

Compare

Sell by Consignment

Consign your car to sell direct at the price you want without hassle.
No sale = no charges!

bmw 318 Price Range: Depreciation: 2010 Vehicle Type: 

Advanced Search

Home » Used Cars » Footprint Creative Hub » BMW 3 Series 318i Sunroof

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Car Leasing

CL
YOUR PREFERRED CAR LEASING
OPTION IN SINGAPORE



6769 7117 8720 5000 8720 8000

Club Med 
amazing you

SAVE UP TO
45%*

time for a
break

BMW 3 Series 318i Sunroof

Overview Financial Accessories Similar Research Photos Map

PREMIUM AD

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$39,800	
Depreciation	\$12,780 /yr View models with similar depreciation	
Reg Date	27-Apr-2010 (1yr 11mths 10days COE left)	
Manufactured	2010	
Mileage	132,000 km (16.4k /yr)	
Transmission	Auto	
Engine Cap	1,995 cc	
Road Tax	\$1,208 /yr	
Power	100.0 kW (134 bhp) View specs of the BMW 3 Series Sedan (2005-2012)	
Curb Weight	1,390 kg	
Features	Powerful And Responsive 2.0L Inline 4 Engine, 134 Bhp, SRS Airbags, ABS, Cruise Control, Electronic Memory Seats, Rain Sensors, Auto Headlights.	
Accessories	Sunroof, GPS, New Red Leather Interior Worth Over \$2000+, Sports Rims, Multi Function Steering Controls, Factory Fitted Audio Sound System, Fog Lamps.	
Description	Full Service Records, Major Parts Replaced, Maintained By Reputable Workshop, Accident Free, Evaluation Welcome, Car Is Always Parked Under Shelter, Sporty Midnight Black With Red Interior, High Loan Available, Trade In Welcome, Viewing By Appointment.	
COE	\$40,001	
OHV	\$29,800	
ARF	\$29,800	
Dereg Value	\$24,182 as of today (change)	
No. of Owners	4	
Type of Veh	Luxury Sedan	
Category	PARF Car, Premium Ad Car	
Availability	Available	PREMIUM AD

Add to Shortlist

Add to Compare

Add a Note

Posted on: 05-May-2018 | Last Updated on: 15-May-2018

Tags: BMW 318i, 2010 BMW 318i, BMW, 318i, Used BMW

Upfront Payment

= more Financial info

Transfer Fee	\$25	
Down Payment	\$11,940 (change)	Maximum 70% Loan 
1st Instalment	\$1,290	



Seller Information

Company	Footprint Creative Hub = dealer's pricelist = 7 vehs sold 17 vehs available
Address	55 Changi Road #01-22 Search cars nearby this location
Location	Mileage
Contact Person(s)	Darren Koh 86689494 Samuel Nah 81866601

Useful Services



Make sure of this car condition with STA Evaluation.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/05/2018 21:13
Date Of Accident	12/05/2018 16:00
Exact Location Of Accident	NORTH - SOUTH HIGHWAY
Country/State of Loss	MALAYSIA/NEGERI SEMBILAN DARUL KHUSUS

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKS1486U
Insured/Policyholder	
Name Of Registered Owner	NOORMALA BINTE SUJUDDIN
NRIC No	S1466679F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90884636
Alternative Phone No	OTHERS-85001904

Vehicle Particulars

Manufacturer	BMW
Model	318I 2.0L A/T ABS D/AIRBAG 2WD 4DR SR

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC17A00431101
Cover Note Number	

Driver

Name of Driver	MUHAMMAD ZAHIL FADZULI BIN ZAKARIA
NRIC No	S9004068E
Date Of Birth	08/02/1990
Occupation	INDOOR
Date Of Driving Pass	13/08/2012
Driving Experience	5 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85001904
Fax Number	
Contact Number	
Email Address	MDZAHIL@YAH00.COM

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

WA6466P

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

SAFIZA BINTE BUANG

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

SHARIFAH HAYATUNNUR BINTE MOHAMED

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SKS1486U

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



KETUA POLIS DAERAH
IBU PEJABAT POLIS DAERAH SEREMBAN
70300 SEREMBAN
NEGERI SEMBILAN

Tel :066033222 Samb :3394

Ruj : SEREMBAN/JSPT/KST/02387/18
Tkh : 12/05/2018

MUHAMMAD ZAHIL FADZULI BIN ZAKARIA No KP :
APT BLK 219 PASIR RIS STREET 21 #02- 164 SINGAPORE
510219 - Motokar SKS1486U

KEPUTUSAN PENYIASATAN KES

No. Pengaduan Polis : TRAFIK SEREMBAN/007817/18
Tkh/Masa Rpt : 12/05/2018 17:40 HRS
Kesalahan : R10 LN166/59
Tkh/Masa Kemalangan : 12/05/2018 16:00 HRS
Tempat Kemalangan : LEBUH RAYA UTARA SELATAN

Dengan hormatnya saya merujuk kepada pengaduan yang dibuat sepertimana dinyatakan di atas.

2. Untuk makluman, pihak yang bertanggungjawab melakukan kesalahan di atas telah disaman polis (RM 300) pada 12/5/2018 (CARS180093909).

3. Butir-butir pihak yang disalahkan adalah seperti berikut :-

FATIN NADIA BINTI AHMAD KAMIL KP : 920911015062
13 A KAMPUNG GUDANG GARAM SEGAMAT
85000
JRT2376 PEMANDU Motokar

"BERHATI-HATI DI JALAN RAYA"

(SAIFUL BAHTHIAR BIN ISMAIL) S/N YP086/
PENYIASAT
UNIT SASATAN LEBUH RAYA
K. P. T. RIUKT AMAN

(R194887 - SAIFUL BAHTHIAR BIN ISMAIL)
AIO TRAFIK
70300 SEREMBAN

s . k KST No : SEREMBAN/JSPT/KST/02387/18
[Notis ini hanya sebagai makluman anda sahaja]



POLIS DIRAJA MALAYSIA

REPOT POLIS

Balai : TRAFIK SEREMBAN
 Daerah : SEREMBAN
 Kontinjen : NEGERI SEMBILAN
 No Repot : TRAFIK SEREMBAN/007813/18
 Tarikh : 12/05/2018
 Waktu : 1700 PM
 Bahasa Diterima : B. Malaysia

Pegawai Penyiasat : R194887
 No Repot Bersangkut : TRAFIK
 SEREMBAN/007807/18

Butir-butir Penerima Repot

Nama : SAIFUL BAHTHIAR BIN ISMAIL

No Personel : R194887

Pangkat : SJN

Butir-butir Jurubahasa (Jika Ada)

Nama : —

No K/P (Baru) : —

No Polis/Tentera : —

No Paspot : —

Bahasa Asal : —

Alamat : —

Butir-butir Pengadu

Nama : FATIN NADIA BINTI AHMAD KAMIL

No K/P (Baru) : 920911015062

No Polis/Tentera : —

No Paspot : —

No Sijil Beranak : —

Jantina : Perempuan

Tarikh Lahir : 11/09/1992

Umur : 25 tahun 8 bulan

Keturunan : Melayu

Warganegara : Malaysia

Pekerjaan : GURU

Alamat Tempat Tinggal : 13 A KAMPUNG GUDANG GARAM 85000 SEGAMAT JOHOR MALAYSIA

Alamat Ibu/Bapa : —

Alamat Pejabat : —

No Tel (Rumah) : —

No Tel (Pejabat) : —

No Tel (HP) : 013-7005405

Emel : —

Pengadu Menyatakan:-

PADA 12/05/2018 JAM LEBIH KURANG 1600 PETANG, SAYA MEMANDU MOTOKAR NOMBOR JRT2376 JENIS PRODUA ALZA DARI JOHOR MENGHALA KUALA LUMPUR. PADA KETIKA ITU, APABILA SAYA SAMPAI DI KM 257 9U) LEBUH RAYA UTARA SELATAN, SAYA LIHAT SEBUAH MOTOKAR NOMBOR SKS1486U YANG BERADA DI HADAPAN SAYA, BERHENTI SECARA MENGEJUT. KETIKA ITU JALAN LICIN DAN BASAH, SAYA TERUS MENEKAN BREK DAN CUBA MENGELAK TETAPI TERKENA JUGA DI BAHAGIAN BUMPER BELAKANG KENDERAAN TERSEBUT. DALAM KEJADIAN ITU, SAYA TIDAK MENGALAMI APA-APA KECEDERAAN. KEROSAKAN MOTOKAR SAYA IALAH BUMPER HADAPAN ROSAK, RADIATOR PECAH, LAMPU BESAR PECAH, BONET KEMEK, PINTU KIRI KANAN ROSAK, AIR BEG DUA-DUA KELUAR DAN LAIN-LAIN KEROSAKAN TIDAK PASTI.

Tandatangan Pengadu:

Tandatangan Jurubahasa (Jika ada):

Tandatangan Penerima Repot:

SALINAN DIAKUISAH
 UNTUK TINDAKAN
 CIVIL DAN INSURANS

ID Pencetak | Tarikh @ Masa Cetak

: R125880 / 13/05/2018 06:25:36 AM

(SAIFUL BAHTHIAR BIN ISMAIL)
 PEN. PEG. PEN. T. J. J.
 UNIT SIASATAN LEBUHRAYA
 I.S.P.T BUKIT AMAN

KUNCI RAJAH KASAR KEMALANGAN JALN RAYA
SEREMBAN (T) REPORT NO 7807/18
BERTARIKH 12/05/2018
DI KM 257 (U) L/RAYA UTARA SELATAN

KUNCI RAJAH KASAR.

- =====
- A1- KEDUDUKAN PENGHADANG BESI DI SEBELAH KIRI, DARI ARAH SELATAN MENGHALA KE UTARA
- A2- KEDUDUKAN GARISAN LURUS DI SEBELAH KIRI, DARI ARAH SELATAN MENGHALA KE UTARA
- A3- KEDUDUKAN GARISAN LURUS PUTUS- PUTUS DI SEBELAH KIRI DARI ARAH SELATAN
MENGHALA KE UTARA
- A4- KEDUDUKAN GARISAN LURUS PUTUS- PUTUS DI SEBELAH KANAN DARI ARAH DARI ARAH
SELATAN MENGHALA KE UTARA
- A5- KEDUDUKAN PENGHADANG BESI DI SEBELAH KANAN, DARI ARAH SELATAN MENGHALA KE
UTARA

UKURAN DALAM METER.

- =====
- 1) A1-----A2 3.00METER
- 2) A2-----A3 3.70METER
- 3) A3-----A4 3.70METER
- 4) A4-----A5 3.70METER

SALINAN DIAKSES SAH
UNTUK TINJAUAN
CIVIL DAN INSURANS

(SAUDU BATHARI BIN ISMAIL) S/N 114611/1
PEN. PEG PENYIASAT
UNIT SIASATAN LEBUHRAYA
J.S.P.T BUKIT AMAN



FALCON - AIR AUTO SERVICES PTE LTD
CO. REG. No.: 1995-01140-D

INSURER: **ECICS Limited (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC17A00431101	Date of Loss:	12/05/2018
Vehicle Reg. No.:	SKS1486U	Driveable?	
Driver Age/Info:	28 / MALE	Party At Fault:	THIRD PARTY
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NOORMALA BINTE SUJUDDIN		
Driver:	MUHAMMAD ZAHIL FADZULI BIN ZAKARIA		
Make/Model:	BMW 318I, 2.0 (A)	Vehicle Reg. Date:	30/03/2010
Vehicle Colour:	BLACK		
Engine No:	A172I664N46B20BZ	Chassis No:	WBAPF72070A793680
Odometer:	1 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Description of Accident/Loss	REFER TO M'SIA POLIRE REPORT.		
Remarks:	VEHICLE IS IN.		
Present Location:	FALCON-AIR AUTO SERVICES PTE LTD (SIN MING)		

COST OF CLAIMS	Amount
Parts	13,526.00
Miscellaneous Items	0.00
Labour	4,560.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	18,086.00
+ GST 7.00% (\$\$)	1,266.02
Nett Amount (\$\$)	19,352.02

This claim is handled by: JOSHUA NG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

70650

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 May 2018)

Parts: 143 BMW 318I 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Falcon-Air Auto Services Pte Ltd/SKS1486U/16/05/2018 09:35

Validity: These estimates are valid only if they contain the print code (above) on all numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%
1	1		*Bonnet Cover	✓
2	1		*Bonnet Logo	✓
3	2		*Bonnet Lock	✓
4	2		*Bonnet Lock Striker	✓
5	1		*Bonnet Release Catch	✓
6	2		*Headlamp	✓
7	2		*Headlamp Panel	✓
8	1		*Front Bumper	✓
9	10		*Front Bumper Clip	✓
10	2		*Front Bumper Side Retainer	✓
11	1		*Front Bumper Lower Grille	✓
12	1		*Front Bumper Reinforcement	✓
13	1		*Front Support Panel	✓
14	1		*Front Brace Panel	✓
15	2		*Radiator Grille	✓
16	1		*Air Con Condenser	✓
17	1		*Radiator	✓
18	1		*Air Guide	✓
19	1		*Power Steering Loop	✓
20	1		*Front Number Plate	✓
21	1		*Boot Cover	✓
22	1		*Boot Logo	✓
23	2		*Boot Hinge	✓
24	1		*Boot Lock	✓
25	1		*Boot Weatherstrip	✓
26	8		*Boot Inner Trim Clip	✓
27	1		*Rear Bumper	✓
28	10		*Rear Bumper Clip	✓
29	2		*Rear Bumper Side Retainer	✓
30	1		*Rear Bumper Reinforcement	✓
31	1		*Rear Bumper Inner Panel	✓
32	1		*Rear Bumper Tow Cover	✓
33	4		*Rear Bumper Sensor	✓
34	1		*Rear Bumper Under Cover (Front)	✓
35	1		*Rear Bumper Under Cover (Middle)	✓
36	1		*Rear Bumper Under Cover (RH)	✓
37	16		*Rear Bumper Under Cover Clip	✓
38	1		*Rear Number Plate	✓
39	1		*Rear End Panel	✓
40	16		*Rear End Panel Rivet	✓

0 0.00 *80.00FS

Falcon-Air Auto Services Pte Ltd/SKS1486U/16/05/2018 09:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
41	1		*Rear End Panel Garnish	✓ 0.00	0.00	*58.00F MSV
42	2		*Rear End Panel Sealant	✓ 0	0.00	60 *280.00FS HECV
43	1		*Rear Compartment Board	✓ 0.00	0.00	*160.00F LUTV
44	1		*Rear Compartment Panel	✓ 0.00	0.00	*208.00F BR
45	16		*Rear Compartment Panel Rivet	✓ 0	0.00	NN *80.00FS HECV
46	2		*Rear Compartment Panel Sealant	✓ 0	0.00	NN *280.00FS HECV
47	1		*Rear Silencer	✓ 0.00	0.00	*620.00F DDV
48	2		*Rear Silencer Chrome Muffler	✓ 0.00	0.00	*150.00F BEVD
49	3		*Rear Silencer Chrome Mounting	✓ 0.00	0.00	*69.00F LUTV
50	3		*Rear Silencer Chrome Mounting Bracket	✓ 0.00	0.00	*90.00F DISV
51	1		*Rear Silencer Gasket	✓ 0.00	0.00	*30.00F HECV
52	1		*Rear Silencer Heat Shield	✓ 0.00	0.00	*55.00F DISV

F=Franchise part. S=SpcNett.

Sub Total (S\$) **12,390.00**
+ Margin on L,N Items 10.00% (S\$) **1,136.00**

Total Parts (S\$) **13,526.00**

Falcon-Air Auto Services Pte Ltd/SKS1486U/16/05/2018 09:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To focus headlamp	New	30 50.00
2	To remove/refix air con condenser, pipe vacuum and top up air con gas	New	7 120.00 ✓
3	To check rear wiring	New	25 50.00
4	To transfer boot mechanism	New	60 100.00
5	To remove/refix trims, etc to facilitate repairs	New	150 280.00
6	To remove / replace /realign exhaust system	New	80 160.00
7	To straighten LH / RH front chassis, LH / RH front fender, LH / RH rear chassis, LH / RH rear fender, cut out /re-weld front support panel, rear end panel, rear compartment panel	New	1500 1,800.00
8	To spray paint on bonnet, front bumper, LH / RH front fender, boot cover, rear bumper, rear bumper reinforcement, rear end panel, LH / RH rear fender	New	1200 2,000.00
Gross Labour Cost (S\$)			4,560.00

Falcon-Air Auto Services Pte Ltd/SKS1486U/16/05/2018 09:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines S1 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg

Revert.
Before paint job
LOR Auto WA

16/5/2018

11 wdays

x \$500/2

8/6/18



FALCON - AIR AUTO SERVICES PTE LTD
CO. REG. No: 1995-01140-D

(SUPPLEMENTARY)

INSURER: ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC17A00431101	Date of Loss:	12/05/2018
Vehicle Reg. No.:	SKS1486U	Driveable?	
Driver Age/Info:	28 / MALE	Party At Fault:	THIRD PARTY
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NOORMALA BINTE SUJUDDIN		
Driver:	MUHAMMAD ZAHIL FADZULI BIN ZAKARIA		
Make/Model:	BMW 318I, 2.0 (A)	Vehicle Reg. Date:	30/03/2010
Vehicle Colour:	BLACK		
Engine No:	A172I664N46B20BZ	Chassis No:	WBAPF72070A793680
Odometer:	1 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Description of Accident/Loss	REFER TO M'SIA POLIRE REPORT.		
Present Location:	FALCON-AIR AUTO SERVICES PTE LTD (SIN MING)		

COST OF CLAIMS

	Amount
Parts	1,804.00
Miscellaneous Items	0.00
Labour	760.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,564.00
+ GST 7.00% (S\$)	179.48
Nett Amount (S\$)	2,743.48
+ Previous Estimates (S\$)	19,352.02
Claim Total (S\$)	22,095.50

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 02 Aug 2018)
Parts: 143	BMW 318i 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: Falcon-Air Auto Services Pte Ltd/SKS1486U/02/08/2018 17:41	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	2		*Front Head Rest Repair Kit	Ref	0.00	*390.00F
2	1		*LH Side Compartment Panel	Ref	0.00	*180.00F
3	2		*Headlamp Retainer	Ref	0.00	*170.00F
4	2		*Taillamp	Ref	0.00	*900.00F
Sub Total (\$\$)						1,640.00
+ Margin on L,N Items 10.00% (\$\$)						164.00
Total Parts (\$\$)						1,804.00

F=Franchise part.

Falcon-Air Auto Services Pte Ltd/SKS1486U/02/08/2018 17:41. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To replace front head rest repair kit	New	200 480.00
2	To diagnose and reset air bag light	New	150 280.00
Gross Labour Cost (\$\$)			760.00

Falcon-Air Auto Services Pte Ltd/SKS1486U/02/08/2018 17:41. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 8th 178 Sin Ming Drive #01-060/7/13, #05-17 Sin Ming Autocare S(575221) Tel: 6452-0880 / 6458-0880 Fax: 6454-7882
Branches: Tampines St 83 #01-0008 #01-200 S(528840) Tel: 6789-7997 Fax: 6789-7997 No 8 Pandan Loop S(128228) Tel: 6779-8865 Fax: 6779-1119
Website: www.falconair.com.sg Email: email@falconair.com.sg

**FALCON-AIR**
FALCON - AIR AUTO SERVICES PTE LTD
 CO. REG. No.: 199501140D

Attn: Catherine

 INSURER: **ECICS Limited (HQ)**
PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC17A00431101	Date of Loss:	12/05/2018
Vehicle Reg. No.:	SKS1486U	Driveable?	
Driver Age/Info:	28 / MALE	Party At Fault:	THIRD PARTY
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NOORMALA BINTE SUJUDDIN		
Driver:	MUHAMMAD ZAHIL FADZULI BIN ZAKARIA		
Make/Model:	BMW 318I, 2.0 (A)	Vehicle Reg. Date:	30/03/2010
Vehicle Colour:	BLACK		
Engine No:	A172I664N46B20BZ	Chassis No:	WBAPF72070A793680
Odometer:	1 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Description of Accident/Loss	REFER TO M'SIA POLIRE REPORT.		
Remarks:	VEHICLE IS IN.		
Present Location:	FALCON-AIR AUTO SERVICES PTE LTD (SIN MING)		

COST OF CLAIMS	Amount
Parts	13,526.00
Miscellaneous Items	0.00
Labour	4,560.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	18,086.00
+ GST 7.00% (S\$)	1,266.02
Nett Amount (S\$)	19,352.02

This claim is handled by: JOSHUA NG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 May 2018)

Parts: 143 BMW 318i 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Falcon-Air Auto Services Pte Ltd/SKS1486U/16/05/2018 09:35

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Bonnet Cover	✓ 0.00	0.00	*720.00 F
2	1		*Bonnet Logo	✓ 0.00	0.00	*50.00 F
3	2		*Bonnet Lock	✓ 0.00	0.00	*160.00 F
4	2		*Bonnet Lock Striker	✓ 0.00	0.00	*36.00 F
5	1		*Bonnet Release Catch	✓ 0.00	0.00	*18.00 F
6	2		*Headlamp	✓ 0.00	0.00	*1,040.00 F
7	2		*Headlamp Panel	✓ 0.00	0.00	*110.00 F
8	1		*Front Bumper	✓ 0.00	0.00	*750.00 F
9	10		*Front Bumper Clip	✓ 0	0.00	*50.00 FS
10	2		*Front Bumper Side Retainer	✓ 0.00	0.00	*20.00 F
11	1		*Front Bumper Lower Grille	✓ 0.00	0.00	*60.00 F
12	1		*Front Bumper Reinforcement	✓ 0.00	0.00	*450.00 F
13	1		*Front Support Panel	✓ 0.00	0.00	*480.00 F
14	1		*Front Brace Panel	✓ 0.00	0.00	*18.00 F
15	2		*Radiator Grille	✓ 0.00	0.00	*170.00 F
16	1		*Air-Con Condenser	✓ 0.00	0.00	*650.00 F
17	1		*Radiator	✓ 0.00	0.00	*465.00 F
18	1		*Air Guide	✓ 0.00	0.00	*125.00 F
19	1		*Power Steering Loop	✓ 0.00	0.00	*95.00 F
20	1		*Front Number Plate	✓ 0	0.00	*45.00 FS
21	1		*Boot Cover	✓ 0.00	0.00	*1,150.00 F
22	1		*Boot Logo	✓ 0.00	0.00	*55.00 F
23	2		*Boot Hinge	✓ 0.00	0.00	*130.00 F
24	1		*Boot Lock	✓ 0.00	0.00	*80.00 F
25	1		*Boot Weatherstrip	✓ 0.00	0.00	*55.00 F
26	8		*Boot Inner Trim Clip	✓ 0	0.00	*40.00 FS
27	1		*Rear Bumper	✓ 0.00	0.00	*950.00 F
28	10		*Rear Bumper Clip	✓ 0	0.00	*50.00 FS
29	2		*Rear Bumper Side Retainer	✓ 0.00	0.00	*114.00 F
30	1		*Rear Bumper Reinforcement	✓ 0.00	0.00	*280.00 F
31	1		*Rear Bumper Inner Panel	✓ 0.00	0.00	*33.00 F
32	1		*Rear Bumper Tow Cover	✓ 0.00	0.00	*36.00 F
33	4		*Rear Bumper Sensor	✓ 0.00	0.00	*860.00 F
34	1		*Rear Bumper Under Cover (Front)	✓ 0.00	0.00	*65.00 F
35	1		*Rear Bumper Under Cover (Middle)	✓ 0.00	0.00	*60.00 F
36	1		*Rear Bumper Under Cover (RH)	✓ 0.00	0.00	*65.00 F
37	16		*Rear Bumper Under Cover Clip	✓ 0	0.00	*80.00 FS
38	1		*Rear Number Plate	✓ 0	0.00	*45.00 FS
39	1		*Rear End Panel	✓ 0.00	0.00	*570.00 F
40	16		*Rear End Panel Rivet	✓ 0	0.00	*80.00 FS

Falcon-Air Auto Services Pte Ltd/SKS1486U/16/05/2018 09:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
41	1		*Rear End Panel Garnish / <i>22.</i>	✓ 0.00	0.00	*58.00 F
42	2		*Rear End Panel Sealant	✓ 0	0.00	*280.00 FS
43	1		*Rear Compartment Board / <i>cut</i>	✓ 0.00	0.00	*160.00 F
44	1		*Rear Compartment Panel	✓ 0.00	0.00	*208.00 F
45	16		*Rear Compartment Panel Rivet	✓ 0	0.00	*80.00 FS
46	2		*Rear Compartment Panel Sealant	✓ 0	0.00	*280.00 FS
47	1		*Rear Silencer	✓ 0.00	0.00	*620.00 F
48	2		*Rear Silencer Chrome Muffler	✓ 0.00	0.00	*150.00 F
49	3		*Rear Silencer Chrome Mounting	✓ 0.00	0.00	*69.00 F
50	3		*Rear Silencer Chrome Mounting Bracket / <i>BT</i>	✓ 0.00	0.00	*90.00 F
51	1		*Rear Silencer Gasket	✓ 0.00	0.00	*30.00 F
52	1		*Rear Silencer Heat Shield / <i>fine.</i>	✓ 0.00	0.00	*55.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$) 9654.00 12,390.00
 + Margin on L,N items 10.00% (S\$) 965.40 1,136.00
 Total Parts (S\$) 10619.40 13,526.00

Falcon-Air Auto Services Pte Ltd/SKS1486U/16/05/2018 09:35. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

2PLS front Head Rest Repair Kit 2x195 390.00 = *part.*
 2PLS Headlamp Retainer 2x25 175.00
 2PLC ~~tail~~ lamp 2x450 500.00 = *CRA*

7. Replace front Head Rest Repair Kit 480.00

7. diagnose and Rect on big light 280.00

1PL LH side compartment panel 180.00 = *CRA.*

Emo Qrp.
 21/5/18

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To focus headlamp	New	30 50.00
2	To remove/refix air con condenser, pipe vacuum and top up air con gas	New	✓? 120.00
3	To check rear wiring	New	30 50.00
4	To transfer boot mechanism	New	60 100.00
5	To remove/refix trims, etc to facilitate repairs	New	150 200.00
6	To remove / replace /realign exhaust system	New	80 100.00
7	To straighten LH / RH front chassis, LH / RH front fender, LH / RH rear chassis, LH / RH rear fender, cut out /re-weld front support panel, rear end panel, rear compartment panel	New	1500 1,800.00
8	To spray paint on bonnet, front bumper, LH / RH front fender, boot cover, rear bumper, rear bumper reinforcement, rear end panel, LH / RH rear fender	New	1200 2,000.00
Gross Labour Cost (\$\$)			4,560.00

Falcon-Air Auto Services Pte Ltd/SKS1486U/16/05/2018 09:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 175 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(676721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines Bl 93 Blk 9006 #01-250 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128226) Tel: 6779-5555 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg

Parts - 10619.40
S/N - 1030.00
Supply - 2564.00
Labour - 3170.00
t.f.-1 - 17383.40
LS-Joi. - \$13906.72
LS - \$12800.00
MAX

Revert,
Before Paul A. Paul
L & B Auto WPA
16/5/2018
11 wdays
x9 \$500/2

8966, 8967, 8968, 8969, 8970, 8971

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 May 2018 21:49 Sendback Est	16 May 2018 09:35 S\$18,086.00	16 May 2018 10:39 Edit Adj Rpt	S\$12,800.00 Edit Estimates	S\$12,800.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	02 Aug 2018 17:38	02 Aug 2018 17:41 S\$2,564.00	02 Aug 2018 17:41			(Combined)	Combined with Main Uncombine Suppl.

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	NOORMALA BINTE SUJUDDIN , ID: S1466679F, Email: mdzahil@yahoo.com		
Vehicle Reg. No.:	SKS1486U	Date of Loss:	12/05/2018 16:00 - :59 [97 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / DMPC1800187H	Policy/Cover Note No.:	MPC17A00431101 (Comprehensive) Coverage: 30/09/2017 - 29/09/2018
		Excess:	S\$500.00
Repairer:	Falcon-Air Auto Services Pte Ltd (Sin Ming) 176 Sin Ming Drive #01-06, Sin Ming Autocare, 575721 Sin Ming - Tel: 6452 0880		
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Janice Goh - 6303 0182]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 25/05/2018]		
Driver/Custodian:	MUHAMMAD ZAHIL FADZULI BIN ZAKARIA (28 / Male), NRIC: S9004068E, Tel: +6585001904		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- ECICS (18/05/2018): Alert - Adj Mandate Approved (S\$12860.00) - SKS1486U - Claim Handler: Janice Goh

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

**SKS1486U (DMPC1800187H)
OD
May 12 2018 4:00PM
[NOORMALA BINTE SUJUDDIN]
Falcon-Air Auto Services Pte Ltd**

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Assessment Reports				1 per page	☒
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Sin Ming)	Thumbnail	Print	
1	16/05/18 09:35	Repairer Estimates	 Load HTM		
2	02/08/18 17:41	Repairer Estimates Suppl. #1	 Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	18/05/18 10:25	Adjuster Immediate Advice	 Load HTM		

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	06/08/18 17:23	General View	 Load JPG	☒	
2	06/08/18 17:23	Chassis Number	 Load JPG	☒	
3	06/08/18 17:23	Odometer Reading	 Load JPG	☒	
4	06/08/18 17:23	General View	 Load JPG	☒	
5	06/08/18 17:23	General View	 Load JPG	☒	
6	06/08/18 17:23	General View	 Load JPG	☒	
7	06/08/18 17:23	General View	 Load JPG	☒	
8	06/08/18 17:23	General View	 Load JPG	☒	
9	06/08/18 17:23	General View	 Load JPG	☒	
10	06/08/18 17:23	General View	 Load JPG	☒	
11	06/08/18 17:23	General View	 Load JPG	☒	
12	06/08/18 17:23	General View	 Load JPG	☒	
13	06/08/18 17:23	General View	 Load JPG	☒	
14	06/08/18 17:23	General View	 Load JPG	☒	
15	06/08/18 17:23	General View	 Load JPG	☒	
16	06/08/18 17:23	General View	 Load JPG	☒	
17	06/08/18 17:23	General View	 Load JPG	☒	
18	06/08/18 17:23	General View	 Load JPG	☒	
19	06/08/18 17:23	General View	 Load JPG	☒	
20	06/08/18 17:23	General View	 Load JPG	☒	
21	06/08/18 17:23	General View	 Load JPG	☒	
22	06/08/18 17:23	General View	 Load JPG	☒	
23	06/08/18 17:23	General View	 Load JPG	☒	
24	06/08/18 17:23	General View	 Load JPG	☒	
25	06/08/18 17:23	General View	 Load JPG	☒	
26	06/08/18 17:23	General View	 Load JPG	☒	
27	06/08/18 17:23	General View	 Load JPG	☒	
28	06/08/18 17:23	General View	 Load JPG	☒	
29	06/08/18 17:23	General View	 Load JPG	☒	
30	06/08/18 17:23	General View	 Load JPG	☒	
31	06/08/18 17:23	General View	 Load JPG	☒	
32	06/08/18 17:23	General View	 Load JPG	☒	
33	06/08/18 17:23	General View	 Load JPG	☒	

Assessment Reports			1 per page	☒
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Sin Ming)	Thumbnail	Print
				☒
34	06/08/18 17:23	General View	 Load JPG	☒
35	06/08/18 17:23	General View	 Load JPG	☒
36	06/08/18 17:23	General View	 Load JPG	☒
37	06/08/18 17:23	General View	 Load JPG	☒
38	06/08/18 17:23	General View	 Load JPG	☒
39	06/08/18 17:23	General View	 Load JPG	☒
40	06/08/18 17:23	General View	 Load JPG	☒
41	06/08/18 17:23	General View	 Load JPG	☒
42	06/08/18 17:23	General View	 Load JPG	☒
43	06/08/18 17:23	General View	 Load JPG	☒
44	06/08/18 17:23	General View	 Load JPG	☒
45	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
46	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
47	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
48	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
49	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
50	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
51	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
52	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
53	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
54	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
55	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
56	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
57	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
58	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
59	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
60	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
61	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
62	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
63	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
64	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
65	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
66	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
67	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
68	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
69	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
70	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
71	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
72	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
73	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
74	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
75	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
76	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
77	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
78	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
79	06/08/18 17:23	Reinspection Photo	Load JPG	☒
80	06/08/18 17:23	Reinspection Photo	Load JPG	☒
81	06/08/18 17:23	Reinspection Photo	Load JPG	☒
82	06/08/18 17:23	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Sin Ming)	Thumbnail	Print
83	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
84	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
85	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
86	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
87	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
88	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
89	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
90	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
91	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
92	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
93	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
94	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
95	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
96	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
97	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
98	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
99	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
100	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
101	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
102	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
103	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
104	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
105	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
106	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
107	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
108	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
109	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
110	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
111	06/08/18 17:23	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Sin Ming)	Thumbnail	Print
1	16/05/18 09:34	E-filed GIA report	 Load PDF	
2	16/05/18 09:34	Certificate of Insurance	 Load PDF	
3	16/05/18 09:34	Driver's NRIC & Driving License	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Sin Ming)	Thumbnail	Print
1	14/05/18 21:43	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Sin Ming)	Thumbnail	Print
1	14/05/18 21:37	Accident Photo	 Load JPG	☒
2	14/05/18 21:37	Accident Photo	 Load JPG	☒
3	14/05/18 21:37	Accident Photo	 Load JPG	☒
4	14/05/18 21:37	Accident Photo	 Load JPG	☒
5	14/05/18 21:37	Accident Photo	 Load JPG	☒
6	14/05/18 21:37	Accident Photo	 Load JPG	☒
7	14/05/18 21:37	Accident Photo	 Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Sin Ming)	Thumbnail	Print
				☒
8	14/05/18 21:37	Accident Photo	Load JPG	☒
9	14/05/18 21:37	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Sin Ming)	Thumbnail	Print
1	14/05/18 21:35	Sketch Plan	Load TIF	
2	14/05/18 21:36	Police Report	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One
Singapore 038987

Our File No: CS/ICS18008876/DQD3E2

Date: 30/08/2018

REFERENCE

Insured/Claimant: NOORMALA BINTE SUJUDDIN Policy No: MPC17A00431101
Date of Loss: 12/05/2018 Nature of Claim: OD Claim No: DMPC1800187H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKS1486U**
Make & Model: BMW 318i, 2.0 (A) Engine No: A172I664N46B20BZ
Reg. Date: 30/03/2010 (Man. Year: 2010) Chassis No: WBAPF72070A793680
Colour: Black Odometer: 195779 km
Engine Capacity: 1995 cc
Market Value/New Car Price: S\$34,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35 R19 Rear Tyre Size: 265/30 R19
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,330.00	12,678.70	2,651.30	17.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,320.00	3,520.00	1,800.00	33.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,650.00	16,198.70	4,451.30	21.56
Approved Total (Overridden) (S\$)		12,800.00		
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	20,650.00	12,300.00	8,350.00	40.44
+ GST 7.00/7.00% (S\$)	1,445.50	861.00	584.50	40.44
Nett Amount (S\$)	22,095.50	13,161.00	8,934.50	40.44

INSPECTION

Date of Assignment: 16/05/2018 Present Location: Falcon-Air Auto Services Pte Ltd (Sin Ming)
Date Inspected: 16/05/2018 Inspected At: Falcon-Air Auto Services Pte Ltd (Sin Ming)
176 Sin Ming Drive #01-06, Sin Ming Autocare
Singapore 575721
Estimated Period of Repair: 11.0 days

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Aug 2018)
Parts:	143	BMW 318i 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKS1486U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Bonnet Cover	Bent	720.00 F	*720.00 F
2	1		*Bonnet Logo	Necessary	50.00 F	*50.00 F
3	2		*Bonnet Lock	Not Necessary	160.00 F	*- F
4	2		*Bonnet Lock Striker	Not Necessary	36.00 F	*- F
5	1		*Bonnet Release Catch	Not Necessary	18.00 F	*- F
6	2		*Headlamp	Cracked / Broken	1,040.00 F	*1,040.00 F
7	2		*Headlamp Panel	Not Necessary	110.00 F	*- F
8	1		*Front Bumper	Cut	750.00 F	*750.00 F
9	10		*Front Bumper Clip	Necessary	50.00 FS	*50.00 FS
10	2		*Front Bumper Side Retainer	Necessary	20.00 F	*20.00 F
11	1		*Front Bumper Lower Grille	Not Necessary	60.00 F	*- F
12	1		*Front Bumper Reinforcement	Bent	450.00 F	*450.00 F
13	1		*Front Support Panel	Cracked / Bent	480.00 F	*480.00 F
14	1		*Front Brace Panel	Bent	18.00 F	*18.00 F
15	2		*Radiator Grille	Broken	170.00 F	*170.00 F
16	1		*Air Con Condenser	Not Necessary	650.00 F	*- F
17	1		*Radiator	Not Necessary	465.00 F	*- F
18	1		*Air Guide	Distorted	125.00 F	*125.00 F
19	1		*Power Steering Loop	Not Necessary	95.00 F	*- F
20	1		*Front Number Plate	Bent	45.00 FS	*45.00 FS
21	1		*Boot Cover	Dented	1,150.00 F	*1,150.00 F
22	1		*Boot Logo	Necessary	55.00 F	*55.00 F
23	2		*Boot Hinge	Not Necessary	130.00 F	*- F
24	1		*Boot Lock	Bent	80.00 F	*80.00 F
25	1		*Boot Weatherstrip	Cut	55.00 F	*55.00 F
26	8		*Boot Inner Trim Clip	Necessary	40.00 FS	*40.00 FS
27	1		*Rear Bumper	Distorted	950.00 F	*950.00 F
28	10		*Rear Bumper Clip	Necessary	50.00 FS	*50.00 FS
29	2		*Rear Bumper Side Retainer	Necessary	114.00 F	*114.00 F
30	1		*Rear Bumper Reinforcement	Bent	280.00 F	*280.00 F
31	1		*Rear Bumper Inner Panel	Cracked	33.00 F	*33.00 F
32	1		*Rear Bumper Tow Cover	Missing	36.00 F	*36.00 F
33	4		*Rear Bumper Sensor	Cut	860.00 F	*860.00 F
34	1		*Rear Bumper Under Cover (Front)	Necessary	65.00 F	*65.00 F
35	1		*Rear Bumper Under Cover (Middle)	Necessary	60.00 F	*60.00 F
36	1		*Rear Bumper Under Cover (RH)	Necessary	65.00 F	*65.00 F
37	16		*Rear Bumper Under Cover Clip	Necessary	80.00 FS	*80.00 FS
38	1		*Rear Number Plate	Cut	45.00 FS	*45.00 FS
39	1		*Rear End Panel	Bent	570.00 F	*570.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	16		*Rear End Panel Rivet	Necessary	80.00 FS	*80.00 FS
41	1		*Rear End Panel Garnish	Deformed / Distorted	58.00 F	*58.00 F
42	2		*Rear End Panel Sealant	Necessary	280.00 FS	*60.00 FS
43	1		*Rear Compartment Board	Cut	160.00 F	*160.00 F
44	1		*Rear Compartment Panel	Broken	208.00 F	*208.00 F
45	16		*Rear Compartment Panel Rivet	Not Necessary	80.00 FS	*- FS
46	2		*Rear Compartment Panel Sealant	Not Necessary	280.00 FS	*- FS
47	1		*Rear Silencer	Dented	620.00 F	*620.00 F
48	2		*Rear Silencer Chrome Muffler	Dented	150.00 F	*150.00 F
49	3		*Rear Silencer Chrome Mounting	Not Necessary	69.00 F	*- F
50	3		*Rear Silencer Chrome Mounting Bracket	Not Necessary	90.00 F	*- F
51	1		*Rear Silencer Gasket	Necessary	30.00 F	*30.00 F
52	1		*Rear Silencer Heat Shield	Buckled / Distorted	55.00 F	*55.00 F
Supplementary #1						
53	2		*Front Head Rest Repair Kit	Activated	390.00 F	*390.00 F
54	1		*LH Side Compartment Panel	Cracked	180.00 F	*180.00 F
55	2		*Headlamp Retainer	Activated	170.00 F	*170.00 F
56	2		*Taillamp	Cracked	900.00 F	*900.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	14,030.00	11,567.00
+ Margin on L,N Items 10.00/10.00% (S\$)	1,300.00	1,111.70
Total Parts (S\$)	15,330.00	12,678.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To focus headlamp	New	50.00	30.00
2	To remove/refix air con condenser, pipe vacuum and top up air con gas	New	120.00	120.00
3	To check rear wiring	New	50.00	30.00
4	To transfer boot mechanism	New	100.00	60.00
5	To remove/refix trims, etc to facilitate repairs	New	280.00	150.00
6	To remove / replace /realign exhaust system	New	160.00	80.00
7	To straighten LH / RH front chassis, LH / RH front fender, LH / RH rear chassis, LH / RH rear fender, cut out /re-weld front support panel, rear end panel, rear compartment panel	New	1,800.00	1,500.00
8	To spray paint on bonnet, front bumper, LH / RH front fender, boot cover, rear bumper, rear bumper reinforcement, rear end panel, LH / RH rear fender	New	2,000.00	1,200.00
Supplementary #1				
Labour Items				
9	To replace front head rest repair kit	New	480.00	200.00
10	To diagnose and reset air bag light	New	280.00	150.00
Gross Labour Cost (S\$)			5,320.00	3,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 May 2018)

Parts: 143 BMW 318i 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Falcon-Air Auto Services Pte Ltd/SKS1486U/16/05/2018 09:35

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*Bonnet Cover	0.00	0.00	*720.00 F	BT ✓
2	1		*Bonnet Logo	0.00	0.00	*50.00 F	NECV ✓
3	2		*Bonnet Lock	0.00	0.00	*160.00 F	NNX ✓
4	2		*Bonnet Lock Striker	0.00	0.00	*36.00 F	NNX ✓
5	1		*Bonnet Release Catch	0.00	0.00	*18.00 F	NNX ✓
6	2		*Headlamp	0.00	0.00	*1,040.00 F	BR ✓
7	2		*Headlamp Panel	0.00	0.00	*110.00 F	NNX ✓
8	1		*Front Bumper	0.00	0.00	*750.00 F	CUT ✓
9	10		*Front Bumper Clip	0	0.00	*50.00 FS	NECV ✓
10	2		*Front Bumper Side Retainer	0.00	0.00	*20.00 F	NECV ✓
11	1		*Front Bumper Lower Grille	0.00	0.00	*60.00 F	NNX ✓
12	1		*Front Bumper Reinforcement	0.00	0.00	*450.00 F	BT ✓
13	1		*Front Support Panel	0.00	0.00	*480.00 F	BT ✓
14	1		*Front Brace Panel	0.00	0.00	*18.00 F	BT ✓
15	2		*Radiator Grille	0.00	0.00	*170.00 F	BR ✓
16	1		*Air Con Condenser	0.00	0.00	*650.00 F	NNX ✓
17	1		*Radiator	0.00	0.00	*465.00 F	NNX ✓
18	1		*Air Guide	0.00	0.00	*125.00 F	DIS ✓
19	1		*Power Steering Loop	0.00	0.00	*95.00 F	NNX ✓
20	1		*Front Number Plate	0	0.00	*45.00 FS	BT ✓
21	1		*Boot Cover	0.00	0.00	*1,150.00 F	DD ✓
22	1		*Boot Logo	0.00	0.00	*55.00 F	NECV ✓
23	2		*Boot Hinge	0.00	0.00	*130.00 F	NNX ✓
24	1		*Boot Lock	0.00	0.00	*80.00 F	BT ✓
25	1		*Boot Weatherstrip	0.00	0.00	*55.00 F	CUT ✓
26	8		*Boot Inner Trim Clip	0	0.00	*40.00 FS	NECV ✓
27	1		*Rear Bumper	0.00	0.00	*950.00 F	DIS ✓
28	10		*Rear Bumper Clip	0	0.00	*50.00 FS	NECV ✓
29	2		*Rear Bumper Side Retainer	0.00	0.00	*114.00 F	NECV ✓
30	1		*Rear Bumper Reinforcement	0.00	0.00	*280.00 F	BT ✓
31	1		*Rear Bumper Inner Panel	0.00	0.00	*33.00 F	NNX ✓
32	1		*Rear Bumper Tow Cover	0.00	0.00	*36.00 F	NNX ✓
33	4		*Rear Bumper Sensor	0.00	0.00	*860.00 F	CUT ✓
34	1		*Rear Bumper Under Cover (Front)	0.00	0.00	*65.00 F	NECV ✓
35	1		*Rear Bumper Under Cover (Middle)	0.00	0.00	*60.00 F	NECV ✓
36	1		*Rear Bumper Under Cover (RH)	0.00	0.00	*65.00 F	NECV ✓
37	16		*Rear Bumper Under Cover Clip	0	0.00	*80.00 FS	NECV ✓
38	1		*Rear Number Plate	0	0.00	*45.00 FS	CUT ✓
39	1		*Rear End Panel	0.00	0.00	*570.00 F	BT ✓
40	16		*Rear End Panel Rivet	0	0.00	*80.00 FS	NECV ✓

Falcon-Air Auto Services Pte Ltd/SKS1486U/16/05/2018 09:35. Not valid without Reference section.

Generated using Merimen e-Claims IEAS