

<< Service Request Details

Claim	S8M00H7Q	Actions	Document Type
Reference		Next Step	Document SubType
CS/ASM18008880/T1sd3s2		PAST DUE: Report that your work is blocked, and modify the Expected Completion Date	
May 14, 2018	Request Date	Complete Work	
May 15, 2018	Due Date	Move	
August 16, 2018	Vendor Name	Upload Documents	
LKK AUTO CONSULTANTS PTE LTD (OD)	Type of Loss		
Own Damage	Services		
Accelerated workshop survey			
Vehicle Information			
Incident Vehicle Registration #	YP2593L	Make	Service Address
MITSUBISHI		Model	Blk 3
FUSO FM65FM2RDEB			Pioneer Road North, . 628457
Primary Contact/Insured			
HOTEL LAUNDRY PTE LTD 80 MARINE PARADE ROAD, #21-01 PARKWAY PARADE, 449269, Singapore 91159333 IRENE@DIINSURANCEAGENCY.COM.SG			
Claim Handler			
TEO Kitty 6568804602 kitty.teo@axa.com.sg			

- Additional Instructions
- EXCESS \$1500
- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes



Service Request Details

Claim	SBM00H7Q		Actions		App
Reference					
CS/ASM16008880/T1sd3s2	Loss Date	PAST DUE: Report that your work is blocked, and modify the Expected Completion Date.			Complete Work
May 14, 2018	Request Date				More
May 15, 2018	Due Date				
August 16, 2018	Vendor Name				
LKK AUTO CONSULTANTS PTE LTD (OD)	Type of Loss				
Own Damage	Services				
Accelerated workshop survey					
Vehicle Information					
Incident Vehicle Registration #		YP2593L		Service Address	
Make					
MITSUBISHI		Model		Bik 3	
FUSO FM65FM2RDEB		Pioneer Road North, . 628457			
Primary Contact/Insured					
HOTEL LAUNDRY PTE LTD 80 MARINE PARADE ROAD, #21-01 PARKWAY PARADE, 449269, Singapore 91159333 IRENE@DIINSURANCEAGENCY.COM.SG					
Claim Handler					
TEO Kitty 6568804602 kitty.teo@axa.com.sg					
Additional Instructions		Messages	Invoices	History	Documents
EXCESS \$1500		Assignment	Metrics	Notes	

<< Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Vehicle & Driver Details

Vehicle Registration#	YP2593L	Purchase Date	mm/dd/yyyy
Registration State	SINGAPORE	Registration Date *	05/16/2016
Mileage	145938	Age of Vehicle	1

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	POST SURVEY INFORMATION
Manufacturing Year	2016		
Make	MITSUBISHI	MITSUBISHI	YANG JUN
Model	FUSO FM65FM2RDEB	FUSO FM65FM2RDEB	mm/dd/yyyy
Type			
Type of Paint			
Chassis No	FM65FMA30088		
Engine No	6M60215185		
Engine Capacity	7545 cc		

Occupation	Unknown
Education Qualification	Other
Driving Experience	5
Driver License #	

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Detailed Assessment

Inspection Date *

06/13/2018

Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

1500

Young/Inexperienced/Unlicensed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good

Tyre Condition

Age of Tyres

Front Tyre Size

11R22.5

Front left side

FIRENZA6mm

Front right side

FIRENZA6mm

Spare wheel

Rear Tyre Size

11R22.5(D)

Rear left side

FIRENZA6mm

Rear right side

FIRENZA6mm

Assessment Details

General & Workshop Details Vehicle & Driver Details

Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts

Add

Approve

Deny

Submit All

EDIT	SIR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC.OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	1	1			FRT BUMPER			Bent	1300				1300	Reviewing	
	2	1			FRT HEADLAMP (RH) ("CHECK \$700.00)				0				0	Reviewing	
	3	1			FRT HEADLAMP BRACKET (RH) ("CHECK \$160.00)				0				0	Reviewing	
	4	1			FRT FOGLAMP (RH) ("CHECK \$800.00)				0				0	Reviewing	
	5	1			FRT CORNER PANEL (RH)			Repair	0				0	Reviewing	
	6	2			FRT STEP GARNISH (RH) (TOP) (1PC ONLY)			Cracked	125				250	Reviewing	
	7	2			FRT WHEEL ARCH (RH) GARNISH (1PC ONLY)			Cracked	375				750	Reviewing	
	8	1			FRT DOOR (RH)			Bent	3200				3200	Reviewing	

<< **Assessment Details**

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

APD

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR	Reviewing		7	
	2	FRT DOOR "BLUE TEC" STICKER (RH)	Reviewing	10	NECESSARY	

SERVICE REQUESTS MESSAGES CLAIMS

<< **Assessment Details**

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Claim Amount \$5,735.00

Claim Amount \$5,735.00

CATEGORY ESTIMATE REVISED AMOUNT

Spare Parts \$5,575.00 \$5,575.00

Labour \$1,650.00 \$1,650.00

Miscellaneous \$10.00 \$10.00

Excess -\$1,500.00 -\$1,500.00

Submit for Review