

2200/2000
 ASS. REC. BY: Guo Geng REF: CS3/SMO18008882/6483 Instruction:
 Surveyor: Grace Teo ASSIGNMENT (Office)
 From (Person): Grace Teo of SMO Date/Time: 16/5/18 @ 9.06am
 Estimated Cost: _____ Bill to: _____
 OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No: DDB 4361 Insured: SKE 8868D
 at Workshop m/s Asia Motorsports Tel: 6745 3811
 of 568 Geylang Road
 Policy No: _____ Claim No: MTD 1801901/HAN
 Sum Insured: _____ Excess: _____
 Make of Veh: _____ D.O.A. 28/04/2018
 (Client's Record) 17/05/18 @ after 10.30am
 CA / REV / REP. / REV 24 HRS (wp) H.O.D. Endorsement: _____
 Date/Time: 9.42am @ 16/5/18 Person Contacted: Ah Siong Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate	
	<u>DDB 4361 - NA/INC 18007936/24</u>	<u>DOA: 28/4/18</u>
	<u>SKE 8868D - CS3/SMO18008338/24b</u>	<u>DOA: 28/4/18</u>
	<u>Dismantle: 25/5/2018</u>	
	<u>After repair: 13/6/2018 (NAZ)</u>	<u>20,000</u>

REF:

No Logrand

Surveyor

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

DOB 4361

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha 135 LC

c.c.

Colour

Red

A/C: Insured / Std / NI / NA

Sp. Reading

291719

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 80/90-17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Maxxis

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

17/5/18

Survey held at

W/S

12pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Estimated repair range \$5,000 - \$6,000 (Bryan)

RECEIVED 17 JUL 2018

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format:

PRS

Lump Sum / I.B.I: (\$

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

TOTAL

100

60+60

220

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Wednesday, 16 May 2018 9:06 AM
To: Asia Motorsports Solution Pte Ltd; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Han, Bernard; Ye, Yong Kang Melvin
Subject: CMTD1801901/HAN - SUV(LKK)/ SKE8868D/ DDB4361 ACC ON 28 APRIL 2018

Our Reference: CMTD1801901/HAN
Your Reference: DDB4361

Without Prejudice

Date: 16th May 2018

Attention:
M/S ASIA MOTORSPORTS SOLUTION PTE LTD

Dear Sir/ Madam,

ACCIDENT INVOLVING SKE8868D & DDB4361 ON 28.04.18

We refer to your email reply dated 15/05/2018.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Dear LKK Auto,

Please make arrangement to conduct the survey for DDB4361.

Please be informed that Mr Bernard Han is the handler of this case.

Best Regards
Grace Teo
Claims Division



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Asia Motorsports Solution Pte Ltd [mailto:asiamotorsports@hotmail.com]

Sent: Tuesday, May 15, 2018 9:12 PM

To: Teo, Grace; Claims - Motor Survey; claimsreport

Cc: Han, Bernard; Ye, Yong Kang Melvin

Subject: Re: ACCIDENT INVOLVING DDB 4361 & SKE 8868 D ON 28 APRIL 2018 - OUR COUNTER-PROPOSED LIST OF MOTOR SURVEYORS AS SINGLE JOINT EXPERT

Your Ref:

Our Ref: DDB 4361

15 May 2018

Sompo Insurance Singapore Pte Ltd
50 Raffles Place
#05-01/06
Singapore Land Tower

Singapore 048623

Attn: Claims Department

Dear Sir/Mdm,

**PROPERTY CLAIM
(WITHOUT PREJUDICE
TO: Any Personal Injury
Claims)**

ACCIDENT INVOLVING DDB 4361 & SKE 8868 D ON 28 APRIL 2018 - OUR COUNTER-PROPOSED LIST OF MOTOR SURVEYORS AS SINGLE JOINT EXPERT

Thank you so much for your reply dated 15 May 2018. However, we regret to inform that we will not be selecting or appointing any motor surveyors from your proposed list.

As required by the new regulations, please find appended below our counter proposed list of motor surveyors for your appointment as Single Joint Expert:

Forensic Consultants Pte Ltd
HJL Auto Appraiser Services
KTO Automobile Assessors
Mc-Coy Appraiser Pte Ltd
YB Lim Appraisal Services
LCW Appraiser Pte Ltd
Treasures Appraisal Services
Pal's Appraiser Pte Ltd
Sincere Appraisal Services
Prudent Adjustors Services

We will appreciate if your kind office can revert by **18 May 2018 (Friday), 1000H** on your selection from the above list, failing which we will appoint a motor surveyor from our list after **18 May 2018 (Friday), 1000H**.

Thank you and we hope to hear from you soonest.

Regards,

Asia Motorsports

6745 3811

6746 5110 (fax)

asiamotorsports@hotmail.com

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Tuesday, May 15, 2018 9:10 AM
To: Asia Motorsports Solution Pte Ltd
Cc: Han, Bernard; Ye, Yong Kang Melvin
Subject: CMTD1801901/HAN - PRI/ SKE8868D/ DDB4361 ACC ON 28 APRIL 2018

Our Reference: CMTD1801901/HAN
Your Reference: DDB4361

Without Prejudice

Date: 15th May 2018

Attention:
M/S ASIA MOTORSPORTS SOLUTION PTE LTD

Dear Sir/ Madam,

ACCIDENT INVOLVING SKE8868D & DDB4361 ON 28.04.18

We refer to your Notice of Accident dated 15/05/2018.

Please be informed that Bernard Han the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg

Sompo Insurance Singapore Pte Ltd

www.sompo.com.sg

Sompo Insurance Singapore Pte Ltd

| **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Asia Motorsports Solution Pte Ltd [mailto:asiamotorsports@hotmail.com]

Sent: Monday, May 14, 2018 9:12 PM

To: Claims - Motor Survey; claimsreport

Subject: NOTICE OF ACCIDENT: ACCIDENT INVOLVING DDB 4361 & SKE 8868 D ON 28 APRIL 2018

Your Ref:

Our Ref: DDB 4361

14 May 2018

Sompo Insurance Singapore Pte Ltd
50 Raffles Place
#05-01/06
Singapore Land Tower
Singapore 048623

Attn: Claims Department

**PROPERTY CLAIM
(WITHOUT PREJUDICE
TO: Any Personal Injury
Claims)**

Dear Sir/Mdm,

NOTICE OF ACCIDENT: ACCIDENT INVOLVING DDB 4361 & SKE 8868 D ON 28 APRIL 2018

We are instructed to notify you of a road traffic accident on **28 April 2018** at about **11.40 pm** at **Pan Island Expressway** involving our client's vehicle registration number **DDB 4361** and vehicle registration number **SKE 8868 D** driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice and your proposed list of 10 recommended motor surveyors for our appointment.

Kindly note that if we do not hear from you by **17 May 2018 (Thursday), 1000H**, we will be forwarding **our proposed list of 10 motor surveyors** for your appointment, in accordance to the new regulations.

Thank you and we hope to hear from you soonest.

Regards,
Asia Motorsports Solution Pte Ltd
6745 3811
6746 5110 (fax)
asiamotorsports@hotmail.com





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT				
SOMPO INSURANCE SINGAPORE PL		Ref: CS3/SMO18008882/Gz4d3e2		
50 RAFFLES PLACE #05-01/06		Date: 16-07-2018		
SINGAPORE LAND TOWERSINGAPORE 048623				
		Code: SMO		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SKE 8868D	Veh. Inspected	DDB 4361	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1801901/HAN	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	16/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA 135LC	c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour	RED	
Odometer	291719 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	80/90-17	MAXXIS	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	80/90-17	MAXXIS	5 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S, O/S BODY AND FRONT PORTION.				
5. General Information				
Accident Date	28/04/2018	Inspect Date / Time	17/05/2018 (12:00 PM)	
Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 568 GEYLANG ROAD SINGAPORE 389514			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		

Report Ref No. CS3/SMO18008882/Gz4d3e2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.