

ASS. REC. BY

REF:

CS/MSG18008897/K/s#031

Initial Instruction:

Surveyor

kalvin

Merimen

From (Person):

Irene Tan

of

MSG

Date/Time:

16/5/18 @ 2:18pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 8983E

Insured:

GW7642Y

at Workshop m/s

Premier Automotive

Tel:

6214 8880

of

23 changi south Ave 2 # 01-02

Policy No:

2883 2451MKC

Claim No:

558443

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/05/2018

CA / REV / REP. / REV 24 HRS 'w/p'

H.O.D. Endorsement:

Date/Time:

2:44pm @ 16/5/18

Person Contacted:

Gary

Vehicle

IN OUT

Date/Time

Action/Instruction

(✓) Estimate

SHB 8983E - CS/AIG11001252/T1bs2

D.O.A: 30/4/2010

GW 7642Y - X

18/05/18

@ 15:14 p.m. Revised IA to Irene Tan Acc Ing via merimen.

(08/11/13)

Q. Insured: Kevin

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / .REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHB 8983E Yr Regn: 30 Apr 12/14Type: M.Car / M.Cycle / Bus / Van / Lorry / T~~o~~ / Prime Mover /

Truck / Trailer or

Make: KIA Optima c.c. 1685...Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 35704 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KNAH44ME54 6264Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size; F: 205/65 R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxx3

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 15/5/18 D.O.I. 16/5/18Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
27/6/18	Home 4/5 \$2700 / 4/5. <span style="float: right;">MSZ</span>
	( \$ 1,962.25 Red - 42% ) <span style="float: right;">4/5.</span>

RECEIVED 27 JUN 2018

Date/Time, File Pass to?

27/6/18

1) Typist

Date/Time, File Return to?

2) \_\_\_\_\_

☐ : Prell. Report☒ : Final ReportDays Of Repair: 4Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)Survey Fee: 150

Transportation: \_\_\_\_\_

S + RS. SI

Photos

Others 10

TOTAL

Report Format: \_\_\_\_\_

Lump Sum / I.B.I. (\$ 2,700.00 4/5)

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 May 2018		16 May 2018 14:18 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	POLINK ENGINEERING PTE LTD, Co. Reg. No.: 200005867H		
Main Claimant:	PREMIER TAXIS PTE LTD, Co. Reg. No.: 200304975H		
Vehicle Reg. No.:	SHB8983E	Date of Loss:	15/05/2018 15:00 - :59 [48 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 558443	Policy/Cover Note No.:	28832451MKC (TP, Fire & Theft) Coverage: 23/10/2017 - 22/10/2018
Vehicle Reg. No. (Insured):	GW7642Y	Policy No. (Claimant):	
		Excess:	
Repairer:	Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02, 486443 Changi - Tel: 62148880		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/05/2018]		
Adj Asg. Remarks:	liability unknown oi non -reporting		

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18008897/K1s3d3

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 16-05-2018



Code : MSG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GW 7642Y	Veh. Inspected	SHB 8983E
Policy No.	28832451MKC	Coverage (\$)	0.00
Claim No.	558443	Excess (\$)	0.00
Assign From	MERIMEN ( IRENE TAN)	Assign Date	16/05/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	15/05/2018	Inspection Date	16/05/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

## 5a. Remarks


A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
----------------------------------------------------------------------------------------------------------------------------------------

# 1 / 10

16-05-18;11:17

**PREMIER TAXIS PTE LTD**

23 CHANGI SOUTH AVE 2 #03-02  
SINGAPORE 486443  
TEL:65446676, 65446689 FAX:62141511



Our Ref: SHB8983E

WITHOUT PREJUDICE

Date: 15 May 2018

Attn: The Motor Claims Department  
MSIG Insurance (Singapore) Pte Ltd  
4, Shenton Way #21-01  
SGX Centre 2  
Singapore 068807

(BY FAX ONLY)

**ACCIDENT INVOLVING SHB8983E & GW7642Y ALONG SLIP ROAD OF CTE  
- PIE/CHANGI ON 15.05.2018**

We are the registered owner of vehicle number of SHB8983E which was involved on the above mentioned accident between GW7642Y.

Investigation reveals that the motor vehicle number GW7642Y was insured with you at the material time of the said accident.

As a result of the accident was caused solely and completely by the negligence of your insured vehicle number GW7642Y. Therefore, we are holding you liable for the repair costs and other consequential loss which was sustained by us.

Kindly arrange your representative to survey our vehicle at 23 CHANGI SOUTH AVE 2 SINGAPORE 486443 within two (2) days from the date hereof as to avoid further LOR/I incur. We enclosed hereby the GIA report of SHB8983E for your kind attention.

Failing which, we have no alternative but to proceed with the necessary repairs and the bill will be forward to you for reimbursement.

Yours Faithfully,



PREMIER TAXIS PTE LTD

\* Dear all,

kindly arrange for  
survey soonest.

vehicle available  
for survey.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 18 May 2018

**Preliminary Advice**

Insured Vehicle No	: GW7642Y	Accident Date	: 15/05/2018
TP Vehicle No	: SHB8983E	Assignment Date	: 16/05/2018
Make	: KIA OPTIMA	Est. Duration of Repair	: 4 days
Date of Inspection	: 16/05/2018		
Inspection At	: Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02 Singapore 486443		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,662.25
Revised Amount	:S\$	2,860.85
Check Items (Estimated)	:S\$	1,245.40
Total	:S\$	4,106.25

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	15/05/2018 16:28
Date Of Accident	15/05/2018 15:40
Exact Location Of Accident	SLIP OF CTE INTO PIE/CHANGI
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB8983E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	PREMIER TAXIS PTE LTD
Co Reg No	200304975H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62148880

### Vehicle Particulars

Manufacturer	KIA
Model	OPTIMA-1.7 D (A)
Exact Purpose for which vehicle was being used at time of accident	HIRED & REWARDS
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5095103893
Cover Note Number	

### Driver

Name of Driver	LEE CHIH WEN
NRIC No	S7677374B
Date Of Birth	24/09/1976
Occupation	OUTDOOR
Date Of Driving Pass	23/10/1999
Driving Experience	18 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97238300
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 122 #09-457 YUAN CHING ROAD
Postcode	610122
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : PAX IN THE REAR SEAT - FOREIGNERS/FILIPINOS GENDER: : FEMALE
Passenger 2	NAME: : PAX IN THE REAR SEAT - FOREIGNERS/FILIPINOS GENDER: : FEMALE
Passenger 3	NAME: : PAX IN THE REAR SEAT - FOREIGNERS/FILIPINOS - CHIL GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

VEH. A - 3 PAX VEH. B - NO PAX

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GW7642Y
Vehicle Make/Model/Colour	LORRY
Details Of Properties	VEH. B
Vehicle Category	GOODS VEHICLE
Name of Driver	MALE INDIAN
NRIC/Passport Number	



Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

DAMAGED ON THE FRONT PORTION

No. Of Passenger (Including Driver)

1

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

15 MAY 2013

57677374B  
SHB8983E

## Sketch Plan Pg. 2

### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A: CHB 8983e

B: GW 7642y

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature \_\_\_\_\_  
Date & Time: \_\_\_\_\_

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Describe Circumstance of the Accident.

ON 15/05/2018 @ 1540 HRS, I WAS DRIVING MY TAXI ( SHB8983E )  
TRAVELLING ALONG THE SLIP ROAD OF CTE INTO PIE/CHANGI AIRPORT WITH 3  
PASSENGER ONBOARD.

I STOPPED MY TAXI AS VEHICLES AHEAD OF ME STOPPED.


WHILE STATIONARY FOR A FEW SECONDS, SUDDENLY I FELT AN IMPACT FROM THE  
REAR.

WHEN INSPECTED, I DISCOVERED THAT VEHICLE B ( GW 7642 Y – LORRY )  
WHICH WAS BEHIND ME – HAD COLLIDED ONTO THE REAR OF MY TAXI.

DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE REAR PORTION AND VEHICLE  
B HAD DAMAGES ON THE FRONT PORTION.

NO INJURY INVOLVED.  
NO PASSENGERS ONBOARD VEHICLE B.

\*VIDEO FOOTAGE CAPTURED.



 576773743 



Driver's Signature & NRIC Number  
Tuesday, May 15, 2018 @ 4:35:38 PM

( attended by  )

Text size + -

**Enquire Transaction History****Transaction History Details**

Log Date/Time:	30 Apr 2014 / 09:50:03	Receipt No.:	AACCK001-AX239-140430-000002
Asset Type:	Vehicle	Transaction Amount:	\$72,769.00
Asset ID:	SHB8983E	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20140430095003535386		
Vehicle No.:	SHB8983E		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	30 Apr 2014		
Original Registration Date:	30 Apr 2014		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414ME5462640		
Engine No.:	D4FDDH308950		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2013		
Open Market Value:	\$20,184.00		
Minimum PARF Benefit:	\$7,654.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	30 Apr 2014 09:50:03		
COE No.:	2014043001001109D		
COE Expiry Date:	29 Apr 2022		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$59,871.00		
Lifespan Expiry Date:	29 Apr 2022		
Owner ID Type:	Company		





**PREMIER AUTOMOTIVE SERVICES PTE LTD****23 Changi South Ave 2****#01-02, Singapore 486443****Assessment Number: MSIG0010****Version: PREMIERA/1****Assessor Report****Printed: 16/05/2018****Summary Information****Claim**

Claim Reference:	SHB8983E	Insured:	
Policy Number:		Third Party:	
Date of Decision:	16/05/2018	Able to Authorise Repairs:	TBA
Repairer:		Repairs Authorised?	TBA
Estimated Repair Time (Working Days):	0.0		

**Insured's Liability**

Excess:	TBA
Customer Contribution:	\$0.00 (excl GST)

**Vehicle Details****Vehicle**

Registration:	SHB8983E	VIN/Chassis Number:	
Manufacturer:	KIA	Model:	Optima
Registration Month:	April	Registration Year:	2014
Odometer:	Not Known	Colour:	
Build Date:			
Model Specs	FROM 01/2014 REAR PARKING SYSTEM 2.0 LTR 121KW PREPARE OFF VEHICLE BASECOAT CLEAR		

**Vehicle Condition****Vehicle Status**

Date of Incident:	15/05/2018	Market Value:	Unknown
Pre-Accident Condition:		Salvage Value:	Unknown
Pre-Accident Damage:		Date of Inspection:	16/05/2018
Steering Rim Ply:		Place of Inspection:	
Brake Pedal Travel:			
Vehicle Status:			
Damage Severity:			

**Tyres Condition:**

Tread Depth LHF:  
Tread Depth LHR:

Tread Depth RHF:  
Tread Depth RHR:

**Repair Information****LABOUR**

**Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR**  
**Price/Dent = \$50.00/HR**

**Repair /****Guide Number Repair Details**

		<b>WU</b>	<b>Cost Price (\$)</b>
86520R00	RENEW REAR BUMPER (REMOVED)	<b>11.0</b>	<b>55.00</b>
86630R00)	R + R REAR BUMPER CARRIER	<b>4.0</b>	<b>20.00</b>
69200R00	RENEW BOOTLID	<b>15.0</b>	<b>75.00</b>
	INCLUDES: BOOTLID, BOTH INN REARLAMP AND REQUIRED ATTACHED PARTS REMOVE AND REFIT		



51 Ubi Avenue 1, #01-25  
Paya Ubi Industrial Park  
Singapore  
408933

Claim Reference: SHB8983E  
Assessment Number: MSIG0010  
Version: LKKAUTOC/3

Full Report - V1  
Registration: SHB8983E  
Printed: 25/06/2018 09:59

## Summary Information

### Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	15/05/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:	SHB8983E	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

### Vehicle Details

#### Vehicle

Manufacturer:	KIA
Model:	Optima
Sub Model:	BASE MODEL
Model Sheet Number:	2836 01
Registration:	SHB8983E
Registration Month:	April
Registration Year:	2014
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

#### Model Specs

FROM 01/2014	REAR PARKING SYSTEM
2.0 LTR 121KW	PREPARE OFF VEHICLE
BASECOAT CLEAR	

### Vehicle Condition

#### Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	16/05/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		

**PREMIER AUTOMOTIVE SERVICES PTE LTD**

**23 Changi South Ave 2  
#01-02, Singapore 486443**

**Assessment Number: MSIG0010**

**Version: PREMIERA/1**

**Assessor Report**

**Printed: 16/05/2018**

28700R00	R + R REAR MUFFLER	4.0	20.00	*
3486	REPAIR R/R OUTER SIDE PANEL	20.0*	100.00	
<b>LABOUR COST</b>				
	<b>Total Work Units</b>	<b>54.0</b>		
	<b>Corrosion Protection External Labour</b>	<b>0.0HRS</b>	<b>0.00</b>	
	<b>Corrosion Protection Internal Labour</b>	<b>0.0HRS</b>	<b>0.00</b>	
	<b>Sub Total</b>	<b>5.4HRS</b>	<b>\$270.00</b>	
	<b>Paint Labour</b>	<b>8.4HRS</b>	<b>\$420.00</b>	
	<b>Total Labour</b>	<b>13.8HRS</b>	<b>\$690.00</b>	

<b>PAINT WORK</b>		<b>Time Basis 10 WU = 1 HR. Price = \$50.00/HR</b>		
<b>Guide Number</b>	<b>Description</b>	<b>WU</b>	<b>Cost Price (\$)</b>	
	- PREPARE OFF VEHICLE			
	- BASECOAT CLEAR			
2931	BOOTLID NEW PART PAINTING	19.0		
2583	REAR BUMPER NEW PART PAINT K1R	14.0		
2935	BOOTLID OUT PANEL NEW PART PAINT K1R	5.0		
3486	R/R OUTER SIDE PANEL REPAIR PAINTING <50%	16.0		
<b>LABOUR COST - PAINT</b>				
	<b>TIME(PAINT)</b>	<b>54.0</b>		
	<b>Preparation Main Work Plastic</b>	<b>5.0</b>		
	<b>Preparation Main Work Metal</b>	<b>25.0</b>		
	<b>Preparation Work Multi Layer Paint</b>	<b>0.0</b>		
	<b>Total Work Units (10WU/HR)</b>	<b>84.0</b>		
	<b>Total Paintwork Labour</b>	<b>8.4HRS</b>	<b>\$420.00</b>	
<b>MATERIAL COST - PAINT</b>				
			<b>Cost Price</b>	
	<b>New Part Painting</b>		<b>\$55.73</b>	
	<b>New Part Painting - Plastic K1R</b>		<b>\$85.12</b>	
	<b>Material-Constant Main Work Metal</b>		<b>\$28.60</b>	
	<b>Repair Painting</b>		<b>\$26.16</b>	
	<b>Material-Const Main Work Plastic</b>		<b>\$9.00</b>	
	<b>Total Excluding Pearlescent Uplift</b>		<b>\$204.61</b>	
	<b>Pearlescent Uplift @ 0.0%</b>		<b>\$0.00</b>	
	<b>Total Paint Material Cost</b>		<b>\$204.61</b>	

**PARTS**

				Price Valid: 01/06/2015		
<b>Guide No.</b>	<b>Qty</b>	<b>Description</b>	<b>Part Number</b>	<b>Supplier</b>	<b>Bet.</b>	<b>Price (\$)</b>
2931	1	BOOTLID	692002T510	✓ <i>Part</i>	0%	1,119.00*
2935	1	BOOTLID OUT PANEL	873702T600	X <i>mpa</i>	0%	290.00*
2617	1	L/R BUMPER BRACKET	866132T501	X <i>sc</i>	0%	29.00*
2641	1	L/R C-MEMBER BRACKET	866412T500	✓ <i>Part</i>	0%	56.00*
2618	1	R/R BUMPER BRACKET	866142T501	X <i>sc</i>	0%	29.00*
2642	1	R/R C-MEMBER BRACKET	866422T500	✓ <i>Part</i>	0%	56.00*
3290	1	R/R INNER LAMP	924132T520	X <i>sc</i>	0%	350.00*
3288	1	R/R OUTER LAMP	924122T510	✓ <i>sc</i>	0%	421.00*
3015	1	REAR BADGE	863202T500	✓ <i>sc</i>	0%	47.60U
2583	1	REAR BUMPER	866112T510	✓ <i>Part</i>	0%	696.00*
2644	1	REAR BUMPER DAMPER	866202T500	✓ <i>sc</i>	0%	116.00*
2770	1	REAR BUMPER SPOILER	866122T500	✓ <i>sc</i>	0%	206.00*

**PREMIER AUTOMOTIVE SERVICES PTE LTD**

23 Changi South Ave 2

#01-02, Singapore 486443

Assessment Number: MSIG0010

Version: PREMIERA/1

Assessor Report

Printed: 16/05/2018

2640	1	REAR BUMPER SUPPORT	866312T500	✓	0%	607.00*
8839	1	REAR MOUNTING	287853K100	X	0%	14.00*
8833	1	RR EXHAUST SILENCER	287102T110	X	0%	1,009.00*
f: OEM Parts						Sub Total
g: Original						\$5,045.60
h: Secondhand						Deduction from RRP (35 %)
p: Parallel						-\$1,765.96
x: Exchange						<b>Total Parts</b>
						<b>\$3,279.64</b>

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

**Extras**

Description	Betterment	Price
REVERSE SENSOR SPECIALIST	0%	\$280.00
REAR BUMPER CLIPS SPECIALIST		\$48.00
BOOTLID STICKERS SPECIALIST	0%	\$100.00
REAR FENDER STICKER SPECIALIST		\$60.00
<b>Total Extras</b>		<b>\$488.00</b>

**Final Calculation**

<b>Total Parts</b>	<b>\$3,279.64</b>
<b>Labour</b>	
Total Panel/Mechanical	\$270.00
Total Paintwork	\$420.00
<b>Total Labour</b>	<b>\$690.00</b>
<b>Additional Costs</b>	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$488.00
<b>Total of Additional Costs</b>	<b>\$488.00</b>
<b>Total Paint/Material Costs</b>	<b>\$204.61</b>
<b>Grand Total Excludes GST</b>	<b>\$4,662.25</b>
GST @ 7 %	\$326.36
<b>Grand Total Includes GST</b>	<b>\$4,988.61</b>

**Assessment Notes**

Kalin CLKK  
 16/5/18 160hrs  
 4 Days  
 4/5  
 After Repair photo



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Addresses****Cost Summary**

Total Labour	\$690.00
Total Paint/Material	\$204.61
Total Parts	\$2,160.99
Total of Additional Costs	\$348.00
Excess:	TBA
Grand Total Exc GST:	\$3,403.60
7 % GST:	\$238.25
Grand Total Inc GST:	\$3,641.85

**Repair Information****LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR

Price/Dent = \$50.00/HR

**Repair /****Guide Number Repair Details**

		WU	Cost Price (\$)
86520R00	RENEW REAR BUMPER (REMOVED)	11.0	55.00
86630R00)	R + R REAR BUMPER CARRIER	4.0	20.00
69200R00	RENEW BOOTLID	15.0	75.00
	INCLUDES: BOOTLID, BOTH		
	INN REARLAMP AND REQUIRED ATTACHED		
	PARTS		
	REMOVE AND REFIT		
1000	REMOVE&REFIT R+R REAR MUFFLER	4.0*	20.00
3486	REPAIR R/R OUTER SIDE PANEL	20.0*	100.00

**LABOUR COST****Total Work Units**

54.0

**Sub Total**

5.4HRS

\$270.00

**Paint Labour**

8.4HRS

420.00

**Total Labour**

13.8HRS

\$690.00

**PAINT WORK**

Time Basis 10 WU = 1 HR. Price = \$50.00/HR

**Guide Number Description**

		WU	Cost Price (\$)
	- PREPARE OFF VEHICLE		
	- BASECOAT CLEAR		
2931	BOOTLID NEW PART PAINTING	19.0	
2583	REAR BUMPER NEW PART PAINT K1R	14.0	
2935	BOOTLID OUT PANEL NEW PART PAINT K1R	5.0	
3486	R/R OUTER SIDE PANELREPAIR PAINTING <50%	16.0	

**LABOUR COST - PAINT****TIME(PAINT)**

54.0

**Preparation Main Work Plastic**

5.0

**Preparation Main Work Metal**

25.0

**Preparation Work Multi Layer Paint**

0.0

Total Work Units (10WU/HR)	84.0	
Total Paintwork Labour	8.4HRS	\$420.00
<b>MATERIAL COST - PAINT</b>		<b>Cost Price</b>
New Part Painting		\$55.73
New Part Painting - Plastic K1R		\$85.12
Material-Constant Main Work Metal		\$28.60
Repair Painting		\$26.16
Material-Const Main Work Plastic		\$9.00
Total Excluding Pearlescent Uplift		\$204.61
Pearlescent Uplift @ 0.0%		\$0.00
<b>Total Paint Material Cost</b>		<b>\$204.61</b>

**PARTS**

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
2931	1	BOOTLID	692002T510	Ad	0%	1,119.00*
2641	1	L/R C-MEMBER BRACKET	866412T500	ca	0%	56.00*
2642	1	R/R C-MEMBER BRACKET	866422T500	ca	0%	56.00*
3288	1	R/R OUTER LAMP	924122T510	ca	0%	421.00*
3015	1	REAR BADGE	863202T500	ca	0%	47.60U
2583	1	REAR BUMPER	866112T510	Ad	0%	696.00*
2644	1	REAR BUMPER DAMPER	866202T500	tm	0%	116.00*
2770	1	REAR BUMPER SPOILER	866122T500	ca	0%	206.00*
2640	1	REAR BUMPER SUPPORT	866312T500	ca	0%	607.00*
f: OEM Parts			Sub Total			\$3,324.60
g: Original			Deduction from RRP (35 %)			-\$1,163.61
h: Secondhand			<b>Total Parts</b>			<b>\$2,160.99</b>
p: Parallel						
x: Exchange						

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

**Extras**

Description	Betterment	Price
REAR BUMPER CLIPS SPECIALIST	0% ne	\$48.00
BOOTLID STICKERS SPECIALIST	0% ne	\$100.00
REVERSE SENSOR SPECIALIST	0% ne	\$200.00
<b>Total Extras</b>		<b>\$348.00</b>

**Final Calculation**

<b>Total Parts</b>	<b>\$2,160.99</b>
<b>Labour</b>	
Total Panel/Mechanical	\$270.00
Total Paintwork	\$420.00
<b>Total Labour</b>	<b>\$690.00</b>
<b>Additional Costs</b>	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$348.00
<b>Total of Additional Costs</b>	<b>\$348.00</b>
<b>Total Paint/Material Costs</b>	<b>\$204.61</b>
<b>Grand Total Excludes GST</b>	<b>\$3,403.60</b>
GST @ 7 %	\$238.25
<b>Grand Total Includes GST</b>	<b>\$3,641.85</b>

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference: SHB8983E

Full Report - V1

Assessment Number: MSIG0010

Registration: SHB8983E

Version: LKKAUTOC/3

Printed: 25/06/2018 09:59

## **Assessment Notes**

---

































### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed
Main	15 May 2018		16 May 2018 14:18 <a href="#">Edit Adj Rpt</a>	<b>S\$2,700.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,700.00</b> <a href="#">View Rpt</a>	
						<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>POLINK ENGINEERING PTE LTD</b> , Co. Reg. No.: 200005867H								
Main Claimant:	<b>PREMIER TAXIS PTE LTD</b> , Co. Reg. No.: 200304975H								
Vehicle Reg. No.:	<b>SHB8983E</b>	Date of Loss:	15/05/2018 15:00 - :59 [48 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 558443</b>	Policy/Cover Note No.:	28832451MKC (TP, Fire & Theft) Coverage: 23/10/2017 - 22/10/2018						
Vehicle Reg. No. (Insured):	<b>GW7642Y</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Premier Automotive Services Pte Ltd (HQ)</b> 23 Changi South Ave 2, #01-02, 486443 Changi - Tel: 62148880								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Irene Tan Gek Ing</b> - 6594 2541]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KALVIN ANG WEI KUN</b> ] ... [Final Rpt due 15/06/2018]								
Adj Asg. Remarks:	liability unknown oi non -reporting								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SHB8983E (558443)  
[GW7642Y]  
TP  
PREMIER TAXIS PTE LTD  
May 15 2018 3:00PM  
[POLINK ENGINEERING PTE LTD]  
Premier Automotive Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Letters/Correspondences									1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail		Print	
1	16/05/18 13:28	Non Reporting Letter to OI							 Load HTM			
Assessment Reports									1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print	
1	18/05/18 15:14	Adjuster Immediate Advice							 Load HTM			
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print	
1	17/05/18 08:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
2	17/05/18 08:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
3	17/05/18 08:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
4	17/05/18 08:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
5	17/05/18 08:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
6	17/05/18 08:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
7	17/05/18 08:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
8	17/05/18 08:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
9	17/05/18 08:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
10	17/05/18 08:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
11	17/05/18 08:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
12	17/05/18 08:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
13	17/05/18 08:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
14	17/05/18 08:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
15	17/05/18 08:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
16	17/05/18 08:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
17	17/05/18 08:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
18	17/05/18 08:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
19	17/05/18 08:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
20	17/05/18 08:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
21	17/05/18 08:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
22	17/05/18 08:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
23	17/05/18 08:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
24	17/05/18 08:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
25	17/05/18 08:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
26	17/05/18 08:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
27	25/06/18 08:40	Reinspection Photo							 Load JPG		<input checked="" type="checkbox"/>	
28	25/06/18 08:40	Reinspection Photo							 Load JPG		<input checked="" type="checkbox"/>	
29	25/06/18 08:40	Reinspection Photo							 Load JPG		<input checked="" type="checkbox"/>	
30	25/06/18 08:40	Reinspection Photo							 Load JPG		<input checked="" type="checkbox"/>	



Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
31	25/06/18 08:40	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
32	25/06/18 08:40	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
33	25/06/18 08:40	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
34	25/06/18 08:40	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
35	25/06/18 08:40	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
36	25/06/18 08:40	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
37	25/06/18 08:40	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
38	25/06/18 08:40	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
39	25/06/18 08:40	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
40	25/06/18 08:40	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	16/05/18 13:25	PRI - SHB8983E.pdf		Load PDF	
2	16/05/18 13:25	TPD SHB8983E GIA REPORT.pdf		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/06/18 09:55	AUTODAX		Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18008897/K1SD3E2

Date: 04/07/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28832451MKC

Claimant Vehicle No : SHB8983E

Insured Vehicle No : GW7642Y

Date of Loss: 15/05/2018

Nature of Claim: TP

Claim No: 558443

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SHB8983E

Make &amp; Model: KIA OPTIMA, 1.7 D (A)

Engine No: D4FDDH308950

Reg. Date: 30/04/2014 (Man. Year: 2013)

Chassis No: KNAGM414ME5462640

Colour: Silver

Odometer: 357040 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/65 R16

Rear Tyre Size: 205/65 R16

Front Left Side: Maxxis 7 mm

Rear Left Side: Maxxis 7 mm

Front Right Side: Maxxis 7 mm

Rear Right Side: Maxxis 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,767.64	2,508.99	1,258.65	33.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	894.61	894.61	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,662.25</b>	<b>3,403.60</b>	<b>1,258.65</b>	<b>27.00</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,700.00</b>		
(S\$)	4,662.25	2,700.00	1,962.25	42.09
+ GST 7.00/7.00% (S\$)	326.36	189.00	137.36	42.09
<b>Nett Amount (S\$)</b>	<b>4,988.61</b>	<b>2,889.00</b>	<b>2,099.61</b>	<b>42.09</b>

## INSPECTION

Date of Assignment: 16/05/2018

Date Inspected: 16/05/2018 Inspected At:

Premier Automotive Services Pte Ltd (HQ)  
23 Changi South Ave 2, #01-02  
Singapore 486443

Estimated Period of Repair: 4.0 days

**Adjuster:** KALVIN ANG WEI KUN

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 04 Jul 2018)
<b>Parts:</b> 143	KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SHB8983E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	1,119.00 FL	*1,119.00 FL
2	1		*BOOTLID OUT PANEL	Repair	290.00 FL	*- FL
3	1		*L/R BUMPER BRACKET	Serviceable	29.00 FL	*- FL
4	1		*R/R BUMPER BRACKET	Serviceable	29.00 FL	*- FL
5	1		*R/R C-MEMBER BRACKET	Bent	56.00 FL	*56.00 FL
6	1		*R/R INNER LAMP	Serviceable	350.00 FL	*- FL
7	1		*R/R OUTER LAMP	Cracked	421.00 FL	*421.00 FL
8	1		*REAR BADGE	Necessary	47.60 FL	*47.60 FL
9	1		*REAR BUMPER	Deformed	696.00 FL	*696.00 FL
10	1		*REAR BUMPER DAMPER	Cracked	116.00 FL	*116.00 FL
11	1		*RERA BUMPER SPOILER	Cracked	206.00 FL	*206.00 FL
12	1		*REAR BUMPER SUPPORT	Cracked	607.00 FL	*607.00 FL
13	1		*REAR MOUNTING	Serviceable	14.00 FL	*- FL
14	1		*RR EXHAUST SILENCER	Serviceable	1,009.00 FL	*- FL
15	1		*REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
16	1		*REAR BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
17	1		*BOOTLID STICKERS	Necessary	100.00 FS	*100.00 FS
18	1		*REAR FENDER STICKER	Not Necessary	60.00 FS	*- FS
19	1		*L/R C-MEMBER BRACKET	Bent	56.00 FL	*56.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>5,533.60</b>	<b>3,672.60</b>
<b>- List Item Discount on L Items 35.00/35.00% (S\$)</b>	<b>1,765.96</b>	<b>1,163.61</b>
<b>Total Parts (S\$)</b>	<b>3,767.64</b>	<b>2,508.99</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOTAL PANEL / MECHANICAL	New	270.00	270.00
2	TOTAL PAINTWORK	New	420.00	420.00
3	TOTAL PAINT / MATERIAL COSTS	New	204.61	204.61
Gross Labour Cost (S\$)			<b>894.61</b>	<b>894.61</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >