



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKC2538G

Mr Lim Thiam Wee, Thomas

Blk 8 Boon Keng Road
#39-150
Singapore 330008

Mobile: 94555651

Vehicle & Document Information

WIP No **23664**
Reg No/Reg Date **SKC2538G / 03/08/2011**
Date In/Mileage **/ 0**
Chassis No **WDD2040452A578470**
Engine No **27191031346023**
Make/Model **MB/C 180K (BlueEFFICIENCY) S**
Colour/Trim **026 650 Calcit Whit/ 042 221 Leather BI**

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	15/05/2018/ 17:48	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST				
Customer Request				
A BPILAB				960 1920.00
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				
A BPIRES				600 960.00
RESPRAY REAR BUMPER				
A BPILAB			0.10	✓ 380.00
USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT				
A BPILAB				✓ 120.00
CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT				
M REAR BUMPER	1.00	1361.96	00.00	de 1361.96
M CTR/ REAR BUMPER CHROME MOULDING	1.00	186.40	00.00	re 186.40
M LH/ REAR BUMPER CHROME MOULDING	1.00	132.56	00.00	re 132.56
M RH/ REAR BUMPER CHROME MOULDING	1.00	132.56	00.00	re 132.56
M LH/ REAR BUMPER SIDE STABILITY	1.00	36.21	00.00	? 36.21
M RH/ REAR BUMPER SIDE STABILITY	1.00	36.21	00.00	? 36.21
M COVER, REAR-END FLOOR	1.00	45.62	00.00	? 45.62
M CTR/ REAR BUMPER REINFORCEMENT	1.00	135.13	00.00	? 135.13
M REAR CROSS MEMBER	1.00	670.31	00.00	? 670.31

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:
Confirmed & accepted by
Date:

Kerlyn Ong Kai Li
DID : 6771 4420 HP : 9186 5113
Email : kerlyn.ong@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Tham 97495749
WIP
5/6/18 21:30
03 days
sur@lkkauto.com
** Resurvey before part*

Nett **6,116.96**
7% GST on **6116.96** **428.19**
Total Payable 6,545.15

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg