

Shenhi

cc 4, III 1800 8909, Sna3 sr

Surveyor:

ywk

DOI:

ASSIGNMENT

15/5/18

Date / Time:

15/5/18

Registered in Merimen:

- 25/5/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHD 422M

Name of Insured:

COTPL

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

13/5/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

M. Narayan s/o Harikrishna

Driver Tel No.:

84987101

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHB 5599 B



INSRS:

WSP:

Tel:

Liability:

RMKS:

smpt, w



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

RECEIVED 16 JUL 2018

RECEIVED 16 AUG 2018

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. : 21

Repair Cost:

S\$

10188.95

Loss of Rental (LOR):

S\$

1251.90

(

10 days)

x 125.19

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

11440.85

Global Sum S\$:

11440.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

11440.00

Name 1:

SMART TAXIS PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

16/8/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

6600.00

REF:

8909 / 2013

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 8 days Res: Yes or NoLum Sum: P/P % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 314 B 5577B Yr Regn: 3/11/17Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Prime Mover /

Truck / Trailer or _____

Make: Toyota Prins 4 a.c. 1798Colour: Maroon A/C: Insured / Std / NI / NASp. Reading: 7045 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDK133F4 3055 74007Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Ni / S/Rim / STD A/Rim orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 12/5/18Survey held at SMINTDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

TAX/65/18/2061

\$ 10188.95 (Red. \$ 18352.19/64%) Tick

Li

SHD4212M.

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee: _____

Transportation: _____

) \$ + RS. SI

) Photos

) Others

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III18008909/Sua3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 16-05-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4212M	Veh. Inspected	SHB 5599B	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	16/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/05/2018	Inspection Date	15/05/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705


FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates**Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre**

Reg. No : SHB5599B
Ref. No : TAX/05/18/2061
Reg. Date : 03/11/2017
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS4
Name of Driver : GOH CHYE SENG
Type of Accident : HEAD TO REAR
Date / Time of Accident : 13/05/2018 11:50:00 PM
Accident Reported Date / Time : 14/05/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : Sebastian
Vehicle is Towed Back? : Yes
Towed Back Date/Time : 14/05/2018
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024096057
Special Instruction to ARC, if any :
TOWED \$40 / SHD4212M - III
BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL
SURVEYOR SEBASTIAN (LKK) & Email : sebastianyeang @lkkauto.com HP:90036121
Prepared Date : 14/05/2018 02:22:42 PM

Recording Camera ☐Radio Antenna ☐

1st witness

Date

2nd witness

Date

69045 km

1-1-1-1

QC 23/5/18 14:58 pass

Supplementary
* Refer to the Supplementary part 11/12

LEE SHENG AUTO PTE LTD

69104

Vehicle Return Date: 23-5-18

Vehicle Return Time: 14:05

SMRT staff sign: _____

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU303574007

Mileage


0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	1,859.00	1,200.00
Total Spray Painting Charges	3,294.00	850.00
Total Material Charges	11,900.76	6,923.95
Other Charges	2,335.00	1,215.00
TOTAL	19,388.76	10,188.95
Lump Sum Total	0.00	0.00
No. of Repair Days	11.00	8.00
Prepared / Adjusted By		SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	14/05/2018 06:15:02 PM	15/05/2018 04:13:26 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 14/05/2018 06:14:15 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1805-0608

Invoice No :

Quotation Date : 25/5

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 5/14/2018 6:14:25 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,859.00	1,200.00 /
Total Labour	1,859.00	1,200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00 /
TO RESPRAY FILLER RR BUMPER LH	180.00	50.00 /
TO RESPRAY FILLER RR BUMPER RH	180.00	50.00 /
TO RESPRAY TAIL GATE	378.00	200.00 /
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100.00 /
TO RESPRAY REAR SPOILER	180.00	0.00
TO RESPRAY RH RAIL ROOF SIDE	180.00	0.00
TO RESPRAY LH RAIL ROOF SIDE	180.00	0.00
TO RESPRAY REAR PANEL	180.00	100.00 /
TO RESPRAY REAR SPARE TYRE PANEL	180.00	100.00 /
TO RESPRAY REAR MEMBER,LH	180.00	0.00
TO RESPRAY REAR MEMBER,RH	180.00	0.00
TO RESPRAY TROUGH BACK DOOR LH	180.00	50.00 /
TO RESPRAY REAR FENDER LH	378.00	0.00
TO RESPRAY RIM	180.00	0.00
Total Spray Painting & Panel Beating	3,294.00	850.00 /

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

5153

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	40.00 /
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30.00 /
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	50.00 /
TO CHECK & RESET SYSTEM FUNCTION	350.00	250.00 /
TO REMOVE & REFIT EXHAUST	120.00	60.00 /
TO ALIGN CHASSIS	350.00	200.00 /
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00 <i>2N1 hel</i>	125.00 /
TO TRANSFER REAR TAILGATE MECHANISM	120.00	80.00 /
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	120.00 /
TO REMOVE AND REFIT WIRE HARDESS	250.00	150.00 /
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00 /
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	50.00 /
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30.00 /
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	2,335.00	1,215.00 /

2335

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached	
5215947913			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace	No	CRK
5216116010			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace	No	NEC
5246247030			PAD, RR BUMPER, RH & LH, 1	2	3.80	25.00	5.70	Replace	Check	No	X
5246247020			PAD, RR BUMPER, RH & LH, 2	2	3.80	25.00	5.70	Replace	Check	No	X
5246247010			PAD, RR BUMPER, RH & LH, 3	2	3.80	25.00	5.70	Replace	Check	No	X
5219147030			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Check	No	X
5259247040			SEAL, RR BUMPER, LH	1	85.20	25.00	63.90	Replace	Check	No	X
5256647900			FILLER, RR BUMPER, LH	1	119.90	25.00	89.92	Replace	Replace	No	
5256547900			FILLER, RR BUMPER, RH	1	119.90	25.00	89.92	Replace	Replace	No	
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No	
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No	
5257647040			RETAINER, RR BUMPER, LH	1	111.50	25.00	83.63	Replace	Check	No	X
5257547040			RETAINER, RR BUMPER, RH	1	112.70	25.00	84.53	Replace	Check	No	X
5259968030			STOPPER, RR BUMPER, RH & LH	2	4.30	25.00	6.45	Replace	Replace	No	
9018906029			REAR BUMPER GROMMET SCREW	2	2.20	25.00	3.30	Replace	Replace	No	
5202347030			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace	No	
5245347010			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace	No	
5216947020			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace	No	
5246147010			PAD, RR BUMPER, CTR	3	2.20	25.00	4.95	Replace	Check	No	X
9046717026A0			CLIP, FLOOR UNDER COVER, NO.1	10	2.60	25.00	19.50	Replace	Replace	No	
9046717027C0			CLIP, FLOOR UNDER COVER, NO.2	10	3.20	25.00	24.00	Replace	Replace	No	
5839947030			COVER, REAR FLOOR UNDER, LH	1	234.30	25.00	175.72	Replace	Replace	No	
5839847050			COVER, REAR FLOOR UNDER, RH	1	169.50	25.00	127.12	Replace	Replace	No	
6625947010			COVER, REAR FLOOR UNDER CENTER	1	222.60	25.00	166.95	Replace	Replace	No	
5832747040			EXHAUST HEAT SHIELD INSULATOR, MAIN MUFFLER REAR	0	137.00	25.00	0.00	Replace	Not given	No	X
1743037730			PIPE ASSY, EXHAUST, TAIL	0	1,173.90	25.00	0.00	Replace	Not given	No	X
1756522040			SUPPORT, EXHAUST PIPE NO.5	0	41.10	25.00	0.00	Replace	Not given	No	X
8159147010			LENS & BODY ASSY, RR BUMPER, LH	1	486.80	10.00	438.12	Replace	Replace	No	
8999730100			ANTENNA, ELECTRICAL KEY	1	60.30	10.00	54.27	Replace	Replace	No	

4822.90

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
8218347020			WIRE, LUGGAGE ROOM	1	143.50	10.00	129.15	Replace	Check	No X NN
6700547440			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	25.00	697.20	Replace	Replace	No / Defom NN
6947847010			TAIL GATE CUSHION, BACK DOOR, RH & LH	2	8.20 16.40	25.00	12.30	Replace	Check	No X NN
5611750140			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	1	27.90	25.00	20.92	Replace	Replace	No /
7557147010			TAIL GATE MOULDING GLASS, BACK DOOR	1	29.70	25.00	22.27	Replace	Replace	No /
6480147031			TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR	1	725.90	25.00	544.42	Replace	Replace	No / NEC
689600W860			TAIL GATE STAY ASSY, BACK DOOR, LH	1	235.00	25.00	176.25	Replace	Check	No X
689500W860			TAIL GATE STAY ASSY, BACK DOOR, RH	1	235.00	25.00	176.25	Replace	Check	No X NN
6935047050			TAIL GATE LOCK ASSY, BACK DOOR	1	452.10	10.00	406.89	Replace	Replace	No / Jm
6932147010			TAIL GATE LOCK COVER, BACK DOOR	0	25.30	25.00	0.00	Replace	Not given	No X NN
7680147110A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	25.00	668.40	Replace	Replace	No / CRK
7540348010			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.72	Replace	Replace	No /
7544147090			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No /
7544247130			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No / NEC
	REAR		NUMBER PLATE	1	30.00	0.00	30.00	Replace	Replace	No / SCR
			NUMBER PLATE FRAME	1	25.00	0.00	25.00	Replace	Replace	No / SCR
8127033110			LAMP ASSY, LICENSE PLATE	2	63.70 127.40	10.00	114.66	Replace	Check	No X
8678047010			CAMERA REAR ASSY, TELEVISION	1	1,103.80	10.00	993.42	Replace	Check	No X NN
8484047040			SWITCH ASSY, BACK DOOR OPENER	1	149.40	10.00	134.46	Replace	Check	No X
	COMMO N		SEALANT W/SCREEN	3	37.00 111	0.00	111.00	Replace	Replace	No / NEC
6943052050			TAIL GATE STRIKER ASSY, BACK DOOR	1	24.90	25.00	18.68	Replace	Check	No X
7481147020C0			TAILGATE BOARD, HANDLE PULL	1	19.50	25.00	14.63	Replace	Check	No X NN
6775047080C0			TAILGATE BOARD ASSY	1	251.50	25.00	188.63	Replace	Check	No X
6793847060C0			TAILGATE TRIM, LH	1	92.10	25.00	69.07	Replace	Replace	No / Jm
6775147110C0			TAILGATE TRIM, LOWER	1	218.50	25.00	163.88	Replace	Check	No X
6793747060C0			TAILGATE TRIM, RH	1	92.10	25.00	69.08	Replace	Check	No X NN

6107.70

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
64790470 60C0			TAILGATE TRIM , UPPER	1	50.50	25.00	37.88	Replace	Check	No ☒
82184474 90			WIRE, TAIL GATE BACK DOOR,	1	246.80	10.00	222.12	Replace	Check	No ☒
82185471 50			WIRE, TAIL GATE BACK DOOR , NO.2	1	246.80	10.00	222.12	Replace	Check	No ☒
76085479 16			SPOILER SUB-ASSY, REAR	0	1,322.10	25.00	0.00	Replace	Not given	No ☒
81006470 30			LAMP SET, STOP CENTER	0	186.50	10.00	0.00	Replace	Not given	No ☒
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No ☒
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No ☒
58307470 90			END PANEL SUB- ASSY, BODY LOWER BACK	1	629.80	25.00	472.35	Replace	Replace	No ☒
64718470 80C0			END PANEL , COVER, DECK TRIM SERVICE HOLE	1	47.00	25.00	35.25	Replace	Check	No ☒
64716471 30C0			END PANEL , COVER, DECK TRIM, REAR	1	122.80	25.00	92.10	Replace	Replace	No ☒
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No ☒
58311471 30			SPARE TYRE PANEL , PAN, REAR FLOOR	1	564.80	25.00	423.60	Replace	Replace	No ☒
58350470 10			REINFORCEMENT ASSY, REAR FLOOR END PANEL , RH & LH	2	56.70 113.40	25.00	85.05	Replace	Check	No ☒
57603470 60			MEMBER SUB-ASSY, REAR FLOOR SIDE , REAR RH	1	268.60	25.00	201.45	Replace	Check	No ☒
57604470 60			MEMBER SUB-ASSY, REAR FLOOR SIDE , REAR LH	1	268.60	25.00	201.45	Replace	Check	No ☒
67881470 50			TAIL GATE WEATHERSTRIP, BACK DOOR	0	360.70	25.00	0.00	Replace	Not given	No ☒
51931470 30			CARRIER, SPARE WHEEL	1	20.00	25.00	15.00	Replace	Replace	No ☒
64997470 60			BOX, DECK FLOOR, LH	1	303.40	25.00	227.55	Replace	Check	No ☒
64995470 50			BOX, DECK FLOOR, RH	1	304.00	25.00	228.00	Replace	Check	No ☒
58415471 10C2			BOARD, REAR FLOOR, NO.1	1	502.20	25.00	376.65	Replace	Check	No ☒
64740471 90C2			PANEL ASSY, DECK TRIM SIDE, LH	1	344.70	25.00	258.52	Replace	Replace	No ☒
64730472 40C2			PANEL ASSY, DECK TRIM SIDE, RH	1	344.70	25.00	258.53	Replace	Check	No ☒
61018470 10			MEMBER SUB-ASSY, RAIL ROOT SIDE REAR LH	1	279.20	25.00	209.40	Replace	Check	No ☒
61017470 10			MEMBER SUB-ASSY, RAIL ROOT SIDE REAR RH	1	279.20	25.00	209.40	Replace	Check	No ☒
81561471 51			LENS & BODY, REAR COMBINATION LAMP LH	1	438.10	10.00	394.29	Replace	Replace	No ☒
61622470 60			TROUGH, BACK DOOR , LH	1	99.80	100.00	0.00	Replace	Repair	No ☒
61602471 60			PANEL SUB-ASSY, FENDER REAR LH	0	824.80	25.00	0.00	Replace	Not given	No ☒

8234.90

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
6294047010			DUCT ASSY, QUARTER VENT, RH & LH	0	65.00	25.00	0.00	Replace	Not given	No ☒
6563847060			LINER, REAR FENDER, LH	0	135.80	25.00	0.00	Replace	Not given	No ☒
			TYRE	0	126.74	0.00	0.00	Replace	Not given	No ☒
4261147450			WHEEL, DISC	0	1,555.10	25.00	0.00	Replace	Not given	No ☒
TOTAL MATERIALS							1882.64	11,900.83	6,923.95	
TOTAL MATERIALS(Discounted)								11,900.76	6,923.95	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

28541.14

6923.95 /

+ 1200.00 /

+ 2065.00 /

10,188.95 /

Sebastian
7/6/18

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5599B
 Ref. No : TAX/05/18/2061
 Reg. Date : 03/11/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : GOH CHYE SENG
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 13/05/2018 11:50:00 PM
 Accident Reported Date / Time : 14/05/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 14/05/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024096057
 Special Instruction to ARC,if any :
 TOWED \$40 / SHD4212M
 Prepared Date : 14/05/2018 02:22:42 PM



Sebastian
 15/5/18
 - Part by part repair
 - Question Mark Item
 Photo
 - Photo Before Paint

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU303574007

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	1,859.00	0.00
Total Spray Painting Charges	3,294.00	0.00
Total Material Charges	16,531.55	16,531.55
Other Charges	2,335.00	0.00
TOTAL	24,019.55	0.00
Lum Sum Total	0.00	0.00
No. of Repair Days	11.00	0.00
Prepared / Adjusted By		3 days
Arc / Surveyor Sign Off Date	14/05/2018 06:15:02 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 14/05/2018 06:14:15 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 5/14/2018 6:14:25 PM

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,859.00	0.00 1200
Total Labour	1,859.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY FILLER RR BUMPER LH	180.00	0.00 50
TO RESPRAY FILLER RR BUMPER RH	180.00	0.00 50
TO RESPRAY TAIL GATE	378.00	0.00 200
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 100
TO RESPRAY REAR SPOILER	180.00	0.00 X
TO RESPRAY RH RAIL ROOF SIDE	180.00	0.00 ?
TO RESPRAY LH RAIL ROOF SIDE	180.00	0.00 ?
TO RESPRAY REAR PANEL	180.00	0.00 100
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00 100
TO RESPRAY REAR MEMBER,LH	180.00	0.00 ?
TO RESPRAY REAR MEMBER,RH	180.00	0.00 ?
TO RESPRAY TROUGH BACK DOOR LH	180.00	0.00 50
TO RESPRAY REAR FENDER LH	378.00	0.00 X
TO RESPRAY RIM	180.00	0.00 X
Total Spray Painting & Panel Beating	3,294.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 50
TO CHECK & RESET SYSTEM FUNCTION	350.00	0.00 250
TO REMOVE & REFIT EXHAUST	120.00	0.00 60
TO ALIGN CHASSIS	350.00	0.00 200
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00 ✓
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 80
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0.00 120
TO REMOVE AND REFIT WIRE HARDESS	250.00	0.00 150
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 50
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	2,335.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
5215947913			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace ✓ <i>RR</i>	No
5216116010			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace ✓	No <i>NEC</i>
5246247030			PAD, RR BUMPER, RH & LH , 1	2	3.80	25.00	5.70	Replace	Replace	No
5246247020			PAD, RR BUMPER, RH & LH , 2	2	3.80	25.00	5.70	Replace	Replace	No <i>?</i>
5246247010			PAD, RR BUMPER, RH & LH , 3	2	3.80	25.00	5.70	Replace	Replace	No
5219147030			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Replace <i>?</i>	No
5259247040			SEAL, RR BUMPER , LH	1	85.20	25.00	63.90	Replace	Replace <i>?</i>	No
5256647900			FILLER, RR BUMPER , LH	1	119.90	25.00	89.92	Replace	Replace ✓	No <i>MS</i>
5256547900			FILLER, RR BUMPER , RH	1	119.90	25.00	89.92	Replace	Replace ✓	No <i>MS</i>
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace ✓	No <i>Dmg</i>
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace ✓	No <i>NEC</i>
5257647040			RETAINER, RR BUMPER, LH	1	111.50	25.00	83.62	Replace	Replace ✓	No <i>?</i>
5257547040			RETAINER, RR BUMPER, RH	1	112.70	25.00	84.52	Replace	Replace	No <i>?</i>
5259968030			STOPPER, RR BUMPER, RH & LH	2	4.30	25.00	6.45	Replace	Replace ✓	No <i>NEC</i>
9018906029			REAR BUMPER GROMMET SCREW	2	2.20	25.00	3.30	Replace	Replace ✓	No <i>NEC</i>
5202347030			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace ✓	No <i>BSI</i>
5245347010			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace ✓	No <i>MS</i>
5216947020			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace ✓	No <i>MS</i>
5246147010			PAD, RR BUMPER, CTR	3	2.20	25.00	4.95	Replace	Replace <i>?</i>	No
9046717026A0			CLIP , FLOOR UNDER COVER , NO.1	10	2.60	25.00	19.50	Replace	Replace ✓	No <i>NEC</i>
9046717027C0			CLIP , FLOOR UNDER COVER , NO.2	10	3.20	25.00	24.00	Replace	Replace ✓	No <i>NEC</i>
5839947030			COVER, REAR FLOOR UNDER , LH	1	234.30	25.00	175.72	Replace	Replace <i>?</i>	No <i>MS</i>
5839847050			COVER, REAR FLOOR UNDER , RH	1	169.50	25.00	127.12	Replace	Replace ✓	No <i>NEC</i>
6625947010			COVER, REAR FLOOR UNDER CENTER	1	222.60	25.00	166.95	Replace	Replace ✓	No <i>MS</i>
5832747040			EXHAUST HEAT SHIELD INSULATOR, MAIN MUFFLER REAR	1	137.00	25.00	102.75	Replace	Replace <i>x</i>	No
1743037730			PIPE ASSY, EXHAUST, TAIL	1	1,173.90	25.00	880.42	Replace	Replace <i>x</i>	No
1756522040			SUPPORT, EXHAUST PIPE NO.5	2	41.10	25.00	61.65	Replace	Replace <i>x</i>	No
8159147010			LENS & BODY ASSY , RR BUMPER , LH	1	486.80	10.00	438.12	Replace	Replace ✓	No <i>RR</i>

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
8999730100			ANTENNA, ELECTRICAL KEY	1	60.30	10.00	54.27	Replace	Replace ✓	No <i>Dmg.</i>
8218347020			WIRE, LUGGAGE ROOM	1	143.50	10.00	129.15	Replace	Replace ✓	No
6700547440			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	25.00	697.20	Replace	Replace ✓	No <i>Defect</i>
6947847010			TAIL GATE CUSHION, BACK DOOR, RH & LH	2	8.20	25.00	12.30	Replace	Replace ✓	No
5611750140			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	1	27.90	25.00	20.92	Replace	Replace ✓	No <i>NEC</i>
7557147010			TAIL GATE MOULDING GLASS, BACK DOOR	1	29.70	25.00	22.27	Replace	Replace ✓	No <i>NEC</i>
6480147031			TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR	1	725.90	25.00	544.42	Replace	Replace ✓	No <i>NEC</i>
689600W860			TAIL GATE STAY ASSY, BACK DOOR, LH	1	235.00	25.00	176.25	Replace	Replace ✓	No
689500W860			TAIL GATE STAY ASSY, BACK DOOR, RH	1	235.00	25.00	176.25	Replace	Replace ✓	No
6935047050			TAIL GATE LOCK ASSY, BACK DOOR	1	452.10	10.00	406.89	Replace	Replace ✓	No <i>3m.</i>
6932147010			TAIL GATE LOCK COVER, BACK DOOR	1	25.30	25.00	18.97	Replace	Replace ✓	No
7680147110A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	25.00	668.40	Replace	Replace ✓	No <i>CRK</i>
7540348010			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.72	Replace	Replace ✓	No <i>NEC</i>
7544147090			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace ✓	No <i>NEC</i>
7544247130			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace ✓	No <i>NEC</i>
	REAR		NUMBER PLATE	1	30.00	0.00	30.00	Replace	Replace ✓	No <i>SCR</i>
			NUMBER PLATE FRAME	1	25.00	0.00	25.00	Replace	Replace ✓	No <i>SCR</i>
8127033110			LAMP ASSY, LICENSE PLATE	2	63.70	10.00	114.66	Replace	Replace ✓	No
867B047010			CAMERA REAR ASSY, TELEVISION	1	1,103.80	10.00	993.42	Replace	Replace ✓	No
8484047040			SWITCH ASSY, BACK DOOR OPENER	1	149.40	10.00	134.46	Replace	Replace ✓	No
	COMMO N		SEALANT W/SCREEN	3	37.00	0.00	111.00	Replace	Replace ✓	No <i>NEC</i>
6943052050			TAIL GATE STRIKER ASSY, BACK DOOR	1	24.90	25.00	18.67	Replace	Replace ✓	No
7481147020C0			TAILGATE BOARD, HANDLE PULL	1	19.50	25.00	14.62	Replace	Replace ✓	No
6775047080C0			TAILGATE BOARD ASSY	1	251.50	25.00	188.62	Replace	Replace ✓	No
6793847060C0			TAILGATE TRIM, LH	1	92.10	25.00	69.07	Replace	Replace ✓	No <i>TW</i>

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
6775147110C0			TAILGATE TRIM , LOWER	1	218.50	25.00	163.87	Replace	Replace ✓	No
6793747060C0			TAILGATE TRIM , RH	1	92.10	25.00	69.07	Replace	Replace ✓	No
6479047060C0			TAILGATE TRIM , UPPER	1	50.50	25.00	37.87	Replace	Replace ✓	No
8218447490			WIRE, TAIL GATE BACK DOOR,	1	246.80	10.00	222.12	Replace	Replace ✓	No
8218547150			WIRE, TAIL GATE BACK DOOR , NO.2	1	246.80	10.00	222.12	Replace	Replace ✓	No
7608547916			SPOILER SUB-ASSY, REAR	1	1,322.10	25.00	991.57	Replace	Replace ✓	No
8100647030			LAMP SET, STOP CENTER	1	186.50	10.00	167.85	Replace	Replace ✓	No
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓	No NCC
	COMMO N		STICKER DECAL 65558888	1	21.60	0.00	21.60	Replace	Replace ✓	No NCC
5830747090			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	25.00	472.35	Replace	Replace ✓	No DT
6471847080C0			END PANEL , COVER, DECK TRIM SERVICE HOLE	1	47.00	25.00	35.25	Replace	Replace ✓	No
6471647130C0			END PANEL , COVER, DECK TRIM, REAR	1	122.80	25.00	92.10	Replace	Replace ✓	No
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace ✓	No NCC
5831147130			SPARE TYRE PANEL , PAN, REAR FLOOR	1	564.80	25.00	423.60	Replace	Replace ✓	No DT
5835047010			REINFORCEMENT ASSY, REAR FLOOR END PANEL , RH & LH	2	56.70	25.00	85.05	Replace	Replace ✓	No
5760347060			MEMBER SUB-ASSY, REAR FLOOR SIDE , REAR RH	1	268.60	25.00	201.45	Replace	Replace ✓	No
5760447060			MEMBER SUB-ASSY, REAR FLOOR SIDE , REAR LH	1	268.60	25.00	201.45	Replace	Replace ✓	No
6788147050			TAIL GATE WEATHERSTRIP, BACK DOOR	1	360.70	25.00	270.52	Replace	Replace ✓	No
5193147030			CARRIER, SPARE WHEEL	1	20.00	25.00	15.00	Replace	Replace ✓	No
6499747060			BOX, DECK FLOOR, LH	1	303.40	25.00	227.55	Replace	Replace ✓	No
6499547050			BOX, DECK FLOOR, RH	1	304.00	25.00	228.00	Replace	Replace ✓	No
5841547110C2			BOARD, REAR FLOOR, NO.1	1	502.20	25.00	376.65	Replace	Replace ✓	No
6474047190C2			PANEL ASSY, DECK TRIM SIDE, LH	1	344.70	25.00	258.52	Replace	Replace ✓	No
6473047240C2			PANEL ASSY, DECK TRIM SIDE, RH	1	344.70	25.00	258.52	Replace	Replace ✓	No
6101847010			MEMBER SUB-ASSY, RAIL ROOT SIDE REAR LH	1	279.20	25.00	209.40	Replace	Replace ✓	No
6101747010			MEMBER SUB-ASSY, RAIL ROOT SIDE REAR RH	1	279.20	25.00	209.40	Replace	Replace ✓	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
8156147151			LENS & BODY, REAR COMBINATION LAMP, LH	1	438.10	10.00	394.29	Replace	Replace ✓	No <i>CRK</i>
6162247060			TROUGH, BACK DOOR, LH	1	99.80	25.00	74.85	Replace	Replace <i>R</i>	No
6160247160			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	25.00	618.60	Replace	Replace ✗	No
6294047010			DUCT ASSY, QUARTER VENT, RH & LH	1	65.00	25.00	48.75	Replace	Replace ✗	No
6563847060			LINER, REAR FENDER, LH	1	135.80	25.00	101.85	Replace	Replace ✗	No
			TYRE	1	126.74	0.00	126.74	Replace	Replace ✗	No
4261147450			WHEEL, DISC	1	1,555.10	25.00	1,166.32	Replace	Replace ✗	No
TOTAL MATERIALS								16,531.69	16,531.55	
TOTAL MATERIALS(Discounted)								16,531.55	16,531.55	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 15 May 2018 10:02 AM
To: Shanti B Thaiyal Nayagi (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims); 'sur@lkkauto.com'; Nivitha (LKK Auto)
Cc: Sherini Pillai
Subject: RE: SHB5599B - Survey (III)
Attachments: 2061 - 5599.pdf; SHB5599B.PDF

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SHB5599B and let us have your report urgently.

This claim will be handled by Ms Sherini.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

10:18am @ 15/5/18
Vehicle In
person @ Alex
sur @ sebastian

From: Shanti B Thaiyal Nayagi (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims) [mailto:BThaiyalN@smrt.com.sg]
Sent: 15 May, 2018 9:47 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: RE: SHB5599B - Survey (III)

Dear Sir / Mdm,

We agree to your proposal.

Regards

Shanti

SMRT Automotive Services PTE LTD

Accident Reporting Center (Claims Dept)

6866 2671/2 | bthaiyaln@smrt.com.sg



From: Motor Claim - III [mailto:motorclaim@iii.com.sg]
Sent: 15/05/2018 09:41
To: Shanti B Thaiyal Nayagi (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims)
Subject: RE: SHB5599B - Survey (III)

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Shanti B Thaiyal Nayagi (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims) [<mailto:BThaiyalN@smrt.com.sg>]

Sent: 15 May, 2018 9:18 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: Kok Tuck Foo (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <TuckFoo@smrt.com.sg>; Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>; Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC) <YewChung@smrt.com.sg>; Phua Zhi Yang (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) <ZhiYang.Phua@smrt.com.sg>; Grace Ng Siu Ching (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) <ngsiuching@smrt.com.sg>; Lim Kha Chiew (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) <limkhachiew@smrtlan.com.sg>; Lim Wei Siong (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims) <weisiong@smrt.com.sg>; Chin Kim Ming (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) <kimming.chin@smrtlan.com.sg>

Subject: RE: SHB5599B - Survey (III)

Dear Sir / Mdm

Kindly arrange to survey the vehicle **SHB5599B** within 48 hours according to GIA guide line, involving your insured **SHD4212M**

Vehicle in **Woodlands SMRT Depot**

Regards

Shanti

SMRT Automotive Services PTE LTD

Accident Reporting Center (Claims Dept)

6866 2671/2 | bthaiyaln@smrt.com.sg



Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Print Received Message

This mail is associated with :

*SHB5599B (MCT18050339)

[SHD4212M]

TP

SMRT TAXIS PTE LTD

May 13 2018 11:00PM

[COMFORT TRANSPORTATION PTE LTD]
SMRT Automotive Services Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 27/07/2018 14:39 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$11440.85) - SHB5599B - Claim Handler: Sherini Pillai

Approved: 11440.85.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 May 2018 Edit Reg		15 May 2018 00:00 Edit Adj Rpt	S\$10,188.95 Edit Estimates	S\$10,188.95 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K		
Vehicle Reg. No.:	SHB5599B	Date of Loss:	13/05/2018 23:00 - :59 [6 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT18050339	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SHD4212M	Policy No. (Claimant):	D-18090213MFSH
		Excess:	
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 06/06/2018]		
Driver/Custodian (Insured):	MANIMARAN S/O HARIKRISHNAN (), NRIC: S7776162D		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III_SG (27/07/2018): Alert - Adj Mandate Approved (S\$11440.85) - SHB5599B - Claim Handler: Sherini Pi...
- III_SG (31/05/2018): Alert - Adj Mandate Approved (S\$0.00) - SHB5599B - Claim Handler: Sherini Pillai

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHB5599B (MCT18050339)**
[SHD4212M]

TP

SMRT TAXIS PTE LTD

May 13 2018 11:00PM

[COMFORT TRANSPORTATION PTE LTD]

SMRT Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/05/18 15:30	General View	 Load JPG	✓
2	28/05/18 15:30	General View	 Load JPG	✓
3	28/05/18 15:30	General View	 Load JPG	✓
4	28/05/18 15:30	General View	 Load JPG	✓
5	28/05/18 15:30	General View	 Load JPG	✓
6	28/05/18 15:30	General View	 Load JPG	✓
7	28/05/18 15:30	General View	 Load JPG	✓
8	28/05/18 15:30	General View	 Load JPG	✓
9	28/05/18 15:30	General View	 Load JPG	✓
10	28/05/18 15:30	General View	 Load JPG	✓
11	28/05/18 15:30	General View	 Load JPG	✓
12	28/05/18 15:30	General View	 Load JPG	✓
13	28/05/18 15:30	General View	 Load JPG	✓
14	28/05/18 15:30	General View	 Load JPG	✓
15	28/05/18 15:30	General View	 Load JPG	✓
16	28/05/18 15:30	General View	 Load JPG	✓
17	28/05/18 15:30	General View	 Load JPG	✓
18	28/05/18 15:30	General View	 Load JPG	✓
19	28/05/18 15:30	General View	 Load JPG	✓
20	28/05/18 15:30	General View	 Load JPG	✓
21	28/05/18 15:30	General View	 Load JPG	✓
22	28/05/18 15:30	General View	 Load JPG	✓
23	28/05/18 15:30	General View	 Load JPG	✓
24	28/05/18 15:30	General View	 Load JPG	✓
25	28/05/18 15:30	General View	 Load JPG	✓
26	28/05/18 15:30	General View	 Load JPG	✓
27	28/05/18 15:30	General View	 Load JPG	✓
28	28/05/18 15:30	General View	 Load JPG	✓
29	28/05/18 15:30	General View	 Load JPG	✓
30	28/05/18 15:30	General View	 Load JPG	✓
31	28/05/18 15:30	General View	 Load JPG	✓
32	28/05/18 15:30	General View	 Load JPG	✓
33	28/05/18 15:30	General View	 Load JPG	✓
34	28/05/18 15:30	General View	 Load JPG	✓
35	28/05/18 15:30	General View	 Load JPG	✓

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	28/05/18 15:30	General View	 Load JPG	✓
37	28/05/18 15:30	General View	 Load JPG	✓
38	28/05/18 15:30	General View	 Load JPG	✓
39	28/05/18 15:30	General View	 Load JPG	✓
40	28/05/18 15:30	General View	 Load JPG	✓
41	28/05/18 15:30	General View	 Load JPG	✓
42	28/05/18 15:30	General View	 Load JPG	✓
43	28/05/18 15:30	General View	 Load JPG	✓
44	28/05/18 15:30	General View	 Load JPG	✓
45	28/05/18 15:30	General View	 Load JPG	✓
46	28/05/18 15:30	General View	 Load JPG	✓
47	28/05/18 15:31	General View	 Load JPG	✓
48	28/05/18 15:31	General View	 Load JPG	✓
49	28/05/18 15:31	General View	 Load JPG	✓
50	28/05/18 15:31	General View	 Load JPG	✓
51	28/05/18 15:31	General View	 Load JPG	✓
52	28/05/18 15:31	General View	 Load JPG	✓
53	28/05/18 15:31	Odometer Reading	 Load JPG	✓
54	28/05/18 15:31	General View	 Load JPG	✓
55	28/05/18 15:31	General View	 Load JPG	✓
56	28/05/18 15:31	Chassis Number	 Load JPG	✓
57	28/05/18 15:31	Reinspection Photo	 Load JPG	✓
58	28/05/18 15:31	Reinspection Photo	 Load JPG	✓
59	28/05/18 15:31	Reinspection Photo	 Load JPG	✓
60	28/05/18 15:31	Reinspection Photo	 Load JPG	✓
61	28/05/18 15:31	Reinspection Photo	 Load JPG	✓
62	28/05/18 15:31	Reinspection Photo	 Load JPG	✓
63	28/05/18 15:31	Reinspection Photo	 Load JPG	✓
64	28/05/18 15:31	Reinspection Photo	 Load JPG	✓
65	28/05/18 15:31	Reinspection Photo	 Load JPG	✓
66	28/05/18 15:31	Reinspection Photo	 Load JPG	✓
67	28/05/18 15:31	Reinspection Photo	 Load JPG	✓
68	28/05/18 15:31	Reinspection Photo	 Load JPG	✓
69	07/06/18 10:43	BEFORE PAINT	 Load JPG	✓
70	07/06/18 10:43	BEFORE PAINT	 Load JPG	✓
71	07/06/18 10:43	BEFORE PAINT	 Load JPG	✓
72	07/06/18 10:43	BEFORE PAINT	 Load JPG	✓
73	07/06/18 10:43	BEFORE PAINT	 Load JPG	✓
74	07/06/18 10:43	BEFORE PAINT	 Load JPG	✓
75	07/06/18 10:43	BEFORE PAINT	 Load JPG	✓
76	07/06/18 10:43	BEFORE PAINT	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/05/18 17:05	TP ESTIMATE.	 Load PDF	
2	25/05/18 17:05	TP GIA REPOR	 Load PDF	
3	25/05/18 17:05	ACKNOWLEDGEMENT EMAIL TO III DD 15.05.2018	 Load PDF	
4	27/05/18 10:32	TP ESTIMATE - MARKED	 Load PDF	
5	27/07/18 09:39	LOD	 Load PDF	

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
6	27/07/18 09:39	RENTAL RECEIPT		Load PDF
7	27/07/18 09:39	WORKSHOP INVOICE		Load PDF
8	23/08/18 16:00	AUTHORISATION TO ACT		Load PDF
9	23/08/18 16:00	DISCHARGE VOUCHER		Load PDF
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail Print
1	28/05/18 10:36	Singapore Accident Statement-IV		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18008909/SUA3S2

Date: 23/08/2018

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015	
Claimant Vehicle No :	SHB5599B	Insured Vehicle No :	SHD4212M	
Date of Loss:	13/05/2018	Nature of Claim:	TP	Claim No: MCT18050339

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB5599B		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)		
Reg. Date:	03/11/2017 (Man. Year: 2017)	Engine No:	2ZRS103467
Colour:	Maroon	Chassis No:	JTDKB3FU303574007
Engine Capacity:	1798 cc	Odometer:	69045 km
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,178.14	7,048.95	14,129.19	66.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,363.00	3,140.00	4,223.00	57.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	28,541.14	10,188.95	18,352.19	64.30
+ Car Rental (10.0 x S\$125.19/day) (S\$)		1,251.90		
	Nett Liability (S\$)	11,440.85		
	Global Sum Settlement (S\$)	11,440.00		

INSPECTION

Date of Assignment:	15/05/2018	
Date Inspected:	15/05/2018	Inspected At: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	8.0 days	

Adjuster: Sebastian Yeang Wai Keen

Manager: THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Aug 2018)

Parts: 144 TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHB5599B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*COVER, RR BUMPER ASSY (DISC 25%)	Cracked	423.90 F	*317.92 F
2	1	*CLIPS PIECE, FRT & RR BUMPER (DISC 25%) 10pcs	Necessary	15.00 F	*11.25 F
3	1	*FILLER, RR BUMPER, LH (DISC 25%)	Missing	119.90 F	*89.92 F
4	1	*FILLER, RR BUMPER, RH (DISC 25%)	Missing	119.90 F	*89.92 F
5	1	*STOPPER, RR BUMPER, RH & LH (DISC 25%) 2pcs	Necessary	8.60 F	*6.45 F
6	2	*REAR BUMPER GROMMET SCREW (DISC 25%)	Necessary	4.40 F	*3.30 F
7	1	*REAR BUMPER REINFORCEMENT (DISC 25%)	Bent	318.80 F	*239.10 F
8	1	*GUARD, RR BUMPER, LOWER (DISC 25%)	Missing	558.30 F	*418.72 F
9	1	*COVER, GUARD RR BUMPER LOWER (DISC 25%)	Missing	14.80 F	*11.10 F
10	10	*CLIP, FLOOR UNDER COVER, NO.1 (DISC 25%)	Necessary	26.00 F	*19.50 F
11	10	*CLIP, FLOOR UNDER COVER, NO.2 (DISC 25%)	Necessary	32.00 F	*24.00 F
12	1	*COVER, REAR FLOOR UNDER, LH (DISC 25%)	Torn	234.30 F	*175.72 F
13	1	*COVER, REAR FLOOR UNDER, RH (DISC 25%)	Necessary	169.50 F	*127.12 F
14	1	*COVER, REAR FLOOR UNDER CENTER (DISC 25%)	Missing	222.60 F	*166.95 F
15	1	*TAIL GATE PANEL SUB-ASSY, BACK DOOR (DISC 25%)	Deformed	929.60 F	*697.20 F
16	1	*TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE (DISC 25%)	Necessary	27.90 F	*20.92 F
17	1	*TAIL GATE MOULDING GLASS, BACK DOOR (DISC 25%)	Necessary	29.70 F	*22.27 F
18	1	*TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR (DISC 25%)	Necessary	725.90 F	*544.42 F
19	1	*TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY (DISC 25%)	Cracked	891.20 F	*668.40 F
20	1	*EMBLEM SUB-ASSY REAR (DISC 25%)	Necessary	46.30 F	*34.72 F
21	1	*NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR (DISC 25%)	Necessary	52.30 F	*39.22 F
22	1	*NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR (DISC 25%)	Necessary	52.30 F	*39.22 F
23	1	*TAILGATE TRIM, LH (DISC 25%)	Torn	92.10 F	*69.07 F
24	1	*END PANEL SUB-ASSY, BODY LOWER BACK (DISC 25%)	Dented	629.80 F	*472.35 F
25	1	*END PANEL, COVER, DECK TRIM, REAR (DISC 25%)	Deformed	122.80 F	*92.10 F
26	1	*SPARE TYRE PANEL, PAN, REAR FLOOR (DISC 25%)	Dented	564.80 F	*423.60 F
27	1	*CARRIER, SPARE WHEEL (DISC 25%)	Cracked	20.00 F	*15.00 F
28	1	*PANEL ASSY, DECK TRIM SIDE, LH (DISC 25%)	Deformed	344.70 F	*258.52 F
29	1	*LENS & BODY ASSY, RR BUMPER, LH (DISC 10%)	Cracked	486.80 F	*438.12 F
30	1	*ANTENNA, ELECTRICAL KEY (DISC 10%)	Damaged	60.30 F	*54.27 F
31	1	*TAIL GATE LOCK ASSY, BACK DOOR (DISC 10%)	Jammed	452.10 F	*406.89 F
32	1	*LENS & BODY, REAR COMBINATION LAMP, LH (DISC 10%)	Cracked	438.10 F	*394.29 F
33	1	*SENSOR REVERSE (SN)	Damaged	180.00 F	*180.00 F
34	2	*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
35	1	*NUMBER PLATE (SN)	Scratched	30.00 F	*30.00 F
36	1	*NUMBER PLATE FRAME (SN)	Scratched	25.00 F	*25.00 F
37	3	*SEALANT W/SCREEN (SN)	Necessary	111.00 F	*111.00 F
38	1	*SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F
39	1	*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
40	1	*SEALANT SIKAFLEX (SN)	Necessary	37.00 F	*37.00 F
41	2	*PAD, RR BUMPER, RH & LH, 1	Not Necessary	7.60 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
42	2	*PAD, RR BUMPER, RH & LH, 2	Not Necessary	7.60 F	*- F
43	2	*PAD, RR BUMPER, RH & LH, 3	Not Necessary	7.60 F	*- F
44	2	*SEAL, RR BUMPER ARM, RH & LH	Not Necessary	22.00 F	*- F
45	1	*SEAL, RR BUMPER, LH	Not Necessary	85.20 F	*- F
46	1	*RETAINER, RR BUMPER, LH	Not Necessary	111.50 F	*- F
47	1	*RETAINER, RR BUMPER, RH	Not Necessary	112.70 F	*- F
48	3	*PAD, RR BUMPER CTR	Not Necessary	6.60 F	*- F
49	1	*EXHAUST HEAT SHIELD INSULATOR, MAIN MUFFLER REAR	Not Necessary	137.00 F	*- F
50	1	*PIPE ASSY, EXHAUST, TAIL	Not Necessary	1,173.90 F	*- F
51	1	*SUPPORT, EXHAUST PIPE NO.5	Not Necessary	41.10 F	*- F
52	1	*WIRE LUGGAGE ROOM	Not Necessary	143.50 F	*- F
53	2	*TAIL GATE CUSHION, BACK DOOR, RH & LH	Not Necessary	16.40 F	*- F
54	1	*TAIL GATE STAY ASSY, BACK DOOR, LH	Not Necessary	235.00 F	*- F
55	1	*TAIL GATE STAY ASSY, BACK DOOR, RH	Not Necessary	235.00 F	*- F
56	1	*TAIL GATE LOCK COVER, BACK DOOR	Not Necessary	25.30 F	*- F
57	2	*LAMP ASSY, LICENCE PLATE	Not Necessary	127.40 F	*- F
58	1	*CAMERA REAR ASSY, TELEVISION	Not Necessary	1,103.80 F	*- F
59	1	*SWITCH ASSY, BACK DOOR OPENER	Not Necessary	149.40 F	*- F
60	1	*TAIL GATE STRIKER ASSY, BACK DOOR	Not Necessary	24.90 F	*- F
61	1	*TAILGATE BOARD, HANDLE PULL	Not Necessary	19.50 F	*- F
62	1	*TAILGATE BOARD ASSY	Not Necessary	251.50 F	*- F
63	1	*TAILGATE TRIM, LOWER	Not Necessary	218.50 F	*- F
64	1	*TAILGATE TRIM, RH	Not Necessary	92.10 F	*- F
65	1	*TAILGATE TRIM, UPPER	Not Necessary	50.50 F	*- F
66	1	*WIRE, TAIL GATE BACK DOOR,	Not Necessary	246.80 F	*- F
67	1	*WIRE, TAIL GATE BACK DOOR, NO.2	Not Necessary	246.80 F	*- F
68	1	*SPOILER SUB-ASSY, REAR	Not Necessary	1,322.10 F	*- F
69	1	*LAMP SET, STOP CENTER	Not Necessary	186.50 F	*- F
70	1	*END PANEL, COVER, DECK TRIM SERVICE HOLE	Not Necessary	47.00 F	*- F
71	2	*REINFORCEMENT ASSY, REAR FLOOR END PANEL, RH & LH	Not Necessary	113.40 F	*- F
72	1	*MEMBER SUB-ASSY, REAR FLOOR SIDE, REAR RH	Not Necessary	268.60 F	*- F
73	1	*MEMBER SUB-ASSY, REAR FLOOR SIDE, REAR LH	Not Necessary	268.60 F	*- F
74	1	*TAIL GATE WEATHERSTRIP, BACK DOOR	Not Necessary	360.70 F	*- F
75	1	*BOX, DECK FLOOR, LH	Not Necessary	303.40 F	*- F
76	1	*BOX, DECK FLOOR, RH	Not Necessary	304.00 F	*- F
77	1	*BOARD, REAR FLOOR, NO.1	Not Necessary	502.20 F	*- F
78	1	*PANEL ASSY, DECK TRIM SIDE, RH	Not Necessary	344.70 F	*- F
79	1	*MEMBER SUB-ASSY, RAIL ROOT SIDE REAR LH	Not Necessary	279.20 F	*- F
80	1	*MEMBER SUB-ASSY, RAIL ROOT SIDE REAR RH	Not Necessary	279.20 F	*- F
81	1	*PANEL SUB-ASSY, FENDER REAR LH	Not Necessary	824.80 F	*- F
82	1	*DUCT ASSY, QUARTER VENT, RH & LH	Not Necessary	65.00 F	*- F
83	1	*LINER, REAR FENDER, LH	Not Necessary	135.80 F	*- F
84	1	*TYRE	Not Necessary	126.74 F	*- F
85	1	*WHEEL, DISC	Not Necessary	1,555.10 F	*- F
86	1	*TROUGH, BACK DOOR, LH	Repair	99.80 F	*- F
87	1	*SOLAR FILM (SN)	Necessary	125.00 F	*125.00 F

F=Franchise part.

Total Parts (\$\$) 21,178.14 7,048.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODYWORK.	New	1,859.00	1,200.00
2	SPRAY PAINT.	New	3,294.00	850.00
3	TOWING CHARGE.	New	80.00	40.00
4	TO CHECK WIRING AND SYSTEM FUNCTION.	New	80.00	30.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA.	New	100.00	50.00
6	TO CHECK & RESET SYSTEM FUNCTION.	New	350.00	250.00
7	TO REMOVE & REFIT EXHAUST.	New	120.00	60.00
8	TO ALIGN CHASSIS.	New	350.00	200.00
9	TO TRANSFER REAR TAILGATE MECHANISM.	New	120.00	80.00
10	TO REMOVE AND REFIX REAR WINDSCREEN.	New	240.00	120.00
11	TO REMOVE AND REFIT WIRE HARNESS.	New	250.00	150.00
12	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	New	120.00	30.00
13	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	New	120.00	50.00
14	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.	New	120.00	30.00
15	TO REPLACE SUNDRY PARTS.	New	100.00	0.00
16	TO WASH AND VACUUM.	New	60.00	0.00
Gross Labour Cost (S\$)			7,363.00	3,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >