


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5599B
Ref. No : TAX/05/18/2061
Reg. Date : 03/11/2017
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS4
Name of Driver : GOH CHYE SENG
Type of Accident : HEAD TO REAR
Date / Time of Accident : 13/05/2018 11:50:00 PM
Accident Reported Date / Time : 14/05/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : Yes
Towed Back Date/Time : 14/05/2018
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024096057
Special Instruction to ARC,if any :
TOWED \$40 / SHD4212M - III
Prepared Date : 14/05/2018 02:22:42 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU303574007

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,859.00	0.00
Total Spray Painting Charges :	3,294.00	0.00
Total Material Charges :	16,531.55	16,531.55
Other Charges :	2,335.00	0.00
TOTAL :	24,019.55	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	11.00	0.00
Prepared / Adjusted By :		
Arc / Surveyor Sign Off Date :	14/05/2018 06:15:02 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 14/05/2018 06:14:15 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 5/14/2018 6:14:25 PM

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,859.00	0.00
Total Labour	1,859.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00
TO RESPRAY FILLER RR BUMPER LH	180.00	0.00
TO RESPRAY FILLER RR BUMPER RH	180.00	0.00
TO RESPRAY TAIL GATE	378.00	0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00
TO RESPRAY REAR SPOILER	180.00	0.00
TO RESPRAY RH RAIL ROOF SIDE	180.00	0.00
TO RESPRAY LH RAIL ROOF SIDE	180.00	0.00
TO RESPRAY REAR PANEL	180.00	0.00
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00
TO RESPRAY REAR MEMBER,LH	180.00	0.00
TO RESPRAY REAR MEMBER,RH	180.00	0.00
TO RESPRAY TROUGH BACK DOOR LH	180.00	0.00
TO RESPRAY REAR FENDER LH	378.00	0.00
TO RESPRAY RIM	180.00	0.00
Total Spray Painting & Panel Beating	3,294.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00
TO CHECK & RESET SYSTEM FUNCTION	350.00	0.00
TO REMOVE & REFIT EXHAUST	120.00	0.00
TO ALIGN CHASSIS	350.00	0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0.00
TO REMOVE AND REFIT WIRE HARDESS	250.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	2,335.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
5215947913			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace	No
5216116010			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace	No
5246247030			PAD, RR BUMPER, RH & LH , 1	2	3.80	25.00	5.70	Replace	Replace	No
5246247020			PAD, RR BUMPER, RH & LH , 2	2	3.80	25.00	5.70	Replace	Replace	No
5246247010			PAD, RR BUMPER, RH & LH , 3	2	3.80	25.00	5.70	Replace	Replace	No
5219147030			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Replace	No
5259247040			SEAL, RR BUMPER , LH	1	85.20	25.00	63.90	Replace	Replace	No
5256647900			FILLER, RR BUMPER , LH	1	119.90	25.00	89.92	Replace	Replace	No
5256547900			FILLER, RR BUMPER , RH	1	119.90	25.00	89.92	Replace	Replace	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No
5257647040			RETAINER, RR BUMPER, LH	1	111.50	25.00	83.62	Replace	Replace	No
5257547040			RETAINER, RR BUMPER, RH	1	112.70	25.00	84.52	Replace	Replace	No
5259968030			STOPPER, RR BUMPER, RH & LH	2	4.30	25.00	6.45	Replace	Replace	No
9018906029			REAR BUMPER GROMMET SCREW	2	2.20	25.00	3.30	Replace	Replace	No
5202347030			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace	No
5245347010			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace	No
5216947020			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace	No
5246147010			PAD, RR BUMPER, CTR	3	2.20	25.00	4.95	Replace	Replace	No
9046717026A0			CLIP , FLOOR UNDER COVER , NO.1	10	2.60	25.00	19.50	Replace	Replace	No
9046717027C0			CLIP , FLOOR UNDER COVER , NO.2	10	3.20	25.00	24.00	Replace	Replace	No
5839947030			COVER, REAR FLOOR UNDER , LH	1	234.30	25.00	175.72	Replace	Replace	No
5839847050			COVER, REAR FLOOR UNDER , RH	1	169.50	25.00	127.12	Replace	Replace	No
6625947010			COVER, REAR FLOOR UNDER CENTER	1	222.60	25.00	166.95	Replace	Replace	No
5832747040			EXHAUST HEAT SHIELD INSULATOR, MAIN MUFFLER REAR	1	137.00	25.00	102.75	Replace	Replace	No
1743037730			PIPE ASSY, EXHAUST, TAIL	1	1,173.90	25.00	880.42	Replace	Replace	No
1756522040			SUPPORT, EXHAUST PIPE NO.5	2	41.10	25.00	61.65	Replace	Replace	No
8159147010			LENS & BODY ASSY , RR BUMPER , LH	1	486.80	10.00	438.12	Replace	Replace	No
8999730100			ANTENNA, ELECTRICAL KEY	1	60.30	10.00	54.27	Replace	Replace	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
8218347020			WIRE, LUGGAGE ROOM	1	143.50	10.00	129.15	Replace	Replace	No
6700547440			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	25.00	697.20	Replace	Replace	No
6947847010			TAIL GATE CUSHION, BACK DOOR , RH & LH	2	8.20	25.00	12.30	Replace	Replace	No
5611750140			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	1	27.90	25.00	20.92	Replace	Replace	No
7557147010			TAIL GATE MOULDING GLASS, BACK DOOR	1	29.70	25.00	22.27	Replace	Replace	No
6480147031			TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR	1	725.90	25.00	544.42	Replace	Replace	No
689600W860			TAIL GATE STAY ASSY , BACK DOOR , LH	1	235.00	25.00	176.25	Replace	Replace	No
689500W860			TAIL GATE STAY ASSY , BACK DOOR , RH	1	235.00	25.00	176.25	Replace	Replace	No
6935047050			TAIL GATE LOCK ASSY, BACK DOOR	1	452.10	10.00	406.89	Replace	Replace	No
6932147010			TAIL GATE LOCK COVER , BACK DOOR	1	25.30	25.00	18.97	Replace	Replace	No
7680147110A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	25.00	668.40	Replace	Replace	No
7540348010			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.72	Replace	Replace	No
7544147090			NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No
7544247130			NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No
	REAR		NUMBER PLATE	1	30.00	0.00	30.00	Replace	Replace	No
			NUMBER PLATE FRAME	1	25.00	0.00	25.00	Replace	Replace	No
8127033110			LAMP ASSY, LICENSE PLATE	2	63.70	10.00	114.66	Replace	Replace	No
867B047010			CAMERA REAR ASSY, TELEVISION	1	1,103.80	10.00	993.42	Replace	Replace	No
8484047040			SWITCH ASSY, BACK DOOR OPENER	1	149.40	10.00	134.46	Replace	Replace	No
	COMMON		SEALANT W/SCREEN	3	37.00	0.00	111.00	Replace	Replace	No
6943052050			TAIL GATE STRIKER ASSY, BACK DOOR	1	24.90	25.00	18.67	Replace	Replace	No
7481147020C0			TAILGATE BOARD , HANDLE PULL	1	19.50	25.00	14.62	Replace	Replace	No
6775047080C0			TAILGATE BOARD ASSY	1	251.50	25.00	188.62	Replace	Replace	No
6793847060C0			TAILGATE TRIM , LH	1	92.10	25.00	69.07	Replace	Replace	No
6775147110C0			TAILGATE TRIM , LOWER	1	218.50	25.00	163.87	Replace	Replace	No
6793747060C0			TAILGATE TRIM , RH	1	92.10	25.00	69.07	Replace	Replace	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
6479047060C0			TAILGATE TRIM , UPPER	1	50.50	25.00	37.87	Replace	Replace	No
8218447490			WIRE, TAIL GATE BACK DOOR,	1	246.80	10.00	222.12	Replace	Replace	No
8218547150			WIRE, TAIL GATE BACK DOOR , NO.2	1	246.80	10.00	222.12	Replace	Replace	No
7608547916			SPOILER SUB-ASSY, REAR	1	1,322.10	25.00	991.57	Replace	Replace	No
8100647030			LAMP SET, STOP CENTER	1	186.50	10.00	167.85	Replace	Replace	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No
	COMMON		STICKER DECAL 65558888	1	21.60	0.00	21.60	Replace	Replace	No
5830747090			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	25.00	472.35	Replace	Replace	No
6471847080C0			END PANEL , COVER, DECK TRIM SERVICE HOLE	1	47.00	25.00	35.25	Replace	Replace	No
6471647130C0			END PANEL , COVER, DECK TRIM, REAR	1	122.80	25.00	92.10	Replace	Replace	No
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No
5831147130			SPARE TYRE PANEL , PAN, REAR FLOOR	1	564.80	25.00	423.60	Replace	Replace	No
5835047010			REINFORCEMENT ASSY, REAR FLOOR END PANEL , RH & LH	2	56.70	25.00	85.05	Replace	Replace	No
5760347060			MEMBER SUB-ASSY, REAR FLOOR SIDE , REAR RH	1	268.60	25.00	201.45	Replace	Replace	No
5760447060			MEMBER SUB-ASSY, REAR FLOOR SIDE , REAR LH	1	268.60	25.00	201.45	Replace	Replace	No
6788147050			TAIL GATE WEATHERSTRIP, BACK DOOR	1	360.70	25.00	270.52	Replace	Replace	No
5193147030			CARRIER, SPARE WHEEL	1	20.00	25.00	15.00	Replace	Replace	No
6499747060			BOX, DECK FLOOR, LH	1	303.40	25.00	227.55	Replace	Replace	No
6499547050			BOX, DECK FLOOR, RH	1	304.00	25.00	228.00	Replace	Replace	No
5841547110C2			BOARD, REAR FLOOR, NO.1	1	502.20	25.00	376.65	Replace	Replace	No
6474047190C2			PANEL ASSY, DECK TRIM SIDE, LH	1	344.70	25.00	258.52	Replace	Replace	No
6473047240C2			PANEL ASSY, DECK TRIM SIDE, RH	1	344.70	25.00	258.52	Replace	Replace	No
6101847010			MEMBER SUB-ASSY, RAIL ROOT SIDE REAR LH	1	279.20	25.00	209.40	Replace	Replace	No
6101747010			MEMBER SUB-ASSY, RAIL ROOT SIDE REAR RH	1	279.20	25.00	209.40	Replace	Replace	No
8156147151			LENS & BODY, REAR COMBINATION LAMP , LH	1	438.10	10.00	394.29	Replace	Replace	No
6162247060			TROUGH, BACK DOOR , LH	1	99.80	25.00	74.85	Replace	Replace	No
6160247160			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	25.00	618.60	Replace	Replace	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
6294047010			DUCT ASSY, QUARTER VENT , RH & LH	1	65.00	25.00	48.75	Replace	Replace	No
6563847060			LINER, REAR FENDER , LH	1	135.80	25.00	101.85	Replace	Replace	No
			TYRE	1	126.74	0.00	126.74	Replace	Replace	No
4261147450			WHEEL, DISC	1	1,555.10	25.00	1,166.32	Replace	Replace	No
TOTAL MATERIALS							16,531.69	16,531.55		
TOTAL MATERIALS(Discounted)							16,531.55	16,531.55		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									