

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/OD/0564/2018/PH  
Date : 14-May-18

Vehicle not in workshop. Kindly arrange for survey.

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Nishant Kumar  
Address : Blk 54 Keppel Bay View  
#08-18  
Singapore 098404  
Telephone : HP 97291162  
Type of Claim : Own Damage Claim  
Policy No. : 2100335138-04000  
Vehicle No : **SKJ 4399 R**  
Model Code : Audi Q3 2.0 TFSI QU  
Model / Year : Mar-13  
Engine No : CCZ 264059  
Chassis No : WAUZZZ8U9CR053673  
Mileage : -  
Date In :  
Liability : -  
Excess Cost : -  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 19-Nov-17  
Place of Accident : RIVER VALLEY ROAD

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SKJ 4399 R

| S/N            | Nature of Jobs                                                                                                                                                                      | Estimated Charges           |
|----------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|
| 1              | To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.                                                   | S/N \$ 360.00 ✓             |
| 2              | To remove and transfer rhs front door's multi-lock system and power window devices.                                                                                                 | S/N \$ 280.00 ✗             |
| 3              | To dismantle and renew front bumper, rhs front fender, headlight and rhs front door. Align to position. Re-organise front crash management components. Reinstall all parts removed. | \$ <del>3,150.00</del> 1500 |
| 4              | To respray front bumper, rhs front fender, bonnet and rhs front door.                                                                                                               | \$ <del>3,400.00</del> 2200 |
| 5              | To renew rhs front rim and carry out wheel alignment                                                                                                                                | S/N \$ 280.00 ✓             |
| 6              | To carry out diagnostic check                                                                                                                                                       | S/N \$ 192.00 ✓             |
| LABOUR CHARGES |                                                                                                                                                                                     | : \$ <u>7,662.00</u>        |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No SKJ 4399 R.

| S/N                        | Parts Description                              | Damage Parts & Prices |         |
|----------------------------|------------------------------------------------|-----------------------|---------|
|                            |                                                | S/NETT                | REMARKS |
| 1                          | FRONT BUMPER <i>del</i>                        | 1 \$ 1,664.00         | ✓       |
| 2                          | FRONT BUMPER SPOILER <i>at</i>                 | 1 \$ 334.00           | ✓       |
| 3                          | 1 SET FIXING PARTS FOR FRONT BUMPER <i>Hea</i> | 1 \$ 94.00            | +       |
| 4                          | TRIM - RH <i>at</i>                            | 1 \$ 21.00            | ✓       |
| 5                          | AIR GUIDE GRILLE - RH <i>at</i>                | 1 \$ 103.00           | ✓       |
| 6                          | FRONT FENDER - RH <i>Drilled</i>               | 1 \$ 796.00           | ✓       |
| 7                          | ATTACHMENT PARTS FOR ONE FENDER <i>mr</i>      | 1 \$ 60.00            | ✓       |
| 8                          | BRACKET FOR FENDER - FRONT RIGHT <i>Best</i>   | 1 \$ 72.00            | ✓       |
| 9                          | BRACE WING - RIGHT FRONT <i>Best</i>           | 1 \$ 92.00            | ✓       |
| 10                         | WHEEL COVER - FRONT LH <i>2m</i>               | 1 \$ 227.00           | ✓       |
| 11                         | WHEEL COVER - FRONT RH                         | 1 \$ 227.00           | ✓       |
| 12                         | HEADLIGHT FOR GAS DISCHARGE LAMP <i>at</i>     | 1 \$ 1,819.00         | ✓       |
| 13                         | RETAINING PLATE - RH <i>mr</i>                 | 1 \$ 76.00            | k       |
| 14                         | MOUNTING FOR MAIN BEAM HEADLIGHT <i>mr</i>     | 1 \$ 103.00           | ✓       |
| 15                         | DOOR - FRONT RH <i>Repis</i>                   | 1 \$ 2,294.00         | x       |
| 16                         | FRONT OUTER DOOR SEAL - RH <i>mr</i>           | 1 \$ 144.00           | x       |
| 17                         | PROTECTIVE FILM <i>mr</i>                      | 1 \$ 22.00            | ✓       |
| 18                         | 1 SET OF ATTACHMENT PARTS FOR DOOR <i>2m</i>   | 1 \$ 92.00            | +       |
| 19                         | DOOR CATCH <i>mr</i>                           | 1 \$ 105.00           | k       |
| 20                         | COVER FOR DOOR - FRONT RH <i>mr</i>            | 1 \$ 224.00           | x       |
| <b>SPARE PARTS CHARGES</b> |                                                | <b>\$ 8,569.00</b>    |         |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No SKJ 4399 R.

| S/N                       | Parts Description            | Damage Parts & Prices |              |
|---------------------------|------------------------------|-----------------------|--------------|
|                           |                              | S/NETT                | REMARKS      |
| 21                        | DOUBLE-SIDE ADHESIVE TAPE    | 1 \$                  | 53.00        |
| 22                        | DATA PLATE FOR TYRE PRESSURE | 1 \$                  | 36.00        |
| 23                        | ALUMINIUM RIM                | 1 \$                  | 687.00       |
| 24                        | SUNDRIES                     | \$                    | 300.00       |
| TOTAL SPARE PARTS CHARGES |                              | :                     | \$ 9,551.00  |
| TOTAL LABOUR CHARGES      |                              | :                     | \$ 7,662.00  |
| GRAND TOTAL               |                              | :                     | \$ 17,213.00 |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Adrian Lim  
Surveyed Date : 16/05/18  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : Not Authorised, 06 days

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant