

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Josey Loh

Date: 03 Jun 2018

## **Preliminary Advice**

Insured Vehicle No	: FBH9357X	Accident Date	: 08/05/2018
TP Vehicle No	: SKZ8965X	Assignment Date	: 16/05/2018
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 4 days
Date of Inspection	: 15/05/2018		
Inspection At	: Ban Choon Motor Works (HQ) Blk 3 Pioneer Road North #01-15 Singapore 628457		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages ...rear.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,593.23
Revised Amount	:S\$	2,086.05
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,086.05
Lump Sum Repair	:S\$	

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : We have not authorized repairs.