



萬 春 摩 哆

BAN CHOON MOTOR WORKS

Blk 3, Pioneer Road North #01-14/15 Singapore 628457

Tel: 6264 1191 Fax: 6261 1324

E-mail: banchoon@singnet.com.sg

Business Reg./GST Reg. No. 351915/00A

GST Regn No. 35191500A

14/05/2018

FWD Singapore Pte Ltd
6 Temasek Boulevard
#18-01 Suntec Tower Four
Singapore 038986

Attn: Motor Claims Dept.

Dear Sirs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

QUOTATION FOR REPAIRS OF VEHICLE NO. SKZ 8965 X
MODEL: TOYOTA COROLLA ALTIS
DATE OF ACCIDENT: 08/05/2018
YOUR INSURED VEHICLE NO. FBH 9357 X

1 pc	Rear boot cover	\$	980.30	Ry
1 pc	Centre logo		65.20	ne
1 pc	COROLLA emblem		51.30	ne
1 pc	ALTIS emblem		51.20	ne
1 pc	Rear bumper		380.10	mis
2 pcs	Rear bumper reflectors @ \$131.20 each		262.40	mis
1 pc	Rear bumper reinforcement		371.20	bt
2 pcs	Rer bumper side retainers @ \$171.30 each		342.60	X
		\$	2,504.30	
	Less: 25% discount		626.07	
		\$	1,878.23	
1 pc	Reverse sensor		380.00	SN 200nw
1 pc	Rear number plate		35.00	SN X

LABOUR CHARGES:

To knocking and straightening of all necessary damaged parts.
To changing of the above parts
To putty and spray painting on accident damaged parts.

	600.00	400.
	700.00	600
\$	3,593.23	

Yours faithfully,

Peelindayo

Tanjiun 97495749
-wp

15/5/18 21440.

sun@lkkauto.com

4 days

~~banchoon~~

Resurvey before paint.