



萬 春 摩 哆

BAN CHOON MOTOR WORKS

Blk 3, Pioneer Road North #01-14/15 Singapore 628457

Tel: 6264 1191 Fax: 6261 1324

E-mail: banchoon@singnet.com.sg

Business Reg./GSTReg. No. 351915/00A

GST Regn No. 35191500A

14/05/2018

FWD Singapore Pte Ltd
6 Temasek Boulevard
#18-01 Suntec Tower Four
Singapore 038986

Attn: Motor Claims Dept.

Dear Sirs

QUOTATION FOR REPAIRS OF VEHICLE NO. SKZ 8965 X

MODEL: TOYOTA COROLLA ALTIS

DATE OF ACCIDENT: 08/05/2018

YOUR INSURED VEHICLE NO. FBH 9357 X

1 pc	Rear boot cover	\$	980.30	
1 pc	Centre logo		65.20	
1 pc	COROLLA emblem		51.30	
1 pc	ALTIS emblem		51.20	
1 pc	Rear bumper		380.10	
2 pcs	Rear bumper reflectors @ \$131.20 each		262.40	
1 pc	Rear bumper reinforcement		371.20	
2 pcs	Rer bumper side retainers @ \$171.30 each		342.60	
		\$	2,504.30	
	Less: 25% discount		626.07	
		\$	1,878.23	
1 pc	Reverse sensor		380.00	SN
1 pc	Rear number plate		35.00	SN

LABOUR CHARGES:

To knocking and straightening of all necessary damaged parts.

To changing of the above parts

To putty and spray painting on accident damaged parts.

600.00
700.00
<u>\$ 3,593.23</u>

Yours faithfully,

Pelindayo