

REF: ALG

8925/05

COE Oct 2024

ASSIGNMENT

From Date: 14052018

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SHA 2071G

at Workshop m/s

Chunni Motor

of

AMK

Insured

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

867

days

Res: Yes or No

Lum Sum:

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SHA 2071G

Yr Regn: 2016 / Oct

Type: M/Car / M/Cycle / Bus / Van / Lorry / ☒ Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai I40

C.C. 1685

Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 210730

T/Radio: Insured / Std / NI / NA

Eng/No: D4FDGU683661

C/No:

KMHLP41UMEU056177

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: ☒ M / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60 R 16

R:

— — —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal:

S

mm

R/Bal:

S

mm

L/Bal:

S

mm

L/Bal:

S

mm

D.O.A:

09/05/2018

D.O.I:

14/05/2018

Survey held at

Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S Front

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

08/01/18

ALG SSD 2312 Y

Jmrg 4/5 10,960/- with 8 dgs 2 yr

DOA - 9 May W 13

10 T 10

11 F 4

12 > 5 10

13 > 5 9

DOI - 14 M 1

15 T 2

16 W 3

17 T 6

18 F 5

19 > 5 1

20 > 5 1

21 M 1

22 T 7

R(\$7,507.50/4.7.)

Date/Time: File Pass to?



Prel. Report

Days Of Repair:

1)



Final Report

Resurvey No. of Trip:

Date/Time: File Return to?

2)

Add Fee:



Site Insp (\$



Interview (\$



Tech Inps (\$



Week-end (\$

Report Format :

Lump Sum / I.B.I: (\$

Survey Fee

Transportation

1 \$ = P.L. \$1

1 Photo

1 Other

1

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC4/AIG18008925/Dja3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 16-05-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJD 2312Y	Veh. Inspected	SHA 2071G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	16/05/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	09/05/2018	Inspection Date	14/05/2018
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

CO Surveying LKK 1

FAX : 6542 6039 AIG

11933.72

SHA 2071G

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,300.00
	Spray Painting Charge			\$ 750.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Towing Charge			\$ 50.00
	Remove/Refix Undercarriage (FRT)			\$ 200.00
	FRT Wheel Alignment			\$ 120.00
	Remove/Refix Dashboard			\$ 200.00
			1760/-	
	TOTAL LABOUR			\$ 2,720.00
	ESTIMATE TOTAL			\$ 18,457.60
				13693.72
				4510,950/-

14/05/2018 @ 1330m
 LRT Aulm
 L13mm # 8
 6 deg

 LKK Auto


LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHA 2071 G

Technician:

Mileage: 210730

Time Printed 14.5.18 1:43 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
11°26'		-3°00' 3°00'
4°16'		-0°19' 5°41'
19°15'		-1°30' 1°30'
6°05'		
17°31'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
2°16'		-3°00' 3°00'
4°10'		-0°19' 5°41'
-0°12'		-1°30' 1°30'
13°44'		
16°00'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
9°10'		-3°00' 3°00'
0°06'		-3°00' 3°00'
-7°39'		-3°00' 3°00'
19°03'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-1°50'		-3°30' 2°30'
0°30'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°29'		-3°30' 2°30'
-0°13'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
-0°22'		-3°00' 3°00'
0°17'		-3°00' 3°00'
0°21'		-3°00' 3°00'

UNDERTAKING

I, _____, (NRIC No. _____), hereby confirm that the Singapore Accident Statement lodged by me on _____ at _____ hours pertaining to the accident involving motor car Reg. No: _____, in which I was the driver are true and accurate to the best of my knowledge, information and belief.

I acknowledge that my insurers are not liable under the contract of insurance if there is a breach of policy terms and conditions.

In the event that an unrelated/unreported third party property or injury claim arises or there is evidence emerges that there is a breach of policy terms and conditions, I irrevocably undertake to absolve my insurer from all liability under the contract of insurance and I undertake to re-pay any sums paid by my insurers pursuant to the contract of insurance upon receipt of written demand by my insurers.

Signature : _____
Name of Insured / Driver : _____
Nric No. : _____
Date : _____

Signature : _____
Name of Policyholder : _____
Nric No. : _____
Date : _____



AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way
#07-16

MOTOR ACCIDENT INTERVIEW FORM

NAME (DRIVER) : _____
VEHICLE NUMBER : _____
DATE/TIME OF ACCIDENT : _____
PLACE OF ACCIDENT : _____
THIRD PARTY VEHICLE (IF ANY) : _____

WHERE DID YOU START YOUR JOURNEY AND WHERE WAS THE INTENDED
DESTINATION BEFORE THE ACCIDENT?

DID YOU DRINK ANY ALCOHOLIC DRINKS BEFORE YOU DRIVE ON THE DAY OF
THE ACCIDENT? IF YES, DID THE TRAFFIC POLICE CONDUCT ANY BREATHE-
ANALYSER TEST ON YOU? IF YES, WHAT IS THE RESULT?

WHAT IS THE TYPE OF COLLISION AND THE EXTENSIVENESS OF THE DAMAGES
TO ALL VEHICLES INVOLVED?

WERE YOU OR YOUR PASSENGER/S INJURED? IF INJURED, WHICH HOSPITAL?
WERE YOU TAKEN TO THE TRAFFIC POLICE FOR INVESTIGATION?

.....

Name:

I Affirmed The Above Information Is Given To My Best Knowledge.

Your Ref : SJD 2312Y
Our Ref : SHA 2071G

Peh Bock Chua c/o
CHUNNI MOTOR WORK PTE LTD
Blk 10 Ang Mo Kio Industrial Park 2A
#03-19 AMK AutoPoint
Singapore 568047

Date : 12/06/18

The Motor Claims Department

AG 96 LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Ind park
Singapore 408933

WITHOUT PREJUDICE

Dear Sir / Madam,

RE: ACCIDENT INVOLVING SHA 2071G/SJD 2312Y On 09/05/2018

ALONG Upper Serangoon Rd Twds Hougang After Upper Aljunied Rd Junction

I am the owner/hirer of motor vehicle/taxi, SHA 2071G, which was involved in the above-mentioned accident.

The motor vehicle/taxi was surveyed by your appointed appraiser at the premises of M/S CHUNNI MOTOR WORK PTE LTD. The accident was caused by your insured's negligent driving and or management of his vehicle. Therefore, I am claiming damages and losses sustained by me against you in connection with the accident based on the appraiser's recommendation.

Our claim is as follows:

1) Cost of Repair	S\$ 11,716.50
2) Loss of Rental	S\$ 1,521.00
3) Loss of Income	S\$ 650.00
4) GIA Report Fee	S\$
5) LTA Search Fee	S\$ 2.00
6) Survey Report Fee	S\$
	<u>S\$ 13,889.50</u>

We enclose herewith the following relevant supporting documents :

- a) Authorisation Letter
- b) Final repair bill(s)
- c) LTA Search
- d) GIA report(s)
- e) Insurance Certificate

Kindly look into the matter and revert as soon as possible. Thank you.

Yours faithfully



Attached LTA OISC 1

TAX INVOICE

PEH BOCK CHUA APT BLK 146 SERANGOON NORTH AVE 1 #04-407 SINGAPORE 550146	VEHICLE NO	DATE
	SHA 2071 G	07.06.2018
	MAKE	INVOICE NO
	HYUNDAI	8066
	MODEL	ACC DATE/TIME
	I40	09.05.2018 @ 23:40 HRS

Cost of Repair \$ 10,950.00

Sub-total \$ 10,950.00

Add : 7 % - GST \$ 766.50

Total \$ 11,716.50

(SINGAPORE DOLLARS ELEVEN THOUSAND SEVEN HUNDRED AND SIXTEEN
AND CENTS FIFTY ONLY)



LETTER OF AUTHORITY

To Whom It May Concern :

ACCIDENT INVOLVING **SHA 2071G/SJD 2312Y**

ALONG Upper Serangoon Rd Twds Hougang Aft ON 09/05/2018
Upper Aljunied Rd Junction


I, Peh Bock Chua, NRIC NO. S 1428670E of
Blk 146 Serangoon North Avenue 1 # 04-407 (S) 550146

Owner/hirer of motor vehicle Registration No **SHA 2071G**, insured by
India International Insurance Pte Ltd under Policy No. MCOM 0016

do hereby authorize M/s **Chunni Motor Work Pte Ltd** as my authorized representative to write,
negotiate and settle claim on my behalf in my claim against the owner and/or Motor Vehicle
Registration No. **SJD 2312Y** in respect of the above mentioned accident. I also
hereby authorize that the agreed settlement sum (cost of repair, loss of use, earnings and rental,
Survey report fee, LTA fee & GIA report fee) be made in favour of my representative, M/s
Chunni Motor Work Pte Ltd and that the said payment be forwarded to them as full and final
discharge of my claim.

Dated : 09/05/2018

Signature :


(Company's chop if necessary)

Our Ref: CT18050243

Date: 15 May 2018



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON	09/05/2018 @ 23:40 hrs
ALONG	UPPER SERANGOON RD TWDS HOUGANG AFTER UPPER ALJUNIED RD JUNCTION
INVOLVING	SJD2312Y

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHA2071G** (the "Taxi"). The Taxi was hired to **PEH BOCK CHUA IC NO S1428670E** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$117.00** per day (inclusive of GST).

Please be advised that the Taxi was insured with **India International Insurance Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

DATA 20716

DATE	NAME OF DRIVER	MILEAGE READING	MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)	
				FROM	TO
4/5	P L Lee	208959	158	2315	0300
5.5.18	Peh BC	209152	193	150pm	955p
5/5/18	P L Lee	209418	266	2310	0655
6/5/18.	Nagarajan	209650	214.	08.20	17.25
6.5.18	Peh BC	209755	216	530pm	1030p
7.5.18	Peh BC	209977	221	700AM	1020p
7/5/18	P L Lee	210101	124	2300	0325
8.5.18	Peh BC	210354	253	700AM	957p
8/5/18	P L Lee	210484	130	2300	0300
9.5.18	Peh BC	210705	220	700AM	1003p
9/5/18	P L Lee	210729	24	2300	0002

STARTED (TIME)	DATE	NAME OF DRIVER	MILEAGE READING	MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)	
					FROM	TO
0300	10/5/2018	Peh Boek Chua	Accident		00:15	2145
955p	22/5/2018	Peh Boek Chua	Repair		2145	13:00
0655						
7.22						
1030p						
1020p						
0325						
957p						
0300						
1003p						
0002						

Invoice

<https://www.giarmc.org.sg/claims/index.cfm?fusebox=MTRsas&fusca...>

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-071077

Date of Request: 10/05/2018

Your Ref No:

Online Purchase

Soon Hock Motor Pte Ltd
Blk 10 Ang Mo Kio Industrial Park 2A
#01-05/06 AMK Autopoint
Singapore 568047

Dear Sir/Madam,

Enquiry Date: 10/05/2018
Enquiry By: Chris Lim Gan Koon
TP Vehicle No.: SJD2312Y
Accident Date: 09/05/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJD2312Y	AIG Asia Pacific Insurance Pte. Ltd.	05/01/2018-25/04/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

Invoice

<https://www.giarmc.org.sg/claims/index.cfm?fusebox=MTRsas&fusea...>

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-071077

Date of Request: 10/05/2018

Your Ref No: Online Purchase

Soon Hock Motor Pte Ltd
Blk 10 Ang Mo Kio Industrial Park 2A
#01-05/06 AMK Autopoint
Singapore 568047

Dear Sir/Madam,

Enquiry Date 10/05/2018
Enquiry By Chris Lim Gan Koon
TP Vehicle No. SJD2312Y
Accident Date 09/05/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Friday, 10 August 2018 3:35 PM
To: 'Loh, Chee-Heng'
Cc: Admin A
Subject: RE: 9279209581SG-003 - Urgent

Dear Chee Heng,

- 1) Yes. OI cleared. According to OID, he did not stop as he did not realized that he had hit TP vehicle.
- 2) Photos and survey report in Merimen.

We will proceed to submit wp report.

Thank you.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Loh, Chee-Heng [mailto:Chee-Heng.Loh@aig.com]
Sent: Wednesday, 8 August 2018 5:20 PM
To: Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>
Subject: 9279209581SG-003 - Urgent

Dear Joy,

We are having a bulk settlement with Chunni.

Kindly assist on the below.

- 1) Has insured been cleared on liability, BOLA 15?
- 2) To upload WP report and photos in Merimen by 10 Aug 2018 for our assessment.

Thank you.

Best regards,
Loh Chee Heng
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)
Tel +(65) 6419 1881 | Fax +(65) 6835 7416
Chee-Heng.Loh@aig.com | www.aig.com.sg

Follow us:

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 May 2018 Edit Reg		11 May 2018 00:00 Edit Adj Rpt	\$10,950.00 Edit Estimates	\$10,950.00 View Rpt		Pending for Survey Report Cancel Case


















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	MELVIN CHUA BENG LEE (CAI MINGYI) , ID: S7112372C								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHA2071G	Date of Loss:	09/05/2018 23:00 - :59 [18 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 9279209581SG	Policy/Cover Note No.:	2100496928-01 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJD2312Y	Policy No. (Claimant):	MCOM0015						
		Excess:							
Repairer:	Chunni Motor Work Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6542 7162								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 25/05/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (31/05/2018): Re: No OI GIA Report AIG_SG (17/05/2018): No OI GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHA2071G (9279209581SG)**
[SJD2312Y]
TP
COMFORT TRANSPORTATION PTE LTD
May 9 2018 11:40PM
[MELVIN CHUA BENG LEE (CAI MINGYI)]
Chunni Motor Work Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Video															1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print		
1	05/07/18 15:21	TP video - SHA2071G													Load MP4			
Assessment Reports															1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print		
1	05/07/18 15:23	Accident Statement From: SC - Reg. No: SJD2312Y, Claimant: MELVIN CHUA BENG LEE (CAI MINGYI)													Load HTM			
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	05/06/18 18:07	Front View Right													Load JPG	<input checked="" type="checkbox"/>		
2	05/06/18 18:07	Front View Left													Load JPG	<input checked="" type="checkbox"/>		
3	05/06/18 18:07	General View													Load JPG	<input checked="" type="checkbox"/>		
4	05/06/18 18:07	General View													Load JPG	<input checked="" type="checkbox"/>		
5	05/06/18 18:07	General View													Load JPG	<input checked="" type="checkbox"/>		
6	05/06/18 18:07	General View													Load JPG	<input checked="" type="checkbox"/>		
7	05/06/18 18:07	General View													Load JPG	<input checked="" type="checkbox"/>		
8	05/06/18 18:07	General View													Load JPG	<input checked="" type="checkbox"/>		
9	05/06/18 18:07	General View													Load JPG	<input checked="" type="checkbox"/>		
10	05/06/18 18:07	General View													Load JPG	<input checked="" type="checkbox"/>		
11	05/06/18 18:07	General View													Load JPG	<input checked="" type="checkbox"/>		
12	05/06/18 18:07	General View													Load JPG	<input checked="" type="checkbox"/>		
13	05/06/18 18:07	General View													Load JPG	<input checked="" type="checkbox"/>		
14	05/06/18 18:07	General View													Load JPG	<input checked="" type="checkbox"/>		
15	05/06/18 18:07	General View													Load JPG	<input checked="" type="checkbox"/>		
16	05/06/18 18:07	General View													Load JPG	<input checked="" type="checkbox"/>		
17	05/06/18 18:07	General View													Load JPG	<input checked="" type="checkbox"/>		
18	05/06/18 18:07	General View													Load JPG	<input checked="" type="checkbox"/>		
19	05/06/18 18:07	General View													Load JPG	<input checked="" type="checkbox"/>		
20	05/06/18 18:07	General View													Load JPG	<input checked="" type="checkbox"/>		
21	05/06/18 18:07	General View													Load JPG	<input checked="" type="checkbox"/>		
22	05/06/18 18:07	General View													Load JPG	<input checked="" type="checkbox"/>		
23	05/06/18 18:07	General View													Load JPG	<input checked="" type="checkbox"/>		
24	05/06/18 18:07	General View													Load JPG	<input checked="" type="checkbox"/>		
25	05/06/18 18:07	General View													Load JPG	<input checked="" type="checkbox"/>		
26	05/06/18 18:07	General View													Load JPG	<input checked="" type="checkbox"/>		
27	05/06/18 18:07	General View													Load JPG	<input checked="" type="checkbox"/>		
28	05/06/18 18:07	General View													Load JPG	<input checked="" type="checkbox"/>		
29	05/06/18 18:07	General View													Load JPG	<input checked="" type="checkbox"/>		
30	05/06/18 18:07	General View													Load JPG	<input checked="" type="checkbox"/>		

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
31	05/06/18 18:07	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
32	05/06/18 18:07	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
33	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
81	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	05/06/18 18:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	05/06/18 18:09	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
100	05/06/18 18:09	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
101	05/06/18 18:09	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
102	05/06/18 18:09	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
103	05/06/18 18:09	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
104	05/06/18 18:09	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
105	05/06/18 18:09	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
106	05/06/18 18:09	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
107	05/06/18 18:09	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
108	05/06/18 18:09	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
109	05/06/18 18:09	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
110	05/06/18 18:09	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
111	05/06/18 18:09	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
112	05/06/18 18:09	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
113	05/06/18 18:09	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
114	05/06/18 18:09	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
115	05/06/18 18:09	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
116	05/06/18 18:09	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
117	05/06/18 18:09	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
118	05/06/18 18:09	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
119	05/06/18 18:09	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
120	05/06/18 18:09	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
121	05/06/18 18:09	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
122	05/06/18 18:09	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/05/18 18:22	ACKNOWLEDGEMENT EMAIL TO AIG DD 11.05.2018	 Load PDF	
2	16/05/18 18:22	EMAIL FROM AIG DD 11.05.2018	 Load PDF	
3	16/05/18 18:22	TP ESTIMATE + TP GIA REPORT	 Load PDF	
4	27/05/18 15:40	TP ESTIMATE - MARKED	 Load PDF	
5	27/05/18 15:40	WHEEL ALIGNMENT	 Load PDF	
6	01/06/18 09:28	Non reporting letter	 Load PDF	
7	10/08/18 15:25	GIA SEARCH	 Load PDF	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
8	10/08/18 15:25	RENTAL RECEIPT		Load PDF
9	10/08/18 15:38	EMAIL TO WP REPORT		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	05/07/18 15:18	TP GIA		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18008925/DJA3Q2

Date: 10/08/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100496928-01
Claimant Vehicle No : SHA2071G **Insured Vehicle No :** SJD2312Y
 Date of Loss: 09/05/2018 Nature of Claim: TP Claim No: 9279209581SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA2071G**
 Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A) Engine No: D4FDGU683661
 Reg. Date: 13/10/2016 (Man. Year: 2016) Chassis No: KMHLB41UMHU095309
 Colour: Blue Odometer: 210730 km
 Engine Capacity: 1685 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Hankook 5 mm Rear Left Side: Hankook 5 mm
 Front Right Side: Hankook 5 mm Rear Right Side: Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,737.60	11,933.72	3,803.88	24.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,720.00	1,760.00	960.00	35.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,457.60	13,693.72	4,763.88	25.81
Approved Total (Overridden) (S\$)		10,950.00		
(S\$)	18,457.60	10,950.00	7,507.60	40.67
+ GST 7.00/7.00% (S\$)	1,292.03	766.50	525.53	40.67
Nett Amount (S\$)	19,749.63	11,716.50	8,033.13	40.67
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 11/05/2018
 Date Inspected: 14/05/2018 Inspected At: Chunni Motor Work Pte Ltd (HQ)
 Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint
 Singapore 568047

Estimated Period of Repair: 8.0 days

Adjuster: BRYAN TANI**Manager:** Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Dented	1,052.20 FL	*1,052.20 FL
2	1		*FRONT BUMPER SPONGE	Torn	142.20 FL	*142.20 FL
3	1		*FRONT BUMPER REINFORCEMENT	Bent	526.10 FL	*526.10 FL
4	1		*FRONT BUMPER GRILLE (LH)	Not Necessary	285.50 FL	*- FL
5	1		*FRONT BUMPER GRILLE AIRDUCT (LH)	Not Necessary	155.00 FL	*- FL
6	1		*FRONT BUMPER BRACKET TOP (LH)	Not Necessary	22.40 FL	*- FL
7	1		*FRONT BUMPER BRACKET (LH)	Not Necessary	24.60 FL	*- FL
8	1		*FRONT BUMPER RETAINER MOUNTING	Not Necessary	9.20 FL	*- FL
9	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	398.00 FL	*- FL
10	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	1,067.50 FL	*1,067.50 FL
11	1		*HEADLAMP (LH)	Mtg Broken	1,388.00 FL	*1,388.00 FL
12	1		*FRONT FENDER (LH)	Dented	619.00 FL	*619.00 FL
13	1		*FRONT FENDER APRON PANEL (LH)	Dented	1,575.50 FL	*1,575.50 FL
14	1		*FRONT FENDER SHIELD (LH)	Deformed	169.80 FL	*169.80 FL
15	1		*FRONT WHEEL RIM (LH)	Bent	351.90 FL	*351.90 FL
16	1		*FRONT WHEEL HUB CAP (LH)	Cracked	150.70 FL	*150.70 FL
17	1		*FRONT WHEEL BEARING	Damaged	258.50 FL	*258.50 FL
18	1		*FRONT SHOCK ABSORBER (ASSY) (LH)	Distorted	342.20 FL	*342.20 FL
19	1		*FRONT SHOCK ABSORBER MOUNTING (LH)	Not Necessary	75.10 FL	*- FL
20	1		*FRONT DRIVE SHAFT (LH)	Not Necessary	1,069.55 FL	*- FL
21	1		*RACK & PINION ASSY	Not Necessary	2,184.00 FL	*- FL
22	1		*STG TIE END	Distorted	69.50 FL	*69.50 FL
23	1		*FRONT SUSPENSION LOWER ARM (LH)	Distorted	715.10 FL	*715.10 FL
24	1		*KNUCKLE ARM (LH)	Distorted	582.95 FL	*582.95 FL
25	1		*ENGINE UNDER COVER	Torn	343.10 FL	*343.10 FL
26	1		*ENGINE CROSSMEMBER	Distorted	2,236.90 FL	*2,236.90 FL
27	1		*ABS SENSOR ,LH	Not Necessary	261.50 FL	*- FL
28	1		*WIRING -ENGINE	Broken	3,326.00 FL	*3,326.00 FL
29	1		*FRONT TYRE (LH)	Serviceable	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,618.00	14,917.15
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,880.40	2,983.43
Total Parts (\$\$)	15,737.60	11,933.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,300.00	800.00
2	SPRAY PAINTING CHARGE	New	750.00	500.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	50.00	40.00
5	TOWING CHARGE	New	50.00	0.00
6	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	200.00	180.00
7	FRT WHEEL ALIGNMENT	New	120.00	60.00
8	REMOVE/REFIX DASHBOARD	New	200.00	150.00
Gross Labour Cost (\$\$)			2,720.00	1,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >