

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

not all MARCUS.

14/5/2018

M/S LONPAC INCURANCE

ESTIMATE REPAIR COST FOR SJU 6053D

S/N	QTY	DESCRIPTION			
1	1 PC	FRONT RH DOOR			
2	1 PC	FRONT RH FENDER			
3	1 PC	FRONT RH FENDER SHIELD			
4	1 PC	FRONT HEADLAMP RH			
5	1 PC	BONNET			
6	2 PCS	BONNET HINGE			
7	1 PC	FRONT BUMPER			
8	1 PC	FRONT BUMPER CLIPS (1 set)			
9	1 PC	FRONT BUMPR SIDE RETAINER			
10	1 PC	FRONT BUMPER REINFORCEMENT			
11	1 PC	FRONT BUMPER SPONGE			
12	1 PC	FRONT BUMPER RH FOG LAMP COVER			
13	1 PC	FRONT BUMPER RH FOG LAMP			
14	1 PC	GRILLE BADGE			
15	1 PC	GRILLE			
16	1 PC	WIPER TANK			
17	1 PC	SUPPORT PANEL			
		LESS 25%			
18		CHECK WIRING			
19		LABOUR CHARGE TO REMOVE AND RENEW FRONT PARTS			
20		SPRAY PAINTING			
21		TUFF KOTE			
22		TO REMOVE AND REFIX AIRCON PART REFILL FREON GAS			

	\$	1,439.20	X
Buc	\$	707.42	✓
700m	\$	124.10	✓
300	\$	689.45	✓
m / Buc	\$	707.00	✓
set / m	\$	178.20	✓
Dis	\$	698.10	✓
ner	\$	40.00	✓
set	\$	110.35	✓
	\$	329.00	?
To.1	\$	108.00	✓
2m/m	\$	95.30	✓
one	\$	208.10	✓
ner	\$	87.30	✓
11	\$	207.00	X
20	\$	104.20	✓
	\$	860.45	?
	\$	6,693.17	
	\$	(1,673.29)	
	\$	5,019.88	
	\$	35.00	20
	\$	780.00	600
	\$	1,000.00	850
	\$	80.00	60
	\$	160.00	?
	\$	7,074.88	

LK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- This estimate is not to be used for any other purpose
- This estimate is not to be used for any other purpose

Acknowledged by Repairer

Signature:

Date: