

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

14/5/2018

M/S LONPAC INCURANCE

ESTIMATE REPAIR COST FOR SJU 6053D

S/N	QTY	DESCRIPTION		
1	1 PC	FRONT RH FENDER	\$	707.42
2	1 PC	FRONT RH FENDER SHIELD	\$	124.10
3	1 PC	FRONT HEADLAMP RH	\$	689.45
4	1 PC	BONNET	\$	707.00
5	2 PCS	BONNET HINGE	\$	178.20
6	1 PC	FRONT BUMPER	\$	698.10
7	1 PC	FRONT BUMPER CLIPS (1 set)	\$	40.00
8	1 PC	FRONT BUMPR SIDE RETAINER	\$	110.35
9	1 PC	FRONT BUMPER REINFORCEMENT	\$	329.00
10	1 PC	FRONT BUMPER SPONGE	\$	108.00
11	1 PC	FRONT BUMPER RH FOG LAMP COVER	\$	95.30
12	1 PC	FRONT BUMPER RH FOG LAMP	\$	208.10
13	1 PC	GRILLE BADGE	\$	87.30
14	1 PC	GRILLE	\$	207.00
15	1 PC	WIPER TANK	\$	104.20
16	1 PC	SUPPORT PANEL	\$	860.45
			\$	5,253.97
		LESS 25%	\$	(1,313.49)
			\$	3,940.48
17		CHECK WIRING	\$	35.00
18		LABOUR CHARGE TO REMOVE AND RENEW FRONT PARTS	\$	780.00
19		SPRAY PAINTING	\$	1,000.00
20		TUFF KOTE	\$	80.00
21		TO REMOVE AND REFIX AIRCON PART REFILL FREON GAS	\$	160.00
			\$	5,995.48