

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 52937738A
BOSI TECHNICAL SERVICES
NO 33 SEA AVE

SINGAPORE 424264
TEL : 96663592 FAX :
PH :
ATTN :

Term:

ESTIMATE BILL

Number : EB00004822
Date : 09/05/2018
Case No : AD00009721
Vehicle No : GQ2711X
Chassis : KDH2015022135
Year of Mfr : 2016
Policy No : 5083522173
Model : TOYOTA HIACE DX
3.0 M

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	TAIL GATE <i>30.500</i>	1.0	1,892.80	25	1,419.60
2	TAIL GATE DAMPER LH <i>17</i>	1.0	379.14	25	284.36
3	TAIL GATE DAMPER RH <i>17</i>	1.0	379.14	25	284.36
4	TAIL GATE INNER LOCK	1.0	297.70	25	223.28
5	TAIL GATE EMBLEM <i>new</i>	1.0	78.80	25	59.10
6	TAIL GATE LOGO - HIACE <i>new</i>	1.0	96.14	25	72.11
7	TAIL GATE LOGO - 70KM/H <i>new 105.N</i>	1.0	48.70	25	36.53
8	REAR END PANEL	1.0	695.70	25	521.78
9	REAR BUMPER <i>Dis</i>	1.0	571.40	25	428.55
10	REAR BUMPER STEP PANEL	1.0	608.60	25	456.45
11	REAR BUMPER CLIPS <i>new</i>	4.0	10.60	25	31.80
12	TAIL GATE RUBBER	1.0	427.80	25	320.85
13	BUMPER REVERSE SENSOR <i>1 set shell</i>	1.0	492.80	25	369.60
List Price - Parts Sub Total					4,508.37
Parts Total					4,508.37
14	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	900.00	0 <i>600</i>	900.00
15	SPRAY PAINT ON THE AFFECTED AREAS	1.0	900.00	0 <i>500</i>	900.00
16	TO REMOVE & REFIT WINDSCREEN	1.0	180.00	0 <i>120</i>	180.00
17	ANTI-RUST COATING	1.0	120.00	0 <i>50</i>	120.00
Labour 1 Sub Total					2,100.00
SINGAPORE DOLLARS SEVEN THOUSAND SEVENTY AND CENTS					Less Excess
NINETY-SIX ONLY					SUBTOTAL
					GST 7.00%
					TOTAL

Date of accident : 08/05/2018 09:30 PM. Place : SLIP RD OF TPE TOWARDS PASIR RIS DRIVE 8

E. & O. E.

Acknowledged by Repairer

Signature:

Date:

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE