

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 105/IC/TCAC/CCR/2018
DATE : 09-MAY-2018

FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER
S(038986)
TEL : 6820 8888
FAX :
ATTN : CLAIM MANAGER

OWNER'S NAME : M/S SHAW THEATRES PTE LTD
ADDRESS : 1 SCOTTS ROAD
#13-00 SHAW CENTRE
S(228208)
TELEPHONE NO : 96214267

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100489040-01
VEHICLE NO : GBF4691Z
MODEL CODE : YTKARUM20TWL-CAAC
MODEL/YEAR : NISSAN NV200 1.5L DIESEL VAN (II)
ENGINE NO : K9KC400D055850
CHASSIS NO : VSKYBAM20Z0130973
MILEAGE : 58261 KM
DATE IN : 09/05/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 09/05/2018

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749
21/5/18 01520
wp
Resurvey before paint
Sun C. Meantoun
8 days

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBF4691Z

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	?
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	480.00	360.
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	400.00	100.
4	WACI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION - COMMERCIAL	120.00	✓
5	ZZ/001	RENEW FRONT BUMPER, TOP RIGHT BUMPER PANEL, RIGHT HEADLAMP, FRONT RIGHT FENDER, PROTECTOR, RIM COVER,		
6	ZZ/002	FRONT RIGHT QUARTER GLASS, PANEL, FRONT RIGHT DOOR, RIGHT SLIDING DOOR, RIGHT OUTER SILL ETC		
7	ZZ/003	PANELS & REPAIRS	1900.00	950.
8	ZZ/004	REPLACE RIGHT FRONT & SLIDING DOOR COMPONENTS TO FACILITATE REPAIR	240.00	120.
9	ZZ/005	REPLACE 175/70/R14C TYRE	175.00	80% ant ✓
10	ZZ/006	RESPRAY TOP RIGHT BUMPER PANEL, FRONT RIGHT FENDER, FRONT RIGHT DOOR, REAR SLIDING DOOR, RIGHT OUTER		
11	ZZ/007	SILL, B-PILLAR ETC	1600.00	1000
12	ZZ/008	SUPPLY & REPLACE COMPANY REGISTRATION STICKER	15.00	✓
13	ZZ/009	QC, RETUNE & CONSULT CHECK		
14	ZZ/10	COMPLIMENTARY WASH & VACUUM		
TOTAL LABOUR CHARGES			4978.00	

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBF4691Z

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	RIGHT OUTER SILL	76410-BJ00C	1209.60	Rx	
2	RIGHT SLIDING DOOR	H2100-BJ1AC	1165.20	bt ✓	
3	FRONT RIGHT QUARTER GLASS	76820-3LG1A			228.00 X
4	FRONT RIGHT RIM COVER	40315-BJ01A	93.40	aut	
5	TAPE-FR DOOR,RH	80816-BJ00A	20.00	?	
6	FRONT RIGHT DOOR	H0100-BJ0MA	1651.80	?	
7	FRONT RIGHT QUARTER GLASS FINISHER	63870-BJ00A			45.20 mis
8	FENDER PROTECTOR	63840-BJ00A	138.90	?	
9	FRONT RIGHT FENDER	F3100-BJ0MA	504.70	bt ✓	
10	TOP RIGHT BUMPER PANEL	62024-BJ00H	225.00	Rx	
11	RIGHT FOG LAMP HOLDER	62256-JX00A	86.50	X	
12	RIGHT BUMPER BRACKET	62224-BJ00A	20.90	?	
13	FRONT BUMPER	62022-JX51H	589.70	aut ✓	
14	RIGHT FOG LAMP	26150-8992B			258.00 X
15	RIGHT HEADLAMP	26010-BJ00A	618.10	?	
SUB TOTAL			6323.80	0.00	531.20
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			1264.76	0.00	0.00
GRAND TOTAL			5059.04	0.00	531.20
OVERALL TOTAL			5590.24		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO GBF4691Z

TOTAL LABOUR CHARGES	4978.00
TOTAL SPARE PARTS CHARGES	5590.24

GRAND TOTAL	10568.24 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the
affected vehicle. Should we require further labour
charges & spare parts in the process of repairs, we
shall inform you accordingly.