

REF: 031/SPF18DD8935/Klvb

Special Instruction:

ASSIGNMENT (Office)

From (Person): Abdul Rehman of SPT Date/Time: 14/05/2018
Estimated Cost: _____ Bill to: _____

Partly Paid: ~~1659.47~~

Third Parties:

Claimant:

Surveyor: Vicom Ltd

Workshop: Comfort Delgado

OD/TP Re-inspection / (Evaluation)

To Inspect Vehicle No: SH 880BS Insured: AX 304X

at Workshop m/s _____ (Comfort Delgros)
of _____ 59 Legation Drive
Policy No: _____

Tel:

Policy No: _____ Claim No: AEED/105/DU9/2018/019

Sum Insured: _____ Excess: _____


Make of Veh: _____ D.O.A. 10-02-2018
(Client's Record)

(Client's Record) _____ D.O.A. _____ 10-02-2018
 _____ Do not Finalize
 H.O.D. Endorsement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 17/1/20 Confirmed with _____ Final Fig _____, _____ days (Red \$ _____ / _____ %; Original 3 days)

Date/Time: 17/5/18 Submit Final Fig \$1619.47, 3 days (Red \$ 40 / 2 %; Original days)

Date/Time	Action/Instruction
	SH 88036 - CC3/AXA 11002305 /Dg/Br! Gx 304X -X <div style="text-align: right;"> DCA: 31/07/2011  21/5/2018 </div>

Para(1) : Parts found not replaced	(To highlight R or UB , LR , Etc)
------------------------------------	---

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)	
--	--

RECEIVED 21 MAY 2018

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date: _____

1) Date/Time 21/5- 4:15 File Pass to

2) Date/Time _____ File Return to _____

3) Date/Time 01 File Pass to

4) Date/Time _____ File Return to _____

5) Date/Time: _____ File Pass to: _____

6) Date/Time _____ File Return to _____

Catherine Chong (LKK Auto)

From: Abdul Rahman MOHAMAD SALIM (SPF)
<Abdul_Rahman_Mohamad_Salim@spf.gov.sg>
Sent: Monday, 14 May, 2018 2:40 PM
To: Catherine Chong (LKK Auto)
Cc: 'Olivia Lau'; Rosalyn TAN (SPF); Frankie THAY (SPF)
Subject: SH8808S - Request Paper Survey
Attachments: SH8808S LOD of CDGE.pdf

Your Ref: SH8808S
Our Ref : AEMD/105/009/2018/019

Dear Cath,

Your preceding mail and our assignment on 1 Mar 2018 have reference.

Attached as requested.

Regards

Abdul Rahman (Mr)
Accident Claims Officer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4840 | FAX: (65) 6478 4848



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Saturday, 12 May 2018 3:30 PM
To: Abdul Rahman MOHAMAD SALIM (SPF) <Abdul_Rahman_Mohamad_Salim@spf.gov.sg>
Subject: Request Paper Survey

Dear Mr Abdul Rahman,

Kindly refer to the attachment.

Please assist provide us the LOD for all vehicle for us conduct Paper Survey.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

1 2



SINGAPORE POLICE FORCE

SPF Accidents Claims Section
Automotive Engg & Mgmt Div
Police Logistics Department
No. 1 Mount Pleasant Road
Block 8 Old Police Academy
#02-12 Singapore 298333

Your Ref : SH8808S

Our Ref : AEMD/105/009/2018/019

Date : 1 March 2018

Tel : 64784840

Fax : 64784848

M/s LKK Auto Consultants Pte Ltd
Paya Ubi Industrial Park
51 Ubi Avenue 1 #01/02-25
Singapore 408933

Via Fax only: 62564315

Dear Sir/Madam,

ACCIDENT INVOLVING GOVT VEHICLE QX304X AND OTHER VEHICLE SH8808S ON 10 FEBRUARY 2018

We refer to the above matter.

- 2 Please arrange for a **Paper Survey Inspection** of vehicle no. **SH8808S** which has been repaired at **Messrs ComfortDelgro Engr Pte Ltd** of **205 Braddell Road**, Singapore **579701**.
- 3 Estimates were provided by the workshop.
- 4 Thank you.

Yours faithfully,

Abdul Rahman
Accident Claims Officer
for Assistant Director

A FORCE FOR THE NATION

COMFORTDELGRO ENGINEERING PTE LTD
 #205 Braddell Road
 Blk C Ext 1 3rd Level
 Singapore 579701



Mainline (65) 6458 4555
 Facsimile (65) 6458 1040

www.vicom.com.sg
 Company Registration No: 106100320K

SURVEY REPORT

GENERAL INFORMATION			
VAC Ref. No.	: 522502	Claim No.	: 305115850
Accident Date	: 10/02/2018	Claim Type	: THIRD PARTY
Assignment Date	: 12/02/2018	Policy No.	:
Survey Date	: 12/02/2018	Finalised Dt.:	
Survey Report Date	: 14/02/2018		
VEHICLE PARTICULARS			
Vehicle No.	: SH8808S	Chassis No.	: JTDKB3FU103561451
Registration Date	: 19/07/2017	Engine No.	: OBSCURED
Make	: TOYOTA	Engine Cap.	: 1798 CC
Model	: PRIUS HYBRID	Transmission	: AUTO
		Colour	: BLUE
CONDITION OF VEHICLE DURING SURVEY (VISUAL and STATIC TEST ONLY)			
Foot Brake	: SERVICEABLE	Steering	: SERVICEABLE
Hand Brake	: SERVICEABLE	Modification	: NONE
Mileage	:		
<u>TYRES</u>	<u>SIZE</u>	<u>MAKE</u>	<u>BALANCE (mm)</u>
FRONT RH	195/65R15	WESTLAKE	6
FRONT LH	195/65R15	WESTLAKE	6
REAR RH	195/65R15	WESTLAKE	6
REAR LH	195/65R15	WESTLAKE	6
SURVEY CONDUCTED AT			
ComfortDelGro Engineering Pte Ltd, 59 Loyang Drive Singapore 508969. Assignment given by: MVA Limts (C.D.G.E.)			
REMARKS			
[1]Workshop Estimate : S\$ 2,428.80			
[2]Our Adjustment : S\$ 1,659.47			
[3]Repair Period : 3 days			
[4]We have not authorised repairs. This survey was carried out on without prejudice basis.			

VICOM LTD
SURVEY REPORT

SH8808S @ 10/02/2018

Annex A: Adjustment on Spare Parts

#	Qty	Vehicle Parts Description	Condition follow	Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	1	Rear Trunk Lid Logo (Prius)	Necessary	60.80	60.80
2	1	Rear Trunk Lid Logo (Hybrid)	Necessary	52.40	52.40
3	1	Rear Trunk Lid Logo (Toyota Star)	Necessary	52.90	52.90
4	1	Rear Bumper	Deformed	458.60	458.60
5	1	Rear Bumper Reinforcement	Reuse	318.80	0.00
6	1	Rear Bumper Under Cover	Snapped	552.60	552.60
7	1	Rear Bumper Side Retainer	Reuse	112.70	0.00
8	10	Rear Bumper Clips	Necessary	22.00	22.00
Subtotal				:	1630.80
Less 25 %					407.70
TOTAL				:	1223.10
SPECIAL NETT ITEM					
1	1	Rear Trunk Lid Apps Sticker	Necessary	40.00	40.00
2	1	Rear Trunk Lid Comfort & Tel No. Sticker	Necessary	60.00	60.00
3	1	Rear Bumper Reverse Sensor	Reuse	135.70	0.00
TOTAL				:	235.70
TOTAL FOR SPARE PARTS				:	1458.80
					999.47

VICOM LTD
SURVEY REPORT

SH8808S @ 10/02/2018

Annex B: Adjustment on Labour and Spray Painting

#	Job Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	Labour charges	350.00	200.00
2	Spray painting	400.00	360.00
3	Wiring charges	50.00	20.00
4	Tuff kote	50.00	20.00
5	Remove/ refix reverse sensor	120.00	60.00 20
TOTAL FOR LABOUR AND SPRAY PAINTING		970.00	660.00

Summary

Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
TOTAL FOR SPARE PARTS	1458.80	999.47
TOTAL FOR LABOUR AND SPRAY PAINTING	970.00	660.00
TOTAL REPAIR COST	2428.80	1659.47

VICOM LTD
SURVEY REPORT
Annex C: Conclusion

SH8808S @ 10/02/2018

ASSESSOR'S REPORT

At the place of inspection, we saw this vehicle sustained rear damage.


The damages seen during our survey were at rear bumper, rear trunk lid and surrounding areas. A fuller detailed description of the damages is in Annex A of this survey report.

ASSESSOR'S RECOMMENDATION

Comfortdelgro Engineering Pte Ltd (Loyang) estimated a repair cost of S\$2,428.80. We adjusted it to S\$1,659.47 on a part-by-part basis.

Accordingly, we recommend repairs to this vehicle be carried out on a part-by-part basis at S\$1,659.47.

The repairs would require a period of 3 working days.



Kamarudin Abdul Kadir
for VICOM Ltd



Your Ref: AEMD/105/009/2018/019

Date: 21st May 2018

Our Ref: CS1/SPF18008935/K1vbs2

M/s Automotive Engineering & MGT Division

Accident Claim Section

(Singapore Police Force)

1 Mount Pleasant Road

Blk 8 Old Police Academy

Singapore 298333

(The Motor Claims Department)

Attn: Abdul Rahman

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SH 8808S INSURED VEHICLE: QX 304X ACCIDENT DATE: 10/02/2018**

We thank you for your instruction on 14/05/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SH 8808S from M/s Vicom Ltd.
- b) Colour damaged vehicle photographs of SH 8808S.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SH 8808S
Make & Model	: Toyota Prius Hybrid
Year of Registration	: 2017
Chassis Number	: JTDKB3FU103561451
Engine Capacity	: 1798 cc

2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8808S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TRUNK LID LOGO (PRIUS)	NECESSARY	60.80	60.80
1	REAR TRUNK LID LOGO (HYBRID)	NECESSARY	52.40	52.40
1	REAR TRUNK LID LOGO (TOYOTA STAR)	NECESSARY	52.90	52.90
1	REAR BUMPER	DEFORMED	458.60	458.60
1	REAR BUMPER REINFORCEMENT	REUSE	318.80	-
1	REAR BUMPER UNDER COVER	SNAPPED	552.60	552.60
1	REAR BUMPER SIDE RETAINER	REUSE	112.70	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
	LESS 25% DISCOUNT		-407.70	-299.83
			1,223.10	899.47
<u>SPECIAL NETT ITEMS</u>				
1	REAR TRUNK LID APPS STICKER (SN)	NECESSARY	40.00	40.00
1	REAR TRUNK LID COMFORT & TEL NO. STICKER (SN)	NECESSARY	60.00	60.00
1	REAR BUMPER REVERSE SENSOR (SN)	REUSE	135.70	-
			235.70	100.00
<u>LABOUR</u>				
	LABOUR CHARGES.		350.00	200.00
	SPRAY PAINTING.		400.00	360.00
	WIRING CHARGES.		50.00	20.00
	TUFF KOTE.		50.00	20.00
	REMOVE / REFIX REVERSE SENSOR.		120.00	20.00
			970.00	620.00
GRAND TOTAL			2,428.80	1,619.47
RECOMMENDED COST OF REPAIRS				1,619.47

Report Ref No. CS1/SPF18008935/K1vbs2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
Minst AEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.