

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: AEMD/105/009/2018/041 Date: 28th June 2018

Our Ref: CS1/SPF18008943/Srbs2

## M/s Automotive Engineering & MGT Division

Accident Claim Section
(Singapore Police Force)

1 Mount Pleasant Road
Blk 8 Old Police Academy
Singapore 298333
(The Motor Claims Department)

Attn: Abdul Rahman

Dear Sir / Madam,

## EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO.: SLE 4237P INSURED VEHICLE NO: QX 305T ACCIDENT ON 04/02/2018

We thank you for your instruction on 14/05/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLE 4237P from M/s ROG Associates.
- b) Colour damaged vehicle photographs of SLE 4237P.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SLE 4237P

Make & Mode : Mini Cooper S 2.0 (A)

Year of Registration : 2016

Chassis Number : WMWLN720602D97559

Engine Capacity : 1998 cc



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

- Our finding is that the repair cost of \$14,454.27 (before GST) quoted by M/s Eurokars Habitat Pte Ltd is fair & reasonable.
- We recommend that the repairs of the entire damage require about 12 (Twelve) working days to complete.

Vehicle Inspection By:

YWK

YEANG WAI KEEN Automotive Assessor

HO LEONG/CHUAN

Automotive Assessor