

**Ace Auto Solution**  
Registration number : 53228991M  
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

**Repair Estimate**

Date : 14/5/2018

Reference: SLU1672B  
MAZDA3  
Make: SEDAN 1.5 AT  
EU6

To Whom It May Concern

Dear Sir,

TPAxA  
Thin Thin

RE: VEHICLE : SLU1672B  
CHASSIS NO.: JM6BN22A8H0174181  
ENGINE NO.: P520464159

Name of insured : Alpine Car Rental Pte Ltd  
Date of accident.: 05/05/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

**Parts**

No.	Qty	Part Description	Price (SGD)
1	1	LHF Fender Discolor	\$ 333.90 ✓
2	1	LHF Fender Liner 3ml	\$ 129.30 +
3	1	LHF Bumper Bracket	\$ 18.70 ✓

333.90  
267.12  
Parts Total: \$ 481.90  
Less 10%: \$ 48.19  
20% Total : \$ 433.71

**Labour**

No.	Labour Description	Price (SGD)
Front portion		
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 400.00 2w
2	Carry out spray painting on accident affected area	\$ 400.00 2w

400  
Labour Total : \$ 800.00

**Others**

**Other Description**

No.	Qty		Price (SGD)
1	3	LHF Fender Liner Clips <i>mtm</i>	\$ 19.50

Other Total: \$ 19.50

GRAND TOTAL: \$ 1,253.21

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully



Service Advisor  
Suhaimi

HP : 9189 2617 Email - aceautosolution@gmail.com

*Adrian Ling*  
*P/P 16/05/18*

*02 days*

*total: 667.12*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: