

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: AEMD/105/009/2018/042A

Date: 28th May 2018

Our Ref: CS1/SPF18008947/T1rbs2

M/s Automotive Engineering & MGT Division

Accident Claim Section
(Singapore Police Force)
1 Mount Pleasant Road
Blk 8 Old Police Academy
Singapore 298333
(The Motor Claims Department)

Attn: Abdul Rahman

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO.: SLS 7567T INSURED VEHICLE NO: TP 1118S ACCIDENT ON 10/03/2018

We thank you for your instruction on 14/05/2018.

We acknowledge receipt of the following documents:-

- Automobile Inspection Report of SLS 7567T from M/s AIG Asia Pacific Insurance Pte. Ltd.
- b) Singapore Accident Statement of Vehicles SLS 7567T.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

Information Recorded: -

Registration Number

: SLS 7567T

Make & Mode

: Mercedes-Benz A180

Year of Registration

: 2017

Chassis Number

: WDD1760422J656635

Engine Capacity

: 1595 cc



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

- Our finding is that the repair cost of \$3,932.14 (before GST) quoted by M/s Cycle & Carriage Industries Pte Ltd is fair & reasonable.
- 3. We recommend that the repairs of the entire damage require about <u>5 (Five)</u> working days to complete.

Vehicle Inspection By:

MOHAMAD TAUFIKH M.MATAI, AMSAE-A Automotive Assessor

ADRIAN LING WAI PING

B. Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser