

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

15-May-18

## ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) WAGON REGN NO: SHD 1492 R

1 pc	Rear bumper	\$	811.11	X nn
1 pc	Rear bumper n/s & o/s side bracket @ \$52.20	\$	104.40	?
1 pc	Rear o/s door	\$	2,017.48	✓ dent
2 pcs	Rear o/s door hinges @ \$39.00	\$	78.00	?
1 pc	Rear o/s mud flap	\$	47.45	X nn
1 pc	Rear o/s rim	\$	246.00	✓ scratch
		\$	3,304.44	
		\$	660.89	
		\$	2,643.55	
		Less 20%		
		\$	528.71	
		\$	2,114.84	
		\$	48.00	X nn
		\$	60.00	✓ n/c
		\$	100.00	✓ n/c
		\$	50.00	X nn
		\$	80.00	X nn
		\$	150.00	80
		\$	750.00	600 540
		\$	800.00	600 540
		\$	120.00	50
		\$	4,801.55	
		Total	\$	4,801.55

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.

NAZ LKK  
15/5/18 1130  
1211.  
3 days