

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

16 MAY 2018

E S T I M A T E

@5.30pm

Estimate No. : b1 46910
Date Estimated : 14/05/2018
Prepared By : Han Kwan Yong

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -Annie Wijaya
11 Keppel Bay Drive
#07-19 Corol

Singapore 098017

- ACCOUNT - 40000Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGK7557Z	PL66341	30/06/2008	M3-C	0

DESCRIPTIONVALUETo replace front bumper, front left door including to knock
out front left fender and dent ed area caused by the accident

2550 3,400.00

To respray front bumper, front left fender and front left
door

2527 2,808.00

To carry out body cavity preservation.
(Per panel).

100 118.00

To check steering geometry and conduct wheel alignment
according to BMW specification (1X)

451 531.00

To replace tyre and wheel rim including balancing. (1x).

80 94.00

TO SUPPLY TYRE (LHF) Michellin 245/35 R19

80% cut 519.00

To transfer lock mechanism from old to new door including
conduct checks on new door power window system for proper
function. (1 door).

451 531.00

To check electrical wiring systems and lightings
including reset and check air bags for proper function.

250 295.00

Sundries.

? 150.00

Total Labour 1: 8,446.00

DESCRIPTIONQTYPRICVALUE

ALLOY RIM (81/2Jx19) ET:44

1 1,237.20

cut 1,237.20

FRAME, TRIM GRILLE PRIMED LH

1 25.65

cut 25.65

FRT LH DOOR

1 1,468.45

cut 1,468.45

Set of mount

1 66.50

? 66.50

FRT BUMPER (M)

1 1,315.90

Rx 1,315.90

EMBLEM ADHERED LH

1 79.95

new 79.95

GRILLE SIDE PANEL FRT LH

1 195.15

? 195.15

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46910
Date Estimated : 14/05/2018
Prepared By : Han Kwan Yong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGK7557Z	PL66341	30/06/2008	M3-C	0

DESCRIPTION

FRT LH DOOR JOINT SEAL
FRT LH DOOR WEATHERSTRIP
(DG/SL) ADHESIVE SET K6

QTY	PRIC	VALUE
1	39.70	39.70
1	147.25	147.25
1	53.05	53.05

Total Parts : 4,628.80

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 01/06/2018 1450 Excess S\$ _____

Surveyor's Name Angela Sign Angela

Surveyor's Tel 92445144 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ P.M.L. Yes / No _____

Surveyor's E-mail angela@khanh.com

No. of Working Days Recommend 6-7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	8,446.00
Parts	:	4,628.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	915.24
Grand Total	:	13,990.04

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **