

22/03/2018

ASS. REC. BY

REF: es/MSG18008954/Urd352

Special Instruction:

Surveys by

Marcus

ASSIGNMENT (Office)

Menimen

Pearllyn Kang

of

MSIG

Date/Time: 16/5/18 01:55pm

Estimated Cost:

Bill to:

OD TP/WS/TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

GBD 9787J

Insured:

at Workshop m/s

SMRT Automotive

Tel: 6555 5556

of

60 Woodlands Ind. Prk E 4

Policy No: 28791913MKC

Claim No:

557557

Sum Insured:

Excess:

\$700.00

Make of Veh:
(Client's Record)

D.O.A. 02/05/2018

Insp: I Kaki Bukit Ave 6 #01-58/60

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time: 9:05am @ 17/5/18

Person Contacted:

esther

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate	D.O.A. 02/05/2018
	GBD 9787J - CS/MSG18008210/K/b	
	Impact consistency, report not statement not clear (by Marcus)	
18/5/18	revert thru menimen	
18/5/18	Authorise repair & inform Esther to authorise repair.	

(08/11/13) wef

ASS. REC. BY: Morcu

REF:

es/MSG18008954/Urd3

MS14/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: G3D9787Jat Workshop m/s Smart

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: 700

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 6510.

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: G3D9787JYr Regn: 8115

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CMMake: Toyota Dyna Freer2982Colour: silver

A/C: Insured / Std / NI / NA

Sp. Reading: 81877

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 7TFAT35Y60K204481

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195-115R: 155R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Mexxys

Front

Rear

R/Bal. 6 mmR/Bal. 0/6 mmL/Bal. 6 mmL/Bal. 0/6 mm

D.O.A. _____

D.O.I. 17/5/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

L7A18021 Del 9500P-430Confirmed \$982.50, 5 days
Red: \$11806.50, 92%

RECEIVED 28 JUN 2018

Date/Time, File Pass to?

☐

Preli. Report

1) typist☒

Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 5Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee: 200

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format: TPLump Sum / I.B.I: (\$ 982.50)10



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18008954/Urd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 17-05-2018



Code : MSG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	GBD 9787J
Policy No.	28791913MKC	Coverage (\$)	0.00
Claim No.	557557	Excess (\$)	700.00
Assign From	MERIMEN (PEARLYYN KANG)	Assign Date	17/05/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	02/05/2018	Inspection Date	17/05/2018
Survey held at	LEE SHENG AUTO PTE LTD 1 KAKI BUKIT AVE 6 #01-60 SINGAPORE 417883		

5a. Remarks

- A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 May 2018 Sendback Est	16 May 2018 14:30 S\$12,789.00	16 May 2018 16:55 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	JIA SENG TRADING PTE LTD, Co. Reg. No.: 200800861K			
Vehicle Reg. No.:	GBD9787J	Date of Loss:	02/05/2018 08:00 - :59 [32 Months and 26 Days From LTA Reg Date (Man Yr)]	
Claim Type:	OD / 557557	Policy/Cover Note No.:	28791913MKC (Comprehensive) Coverage: 06/08/2017 - 05/08/2018	
		Excess:	S\$700.00	
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pearlyn Kang Yen Lin - 6594 2588]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/05/2018]			
Driver/Custodian:	QUEK SEIN CHIN (47 / Male), NRIC: S7032766Z, Tel: +6584982766			
Adj Asg. Remarks:	Survey and revert.			

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pearlyn Kang Yen Lin

Date: 18 May 2018

Preliminary Advice

Vehicle No	: GBD9787J	Accident Date	: 02/05/2018
Make	: TOYOTA DYNA 150	Policy No.	: 28791913MKC
Assignment Date	: 16/05/2018	Excess	: S\$700.00
Date of Inspection	: 17/05/2018	Est. Duration of Repair	: 5.00
Inspection At	: SMRT AUTOMOTIVE SERVICES PTE LTD (WOODLANDS) 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,789.00
Revised Amount	:S\$	1,687.00
Check Items (Estimated)	:S\$	5,416.50
Total	:S\$	7,103.50

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	65,000.00
COE / PARF Rebate	:S\$	18,021.00
Salvage Value	:S\$	
Margin for Repair	:S\$	46,979.00

Remarks

- (X) The vehicle is economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.

Print Received Message

This mail is associated with :

GBD9787J (557557)

OD

May 2 2018 8:00AM

[JIA SENG TRADING PTE LTD]
SMRT Automotive Services Pte Ltd

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 18/05/2018 14:41 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$1687.00) - GBD9787J - Claim Handler: Pearllyn Kang Yen Lin

Approved:1687.00:CHECK ITEMS TO BE VERIFIED AND CONFIRMED.

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Friday, May 18, 2018 3:56 PM
To: 'TeyChorKeng@smrt.com.sg'
Cc: Peh Eng Hock (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC); SUR
Subject: GBD 9787J MSIG

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **GBD 9787J (excess \$700/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/05/2018 13:35
Date Of Accident	02/05/2018 08:50
Exact Location Of Accident	KALIDASA AVENUE TEACHER'S HOUSING ESTATE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD9787J
Insured/Policyholder	
Name Of Registered Owner	JIA SENG TRADING PTE LTD
Co Reg No	200800861K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	TOYOTA DYNA 150 MANUAL

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	GOODS VEHICLE
------------------	---------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 28791913 MKC
Cover Note Number	

Driver

Name of Driver	QUEK SEIN CHIN
NRIC No	S7032766Z
Date Of Birth	27/09/1970
Occupation	OUTDOOR
Date Of Driving Pass	17/01/2012
Driving Experience	6 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84982766

Fax Number	
Contact Number	
EMail Address	NOEMAIL
Address	BLK 155 YISHUN STREET 11 #09-90
Postcode	760155
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKN1300Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Jia Seng Trading Pte Ltd
23 Keilasse Avenue
Off Yio Choo Road
Singapore 769402

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was reversing my truck to park at my company. Suddenly car B hit my front side cab.

DECLARATION
We declare the foregoing particulars are true in every respect.
23 Kallang Avenue
Off Yio Chu Kang Road
Singapore 700402

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 0861K

Vehicle Details

Vehicle No.: GBD9787J

Vehicle to be Exported: No

Intended De-registration Date: 17 May 2018

Vehicle Make: TOYOTA

Vehicle Model: TOYOTA DYNA 150 MANUAL

Primary Colour: Silver

Manufacturing Year: 2015

Engine No.: 1KD2491422

Chassis No.: JTFAT35Y60K204485

Maximum Power Output: -

Open Market Value: \$27,856.00

Original Registration Date: 06 Aug 2015

First Registration Date: 06 Aug 2015

Transfer Count: 1

Actual ARF Paid: \$1,393.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 05 Aug 2025

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$24,969.00

COE Rebate Amount: \$18,021.00

Total Rebate Amount: \$18,021.00

The information contained herein is correct as at 17 May 2018

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

- Big Box Retail Warehouse Opens in Jurong East Today
- NS related deaths
- Merc A class

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Nissan Teana 2.0A.



Cheapest In The Market, Low
Mileage 103k, Very Good
Condition, Low Depreciation!
Direct Owner StarAd







Browse by Category

Sort by Date Posted 20 results/page

7 vehicles

Toyota Dyna

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Dyna		Any	Any	2015	Any	Any	Any	Available
	Toyota Dyna 150		\$51,800	\$7,540 /yr	30-Mar-2015	2,982 cc	91,000 km	Truck	Available
Fuel Type: Diesel The Japanese Workhorse For Your Company Needs. Low Maintenance And Low Fuel Consumption. Very Well Maintained! Engine And Gearbox In Excellent Condition! Call Now For Viewing Before You Miss This Vehi...									
Tan Wei Auto Pte Ltd Posted: 16-May-2018 Tags: 2015 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota									
	Toyota Dyna 150		\$53,800	\$7,450 /yr	04-Aug-2015	2,982 cc	13,900 km	Truck	Available
Fuel Type: Diesel The Most Reliable Brand For Your Business Use. Under Utilised Vehicle, Super Low Mileage At 14000Km Only! 3 Days Delivery, Low Maintenance And Low Diesel Consumption. Comes With Half Canopy, Hurry Com...									
Net Link Partners Pte Ltd Posted: 15-May-2018 Tags: 2015 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota									
	Toyota Dyna 150		\$57,000	\$7,630 /yr	02-Nov-2015	2,982 cc	-	Truck	Available
Fuel Type: Diesel Lorry Is Well Maintained And Has Just Went For Servicing.									
Posted: 13-May-2018 Tags: 2015 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota									
	Toyota Dyna 150		\$57,800	\$7,620 /yr	15-Dec-2015	2,982 cc	-	Truck	Available
Fuel Type: Diesel Best 10 Foot Lorry In Town. Very Well Maintained. Reasonable Price. In House Loan Available. Test Drive Today. Don't Miss.									
Index Credit Posted: 12-May-2018 Tags: 2015 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota									
<div>Car Buying</div> <div>Car Selling</div> <div>Car Ownership</div> <div>Car Aftermarket</div> <div>On The Move</div> <div>Lifestyle</div> <div></div>									
	Toyota Dyna 150		\$55,800	\$7,500 /yr	22-Oct-2015	2,982 cc	50,319 km	Truck	Available
Fuel Type: Diesel 1 Owner Toyota Dyna Open Truck. Most Reliable And Efficient 10 Feet Lorry. High Price For Your Trade-In Vehicles. High In-House Loan And Insurance Can Be Arranged. Door Step Viewing Can Be Arranged. C...									
ABWIN (1994) Pte Ltd Posted: 12-May-2018 Tags: 2015 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota									
	Toyota Dyna 150		\$57,800	\$7,580 /yr	29-Dec-2015	2,982 cc	-	Truck	Available
Fuel Type: Diesel Most Reliable And Efficient 10 Feet Lorry. High Price For Your Trade-In Vehicles. High In House Loan And Insurance Can Be Arranged. Door Step Viewing Can Be Arranged. Call Now Before Its Gone To Avoid...									
ABWIN (1994) Pte Ltd Posted: 24-Apr-2018 Tags: 2015 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota									
Compare									

Compare

**SMRT AUTOMOTIVE
SERVICES PTE LTD
60 WOODLANDS
INDUSTRIAL PARK E4
757705**

Claim Reference: WL/MAY2018/001
Assessment Number: CTI10138
Version: SMRTAUTO/1
Date Calculated: 16/05/2018 07:04

Full Report - V1
Registration: GBD9787J
Printed: 16/05/2018 14:05

Summary Information

Claim

Location: Singapore (SG)
 Printed by: MR Raymond
 Authorisation Status: Interim
 Work Provider: MSIG Insurance
 (Singapore) Pte
 Claim Reference: WL/MAY2018/001

Currency: SGD
 Date of Incident: 02/05/2018
 Able to Authorise Repairs: TBA
 Repairs Authorised: TBA

Policy Number:
 Other Reference:
 Third Party:
 Insured Amount:
 Under Warranty:
 Warranty Expired:

Estimated Repair Time:
 Quote Due Date:
 Actual Repair Days:
 Parts Ordered Date:
 Hire Car Start:
 Hire Car End:
 Vehicle Collected:

Not Authorised
Excess \$700
17/5/18
5 day
To be photo before painting

Vehicle Details

Vehicle
 Manufacturer: TOYOTA
 Model: Dyna
 Sub Model: BASE MODEL
 Model Sheet Number: Y1C 01
 Registration: GBD9787J
 Registration Month: August
 Registration Year: 2015
 VIN Number:
 Odometer: Not Known
 Colour:
 Engine Number:
 Fuel Level: %

Model Specs

FROM 01/2017
 4.0 LTR 100KW
 STANDARD CAB

AIR CONDITIONING
 DRIVER AIRBAG
 PAINTING OFF VEHICLE

Vehicle Condition

Vehicle Status

Pre-Accident Condition:
 Steering:

Severity of Impact:
 Vehicle Status on
 Inspection:

Brakes Pedal Travel:
 Place of Inspection:
 Pre-Accident Damage:

Date of Inspection: 15/05/2018

Tyres Condition:
 Tread Depth LHF:
 Tread Depth LHR:
 Damage Areas:

Tread Depth RHF:
 Tread Depth RHR:
 Direction of Impact:

SMRT Auto Insurants hence notify the Repairer of the following:

- To resurvey before spray painting
- To supply damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Terms of survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

SMRT AUTOMOTIVE SERVICES PTE LTD

Claim Reference: WL/MAY2018/001

Assessment Number: CTI10138



Version: SMRTAUTO/1

Date Calculated: 16/05/2018 07:04

Full Report - V1

Registration: GBD9787J

Printed: 16/05/2018 14:05



Addresses

Cost Summary

p-430

Total Labour	\$680.00
Total Parts	\$7,359.00
Total of Additional Costs	\$4,750.00
Excess:	TBA
Grand Total Exc GST:	\$12,789.00
7 % GST:	\$895.23
Grand Total Inc GST:	\$13,684.23

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR
Price/Dent = \$50.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
NO NUMBER	REMOVE AND REFIT CONTROL ROD	9.0	45.00 X
NO NUMBER	RENEW L/F CAB BRACKET	5.0	25.00
NO NUMBER	RENEW R/F CAB BRACKET	5.0	25.00
NO NUMBER	R + R CAB	30.0	150.00
520011	RENEW FRONT BUMPER	10.0	50.00
	INCLUDES: R + R BUMPER AND NECESSARY ATTACHED PARTS		
751011	R + R RADIATOR GRILLE	3.0	15.00
810051)	R + R L/HEADLAMP	1.0	5.00
	(RADIATOR GRILLE REMOVED)		
	DOES NOT INCLUDE: ADJUST HEADLAMP		
810151A	ADJUST HEADLAMPS	3.0	15.00
670051	RENEW L/F DOOR	14.0	70.00
	INCLUDES: R + R DOOR,		
	CONVERT ALL ATTACHED PARTS,		
	ADJUST DOOR		
752051	R + R L/DOOR MIRROR CPL	5.0	25.00
	INCLUDES: L/END MOULDING		
	REMOVE AND REFIT.		
670201)	R + R L/F DOOR HINGE/S	1.0	5.00
883151)	R + R CONDENSER	3.0	15.00
NO NUMBER	R + R COMPRESSOR-/CONDENSER PIPE	3.0	15.00
NO NUMBER	R + R CONDENSER/EVAPORATOR HOSE	3.0	15.00
002889	DRAIN AND REFILL AIR CONDITIONING	7.0	35.00
NO NUMBER	R + R FAN MOTOR	2.0	10.00

LABOUR COST

Total Work Units

104.0

Corrosion Protection External Labour

0.0HRS

0.00

Corrosion Protection Internal Labour

0.0HRS

0.00

SMRT AUTOMOTIVE SERVICES PTE LTD

Claim Reference: WL/MAY2018/001

Assessment Number: CTI10138

Version: SMRTAUTO/1

Date Calculated: 16/05/2018 07:04

Full Report - V1

Registration: GBD9787J

Printed: 16/05/2018 14:05

Sub Total	10.4HRS	\$520.00
Paint Labour	3.2HRS	\$160.00
Total Labour	13.6HRS	\$680.00

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$50.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- PAINTING OFF VEHICLE		
LE 0281	FRONT BUMPER NEW PART PAINT ST 1	11.0	
LE 1481	LEFT FRONT DOOR NEW PART PAINT ST 1	15.0	
NO NUMBER	PREPARE FOR PAINTING	3.0	
NO NUMBER	PAINT PREPARATION FOR PLASTIC PARTS (COMPOSITE WORK)	3.0	
LABOUR COST - PAINT			
TIME(PAINT)		0.0	
Total Work Units (10WU/HR)		32.0	
Total Paintwork Labour		3.2HRS	\$160.00
MATERIAL COST - PAINT			
Total Excluding Pearlescent Uplift			\$0.00
Pearlescent Uplift @ 0.0%			\$0.00
Total Paint Material Cost			\$0.00

PARTS

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
281	1	FRONT BUMPER	52101 37A50	Dr J	0%	140 300.00*
285	12	FRONT BUMPER SCREW	90109 06396	11	0%	0.00
410	1	GRILLE	53111 37891	one	0%	90 280.00*
431	1	BADGE	75315 37080		0%	45.00*
571	1	LEFT HEADLAMP ASSY	81170 37121	one	0%	100 400.00*
1481	1	LEFT FRONT DOOR	67002 37322	11	0%	980.00*
1487	1	L/F UPPER DOOR HINGE	68730 37010	11	0%	30.00*
1495	1	L/F LOWER DOOR HINGE	68710 37020	11	0%	30.00*
2759	1	L/F SUPPORT BRACKET	51702 37380	11	0%	350.00*
2760	1	R/F SUPPORT BRACKET	51701 37460	11	0%	350.00*
2812	1	SHIFT LINKAGE	54801 37250	11	0%	600.00*
4465	1	CONDENSER	88461 37080	11	0%	480.00*
4482	1	COMPR/CONDENSER TUBE	88716 37D20	11	0%	180.00*
4487	1	FAN MOTOR	88550 37140	11	0%	245.00*
4497	1	DRYER/EVAP PIPE	88721 37A80	11	0%	180.00*
1000	1	F/STEPBOARD GARNISH	Renew	11	0%	150.00*
1000	1	F/CROSSMEM SUB FRAME	Renew	11	0%	220.00*
1000	1	LOCK ASSY, TILT LH	Renew	500	0%	480.00*
1000	1	LOCK ASSY, TILT RH	Renew	500	0%	440.00*
1000	1	SPRING TILT CAB,NO.1	Renew	11	0%	380.00*
1000	1	ARM,TILT CAB SPR SUP	Renew	11	0%	230.00*
1000	1	SPACER,BODY MOUNTING	Renew	11	0%	140.00*
1000	1	NUMBER PLATE	Renew	300	0%	40.00*
1000	1	F/DOOR CO.AD STICKER	Renew	one	0%	40.00*
1000	1	TOP UP AIRCON GAS	Renew		0%	120.00*

f: OEM Parts
g: Original
h: Secondhand

Sub Total
Mark Up From Cost (10 %)
Total Parts

\$6,690.00
\$669.00
\$7,359.00

headlamp Right one 100

SMRT AUTOMOTIVE SERVICES PTE LTD

Claim Reference: WL/MAY2018/001

Assessment Number: CTI10138

Version: SMRTAUTO/1

Date Calculated: 16/05/2018 07:04

Full Report - V1

Registration: GBD9787J

Printed: 16/05/2018 14:05

p: Parallel
x: Exchange

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description		Betterment	Price
LABOUR FRT PORTION	SPECIALIST	0%	\$1,500.00 ²⁵⁰
RESpray AFFECT AREA	SPECIALIST		11 \$1,200.00 X
REMOVE&REFIT CABIN	SPECIALIST	0%	11 \$800.00 X
APPLY ANTI RUSH	SPECIALIST		11 \$150.00 X
ALIGN F/CHASSIS FRAM	SPECIALIST	0%	11 \$600.00 X
REP F/CHASSIS FRAME	SPECIALIST		11 \$500.00 X
Total Extras			\$4,750.00

Final Calculation

Total Parts	\$7,359.00
Labour	
Total Panel/Mechanical	\$520.00 ^{285 85}
Total Paintwork	\$160.00 ⁷⁰
Total Labour	\$680.00
Additional Costs	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$4,750.00 ²¹⁰⁰
Total of Additional Costs	\$4,750.00
Total Paint/Material Costs	\$0.00
Grand Total Excludes GST	\$12,789.00
GST @ 7 %	\$895.23
Grand Total Includes GST	\$13,684.23

Assessment Notes

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore

408933

Claim Reference: WL/MAY2018/001
Assessment Number: CTI10138
Version: LKKAUTOC/2
Date Calculated: 18/05/2018 05:26

Full Report - V1
Registration: GBD9787J
Printed: 18/05/2018 12:28

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	02/05/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:	WL/MAY2018/001	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:	LKK	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Dyna
Sub Model:	BASE MODEL
Model Sheet Number:	Y1C 01
Registration:	GBD9787J
Registration Month:	August
Registration Year:	2015
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%



Model Specs

FROM 01/2017	AIR CONDITIONING
4.0 LTR 100KW	DRIVER AIRBAG
STANDARD CAB	PAINTING OFF VEHICLE

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	15/05/2018
Place of Inspection:	Assessor	
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		



Addresses

Cost Summary

Total Labour	\$455.00
Total Parts	\$4,548.50
Total of Additional Costs	\$2,100.00
Excess:	TBA
Grand Total Exc GST:	\$7,103.50
7 % GST:	\$497.25
Grand Total Inc GST:	\$7,600.75

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR
 Price/Dent = \$50.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
NO NUMBER	RENEW L/F CAB BRACKET	5.0	25.00
NO NUMBER	RENEW L/F CAB BRACKET	5.0	25.00
NO NUMBER	RENEW R/F CAB BRACKET	5.0	25.00
NO NUMBER	R + R CAB	30.0	150.00
520011	RENEW FRONT BUMPER	10.0	50.00
	INCLUDES: R + R BUMPER AND NECESSARY ATTACHED PARTS		
751011	R + R RADIATOR GRILLE	3.0	15.00
810051)	R + R L/HEADLAMP	1.0	5.00
	(RADIATOR GRILLE REMOVED)		
	DOES NOT INCLUDE: ADJUST HEADLAMP		
810151A	ADJUST HEADLAMPS	3.0	15.00
883151)	R + R CONDENSER	3.0	15.00
NO NUMBER	R + R COMPRESSOR-/CONDENSER PIPE	3.0	15.00 X
002889	DRAIN AND REFILL AIR CONDITIONING	7.0	35.00 X
NO NUMBER	R + R FAN MOTOR	2.0	10.00 X

LABOUR COST

Total Work Units	77.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	7.7HRS	\$385.00
Paint Labour	1.4HRS	\$70.00
Total Labour	9.1HRS	\$455.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$50.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- PAINTING OFF VEHICLE		
LE 0281	FRONT BUMPER NEW PART PAINT ST 1	11.0	

NO NUMBER	PAINT PREPARATION FOR PLASTIC PARTS (COMPOSITE WORK)	3.0	
LABOUR COST - PAINT			
	TIME(PAINT)	0.0	
	Total Work Units (10WU/HR)	14.0	
	Total Paintwork Labour	1.4HRS	\$70.00
MATERIAL COST - PAINT			
	Total Excluding Pearlescent Uplift		Cost Price
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$0.00

PARTS

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
1000	1	ARM,TILT CAB SPR SUP	Renew		0%	230.00*
431	1	BADGE	75315 37080		0%	45.00*
4482	1	COMPR/CONDENSER TUBE	88716 37D20		0%	180.00*
1000	1	F/CROSSMEM SUB FRAME	Renew		0%	220.00*
1000	1	F/DOOR CO.AD STICKER	Renew		0%	30.00*
4487	1	FAN MOTOR	88550 37140		0%	245.00*
281	1	FRONT BUMPER	52101 37A50		0%	300.00*
410	1	GRILLE	53111 37891		0%	280.00*
2771	1	L/CAB ATTACHMENT	57223 37011		0%	0.00F
2759	1	L/F SUPPORT BRACKET	51702 37380		0%	350.00*
571	1	LEFT HEADLAMP ASSY	81170 37121		0%	400.00*
1000	1	LOCK ASSY, TILT LH	Renew		0%	480.00*
1000	1	LOCK ASSY, TILT RH	Renew		0%	440.00*
1000	1	NUMBER PLATE	Renew		0%	15.00*
2760	1	R/F SUPPORT BRACKET	51701 37460		0%	350.00*
1000	1	SPACER,BODY MOUNTING	Renew		0%	140.00*
1000	1	SPRING TILT CAB,NO.1	Renew		0%	380.00*
1000	1	TOP UP AIRCON GAS	Renew		0%	50.00*

f: OEM Parts

g: Original

h: Secondhand

p: Parallel

x: Exchange

Sub Total

Mark Up From Cost (10 %)

Total Parts

\$4,135.00

\$413.50

\$4,548.50

THIS ASSESSMENT CONTAINS UNPRICED PARTS
 NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
LABOUR FRT SPECIALIST	0%	\$1,500.00
PORTION		
ALIGN F/CHASSIS SPECIALIST		\$600.00
FRAM		

Total Extras

\$2,100.00

Final Calculation

Total Parts

\$4,548.50

Labour

Total Panel/Mechanical

\$385.00

Total Paintwork

\$70.00

Total Labour

\$455.00

Additional Costs

Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$2,100.00	
Total of Additional Costs		\$2,100.00
Total Paint/Material Costs		\$0.00
Grand Total Excludes GST		\$7,103.50
GST @ 7 %		\$497.25
Grand Total Includes GST		\$7,600.75

Assessment Notes

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference: WL/MAY2018/001
Assessment Number: CTI10138
Version: LKKAUTOC/6
Date Calculated: 27/06/2018 09:42

Full Report - V1
Registration: GBD9787J
Printed: 27/06/2018 16:44

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	02/05/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:	WL/MAY2018/001	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:	LKK	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Dyna
Sub Model:	BASE MODEL
Model Sheet Number:	Y1C 01
Registration:	GBD9787J
Registration Month:	August
Registration Year:	2015
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%



Model Specs

FROM 01/2017	AIR CONDITIONING
4.0 LTR 100KW	DRIVER AIRBAG
STANDARD CAB	PAINTING OFF VEHICLE

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	15/05/2018
Place of Inspection:	Assessor	
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		



Addresses

Cost Summary

Total Labour	\$155.00
Total Parts	\$577.50
Total of Additional Costs	\$250.00
Excess:	TBA
Grand Total Exc GST:	\$982.50
7 % GST:	\$68.78
Grand Total Inc GST:	\$1,051.28

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR
 Price/Dent = \$50.00/HR

Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
520011	RENEW FRONT BUMPER INCLUDES: R + R BUMPER AND NECESSARY ATTACHED PARTS	10.0	50.00
751011	R + R RADIATOR GRILLE	3.0	15.00
810051)	R + R L/HEADLAMP (RADIATOR GRILLE REMOVED)	1.0	5.00
810151A	DOES NOT INCLUDE: ADJUST HEADLAMP ADJUST HEADLAMPS	3.0	15.00
LABOUR COST			
	Total Work Units	17.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	1.7HRS	\$85.00
	Paint Labour	1.4HRS	\$70.00
	Total Labour	3.1HRS	\$155.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$50.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- PAINTING OFF VEHICLE		
LE 0281	FRONT BUMPER NEW PART PAINT ST 1	11.0	
NO NUMBER	PAINT PREPARATION FOR PLASTIC PARTS (COMPOSITE WORK)	3.0	
LABOUR COST - PAINT			
	TIME(PAINT)	0.0	
	Total Work Units (10WU/HR)	14.0	
	Total Paintwork Labour	1.4HRS	\$70.00
MATERIAL COST - PAINT			
	Total Excluding Pearlescent Uplift		\$0.00

Pearlescent Uplift @ 0.0%						\$0.00
Total Paint Material Cost						\$0.00
PARTS						
				Price Valid: 01/06/2015		
Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
1000	1	F/DOOR CO.AD STICKER	Renew		0%	30.00*
281	1	FRONT BUMPER	52101 37A50		0%	140.00*
410	1	GRILLE	53111 37891		0%	90.00*
1000	1	HEADLAMP RH	Renew		0%	100.00*
571	1	LEFT HEADLAMP ASSY	81170 37121		0%	100.00*
1000	1	NUMBER PLATE	Renew		0%	15.00*
1000	1	TOP UP AIRCON GAS	Renew		0%	50.00*
f: OEM Parts			Sub Total			\$525.00
g: Original			Mark Up From Cost		(10 %)	\$52.50
h: Secondhand			Total Parts			\$577.50
p: Parallel						
x: Exchange						

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras	Description	Betterment	Price
	LABOUR FRT PORTION	0%	\$250.00
	SPECIALIST		
	Total Extras		\$250.00

Final Calculation

Total Parts	\$577.50
Labour	
Total Panel/Mechanical	\$85.00
Total Paintwork	\$70.00
Total Labour	\$155.00
Additional Costs	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$250.00
Total of Additional Costs	\$250.00
Total Paint/Material Costs	\$0.00
Grand Total Excludes GST	\$982.50
GST @ 7 %	\$68.78
Grand Total Includes GST	\$1,051.28

Assessment Notes



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939

Arrange By

Driver

LMC



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

LEE SHENG AUTO PTE LTD
NO.1 KAKI BUKIT AVE 6
#01-58 / 60 AUTOBAY

S'PORE 417883
TEL : 67477397 FAX : 67457138
ATTN : AH SHENG

SEND>>>NO 8 KAKI BUKIT AVE 4 #06-21 PREMIER@KAKI
BUKIT (GATE 2) (ZOLAR)

TAX INVOICE : AR201805-09591
DATE : 18/05/2018
CUSTOMER ID : LEE005
VEH REG. NO. : GBD9787J
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	T81130-37200/1 ROC KDY231	HEAD LAMP RH (ROC)	PA PL2-P1-090	1	100.00	100.00
2.	T81170-37200/1 ROC KDY231	HEAD LAMP LH (ROC)	PA PL2-N1-090	1	100.00	100.00
3.	T52101-25909/11 KDY231	FRT BUMPER ASSY (25911)	PA PL4-B1-F	1	140.00	140.00
4.	T53111-37700 ROC KDY231	FRT GRILLE (ROC)	PA PL2-P1-140	1	90.00	90.00

3 E

SUB-TOTAL : 430.00
ADD GST 7.00 % 30.10

E. & O.E TOTAL AMOUNT SGD : 460.10

[P] 18/05/2018 12:44:31PM

[E] 18/05/2018 12:42:56PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

Goods Received in Good Order

JAE Auto Pte. Ltd.

Sales Executive: HAN



* AR 201805-09591 *

This is computer generated document.
No signature is required.

Signature / Co Stamp / Date

ORIGINAL

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 May 2018 Sendback Est	16 May 2018 14:30 S\$12,789.00	16 May 2018 16:55 Edit Adj Rpt	S\$982.50 Edit Estimates	S\$982.50 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	JIA SENG TRADING PTE LTD , Co. Reg. No.: 200800861K		
Vehicle Reg. No.:	GBD9787J	Date of Loss:	02/05/2018 08:00 - :59 [32 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 557557	Policy/Cover Note No.:	28791913MKC (Comprehensive) Coverage: 06/08/2017 - 05/08/2018
		Excess:	S\$700.00
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Eliza Ho Teng Boon - 6594 2554]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 15/06/2018]		
Driver/Custodian:	QUEK SEIN CHIN (47 / Male), NRIC: S7032766Z, Tel: +6584982766		
Adj Asg. Remarks:	Survey and revert.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (18/05/2018): **Alert - Adj Mandate Approved (S\$1687.00) - GBD9787J - Claim Handler: Pearllyn Ka...**

ALL ASSOCIATED TASKS
















































[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

GBD9787J (557557)
OD
May 2 2018 8:00AM
[JIA SENG TRADING PTE LTD]
SMRT Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SMRT Automotive Services Pte Ltd (Woodlands)	Thumbnail	Print
1	03/05/18 14:28	Accident Statement	Load HTM	
2	16/05/18 14:30	Repairer Estimates	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/05/18 12:45	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
2	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
3	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
4	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
5	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
6	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
7	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
8	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
9	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
10	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
11	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
12	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
13	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
14	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
15	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
16	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
17	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
18	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
19	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
20	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
21	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
22	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
23	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
24	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
25	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
26	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
27	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
28	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
29	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
30	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>
31	17/05/18 17:03	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				
No	Finalized On	SMRT Automotive Services Pte Ltd (Woodlands)	Thumbnail	Print
32	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
33	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
34	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
35	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
36	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
37	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
38	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
39	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
40	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
41	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
42	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
43	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
44	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
45	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
46	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
47	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
48	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
49	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
50	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
51	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
52	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
53	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
54	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
55	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
56	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
57	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
58	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
59	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
60	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
61	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
62	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
63	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
64	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
65	17/05/18 17:03	General View	 Load JPG	<input checked="" type="checkbox"/>
66	17/05/18 17:04	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
67	17/05/18 17:04	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
68	18/05/18 17:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	18/05/18 17:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	18/05/18 17:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	18/05/18 17:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	18/05/18 17:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	18/05/18 17:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	18/05/18 17:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	18/05/18 17:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	18/05/18 17:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	18/05/18 17:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	18/05/18 17:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	18/05/18 17:54	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				<input checked="" type="checkbox"/>
No	Finalized On	SMRT Automotive Services Pte Ltd (Woodlands)	Thumbnail	Print
80	18/05/18 17:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	18/05/18 17:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	18/05/18 17:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	18/05/18 17:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	26/05/18 12:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	26/05/18 12:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	26/05/18 12:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	26/05/18 12:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	26/05/18 12:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/05/18 14:41	TP GIA Report	 Load PDF	
2	07/05/18 14:41	Enquire Transfer Fee	 Load PDF	
3	07/05/18 14:41	Enquire Rebate	 Load PDF	
No	Finalized On	SMRT Automotive Services Pte Ltd (Woodlands)	Thumbnail	Print
1	16/05/18 14:31	DL	 Load JPG	<input checked="" type="checkbox"/>
2	16/05/18 14:31	IC & DL	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/05/18 12:57	AUTODEX ADJUSTMENT	 Load PDF	
2	18/05/18 12:57	MARKING ESTIMATE	 Load PDF	
3	05/07/18 13:20	PARTS INVOICE	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser	<input checked="" type="checkbox"/>
No	Finalized On	SMRT Automotive Services Pte Ltd (Woodlands)	Thumbnail	Print	
1	03/05/18 14:28	Accident Statement	 Load HTM		
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	SMRT Automotive Services Pte Ltd (Woodlands)	Thumbnail	Print	
1	03/05/18 14:17	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
2	03/05/18 14:17	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
3	03/05/18 14:18	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
4	03/05/18 14:18	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
5	03/05/18 14:18	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
6	03/05/18 14:18	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
Documentation			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	SMRT Automotive Services Pte Ltd (Woodlands)	Thumbnail	Print	
1	03/05/18 14:25	Sketch Plan	 Load TIF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18008954/URD3S2**Date:** 05/07/2018REFERENCE

Insured/Claimant: JIA SENG TRADING PTE LTD
Date of Loss: 02/05/2018

Policy No: 28791913MKC
Nature of Claim: OD

Claim No: 557557

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBD9787J**
Make & Model: TOYOTA DYNA 150, 3.0 D (M)
Reg. Date: 06/08/2015 (Man. Year: 2015)
Colour: Silver
Engine Capacity: 2982 cc
Market Value/New Car Price: S\$65,000.00
Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 1KD2491422
Chassis No: JTFAT35Y60K204485
Odometer: 81877 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 155 R12 (D)
Front Left Side: Maxxis 6 mm Rear Left Side: Maxxis 6/6 mm
Front Right Side: Maxxis 6 mm Rear Right Side: Maxxis 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,359.00	522.50	6,836.50	92.90
Miscellaneous Items	2,730.00	0.00	2,730.00	100.00
Labour	1,500.00	460.00	1,040.00	69.33
Paintwork Labour	1,200.00	0.00	1,200.00	100.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,789.00	982.50	11,806.50	92.32
- Excess (S\$)	700.00	700.00	0.00	0.00
(S\$)	12,089.00	282.50	11,806.50	97.66
+ GST 7.00/7.00% (S\$)	846.23	19.78	826.45	97.66
Nett Amount (S\$)	12,935.23	302.28	12,632.95	97.66

INSPECTION

Date of Assignment: 16/05/2018 Present Location: SMRT Automotive Services Pte Ltd (Woodlands)
SMRT Automotive Services Pte Ltd (Woodlands)
Date Inspected: 17/05/2018 Inspected At: 60 Woodlands Industrial Park E4
Singapore 757705
Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 Jul 2018)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD9787J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS (WCP)		6,690.00 F	*- F
2	1		*FRONT BUMPER (WCP)	Distorted	-	*140.00 F
3	12		*FRONT BUMPER SCREW (NPA) (WCP)	Not Necessary	-	*- F
4	1		*GRILLE (WCP) }	Cracked	-	*90.00 F
5	1		*BADGE (WCP) }		-	*- F
6	1		*LEFT HEADLAMP ASSY (WCP)	Cracked	-	*100.00 F
7	1		*LEFT FRONT DOOR (WCP)	Repair	-	*- F
8	1		*L/F UPPER DOOR HINGE (WCP)	Not Necessary	-	*- F
9	1		*L/F LOWER DOOR HINGE (WCP)	Not Necessary	-	*- F
10	1		*L/F SUPPORT BRACKET (WCP)	Repair	-	*- F
11	1		*R/F SUPPORT BRACKET (WCP)	Repair	-	*- F
12	1		*SHIFT LINKAGE (WCP)	Not Necessary	-	*- F
13	1		*CONDENSER (WCP)	Not Necessary	-	*- F
14	1		*COMPR / CONDENSER TUBE (WCP)	Not Necessary	-	*- F
15	1		*FAN MOTOR (WCP)	Not Necessary	-	*- F
16	1		*DRYER / EVAP PIPE (WCP)	Not Necessary	-	*- F
17	1		*F/STEPBOARD GARNISH (WCP)	Not Necessary	-	*- F
18	1		*F/CROSSMEM SUB FRAME (WCP)	Not Necessary	-	*- F
19	1		*LOCK ASSY, TILT LH (WCP)	Serviceable	-	*- F
20	1		*LOCK ASSY, TILT RH (WCP)	Serviceable	-	*- F
21	1		*SPRING TILT CAB,NO.1 (WCP)	Not Necessary	-	*- F
22	1		*ARM.TILT CAB SPR SUP (WCP)	Not Necessary	-	*- F
23	1		*SPACER, BODY MOUNTING (WCP)	Not Necessary	-	*- F
24	1		*NUMBER PLATE (WCP)	Bent	-	*15.00 F
25	1		*F/DOOR CO.AD STICKER (WCP)	Necessary	-	*30.00 F
26	1		*HEADLAMP RIGHT (WCP)	Cracked	-	*100.00 F

F=Franchise part.

Sub Total (\$\$)	6,690.00	475.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	669.00	47.50
Total Parts (\$\$)	7,359.00	522.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OTHER COST	2,730.00	-
Sub Total (S\$)			2,730.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	LABOUR	New	1,200.00	0.00
<u>Labour Items</u>				
2	LABOUR	New	1,500.00	0.00
3	TOP UP AIR CON GAS.	New	-	55.00
4	LABOUR FRT PORTION.	New	-	250.00
5	RESPRAY AFFECT AREA.	New	-	0.00
6	REMOVE & REFIT CABIN.	New	-	0.00
7	APPLY ANTI RUSH.	New	-	0.00
8	ALIGN F/CHASSIS FRAM.	New	-	0.00
9	REP F/CHASSIS FRAME.	New	-	0.00
10	TOTAL PANEL / MECHANICAL.	New	-	85.00
11	TOTAL PAINTWORK.	New	-	70.00
Gross Labour Cost (S\$)			2,700.00	460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >