LUNGUOT	ASSIGNMENT (Office)
From (Person	assignment (onice)  Justine tok of M819 Date/Time: 16/5/188 3.54pm  Bill to:
	VS/TP RES/OD RES/EVA/INV/MV7CS
	Cehicle No: SLD 4569L Insured: SJE14R
of Ru	m/s Mova Automotive Tel: 6272 38 92 97762
Policy No.	C1008, 8k4 Meruh Lane 3 #01-04
Complete Inches	802377255MP Claim No: 558445
Sum Insured	DACCSS:
Make of Veh (Client's Recon	110513018
	14)
	0 0 0
CA / REV	/ REP. / REV 24 HRS (up) 31.05 2018 @ after 10 am H.O.D. Endorsement
CA / REV	1 REP. / REV 24 HRS (up) 31.052018 @ after 10 am H.O.D. Endorsement:  1 > Sam @ 17   S   18 Person Contacted:  Nither Vehicle IN / OUT
CA / REV	1. Sam & 17/5/18 Person Contacted: Nither Vehicle IN/OUT  Action/Instruction ( ) Estimate
CA / REV	Action/Instruction ( ) Estimate  WKSP IHS Specialist.
CA / REV	REP. / REV 24 HRS (up) 31.052018 @ after 10 am   H.O.D. Endorsement     Sam @ 17 S   Regression Contacted: Nither Vehicle IN. (OUT)    Action/Instruction ( ) Estimate   WKSP IHS Specialist     SLD 45691 - ×
CA / REV	Action/Instruction ( ) Estimate  WKSP IHS Specialist.

# ...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	AdJ Assigned	Adj Rpt	Ad) Sub	mitted	Ins Auth'ed	Status		
Main	15 May 2018		16 May 2018 15:54 Assign					Annual Control	ssignme Case	nt
	Main	Re	ference		Claim Details		Document	s		Show All
CLAIM SU	BFOLDER DE	TAILS		Section 1988		[Create	d by insurer]	- ALEXANDER CORP.	The Part of the Pa	
Insured:	CHAN AH	SUN, ID: S0982	352B			Loverson	a b ,ou. e. j			
Main Claimant:	YVONNE N	OK CHIA LI,	D: S8134965G							
Vehicle Reg No.:	SLD4569	PL .			Date of Loss:		018 00:00 - :59 ths and <b>21</b> Days Fr	om LTA R	leg Date (	Man Yr)]
Claim Type	: <b>TP</b> / 558	445			Policy/Cover Note No.:					
Vehicle Reg No. (Insured):	SJE14R				Policy No. (Claimant):					
					Excess:					
Repairer:	Mova Auto 62723892/	omotive Pte Ltd 64763333	(Bukit Merah)	Blk 1008, #	01-04/06/08/94	, Bukit Mer	ah Lane 3, 159722	Bukit Me	erah - Tel:	
Handling Insurer:	MSIG Inst	ırance (Singapo	re) Pte. Ltd. (H	<b>Q)</b> - Tel: +	55 6827 7888	[Handled	by <b>Jasmine Lok K</b>	heng Kw	vei - 6594	2550]
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Imm.Adv	ice due 1	17/05/2018]			
Adj Asg. Remarks:	ON WP Inst	ured not reported.	W/shop IHS Spe	ecialist , ple	ase assigned to	LKK to sur	vey.			
ASSOCIA	TED MAIL REG	CEIVED					17	View All	Compose	Case Mail
There are r	no mail for this	case.					_			
ALL ASSO	CIATED TAS	KS⊟				View All	Search Tasks	Create N	ew Task	Complete
Due Dat	e Priority	Type Task	Group Subj	ect Han	dler Assign	ned By	Completed On	Cre	ated On	Done

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 01 Jun 2018

## **Preliminary Advice**

Insured Vehicle No	: SJE14R		
TP Vehicle No	: SLD4569L	Accident Date	: 11/05/2018
Make	: VOLKSWAGEN GOLF MATCH TSI	Assignment Date	: 16/05/2018
Date of Inspection	: 31/05/2018	Est. Duration of Repair	: 3.00
Inspection At	: MOVA AUTOMOTIVE PTE LTD (BUK BLK 1008, #01-04/06/08/94, BUKIT M SINGAPORE 159722	T MERAH) ERAH LANE 3	

## Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,106.52
Revised Amount	:S\$	2,579.04
Check Items (Estimated)	:S\$	564.85
Total	:S\$	3,143.89

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

		$\sim$ 1	n	ALC:		•		V. I	-17	
м	U	u	u	NT	$\sim$ 1	A.	-	W.	-11	ш

Date Of Report 12/05/2018 12:55 Date Of Accident 11/05/2018 18:00 **Exact Location Of Accident** WEST RIDGE Country/State of Loss SINGAPORE

#### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number SLD4569L

#### Insured/Policyholder

Name Of Registered Owner YVONNE MOK CHIA LI

NRIC No S8134965G

Email Address KEDMOK@GMAIL.COM Mobile Phone No (LOCAL) +65-96830152 Alternative Phone No OTHERS-96830152

#### Vehicle Particulars

Manufacturer VOLKSWAGEN

Model GOLF MATCH 1.4 TSI DSG 5K12G5

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken THIRD PARTY Vehicle Category PRIVATE CAR

#### Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD Name of Insurance Company

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number

Cover Note Number

#### Driver

Name of Driver YVONNE MOK CHIA LI

NRIC No S8134965G Date Of Birth 15/10/1981 Occupation INDOOR Date Of Driving Pass 28/12/2000

Driving Experience 17 YEARS AND 4 MONTHS

Gender FEMALE.

Mobile Number (LOCAL) +65-96830152

Fax Number

Contact Number OTHERS-96830152

**EMail Address** KEDMOK@GMAIL.COM Address

BLK 61B STRATHMORE AVENUE

#10-28

Postcode

143061

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

.

#### General Information of the Accident

Type Of Accident

COLLIDED INTO PARKED VEHICLE

Weather Conditions

CLEAR

Road Surface

DRY

#### Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

YES

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

0

#### **Details of Police Action**

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

SJE14R

Vehicle Make/Model/Colour

**Details Of Properties** 

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### Sketch Plan Pg. 1

#### SKETCH PLAN

#### **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the Insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of .
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyhalder's Signature

Date & Time: 12 may 2018

Driver's Signature

(If driver is not the policyholder)

Date & Time

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

### Sketch Plan Pg. 2

f	
	Pavked.
4	
DESCRIBE CIRCUMSTANCES OF THE ACCIDEN	NT.
LICENSE PLATE: SLD 45(9 L	ACCIDENT DATE & TIME 11 MAY 2018
CONTACT NUMBER 9683015 2	E-MAIL ADDRESS KEDMOK@GMAIL COM
LOCATION WEST RIDGE	
informed one about +	e. Front right side above tyre is scratched. The other car party the accident when I ment back to
NOTE: PLEASE NOTE THAT YOUR INSUR	RER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN
	RER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN POLICY, PLEASE CHECK YOUR POLICY FOR MORE INFORMATION
OWN DAMAGE CLAIM UNDER YOUR OWN	
OWN DAMAGE CLAIM UNDER YOUR OWN	POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION
OWN DAMAGE CLAIM UNDER YOUR OWN Please state:  ( ) Claim Own Policy ( ) Claim Third Pa	POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION
OWN DAMAGE CLAIM UNDER YOUR OWN Please stake:  ( ) Claim Own Policy Claim Third Page CLARATION	POLICY, PLEASE CHECK YOUR POLICY FOR MORE INFORMATION arty ( ) Claim OD/TP at other workshop ( ) Reporting Only
OWN DAMAGE CLAIM UNDER YOUR OWN Please stake:  ( ) Claim Own Policy Claim Third Page CLARATION	POLICY, PLEASE CHECK YOUR POLICY FOR MORE INFORMATION arty ( ) Claim OD/TP at other workshop ( ) Reporting Only
OWN DAMAGE CLAIM UNDER YOUR OWN Please state:  ( ) Claim Own Policy  ( ) Claim Third Pare  ( ) Claim Own Policy  ( ) Claim Third Pare  ( ) Claim Third Par	POLICY, PLEASE CHECK YOUR POLICY FOR MORE INFORMATION arty ( ) Claim OD/TP at other workshop ( ) Reporting Only sery respect.
OWN DAMAGE CLAIM UNDER YOUR OWN Please state:  ( ) Claim Own Policy  Claim Third Particulars are true in evi  We declare the foregoing particulars are true in evi  Olicyholder's Signature  Driver's Sign	POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION  arty ( ) Claim OD/TP at other workshop ( ) Reporting Only  ery respect.  Reporting Centre Personnel's Signature not the policyholder)  Name:



# **Estimate**

14/05/2018

MSIG INSURANCE (S) PTE LTD (SGX CENTRE) 16, RAFFLES QUAY #24-01 HONG LEONG BUILDING SINGAPORE 048581.

Attention :- XA013

Page # :- 1

Veh # :- SLD4569L

Veh Model :- VOLKSWAGEN GOLF

Estimate# :- CK417435

Claim #

ACC. Date :- 11/05/18

Terms :- C.O.D Days

Remarks :-

Main Office: Mova Building No. 22, Jalan Kilang, Singapore 159419 Tel: (65) 6476 3333 Fax: (65) 6271 5891 www.mova.com.sg

Workshop Dept: Block 1008, Bukit Merah Lane 3, #01-04/06/08/94

Singapore 159722

Tel: (65) 6272 3892 Fax: (65) 6270 8314

Co. Reg. 198904033G GST Reg. M2-0088864-2

4,019.48

No.	Description		Qt	у	l	J.Price	Amounts S\$
1. 2. 3. 4.	LIST ITEMS: FRONT BUMPER FRONT BUMPER OUTER BRACKET RH FRONT OUTER SENSOR RH FRONT BUMPER SENSOR BRACKET		1 1 1 6	PC PC PC		1,293.65 156.36 238.75 38.75	7 de 156.36
5. 6. 7. 8. 9.	FRONT FOG LAMP COVER RH FRONT HEADLAMP WASHER JET RH FRONT FENDER RH FRONT WHEEL RIM RH - CHECK FRONT HEADLAMP RH - CHECK		1 1 1 1	PC PC PC PC		79.85	nn × 79.88 ht > 549.73
	LIST TOTAL S\$ 10% DISCOUNT S\$						2,740.58 -274.06
	To cheek warning light on \$350.00.15	50				***	2,466.52
	TO REPAIR FRONT HEADLAMP PANEL RH. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS & REALIGN ALL AFFECTED ALL  TO SPRAY PAINT ACCIDENT AFFECTED AREAS  TO INSPECT FRONT LIGHTING & WATER LEAKAGE TEST  TO REMOVE AND REPLACE FRONT SENSOR  TO RUST PROOF AFFECTED AREA  TO CONDUCT WHEEL ALIGNMENT  LABOUR TOTAL S\$	LKK Auto Consultants h the Repairer of the follo • To resurvey before/after spr • To display damaged part(s) • Parts prices are subject to c • Third party survey is on a "V • No illegal modification(s) is: • Supplementary item(s) must is subject to final approval fr  Acknowledged by Repairer Signature: Date:	wing ay pa durin onfirm tithou allow be n	g: einting g resurvey mation ut Prejudice ed esurveyed	and		36 6 480.00 480.00 20 40.00 30 80.00 20 60.00 NM X 80.00 1,290.00
	Jup' 31/5/18						4106.52
-	Resurg After repair.  Sur Chlantonum.  Sdays.	NON-T AMOUI GST @	ΝT		NT :	S	3,756.52 262.96

AMOUNT DUE S\$



Main Office; Mova Building No. 22, Jalan Kilang Singapore 159415 Tel: (65) 6476 3333 Fax: (65) 6271 5891 www.mova.com.sg

Workshop Dept: Block 1008 Bukit Merah Lane 3 #01-04/06/08/94 Singapore 159722

Tel: (65) 6272 3892 Fax: (65) 6270 8314

Co. Reg. 198904033G GST Reg. M2-0088864-2

Estimate

Attention :- XA013

14/05/2018

MSIG INSURANCE (S) PTE LTD (SGX CENTRE) 16, RAFFLES QUAY #24-01 HONG LEONG BUILDING SINGAPORE 048581.

Page #

SLD4569L Veh#

VOLKSWAGEN GOLF Veh Model :-

Estimate# :-

CK417435

Claim #

ACC. Date :- 11/05/18

Terms

:- C.O.D Days

Remarks

FRONT BUMPER OUTER BRACKET RH  FRONT OUTER SENSOR RH  FRONT BUMPER SENSOR BRACKET  FRONT FOO SAMP GOVER RH  FRONT HEADLAMP WASHER JET RH  FRONT HEADLAMP WASHER JET RH  FRONT HEADLAMP RH CHECK  FRONT HEADLAMP RH CHECK  FRONT HEADLAMP RH CHECK  LIST TOTAL SS  10% DISCOUNT SS  TO Cheek warning light on \$350.00.150  LABOUR: TO REPAIR FRONT HEADLAMP PANEL RH. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS & REALIGN ALL AFFECTED ALL  TO SPRAY PAINT ACCIDENT AFFECTED AREAS  TO INSPECT FRONT LIGHTING & WATER LEAKAGE  TEST  TO REMOVE AND REPLACE FRONT SENSOR  TO RUST PROOF AFFECTED AREA  TO CONDUCT WHEEL ALIGNMENT  LABOUR TOTAL SS  TANK 9 740 574  LUMPSUM \$ 2700.00 3D945  FE. & O.E  NON-TAX AMOUNT S	. [	Description		Qty	U.Price	Amounts S\$
TO Cheek warning light on \$350.00.150  LABOUR: TO REPAIR FRONT HEADLAMP PANEL RH. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS & REALIGN ALL AFFECTED ALL  TO SPRAY PAINT ACCIDENT AFFECTED AREAS  TO INSPECT FRONT LIGHTING & WATER LEAKAGE TEST  TO REMOVE AND REPLACE FRONT SENSOR  TO RUST PROOF AFFECTED AREA  TO CONDUCT WHEEL ALIGNMENT  LABOUR TOTAL SS  TOWN AFW APA'  E. & O.E  NON-TAX AMOUNT S		FRONT BUMPER FRONT BUMPER OUTER BRACKET RH FRONT OUTER SENSOR RH FRONT BUMPER SENSOR BRACKET FRONT FOG LAMP COVER RI I FRONT HEADLAMP WASHER JET RH FRONT FENDER RH FRONT WHEEL RIM RI I - CHECK FRONT HEADLAMP RH - CHECK		1 PC 1 PC 6 PC 1 PC 1 PC 1 PC	156.36 238.75 38.75 189.74	1,293.6 9 156.3 7 238.7 2 32.5 X 189.7 X 79.6 549.7 2,740.5
TO Cheek warning light on \$350.00.150  LABOUR: TO REPAIR FRONT HEADLAMP PANEL RH. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS & REALIGN ALL AFFECTED ALL  TO SPRAY PAINT ACCIDENT AFFECTED AREAS  TO INSPECT FRONT LIGHTING & WATER LEAKAGE TEST  TO REMOVE AND REPLACE FRONT SENSOR  TO RUST PROOF AFFECTED AREA  TO CONDUCT WHEEL ALIGNMENT  LABOUR TOTAL SS  TAMM 9749579  LUMPSUM \$2700.00 3DAMS  FAMILY AFFORMAN  E. & O.E  NON-TAX AMOUNT S						-274.0
TO REPAIR FRONT HEADLAMP PANEL RH. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS & REALIGN ALL AFFECTED ALL  TO SPRAY PAINT ACCIDENT AFFECTED AREAS  TO INSPECT FRONT LIGHTING & WATER LEAKAGE TEST  TO REMOVE AND REPLACE FRONT SENSOR  TO RUST PROOF AFFECTED AREA  TO CONDUCT WHEEL ALIGNMENT  LABOUR TOTAL SS  TAMAM 97465749  LUMPKUM \$ 2700.00 3DAYS  FUND 16 WE AND REPLACE FOR THE REAL AND		# 3	.150	*		2,466.5
LABOUR TOTAL SS Lumpsum \$ 2700.00 3DAYS  Tanking 97495749  Terry After apar.  Sur C Whantown.  E. & O.E  NON-TAX AMOUNT S		TO REPAIR FRONT HEADLAMP PANEL RH. REMOVE AN REPLACE ACCIDENT DAMAGED PARTS & REALIGN ALL AFFECTED ALL  TO SPRAY PAINT ACCIDENT AFFECTED AREAS  TO INSPECT FRONT LIGHTING & WATER LEAKAGE TEST	Parts \$ 2470.99 Jobour \$ 920			36.0 40.0 20 40.0 36.0 20
LABOUR TOTAL SS  TRANSMENT  LABOUR TOTAL SS  TRANSMENT  LUMPSUM \$ 2700.00 3DAYS  TRANSMENT  LUMPSUM \$ 2700.00 3DAYS  TRANSMENT APPRICE  SUF @ [Wanto wan. E. & O.E]  NON-TAX AMOUNT S		TO RUST PROOF AFFECTED AREA	total \$ 339099-	20%		60.0
Plenny After repair.  Sur @ Whento wom.  E. & O.E  NON-TAX AMOUNTS		TO CONDUCT WHEEL ALIGNMENT	·			χ 80.0
SUF @ Wearts win. / NON-TAX AMOUNTS		1 . 021/6821/6	Lumpsum \$ 2700.0	O 3DAYS	-	1,290.0
AMOUNT S\$ GST @ 7%  AMOUNT DUE S\$	4		AMOU GST (	JNT S\$ @ 7 %	-	3,756.5 262.9 4,019.4

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

# Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Wednesday, 1 August 2018 12:29 PM

To:

Ong, Germaine (VWG Singapore)

Subject:

ASSIST ON THE PARTS PRICES

Dear Germaine,

Kindly assist to check on the parts prices

VEHICLE MODEL: VOLKSWAGEN GOLF

YEAR: 2012

CHASSIS NO: WVWZZZ1KZDW 059026

1) FRONT BUMPER

2) FRONT OUTER SENSOR RH

3) FRONT FENDER RH

Many thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Monday, 6 August 2018 10:43 AM

To:

'Tan Yoong Wei'

Cc:

SUR

Subject:

RE: FINALISE SLD4569L

Dear Yoong Wei,

Noted with thanks.

# Kindly send Final invoice and all supporting documents to MSIG

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Yoong Wei <tanyw@mova.com.sg>

Sent: Friday, 3 August 2018 5:41 PM

To: Veron Chen (LKKAuto) < veronchen@lkkauto.com>

Subject: RE: FINALISE SLD4569L

Hi Veron,

We accept the offer \$2400

Best Regards, Tan Yoong Wei Estimator Mova Automotive Pte Ltd Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Friday, 3 August 2018 3:58 PM

To: Tan Yoong Wei

Cc: SUR

Subject: RE: FINALISE SLD4569L

Dear Yoong Wei,

Unable to finalise cost of repair \$2550.

Please closed at Lump Sum \$2400 with 3 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Yoong Wei < tanyw@mova.com.sg>

Sent: Friday, 3 August 2018 12:46 PM

To: Veron Chen (LKKAuto) < veronchen@lkkauto.com>

Subject: RE: FINALISE SLD4569L

Hi veron,

We finalise cost of repair \$2550 ok?

Best Regards,
Tan Yoong Wei
Estimator
Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Friday, 3 August 2018 10:57 AM
To: Tan Yoong Wei; Taufikh (LKKAuto); SUR

Subject: RE: FINALISE SLD4569L

Dear Yoong Wei,

# WITHOUT PREJUDICE

Kindly confirmed Lump Sum \$2400 with 3 working days.

Front bumper sensor bracket (6 pcs)-\$78/-

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Yoong Wei < tanyw@mova.com.sg> Sent: Wednesday, 1 August 2018 10:42 AM

To: Taufikh (LKKAuto) < Taufikh@lkkauto.com >; SUR < sur@lkkauto.com >

Subject: FINALISE SLD4569L

Hi taufikh,

Please advice whether we can finalise cost of repair lumpsum \$2700 with 3 working days?

Attached check item photo and after repair photo.

Thank you.

Best Regards,
Tan Yoong Wei
Estimator
Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314







This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

Page 1 of 1

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUB	FOLDER TRA	CKING							
Case Main	Notified 15 May 2018	Est Submitted	Adj Assigned 16 May 2018 15:54 Edit Adj Rpt	S\$2,400.00 Edit Estimates	5\$2	Submitted 2,400.00 lew Rpt	Ins Auth'ed	Pending Report Cancel	for Survey
	Main	R	eference	Claim D	etails		Documents	$\Box$	Show All
CLAIM SU	BFOLDER DE	TAILS SUN, ID: S0982	2352B			[Created I	by insurer]		
Main Claimant:		MOK CHIA LI,							
Vehicle Reg No.:	SLD456	9L		Date o	of Loss:		3 00:00 - :59 and <b>21</b> Days From L	TA Reg D	ate (Man Yr)]
Claim Type	: <b>TP</b> / 558	<b>TP</b> / 558445					MP (Comprehensive) 30/12/2017 - 29/12/2	2018	
Vehicle Reg No. (Insured):	SJE14R			Policy (Clain					
Repairer:	Mova Aut 62723892/		(Bukit Merah) Blk	Exces 1008, #01-04/06		Bukit Merah	Lane 3, 159722 Bukit	Merah -	Tel:
Handling Insurer:	NOT 151 CO. (1) CO. (1)					A	Jasmine Lok Kheng		
Adjuster:	15/06/20	Consultants Pte	Ltd (HQ) - Tel: 625	56-3561 [Hand	led by M	10HD TAUF	IKH BIN HAMID]	[Final F	Rpt due
Adj Asg. Remarks:	ON WP Ins	sured not reported	. W/shop IHS Specia	list , please assig	ned to L	KK to survey			
ASSOCIA	TED MAIL RE	CEIVED					View Al	Con	npose Case Mail
There are r	no mail for this	case.							
ALL ASSO	CIATED TAS	iks⊟				View All S	Search Tasks   Creat	e New Tas	k Complete
Due Dat		Type Task	Group Subject	Handler	Assign	ned By	Completed On	Created	I On Done

### Claim Documents

\*SLD4569L (558445) [SJE14R] TP
YVONNE MOK CHIA LI May 11 2018 12:00AM [CHAN AH SUN] Mova Automotive Pte Ltd

Ass	essment Reports		1 per page	~
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/06/18 16:46	Adjuster Immediate Advice	1 Load HTM	
Pho	otos/Images		3 per page	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	-
1	01/06/18 10:05	General View	■ Load JPG	V
2	01/06/18 10:05	General View	1 Load JPG	<b>V</b>
3	01/06/18 10:05	General View	Load JPG	V
4	01/06/18 10:05	General View	Load JPG	V
5	01/06/18 10:05	General View	■ Load JPG	V
6	01/06/18 10:05	General View	1 Load JPG	V
7	01/06/18 10:05	General View	1 Load JPG	~
8	01/06/18 10:05	General View	■ Load JPG	V
9	01/06/18 10:05	General View	Load JPG	V
10	01/06/18 10:05	General View	Load JPG	V
11	01/06/18 10:05	General View	1 Load JPG	V
12	01/06/18 10:05	General View	1 Load JPG	~
13	01/06/18 10:05	General View	1 Load JPG	V
14	01/06/18 10:05	General View	1 Load JPG	V
15	01/06/18 10:05	General View	⑥ Load JPG	V
16	01/06/18 10:05	General View	Load JPG	V
17	01/06/18 10:05	General View	1 Load JPG	V
18	01/06/18 10:05	General View	1 Load JPG	V
19	01/06/18 10:05	General View	1 Load JPG	V
20	01/06/18 10:05	General View	1 Load JPG	V
21	01/06/18 10:05	General View	1 Load JPG	V
22	01/06/18 10:05	General View	1 Load JPG	V
23	01/06/18 10:05	General View	1 Load JPG	V
24	01/06/18 10:05	General View	1 Load JPG	V
25	01/06/18 10:05	General View	1 Load JPG	V
26	01/06/18 10:05	General View	1 Load JPG	V
27	01/06/18 10:05	General View	1 Load JPG	V
28	01/06/18 10:05	General View	1 Load JPG	V
29	01/06/18 10:05	General View	Load JPG	<b>V</b>
30	01/06/18 10:05	General View	Load JPG	<b>V</b>
31	01/06/18 10:05	General View	Load JPG	V
32	03/08/18 10:50	Reinspection Photo	Load JPG	V
33	03/08/18 10:50	Reinspection Photo	Load JPG	<b>V</b>
34	03/08/18 10:50	Reinspection Photo	1 Load JPG	1

Page 2 of 2

Ass	essment Reports		1 per i	page 🗸	V
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
					<b>∀</b>
35	03/08/18 10:50	Reinspection Photo	0	Load JPG	<b>V</b>
36	03/08/18 10:50	Reinspection Photo	0	Load JPG	V
37	03/08/18 10:50	Reinspection Photo	0	Load JPG	<b>✓</b>
38	03/08/18 10:50	Reinspection Photo	0	Load JPG	<b>V</b>
39	03/08/18 10:50	Reinspection Photo	0	Load JPG	<b>V</b>
40	03/08/18 10:50	Reinspection Photo	0	Load JPG	<b>V</b>
41	03/08/18 10:50	Reinspection Photo	0	Load JPG	✓
42	03/08/18 10:50	Reinspection Photo	0	Load JPG	<b>Y</b>
Doc	cumentation		1 per	page V	<b>V</b>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	_
1	16/05/18 14:01	TP EST BILL & ACCDT REPORT	0	Load PDF	

## **Documents Checklist**

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

### LKK Auto Consultants Pte Ltd (Co.Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG18008958/T1VD3E2

Date:

16/08/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

80237725SMP

Claimant Vehicle

SLD4569L

Insured Vehicle No:

SJE14R

No: Date of Loss:

11/05/2018

Nature of Claim:

TP

Claim No: 558445

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

SLD4569L

Make & Model:

VOLKSWAGEN GOLF MATCH TSI, 1.4 (A)

Engine No:

CAXC07858

47083 km

Reg. Date:

20/11/2012 (Man. Year: 2012)

Chassis No: Odometer:

WWZZZ1KZDW039026

Colour:

White

**Engine Capacity:** Market Value/New Car 1390 cc

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side:

Continental 6 mm

Rear Left Side:

Continental 6 mm

Front Right Side:

Continental 6 mm

Rear Right Side:

Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,466.52	2,084.84	381.68	15.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,640.00	920.00	720.00	43.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,106.52	3,004.84	1,101.68	26.83
Approved Total (Overridden) (S\$)		2,400.00		
(S\$)	4,106.52	2,400.00	1,706.52	41.56
+ GST 7.00/7.00% (S\$)	287.46	168.00	119.46	41.56
Nett Amount (S\$)	4,393.98	2,568.00	1,825.98	41.56

INSPECTION

Date of Assignment:

16/05/2018

Date Inspected:

31/05/2018 Inspected At:

Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah

Lane 3

Singapore 159722

Estimated Period of Repair:

3.0 days

Adjuster Report Page 2 of 4

Adjuster: MOHD TAUFIKH BIN HAMID Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

### REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Aug 2018)

VOLKSWAGEN GOLF MATCH TSI 1.4 (A) (Catalogue: Merimen Singapore 1.0) Parts: 144

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLD4569L)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page Validity:

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,293.65 FL	*1,293.65 FL
2	1		*FRONT BUMPER OUTER BRACKET RH	Deformed	156.36 FL	*156.36 FL
3	1		*FRONT OUTER SENSOR RH	Not Working	238.75 FL	*238.75 FL
4	6		*FRONT BUMPER SENSOR BRACKET	Necessary	232.50 FL	*78.00 FL
5	1		*FRONT FOG LAMP COVER RH	Not Necessary	189.74 FL	*- FL
6	1		*FRONT HEADLAMP WASHER JET RH	Not Necessary	79.85 FL	*-FL
7	1		*FRONT FENDER RH	Bent	549.73 FL	*549.73 FL
8	1		*FRONT WHEEL RIM RH (NPA)	Not Necessary	0.00 FL	*- FL
9	1		*FRONT HEADLAMP RH (NPA)	Not Necessary	0.00 FL	*- FL
F=Fra	anchise	part. L=ListIt	emDisc.		5000 St. 5000 St. 500	040040000000000000000000000000000000000
				Sub Total (S\$)	2,740.58	2,316.49
			- List Item Discount on L Items	10.00/10.00% (S\$)	274.06	231.65
				Total Parts (S\$)	2,466.52	2,084.84
						•

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WARNING LIGHT ON	New	350.00	150.00
2	TO REPAIR FRONT HEADLAMP PANEL RH. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS & REALIGN ALL AFFECTED ALL	New	480.00	300.00
3	TO SPRAY PAINT ACCIDENT AFFECTED AREAS	New	550.00	400.00
4	TO INSPECT FRONT LIGHTING & WATER LEAKAGE TEST	New	40.00	20.00
5	TO REMOVE AND REPLACE FRONT SENSOR	New	80.00	30.00
6	TO RUST PROOF AFFECTED AREA	New	60.00	20.00
7	TO CONDUCT WHEEL ALIGNMENT	New	80.00	0.00
	Gross Labo	our Cost (S\$)	1,640.00	920.00
	Report was unsubmitted during	g this print-out.		

< END OF ESTIMATES >