

ASS. REC. BY:

REF:

CS/EG18008966/Und3ⁿ² Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Yee Pei Li of EGI Date/Time: 17/5/18 @ 11:33am

Estimated Cost: Bill to:

OD (TP) AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKC 5747A Insured: SJH 98083

at Workshop m/s Teo Spray Painting Tel: 6283 5474

of Blk 6 Defu Lane 70 # 01-558

Policy No: Claim No: DSMPC1800908 / SL / P1

Sum Insured: Excess:

Make of Veh: D.O.A. 08/05/2018
(Client's Record) 18/05/2018

CA / REV / REP. / REV 24 HRS (wp) H.O.D. Endorsement:

Date/Time: 11:56am @ 17/5/18 Person Contacted: Su chee Vehicle IN (OUT)

Date/Time	Action/Instruction (X) Estimate
	SKC 5747A - X
	SJH 98083 - X
22/5	Revert from email

(08/11/13) wef

REF:

ASS. REC. BY: Marcus

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKC 5747at Workshop m/s Tan Guan

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: 1 Consistent? : Yes or NoEst. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

62835474

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKC5747A Yr Regn: 9, 12Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: mer bent 8250 C.C. 1796Colour: blue A/C: Insured / Std / NI / NASp. Reading: 148888 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD21204724631999Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 265/35-22R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 8/5/18 D.O.I. 18/5/18

Survey held at _____

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop orRear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LTA 722327/6/18 L/S 2200 confirmed with suchan.red: 84952.25, 691.

RECEIVED 07 JUN 2018

Date/Time, File Pass to?

☐ : Preli. Report1) typist☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: TPLump Sum / L.B.I: (\$ 2200)250



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: DSMPC1800908/SL/pl
Our Ref: CS/EGI18008966/Urd3

The Motor Claims Department
ERGO Insurance Pte Ltd

Without Prejudice


Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SKC 5747A .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 18/05/2018 at the premises of M/s TEO SPRAY PAINTING PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ 7,152.25 .
Revised Estimate Amount	: S\$ 2,456.34 .
"Check" Items Amount	: S\$ 1,973.10 .
Market Value	: S\$.
LTA Reimbursement Value	: S\$.
Nett Value	: S\$.

Description of Damage:
The vehicle sustained damages
at the rear portion..



Comments/ Present Status:
Damages Consistent.

Yours faithfully

MARCUS
Automotive Assessor

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Thursday, 17 May 2018 11:33 AM
To: 'admin-d@lkkauto.com'
Subject: OI : SJH9808S / TP : SKC5747A/LKK / DOA : 08/05/2018 (DSMPC1800908)
Attachments: SJH9808S - SAS.pdf; SKC5747A - SAS.pdf; SKC5747A - PRS FORM.pdf; PRS request for SKC5747A (4.47 KB)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **TEO SPRAY PAINTING**,

ADDRESS : BLK 6 DEFU LANE 10
#01-558 DEFU INDUSTRIAL PARK C
SINGAPORE 539187

PERSON TO CONTACT : IRENE @ 6283 5474

ERGO OFFICER-IN-CHARGE : ROHAINI

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 17.05.2018
Our Reference: DSMPC1800908/SL/pl
Your Reference: SKC 5747A

To: TEO SPRAY PAINTING

Sent via Fax
or
Email

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SKC 5747A
Insured's Vehicle: SJH 98085
Date Of Accident: 08.05.2018


We acknowledge receipt of your request for PRS on: 17.05.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

<input checked="" type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's complete GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input type="checkbox"/>	Our Insured's driver has not reported the accident to us todate.
<input checked="" type="checkbox"/>	Others: <u>OFFICER-IN-CHARGE - STEVE LIM</u>

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

Up to 64% off Car Insurance
with SG's No. 1 Motor Insurer

Receive \$150
shopping vouchers*

FIND OUT MORE

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Honda Stream 1.8A RSZ



\$2800 Downpayment Monthly
From \$738 Onwards. Lowest
3.68%P.A@GV Cars Financing
GV Credit Pte Ltd StarAd



Browse by Category ▼

« Back (1 2) Next »

Sort by

24 vehicles

Mercedes Benz e250

Advanced

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mile
Search Selection	Mercedes Benz e250		Any	Any	2012	Any	
	Mercedes-Benz E-Class E250 Avantgarde		\$87,999	\$14,070 /yr	17-Sep-2012	1,796 cc	95
Mercedes Benz E250 7G-Tronic Avantgarde Model Selling At The Price Of A Normal Specs Model, Fully C&C Maintained, E Drive, Accident Free, Nice Selenite Grey Metallic, Origin...							
Posted: 18-May-2018 Tags: 2012 Mercedes-Benz E250, Mercedes-Benz E250, Mercedes-Benz, E250, Used Mercedes-Benz							
	Mercedes-Benz E-Class E250 Cabriolet		\$110,000	\$21,990 /yr	19-Jan-2012	1,796 cc	45
100% Accident Free. Very Low Mileage As Owner Is Overseas 2 Weeks Per Month. Always Parked Under Shelter. Well M. Excellent Condition. Just Changed The Tires At Hurry Tyres. A...							
Posted: 17-May-2018 Tags: 2012 Mercedes-Benz E250, Mercedes-Benz E250, Mercedes-Benz, E250, Used Mercedes-Benz							
	Mercedes-Benz E-Class E250 CGI		\$92,555	\$15,520 /yr	29-Aug-2012	1,796 cc	52
Lowest Pricing And Depreciation In Market! Fully Maintained And Serviced By C&C With Lowest Genuine Mileage Of 5200 And Gearbox Mouting Replaced. High OMV Value! Immaculate O...							
Posted: 17-May-2018 Tags: 2012 Mercedes-Benz E250, Mercedes-Benz E250, Mercedes-Benz, E250, Used Mercedes-Benz							
	Mercedes-Benz E-Class E250		\$77,888	\$13,610 /yr	26-Jan-2012	1,796 cc	14
Down Payment \$7,800 Only! From \$1,360/Month. Luxurious Sedan Maintained By Fervent Owner! C&C Unit, Maintained Workshop! No Expense Spared On Wear And Tears! Only Sheltered Parking!...							
Cars 88 Pte Ltd							
Posted: 17-May-2018 Tags: 2012 Mercedes-Benz E250, Mercedes-Benz E250, Mercedes-Benz, E250, Used Mercedes-Benz							

Car Buying

Car Selling

Car Ownership

Compare

On The Move

Lifestyle



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3631A
Vehicle Details	
Vehicle No.:	SKC5747A
Vehicle to be Exported:	No
Intended De-registration Date:	18 May 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E 250
Primary Colour:	Blue
Manufacturing Year:	2012
Engine No.:	27186030484278
Chassis No.:	WDD2120472A631999
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$52,184.00
Original Registration Date:	21 Sep 2012
First Registration Date:	21 Sep 2012
Transfer Count:	1
Actual ARF Paid:	\$52,184.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Sep 2022
PARF Rebate Amount:	\$36,528.00
Intended COE Rebate Details	
COE Expiry Date:	20 Sep 2022
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$86,999.00
COE Rebate Amount:	\$35,704.00
Total Rebate Amount:	\$72,232.00

The information contained herein is correct as at 18 May 2018

OK



張 噴 漆 TEO SPRAY PAINTING

(INCORPORATED IN THE REPUBLIC OF SINGAPORE)
Reg. Address: BLOCK 6, DEFU LANE 10, DEFU INDUSTRIAL PARK C, #01-558
SINGAPORE 539187 TEL: 6283 5474 (2 LINES) FAX: 6287 2012
REG. NO. 275084 / 00X

Ergo Insurance Pte Ltd
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel : 68299199
Email : ergoinsurance@ergo.com.sg

18.05.2018

RE : Third Party Claims For SKC5747A Against SJH98085,
Accident On 08.05.2018 At Alexandra Road

The following damages are:

1)	REAR BUMPER	DO/AE 1513.62	\$ 2,318.00	✓
2)	REAR BUMPER LOWER GARNISH	8 inch	\$ 662.00	✓ 485.15
3)	REAR REINFORCEMENT	✓	\$ 1,009.00	X
4)	TAIL LAMP PANEL	✓	\$ 1,571.00	X
5)	TAIL LAMP PANEL INNER GARNISH	17	\$ 162.00	X
6)	REAR SENSOR	subhl 2PCS	\$ 350.00	✓
	sub total		\$ 6,072.00	
	less 10%		\$ 607.20	
	sub total		\$ 5,464.80	

add nett items:

1)	Spray	\$ 380.00	350
2)	Labour charges	\$ 550.00	300
3)	Insurance enquiry	\$ 7.45	
4)	Loss of use @ \$150 x 5 days	\$ 750.00	?
	sub total	\$ 1,687.45	
	Total	\$ 7,152.25	6394.80

P-2348.77
102
2113.89
2763.89
2211

Thank you
Teo Spray Painting
Irene

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:


Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD			Ref : CS/EGI18008966/Urd3n2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985			Date : 08-06-2018	
			Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJH 9808S	Veh. Inspected	SKC 5747A	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMPC1800908/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	17/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E250	c.c	1796	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WDD2120472A631999	Colour	BLUE	
Odometer	148888	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	265/35 ZR18	DUNLOP	6 mm	
L/H Front Tyre	265/35 ZR18	DUNLOP	6 mm	
R/H Rear Tyre	265/35 ZR18	DUNLOP	6 mm	
L/H Rear Tyre	265/35 ZR18	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/05/2018	Inspection Date	18/05/2018	
Survey held at	TEO SPRAY PAINTING BLK 6 DEFU LANE 10 DEFU IND PARK C #01-558 SINGAPORE 539187			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKC 5747A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED / DEFORMED	2,318.00	1,513.62
1	REAR BUMPER LOWER GARNISH	GRAZED	662.00	485.15
1	REAR REINFORCEMENT	TO REPAIR SEE LABOUR	1,009.00	-
1	TAIL LAMP PANEL	TO REPAIR SEE LABOUR	1,571.00	-
1	TAIL LAMP PANEL INNER GARNISH	NOT NECESSARY	162.00	-
2	REAR SENSOR	SHORTED	350.00	350.00
	LESS 10% DISCOUNT		-607.20	-234.88
			5,464.80	2,113.89
LABOUR				
	SPRAY.		380.00	350.00
	LABOUR CHARGES INCLUSIVE OF THE REPAIR OF REAR REINFORCEMENT AND TAIL LAMP PANEL.		550.00	300.00
			930.00	650.00
GRAND TOTAL			6,394.80	2,763.89
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,200.00

Report Ref No. CS/EG18008966/Urd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.