

REF:

NS/INC18008967 / Sghnz

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

XE 5658

Policy No:

00619834 03-04 03/02017

Claims No:

M7/0994278-002

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

8 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHC 4212T

Yr Regn:

13/12/13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

c.c 1798

Colour:

Maroon

A/C:

Insured / Std / NI / NA

Sp. Reading

603317

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKN364205713930

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/65 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal.

6 mm

R/Bal.

6

mm

L/Bal.

6 mm

L/Bal.

6

mm

D.O.A.

13/5/18

D.O.I.

15/5/18

Survey held at

SMRT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SHC 4212T - PS/EGZ17016079/Sghnz

PRT: 180317 TR V/05/18/2058

XE 5658 - X

Lick

NTUC

13/5/18 (Red # 16416.42, 78%)

XE 5658

RECEIVED 08 JUN 2018

Date/Time, File Pass to?



Preli. Report

11/08/16 11:55 AM



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

8

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format:

7p

Lump Sum / I.B.A. (\$

4600

160

35

195



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18008967/Sqb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 17-05-2018
189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 565B	Veh. Inspected	SHC 4212T
Policy No.	5061983403-04	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	15/05/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	13/05/2018	Inspection Date	15/05/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="13/05/2018 13:45"/>						
Vehicle No. (For Motor)	<input type="text" value="XE565B"/>								
<input type="button" value="Search"/>									
Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5061983403-04	CHIANG KIONG ENVIRONMENTAL PTE. LTD.	200106873W	GFT	Comprehensive	XE565B	XE565B	03/10/2017	
<input type="button" value="Continue"/>									

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Estimate	Tentative repair cost
1	MT/0997402-002	COMFORT TRANSPORTATION PTE LTD	SHA 3102U	SIK 4437X	03/06/2018	\$ 2,431.58	\$ 450.00
2	MT/0996966-002	CITYCAB PTE LTD	SHA 8202G	SJF 5615T	01/06/2018	\$ 2,077.44	\$ 1,100.00
3	MT/0997824-001	CITYCAB PTE LTD	SHA 811B	SLH 5573X	30/05/2018	\$ 3,265.96	\$ 2,850.00
4	MT/0994720-002	SMRT TAXI PTE LTD	SHB 5571E	GU 5967J	15/05/2018	\$ 6,170.40	\$ 2,240.23
5	MT/0992549-002	SMRT TAXI PTE LTD	SHF 441J	SHB 8401T	01/05/2018	\$ 26,621.94	\$ 8,100.00
6	MT/0994278-002	SMRT TAXI PTE LTD	SHC 4212T	XE 565B	13/05/2018	\$ 21,016.42	\$ 4,600.00
7	MT/0997827-001	SMRT TAXI PTE LTD	SHC 4382K	SKT 1790K	19/05/2018	\$ 1,449.70	\$ 300.00
8	MT/0994682-002	SMRT TAXI PTE LTD	SHC 4536J	GBD 5726L	14/05/2018	\$ 5,555.30	\$ 950.00
9	MT/0997288-002	COMFORT TRANSPORTATION PTE LTD	SHD 3230S	SIN 6185T	02/06/2018	\$ 2,736.58	\$ 1,302.98
10	MT/0997833-001	COMFORT TRANSPORTATION PTE LTD	SHC 1781L	SIT 1714T	03/06/2018	\$ 5,712.98	\$ 2,300.00
11	MT/0997524-002	COMFORT TRANSPORTATION PTE LTD	SHA 3460K	GBG 4353U	05/06/2018	\$ 2,752.02	\$ 900.00
12	MT/0997717-002	COMFORT TRANSPORTATION PTE LTD	SHC 2931P	GBC 3789Z	05/06/2018	\$ 2,751.20	\$ 1,250.00
13	MT/0996973-002	COMFORT TRANSPORTATION PTE LTD	SHA 3075P	FBE 3401G	01/06/2018	\$ 1,087.44	\$ 508.00
14	MT/0997835-001	COMFORT TRANSPORTATION PTE LTD	SHA 3514P	SJA 2496R	04/06/2018	\$ 2,836.58	\$ 800.00

Claim received from LKK Auto

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/05/2018 12:12
Date Of Accident	13/05/2018 04:25
Exact Location Of Accident	SCOTTS RD AND CAIRNHILL RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4212T
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	ERIC LIM TZE BOON
NRIC No	S1766556A
Date Of Birth	17/06/1966
Occupation	OUTDOOR
Date Of Driving Pass	19/01/1993
Driving Experience	25 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 22
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLOUDY
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: UNKNOWN
 GENDER: MALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name TOA PAYOH NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 93 TOA PAYOH CENTRAL TOA PAYOH COMMUNITY BUILDING ,
 POSTCODE: 319194 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-2519999 - FAX NO: 63548749
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT - T/20180513/2017

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: FILE TO BIG
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XE565B
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver LI YUANGE
 NRIC/Passport Number
 Contact Number
 Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

ERIC LIM TZE BOON

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SHC4212T

Were seat belts worn?


Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 14 MAY 2018

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 14 MAY 2018


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180513/2017

1 of 4

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

Report No. T/20180513/2017

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/05/2018 06:59	Vide Report No.:	Station Diary No.: 16
--	------------------	--------------------------

Informant's Particulars

Name of Informant: ERIC LIM TZE BOON			Address: APT BLK 509 SERANGOON NORTH AVENUE 4 #02-372 SINGAPORE 550509	
ID Type / ID No.: NRIC NO / S1766556A			Contact No.: Home/Office:	Mobile: 87528546
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 51	Date of Birth: 17/06/1966	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 2B,3,4 Date of Expiry:	

General Information of the Accident

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 13/05/2018 04:25	Type of Location: T-Junction
Location: Junction of Road 1 and Road 2 SCOTTS ROAD CAIRNHILL ROAD T-junction of Scotts Road and Cairnhill Road.				
Weather: Cloudy		Road Surface: Wet		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC4212T	Car	TOYOTA	PRIUS	Maroon	Seriously Damaged	1
XE565B	Truck	MAN		White	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180513/2017

2 of 4

Report No. T/20180513/2017

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

CONTINUATION OF REPORT

Driver			
Name	ERIC LIM TZE BOON		ID No. S1766556A
Related Vehicle	SHC4212T (Car)		Contact No. 87528546
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL		Class of Driving Licence & Expiry Date Class: 2B,3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Driver			
Name	LI YUANGE		ID No. G8297871U
Related Vehicle	XE565B (Truck)		Contact No. 81228267
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 13/05/2018 at about 0427hrs, I was driving my taxi (SMRT, maroon colour Toyota Prius, vehicle registration number SHC4212T) with one male passenger at the rear left seat along Cairnhill Road. The road is a 3 lane 2-way road. I was on the left most lane and came to stop at the red traffic light at the T-junction. A truck (white coloured, vehicle registration number XE565B) was on my right.

The traffic light turned green so I turned left onto Scotts Road. The truck also turned left. Suddenly, the truck came into my lane and the side of the truck collided into the front right area of my taxi. Due to the accident, my taxi's front bumper dropped out, front right headlight dropped out, and the bonnet cover was dented upwards.

The driver and I alighted our vehicles and exchanged particulars. We also took photographs of the incident. My taxi could not be driven any more so it was towed away to the workshop. My passenger did not complain of any injury and got onto another taxi.

No Police or ambulance attended to the accident. There is a front camera installed in the taxi and has been handed over to my company. Due to the accident, I felt pain in my back, neck and right arm so I went to Mount Alvernia Hospital for a check-up and was granted medical leave for 5 days from 13/05/2018 to 17/05/2018.



**SINGAPORE
POLICE FORCE**



T/20180513/2017

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

CONTINUATION OF REPORT

3 of 4
Report No. T/20180513/2017

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHC4212T
Vehicle to be Exported:	No
Intended De-registration Date:	16 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2013
Engine No.:	2ZR5934737
Chassis No.:	JTDKN36U205713930
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,120.00
Original Registration Date:	13 Dec 2013
First Registration Date:	13 Dec 2013
Transfer Count:	0
Actual ARF Paid:	\$8,368.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Dec 2021
PARF Rebate Amount:	\$6,276.00
Intended COE Rebate Details	
COE Expiry Date:	12 Dec 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$62,740.00
COE Rebate Amount:	\$28,006.00
Total Rebate Amount:	\$34,282.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 16 May 2018

OK

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4212T
 Ref. No : TAX/05/18/2058
 Reg. Date : 13/12/2013
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : ERIC LIM TZE BOON
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 13/05/2018 04:25:00 AM
 Accident Reported Date / Time : 14/05/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 13/05/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024096055
 Special Instruction to ARC, if any :
 TOWED \$40 / XE565B - NTUC IDAC
 Prepared Date : 14/05/2018 12:56:56 PM



Sebastian
 15/5/18
 - Linc Sun Repair.
 - Question Mark Item
 Photo
 - Photo After Paint

Jminto
 25/5/18

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U20-5713930

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,352.00	0.00
Total Spray Painting Charges	: 2,412.00	0.00
Total Material Charges	: 10,019.52	10,019.52
Other Charges	: 1,686.88	0.00
TOTAL	: 15,470.40	0.00
Lum Sum Total	: 15,450.00	0.00
No. of Repair Days	: 8.00	0.00 6 days
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 14/05/2018 03:28:14 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 14/05/2018 03:28:14 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	1,352.00	0.00 800
Total Labour	1,352.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	378.00	0.00 200
TO RESPRAY VIEW MIRROR	180.00	0.00 X
TO RESPRAY FRONT FENDER RH	378.00	0.00 200
TO RESPRAY APRON PANEL RH	180.00	0.00 ?
TO RESPRAY RIM	180.00	0.00 50
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0.00 X
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00 100
TO REPSRAY FRONT HOOD	378.00	0.00 200
Total Spray Painting & Panel Beating	2,412.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00 X
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 40
TO TRANSFER DOOR MECHANISM	120.00	0.00 X
TO REMOVE AND REFIX WING MIRROR	120.00	0.00 50
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 60
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 30
TO REMOVE AND REFIT TYRE	120.00	0.00 X
TO TOP UP A/C GAS	120.00	0.00 ?
TO CONDUCT RADIATOR PRESSURE CHECK	100.00	0.00 ?
TO REMOVE AND REFIT WIRE HARDESS	150.00	0.00 ?
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	0.00 ✓
Total Other Costs	1,686.88	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
67001-47070		6505528	DOOR FRT/RH	1	894.40	25.00	670.80	Replace	Replace <i>R</i>	No
68710-12151			HINGE UPPER RHF, DOOR	1	80.50	25.00	60.37	Replace	Replace <i>?</i>	No
68730-12120			HINGE LOWER RHF, DOOR	1	90.10	25.00	67.57	Replace	Replace <i>?</i>	No
68610-47021			CHECK ASSY, FR DOOR,	1	150.30	25.00	112.72	Replace	Replace <i>?</i>	No
87910-47330		6505600	MIRROR ASSY, RH	1	1,307.10	25.00	980.32	Replace	Replace <i>Y</i>	No
879157-4010		6505598	COVER, OUTER MIRROR, RH	1	107.40	25.00	80.55	Replace	Replace <i>✓</i>	No
81730-52090		6505466	MIRROR LAMP RH	1	65.30	10.00	58.77	Replace	Replace <i>✓</i>	No <i>SCR</i>
87931-47200			MIRROR GLASS RH	1	212.80	25.00	159.60	Replace	Replace <i>X</i>	No
53801-47050		6505557	FENDER FRT/RH	1	723.40	25.00	542.55	Replace	Replace <i>✓</i>	No <i>Defect</i>
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace <i>✓</i>	No <i>NGC</i>
53701-47050			FENDER APRON SUB FRT/RH	1	637.80	25.00	478.35	Replace	Replace <i>?</i>	No
53875-47030		6505553	FENDER LINER FRT/RH	1	171.70	25.00	128.77	Replace	Replace <i>✓</i>	No <i>TN</i>
53851-47040			FENDER LINER PAD, FR WHEEL, RH	1	49.30	25.00	36.97	Replace	Replace <i>✓</i>	No <i>MS</i>
42611-47140 (Frt)		6505658	WHEEL DISC. FRONT	1	1,484.20	25.00	1,113.15	Replace	Replace <i>R</i>	No
		6503707	TYRE	1	126.74	0.00	126.74	Replace	Replace <i>X</i>	No
85315-47140			WIPER WASHER JAR	1	180.10	25.00	135.07	Replace	Replace <i>✓</i>	No <i>Defect</i>
85330-47010			MOTOR NO:1, WIPER WASHER JAR	1	239.00	10.00	215.10	Replace	Replace <i>?</i>	No
85330-60180			MOTOR NO:2, WIPER WASHER JAR	1	240.00	10.00	216.00	Replace	Replace <i>?</i>	No
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace <i>✓</i>	No <i>CRK</i>
52115-47040		6505515	BUMPER SUPPORT F/RH	1	76.40	25.00	57.30	Replace	Replace <i>✓</i>	No <i>MS</i>
52116-47040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Replace <i>✓</i>	No <i>NGC</i>
81511-47050			LENS & BODY, FR TURN RH	1	511.80	10.00	460.62	Replace	Replace <i>✓</i>	No <i>CRK</i>
81519-47050			BRACKET, FR TURN LOWER RH	1	26.00	25.00	19.50	Replace	Replace <i>?</i>	No
81519-47060			BRACKET, FR TURN UPPER RH	1	24.40	25.00	18.30	Replace	Replace <i>?</i>	No
81519-47060			BRACKET, FR TURN	1	58.20	25.00	43.65	Replace	Replace <i>?</i>	No
88710-47150			TUBE & ACCESSORY	1	631.90	25.00	473.92	Replace	Replace <i>?</i>	No
81210-12230		6505439	FOG LAMP RH	1	295.20	10.00	265.68	Replace	Replace <i>?</i>	No
52127-47903			COVER, FR BUMPER HOLE RH	1	18.50	25.00	13.87	Replace	Replace <i>X</i>	No
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.32	Replace	Replace <i>X</i>	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
76851-47020		6505616	BUMPER LIP FRT	1	139.60	25.00	104.70	Replace	Replace X	No
52618-47050		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	25.00	95.77	Replace	Replace ?	No
53113-47040			GRILLE RADIATOR LOWER NO.2	1	94.60	25.00	70.95	Replace	Replace X	No
53201-47902			SUPPORT SUB-ASSY	1	1,460.40	25.00	1,095.30	Replace	Replace ?	No
53289-47032			COVER, RADIATOR	1	122.80	25.00	92.10	Replace	Replace X	No
81170-47500		6505436	HEAD LAMP LH	1	945.20	10.00	850.68	Replace	Replace X	No
81130-47500		6505437	HEAD LAMP RH	1	945.20	10.00	850.68	Replace	Replace ✓	No MS
16281-37030			RADIATOR HOSE, BYPASS NO.4	1	37.20	25.00	27.90	Replace	Replace ?	No
53301-47060		6505555	HOOD PANEL	1	748.10	25.00	561.07	Replace	Replace R	No
53420-47070			HOOD HINGE LH	1	55.90	25.00	41.92	Replace	Replace ✓	No BT
53410-47070			HOOD HINGE RH	1	55.90	25.00	41.92	Replace	Replace ✓	No BT
53395-47020			HOOD END PANEL SEAL	1	35.50	25.00	26.62	Replace	Replace ?	No
53876-47030		6505554	FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace X	No
53852-47020			FENDER LINER PAD, FR WHEEL. LH	1	49.30	25.00	36.97	Replace	Replace X	No
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Replace ?	No
57014-47030			ARM SUB-ASSY, FR BUMPER LH	1	250.40	25.00	187.80	Replace	Replace ?	No
57013-47030			ARM SUB-ASSY, FR BUMPER RH	1	250.40	25.00	187.80	Replace	Replace ?	No
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Replace ?	No
65319-47120			WIPER WASHER INLET	1	36.90	25.00	27.67	Replace	Replace X	No
82113-47180			WIRE, ENGINE ROOM, NO.3	1	242.00	10.00	217.80	Replace	Replace ?	No
TOTAL MATERIALS							12,306.70	12,306.60		
TOTAL MATERIALS(Discounted)							10,019.52	10,019.52		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									



Attached
Supplementary

chia

22-5-18 / 01:00
ARV 22-5-18 / 13:00

23-5-18 / 08:00

SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4212T
Ref. No : TAX/05/18/2058
Reg. Date : 13/12/2013
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : ERIC LIM TZE BOON
Type of Accident : SIDE SWIPE
Date / Time of Accident : 13/05/2018 04:25:00 AM
Accident Reported Date / Time : 14/05/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : Sebastian
Vehicle is Towed Back? : Yes
Towed Back Date/Time : 13/05/2018
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024096055
Special Instruction to ARC, if any :

TOWED \$40 / XE565B - NTUC IDAC
BEFORE PAINT PHOTO AND AFTER REPAIR PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL
SURVEYOR SEBASTIAN (LKK) & Email : sebastianyeang @lkkauto.com HP:90036121
LUMP SUM REPAIR

Prepared Date : 14/05/2018 12:56:56 PM



16-5-18 / 08:00

23/5

ADV


45

11:25


22-5-18

pass

Recording Camera



Radio Antenna



1st witness

[Signature]

Date

15-5-18

2nd witness

[Signature]

Date

22-5-18

1/2
KM 60377

Vehicle to Waga Date In: 16/5/18	Towing: <input checked="" type="checkbox"/>
Time In: —	Driver: —
Waga Job No: 05/0210	
Vehicle sent to SMRT Date In: 22/5/18	Towing: <input checked="" type="checkbox"/>
Time In: 1015	Driver: <i>[Signature]</i>
Received by (SMRT): <i>[Signature]</i>	

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U20-5713930

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,352.00	1,100.00
Total Spray Painting Charges	: 2,412.00	1,050.00
Total Material Charges	: 4,664.76	3,104.71
Other Charges	: 1,606.88	-654.71
TOTAL	: 10,035.64	4,600.00
Lump Sum Total	: 0.00	0.00
No. of Repair Days	: 8.00	8.00 /
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	: 14/05/2018 03:28:14 PM	15/05/2018 04:25:52 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 14/05/2018 03:28:14 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1805-0576

Invoice No :

Quotation Date : 24/5

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	1,352.00	1,100.00 ✓
Total Labour	1,352.00	1,100.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	378.00	200.00 ✓
TO RESPRAY VIEW MIRROR	180.00	0.00
TO RESPRAY FRONT FENDER RH	378.00	200.00 ✓
TO RESPRAY APRON PANEL RH	180.00	100.00 ✓
TO RESPRAY RIM	180.00	50.00 ✓
TO REPSRAY FRONT BUMPER	378.00	200.00 ✓
TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0.00
TO RESPRAY FRONT SUPPORT PANEL	180.00	100.00 ✓
TO REPSRAY FRONT HOOD	378.00	200.00 ✓
Total Spray Painting & Panel Beating	2,412.00	1,050.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40.00 ✓
TO TRANSFER DOOR MECHANISM	120.00	0.00
TO REMOVE AND REFIX WING MIRROR	120.00	50.00 ✓
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60.00 ✓
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30.00 ✓
TO REMOVE AND REFIT TYRE	120.00	0.00
TO TOP UP A/C GAS	120.00	0.00
TO CONDUCT RADIATOR PRESSURE CHECK	100.00	0.00
TO REMOVE AND REFIT WIRE HARDESS	150.00	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88 ✓ Nec
Lump Sum Adjustment by Surveyor	0.00	-1,131.59
Total Other Costs	1,606.88	-654.71

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
67001-47070		6505528	DOOR FRT/RH	1	894.40	100.00	0.00	Replace	Repair	No <i>R</i>
68710-12151			HINGE UPPER RHF, DOOR	1	80.50	25.00	60.38	Replace	Check	No <i>X</i>
68730-12120			HINGE LOWER RHF, DOOR	1	90.10	25.00	67.58	Replace	Check	No <i>X</i>
68610-47021			CHECK ASSY, FR DOOR,	1	150.30	25.00	112.73	Replace	Check	No <i>X</i>
87910-47330		6505600	MIRROR ASSY, RH	0	1,307.10	25.00	0.00	Replace	Not given	No <i>X</i>
879157-4010		6505598	COVER, OUTER MIRROR, RH	0	107.40	25.00	0.00	Replace	Not given	No <i>X</i>
81730-52090		6505466	MIRROR LAMP RH	1	65.30	10.00	58.77	Replace	Replace	No <i>SCR</i>
87931-47200			MIRROR GLASS RH	0	212.80	25.00	0.00	Replace	Not given	No <i>NW</i>
53801-47050		6505557	FENDER FRT/RH	1	723.40	25.00	542.55	Replace	Replace	No <i>Defect</i>
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No <i>NEC</i>
53701-47050			FENDER APRON SUB FRT/RH	1	637.80	25.00	478.35	Replace	Check	No <i>NW</i>
53875-47030		6505553	FENDER LINER FRT/RH	1	171.70	25.00	128.77	Replace	Replace	No <i>TN</i>
53851-47040			FENDER LINER PAD, FR WHEEL, RH	1	49.30	25.00	36.97	Replace	Replace	No <i>MS</i>
42611-47140 (Frt)		6505658	WHEEL DISC. FRONT	1	1,484.20	100.00	0.00	Replace	Repair	No <i>R</i>
		6503707	TYRE	0	126.74	0.00	0.00	Replace	Not given	No <i>NW</i>
85315-47140			WIPER WASHER JAR	1	180.10	25.00	135.07	Replace	Replace	No <i>Defect</i>
85330-47010			MOTOR NO:1, WIPER WASHER JAR	1	239.00	10.00	215.10	Replace	Check	No <i>X</i>
85330-60180			MOTOR NO:2, WIPER WASHER JAR	1	240.00	10.00	216.00	Replace	Check	No <i>NW</i>
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace	No <i>CHK</i>
52115-47040		6505515	BUMPER SUPPORT F/RH	1	76.40	25.00	57.30	Replace	Replace	No <i>MS</i>
52116-47040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Replace	No <i>NEC</i>
81511-47050			LENS & BODY, FR TURN RH	1	511.80	10.00	460.62	Replace	Replace	No <i>CHK</i>
81519-47050			BRACKET, FR TURN LOWER RH	1	26.00	25.00	19.50	Replace	Check	No <i>X</i>
81519-47060			BRACKET, FR TURN UPPER RH	1	24.40	25.00	18.30	Replace	Check	No <i>X</i>
81519-47060			BRACKET, FR TURN	1	58.20	25.00	43.65	Replace	Check	No <i>X</i>
88710-47150			TUBE & ACCESSORY	1	631.90	25.00	473.93	Replace	Check	No <i>NW</i>
81210-12230		6505439	FOG LAMP RH	1	295.20	10.00	265.68	Replace	Check	No <i>X</i>
52127-47903			COVER, FR BUMPER HOLE RH	0	18.50	25.00	0.00	Replace	Not given	No <i>X</i>
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.33	Replace	Replace <i>S</i>	No <i>Defect</i>

9323.94

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
76851-47020		6505616	BUMPER LIP FRT	0	139.60	25.00	0.00	Replace	Not given	No X
52618-47050		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	25.00	95.78	Replace	Check	No X
53113-47040			GRILLE RADIATOR LOWER NO.2	0	94.60	25.00	0.00	Replace	Not given	No X
53201-47902			SUPPORT SUB-ASSY	1	1,460.40	25.00	1,095.30	Replace	Check	No X
53289-47032			COVER, RADIATOR	0	122.80	25.00	0.00	Replace	Not given	No X
81170-47500		6505436	HEAD LAMP LH	0	945.20	10.00	0.00	Replace	Not given	No X
81130-47500		6505437	HEAD LAMP RH	1	945.20	10.00	850.68	Replace	Replace	No X
16281-37030			RADIATOR HOSE, BYPASS NO.4	1	37.20	25.00	27.90	Replace	Check	No X
53301-47060		6505555	HOOD PANEL	1	748.10	100.00	0.00	Replace	Repair	No R
53420-47070			HOOD HINGE LH	1	55.90	25.00	41.92	Replace	Replace	No X
53410-47070			HOOD HINGE RH	1	55.90	25.00	41.92	Replace	Replace	No X
53395-47020			HOOD END PANEL SEAL	1	35.50	25.00	26.63	Replace	Check	No X
53876-47030		6505554	FENDER LINER FRT/LH	0	171.70	25.00	0.00	Replace	Not given	No X
53852-47020			FENDER LINER PAD, FR WHEEL. LH	0	49.30	25.00	0.00	Replace	Not given	No X
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Check	No X
57014-47030			ARM SUB-ASSY, FR BUMPER LH	1	250.40	25.00	187.80	Replace	Check	No X
57013-47030			ARM SUB-ASSY, FR BUMPER RH	1	250.40	25.00	187.80	Replace	Check	No X
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Replace S	No X
65319-47120			WIPER WASHER INLET	0	36.90	25.00	0.00	Replace	Not given	No X
82113-47180			WIRE, ENGINE ROOM, NO.3	1	242.00	10.00	217.80	Replace	Check	No X
TOTAL MATERIALS							7,288.73	3,104.72		
TOTAL MATERIALS(Discounted)							4,664.76	3,104.71		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

3104.71 /
 + 1100.00 /
 + 1526.88 /
 5731.59 /
 - 20%
 4585.27 /

45 \$4600/-
 Sebastian
 7/6/18

21040.82

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18008967/Sqbn2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 19-06-2018

189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 565B	Veh. Inspected	SHC 4212T
Policy No.	5061983403-04	Coverage (\$)	0.00
Claim No.	MT/0994278-002	Excess (\$)	0.00
Assign From		Assign Date	15/05/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JTDKN36U205713930	Colour	MAROON
Odometer	603317	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/05/2018	Inspection Date	15/05/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4212T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FENDER FRT/RH (DISC 25%)	DEFORMED	723.40	542.55
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.92
1	FENDER LINER FRT/RH (DISC 25%)	TORN	171.70	128.77
1	FENDER LINER PAD,FR WHEEL,RH (DISC 25%)	MISSING	49.30	36.97
1	WIPER WASHER JAR (DISC 25%)	DEFORMED	180.10	135.07
1	BUMPER FRT (DISC 25%)	CRACKED	482.00	361.50
1	BUMPER SUPPORT F/RH (DISC 25%)	MISSING	76.40	57.30
1	BUMPER SUPPORT F/LH (DISC 25%)	NECESSARY	76.40	57.30
1	BUMPER GRILLE SUB-ASSY, LOWER (DISC 25%)	DEFORMED	311.10	233.33
1	HOOD HINGE LH (DISC 25%)	BENT	55.90	41.92
1	HOOD HINGE RH (DISC 25%)	BENT	55.90	41.92
1	BUMPER ENERGY ABSORBER FRT (DISC 25%)	CRACKED	78.80	59.10
1	MIRROR LAMP RH (DISC 10%)	SCRATCHED	65.30	58.77
1	LENS & BODY,FR TURN RH (DISC 10%)	CRACKED	511.80	460.62
1	HEAD LAMP RH (DISC 10%)	MISSING	945.20	850.68
1	ADVERTISEMENT STICKER (SN)	NECESSARY	296.88	296.88
1	HINGE UPPER RH, DOOR	NOT NECESSARY	80.50	-
1	HINGE LOWER RH, DOOR	NOT NECESSARY	90.10	-
1	CHECK ASSY,FR DOOR	NOT NECESSARY	150.30	-
1	MIRROR ASSY,RH	NOT NECESSARY	1,307.10	-
1	COVER, OUTER MIRROR,RH	NOT NECESSARY	107.40	-
1	MIRROR GLASS RH	NOT NECESSARY	212.80	-
1	FENDER APRON SUB FRT/RH	NOT NECESSARY	637.80	-
1	TYRE	NOT NECESSARY	126.74	-
1	MOTOR NO.1 WIPER WASHER JAR	NOT NECESSARY	239.00	-
1	MOTOR NO.2 WIPER WASHER JAR	NOT NECESSARY	240.00	-
1	BRACKET,FR TURN LOWER RH	NOT NECESSARY	26.00	-
1	BRACKET,FR TURN UPPER RH	NOT NECESSARY	24.40	-
1	BRACKET,FR TURN	NOT NECESSARY	58.20	-
1	TUBE & ACCESSORY	NOT NECESSARY	631.90	-

Report Ref No. NS/INC18008967/Sqbn2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FOG LAMP RH	NOT NECESSARY	295.20	-
1	COVER,FR BUMPER HOLE RH	NOT NECESSARY	18.50	-
1	BUMPER LIP FRT	NOT NECESSARY	139.60	-
1	BUMPER FRT ABSORBER LOWER	NOT NECESSARY	127.70	-
1	GRILLE RADIATOR LOWER NO 2	NOT NECESSARY	94.60	-
1	SUPPORT SUB-ASSY	NOT NECESSARY	1,460.40	-
1	COVER.RADIATOR	NOT NECESSARY	122.80	-
1	HEAD LAMP LH	NOT NECESSARY	945.20	-
1	RADIATOR HOSE,BYPASS NO 4	NOT NECESSARY	37.20	-
1	HOOD END PANEL SEAL	NOT NECESSARY	35.50	-
1	FENDER LINER FRT/LH	NOT NECESSARY	171.70	-
1	FENDER LINER PAD,FR WHEEL LH	NOT NECESSARY	49.30	-
1	BUMPER REINFORCEMENT FRT	NOT NECESSARY	498.40	-
1	ARM SUB-ASSY,FR BUMPER LH	NOT NECESSARY	250.40	-
1	ARM SUB-ASSY,FR BUMPER RH	NOT NECESSARY	250.40	-
1	WIPER WASHER INLET	NOT NECESSARY	36.90	-
1	WIRE ENGINE ROOM,NO 3	NOT NECESSARY	242.00	-
1	DOOR FRT/RH	TO REPAIR	894.40	-
1	WHEEL DISC,FRONT	TO REPAIR	1,484.20	-
1	HOOD PANEL	TO REPAIR	748.10	-
			15,966.82	3,401.60
	LABOUR			
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		2,402.00	1,240.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		2,512.00	1,090.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			5,074.00	2,330.00
	GRAND TOTAL		21,040.82	5,731.60
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			4,600.00

Report Ref No. NS/INC18008967/Sqbn2



Page No.:3 of 3

Report Ref No. NS/INC18008967/Sqbn2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

**BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.