

Celebrity Auto

17/05/2018

176 Sin Ming Drive

#03-12 S575721

Hp:90222411

Email: Celebrityautosg@gmail.com

To: Great American Insurance Group

Your Ref: SLB6078J

Cc: Ngian Kelvyna / LKK Auto Consultants

Chassis No: **WBA2E320905B44884**

SLB6078J

Section A

PARTS	Damaged	Qty	Price
LH Side mirror complete set with motor	1	1	1258.32
LH Rear passager door	Dent	1	1251.90
LH rear passager fender	Dent	1	1669.20
			4179.42

Special Nett Items

door panel clips	nec	10	55
		Total	55

Section B : Labour Cost

To dismantle parts, replace, cut, weld knock out dents to straighten accident parts as mentioned on the PARTS REPAIR column inclusive of replacement.	\$55/per hrs	36	1980
Spray painting to adjacent panels, job allowance. Paint / Material	Sub -Contract work		1100
Apply rust proofing on the adjacent panels	Sub -contract work		60
Wiring job	\$55/per hrs	1hrs	55
Computer reset after install			120

		Total Labour cost	3315
--	--	-------------------	------

Section C Total repair cost

Damaged parts (section A)	
Discount	
Cost of replacement parts +special items	

Labour Cost (section B)	
--------------------------	--

Total repair cost	
-------------------	--

We recommend a sum of \$\$

X

Leslie Yeo
Manager