

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5660B**AAD1805-065**

Not Notified
11 Sep @ 5250h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5660B

VF1ABL15AUC281153

RENAULT

LATITUDE

7.5.2018

China Tp.

PART		LIST
1 BUMPER COVER FRT	\$	<i>Bu</i> 1,259.42 ✓
1 BUMPER SPOILER FRT	\$	<i>SL</i> 181.75
1 BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68
1 BUMPER RETAINER FRT RH	\$	<i>SL</i> 150.77
1 BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88
1 BUMPER UNDERTRAY FRT	\$	<i>SL</i> 472.83
1 BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80
1 BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i> 207.21
1 BUMPER BEAM FRT	\$	<i>R</i> 914.08
1 HEADLAMP RH	\$	<i>CRT</i> 1,184.43 ✓
1 HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15 X
1 FENDER PANEL FRT RH	\$	<i>R</i> 783.83 X
1 WHEELARCH FRT RH	\$	<i>SL</i> 278.84 X
1 FENDER BRACKET LOWER RH	\$	<i>SL</i> 15.79 X
1 FENDER INSULATOR RH	\$	<i>SL</i> 130.84 X
1 DOOR PANEL FRT RH	\$	<i>R</i> 2,844.66 X
1 RADIATOR GRILLE	\$	<i>CRT</i> 1,707.78 ✓
1 RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>M</i> 225.36 ✓
1 RADIATOR GRILLE FRAME	\$	<i>CRT</i> 1,353.75 ✓
1 RADIATOR FAN COWLING	\$	<i>SL</i> 820.54 X
1 RADIATOR FAN MOTOR LH	\$	<i>SL</i> 967.36 X
1 RADIATOR FAN MOTOR RH	\$	<i>SL</i> 1,479.46 X

TOTAL	\$	15,916.22
10%	\$	1,591.62
	\$	14,324.60

Trans-cab Auto Services Pte Ltd**AAD1805-065**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5660B**Specical Nett**

1SET	BUMPER CLIP FRT	\$	66.00	✓
1	BUMPER BRACKET CLIP FRT RH	\$	12.00	X
1	BUMPER SUPPORT CLIP FRT RH	\$	10.50	X
1SET	BUMPER GRILLE LOWER CLIP	\$	69.00	✓
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	✓
2	FRAME FULL SUPPORT PANEL NUT	\$	20.00	} X
2	FRAME FULL SUPPORT PANEL STUD	\$	30.00	
1SET	WHEELARCH CLIP FRT RH	\$	30.50	
1	FRONT DOOR STICKER 'Trans-cab'	\$	80.00	
1	FRONT DOOR STICKER 'Chassis'	\$	50.00	
1	RIGHT REAR TYRE	\$	380.00	

TOTAL	\$	818.00
--------------	-----------	---------------

TOTAL PARTS	\$	15,142.60
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,500.00	5000
Putty and spray painting of the affected portion.	\$	3,000.00	4400
To rust-proofing of the affected areas.	\$	170.00	300
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	200

Trans-cab Auto Services Pte Ltd

AAD1805-065

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5660B

To transfer of front fender fittings, attachment
and perform water seepage test.

\$ *Na* 380.00 *X*

To vacuum, replace, refix and recharge air
condenser

\$ 380.00 *100%*

To replace, refix and top up coolant for radiator

\$ 170.00 *50%*

To vacuum, replace, refix and recharge Air
Intercooler

\$ 170.00 *50%***TOTAL \$ 8,710.00****Over All Total \$ 23,852.60****LUMP SUM (REPAIR DAY)**~~10 DAYS~~*3 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: