

REF:

FWD LPL

ASSIGNMENT

From:

Date:

16/5/18

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SGN 8882 L

at Workshop m/s

Ethicarz

of

56 Loyeng Way # 04-04

Insured:

Policy No.

5781

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

8

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS¹up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SGN 8882 L

Yr Regn:

29 Dec 2011

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mini One

C.C

1598

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

85165

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WMWSR320807Y59829

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

175 / 65 R15

R:

DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

14/5/18

D.O.I.

16/5/18

Survey held at

Ethicarz

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front / Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

16-8-18

L/S \$12,000/-

Cred: \$10,542.21 (46%)

Date/Time. File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time. File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others:

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Weekend (\$




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18008994/K1ua3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 17-05-2018	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJG 2916P	Veh. Inspected	SGN 8882L	
Policy No.	Z18VP05018247	Coverage (\$)	0.00	
Claim No.	18/18/18/VP05/020603	Excess (\$)	0.00	
Assign From		Assign Date	17/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	14/05/2018	Inspection Date	16/05/2018	
Survey held at	ETHICARZ PTE LTD 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING SINGAPORE 508775			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Toyota Vellfire 2.5A Z G-Edition



Ready Stock Immediate
Registration, Viewing Available.
Call Us For More Info
StarAd

Free VICOM evaluation
Free grooming and 6 months maintenance
In-house workshop ensures quality service
Member of SYTA and hire purchase association
100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category

Sort by Date Posted 20 results/page

3 vehicles

MINI One

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	MINI One		Any	Any	2011	Any	Any	Any	Available
	MINI One 1.6A		\$39,800	\$9,710 /yr	27-Jun-2011	1,598 cc	102,000 km	Hatchback	Available
Lowest Price In The Market, 100% Accident Free And No Repairs Needed, 1 Careful Owner Service At BMW Workshop, View And Test Drive To Believe, Call Early Before The Beauty Is Sold.									
Posted: 11-May-2018 Tags: 2011 MINI One, MINI One, MINI One, Used MINI									
	MINI One 1.6A		\$37,800	\$10,210 /yr	28-Feb-2011	1,598 cc	160,347 km	Hatchback	Available
Buy With A Peace Of Mind, 1 Owner, 100% Genuine Mileage, No Chassis/Structural Damage, Immaculate Condition. All Trade In Welcome, Flexible Financing Package. Non-Consignment Unit, Open For Viewing Da...									
Posted: 10-May-2018 Tags: 2011 MINI One, MINI One, MINI One, Used MINI									
	MINI One 1.6A		\$45,388	\$10,270 /yr	15-Nov-2011	1,598 cc	-	Hatchback	Available
Iconic Mini Cooper That Doesn't Fail To Turn Heads While You Cruise Pass, Smooth 1.6i Natural Aspired Engine That's Ideal For City Driving Providing Low Fuel Consumption, Superb Driving Experience And...									
Kart Automobile									
Posted: 01-May-2018 Tags: 2011 MINI One, MINI One, MINI One, Used MINI									

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & CPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used MINI One, MINI One Singapore, used MINI One Singapore, used MINI One, used vehicles Singapore or even buy used MINI One Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us Careers Contact Us Sitemap Terms of Service Privacy Policy Personal Data Protection Statement

©2004-2018 sgCarMart. All rights reserved.

> Back to OneMotoring



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5789I
Vehicle Details	
Vehicle No.:	SGN8882L
Vehicle to be Exported:	No
Intended De-registration Date:	16 May 2018
Vehicle Make:	MINI
Vehicle Model:	ONE 1.6 AT ABS D/AIRBAG 2WD 3DR
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	B155J019N16B16A
Chassis No.:	WMWSR32080TY59829
Maximum Power Output:	72.0 kW (96 bhp)
Open Market Value:	\$18,255.00
Original Registration Date:	29 Dec 2011
First Registration Date:	29 Dec 2011
Transfer Count:	1
Actual ARF Paid:	\$18,255.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Dec 2021
PARF Rebate Amount:	\$11,865.00
Intended COE Rebate Details	
COE Expiry Date:	28 Dec 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$50,001.00
COE Rebate Amount:	\$18,078.00
Total Rebate Amount:	\$29,943.00

The information contained herein is correct as at 16 May 2018

OK

Sketch Plan Pg. 4



BLOCK 150 CANBERRA DRIVE
THE BROWNSTONE
#12-05
SC7680791



Ethicarz Pte. Ltd. 56 Loyang Way, Singapore (508775) #04-04
Loyang Enterprise Building, Email: kelvinwo@ethicarz.sg
Tel: 63844404, FAX: 63840444

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE: FRONT
TYRE: REAR
CHASSIS NUM:

SGN8882L
MINI ONE
WMWSR32080TY59829

ATTN:			
NO.	DESCRIPTION - PARTS	QTY	PRICE
1	REAR BOOT ✓	1	
2	REAR BOOT LOCK ✕	1	
3	REAR BOOT W/STRIP ✕	1	
4	REAR BOOT HINGE L + R ✕	2	
5	REAR BOOT LOGO ✓	1	
6	REAR BOOT EMBLEM - ONE ✓	1	
7	REAR BOOT W/S GLASS MOLD ✕ ✓	1	
8	REAR BOOT INNER TRIM ✕	1	
9	REAR BOOT ABSORBER L + R ✕	2	
10	REAR BUMPER ✓	1	
11	REAR BUMPER RETAINER L + R ✕	2	
12	REAR BUMPER BRACKET L + R ✕	2	
13	REAR BUMPER LAMP L + R ✕	2	
14	REAR BUMPER TOWING CAP ✓	1	
15	REAR BUMPER LOWER ✓	1	
16	REAR BUMPER REINFORCEMENT ?	1	
17	REAR BUMPER CENTER GARNISH (INNER) ✓	1	
18	REAR BUMPER CLIP ✓	10	
19	REAR BUMPER SPONGE ?	1	
20	REAR BUMPER UNDER COVER ?	1	
21	REAR END PANEL ✕ <i>Myati</i>	1	
22	REAR END PANEL TOP GARNISH ?	1	
23	REAR END PANEL TOP GARNISH CLIP ?	10	
24	REAR SPARE WHEEL PANEL ✕	1	
25	REAR SPARE WHEEL PANEL TOP BOARD ✕	1	
26	REAR FENDER PROTECTOR L + R ✕	2	
27	REAR FENDER COWLING L + R ✕	2	
28	REAR FENDER COWLING CLIP L + R ✕	2	
29	REAR EXHAUST PIPE ?	1	
30	REAR EXHAUST PIPE MTG ?	1	
31	REAR EXHAUST PIPE HEAT SEAL ✓	1	
32	REAR EXHAUST PIPE GASKET ?	1	
33	FRONT BONNET ✓	1	

34	FRONT BONNET LOGO /	1	
35	FRONT BONNET CHROME (FRONT) /	1	
36	FRONT BONNET HEADLAMP CHROME L + R /	2	
37	FRONT BONNET HINGE L + R /	2	
38	FRONT BONNET LOCK L + R /	2	
39	FRONT BONNET ABSORBER L + R X	2	
40	FRONT BONNET CHROME (REAR) X	1	
41	FRONT GRILLE ASSY /	1	
42	HEADLLAMP L + R /	2	
43	FRONT BUMPER /	1	
44	FRONT BUMPER RETAINER L + R X	2	
45	FRONT BUMPER BRACKET L + R X	2	
46	FRONT BUMPER SPONGE L + R X	2	
47	FRONT BUMPER REINFORCEMENT L + R X	2	
48	FRONT BUMPER GRILLE /	1	
49	FRONT BUMPER GRILLE GARNISH /	1	
50	FRONT BUMPER FOG LAMP L + R X	2	
51	FRONT BUMPER FOG LAMP BRACKET L + R X	2	
52	FRONT BUMPER LOWER X	1	
53	FRONT BUMPER CLIP /	1	
54	FRONT FENDER L + R X Repair	2	
55	FRONT FENDER PROTECTOR L + R X	2	
56	FRONT FENDER COWLING L + R X	2	
57	FRONT FENDER COWLING CLIP L + R X	2	
58	HORN X	1	
59	FRONT SUPPORT PANEL /	1	
60	AIR CON CONDENSER /	1	
61	AIR CON CONDENSER SIDE GARNISH L + R /		
62	AIR CON CONDENSER LIQUID PIPE ?	1	
63	AIR CON CONDENSER SUCTION PIPE ?	1	
64	AIR CON CONDENSER DISCHARGE PIPE ?	1	
65	RADIATOR /	1	
66	RADIATOR ELECTRIC FAN COWLING ASSY /	1	
67	RADIATOR TOP HOSE ?	1	
68	RADIATOR SPARE TANK ?	1	
69	RADIATOR SPARE TANK HOSE ?	1	
70	AIR CLEANER BOX ?	1	
71	AIR CLEANER BOX AIR DUCT ?	1	
72	AIR RESONATOR BOX ?	1	
73	WASHER TANK /	1	

74	EXHAUST MANIFOLD ?	1	
75	EXHAUST MANIFOLD COVER ✓	1	
76	ENGINE SOLENOID VAVLE ?	1	
77	ENGINE SOLENOID WIRE SWITCH ?	1	
78	ENGINE DIP STICK ?	1	
79	ENGINE DIP STICK HOLDER ?	1	
80	ENGINE MTG ?	1 SET	
SUBTOTAL			\$ -
LESS 10%			\$ -
PARTS TOTAL			\$ -
SPECIAL NETT		QTY	PRICE
81	REAR BOOT W/S GLASS SEALANT ✓	1	\$ 80.00 60
82	REAR NO PLATE X	1	\$ 50.00
83	REVERSE SENSOR ✓	1	\$ 250.00 200
84	FRONT NO PLATE ✓	1	\$ 50.00 35
SPECIAL NETT TOTAL			\$ 430.00
LABOUR		QTY	PRICE
1	TO RNR ACCIDENT AFFECTED AREAS (REAR)		\$ 600 800.00
2	TO RNR ACCIDENT AFFECTED AREAS (FRONT)		\$ 1,600.00 1200
3	TO RESPRAY ACCIDENT AFFECTED AREAS		\$ 2,200.00 1400
4	TO RUST PROOF ACCIDENT AFFECTED AREAS		\$ 150.00 50
5	TO RNR REAR BOOT W/S GLASS		\$ 150.00 100
6	TO RNR REAR BOOT MECHANISM		\$ 180.00 50
7	TO RNR REAR LUGGAGE COMPARTMENT		\$ 150.00 50
8	TO RNR REAR EXHAUST PIPE		\$ 120.00 60
9	TO RNR REVERSE SENSOR AND CHECK FUNCTIONS		\$ 80.00 20
10	TO CHECK WATER SEEPAGE		\$ 80.00 20
11	TO CHECK WIRING LAYOUT & HEADLAMP FOCUS		\$ 100.00 20
12	TO RNR AIRCON CONDENSER AND REFILL GAS		\$ 150.00 100
13	TO RNR ENGINE AND AUTO TRANS ASSY		\$ 400.00 ?
14	TO RNR AIR CLEANER BOX, EXHAUST MANIFOLD, ENGINE MTG AND ATTACH PARTS		\$ 380.00 ?
LABOUR TOTAL			\$ 6,540.00
GRAND TOTAL COST			\$ 6,970.00

Kalvin LKKK
 16/5/18 1005hrs
 8 Repair Pgs.
 Lump Sum Repair
 After Repair photo

Limit Repair
 96719399
 Kalvin ang G LKKauto.com

- ACKNOWLEDGMENT BY REPAIRER
- I, the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged parts for resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

PASS TO

LAI



Ethicarz Pte. Ltd. 56 Loyang Way, Singapore (508775) #04-04
 Loyang Enterprise Building, Email: kelvinwo@ethicarz.sg
 Tel: 63844404, FAX: 63840444

VEHICLE NUM:
 MAKE & MODEL:
 MILEAGE:
 TYRE: FRONT
 TYRE: REAR
 CHASSIS NUM:

SGN8882L
MINI ONE
WMWSR32080TY59829

ATTN:			
NO.	DESCRIPTION - PARTS	QTY	PRICE
1	REAR BOOT — <i>Paint</i>	1	985.30
2	REAR BOOT LOCK X <i>see</i>	1	
3	REAR BOOT W/STRIP X <i>see</i>	1	
4	REAR BOOT HINGE L + R X <i>repair</i>	2	
5	REAR BOOT LOGO — <i>see</i>	1	59.90
6	REAR BOOT EMBLEM - ONE — <i>see</i>	1	53.20
7	REAR BOOT W/S GLASS MOLD — <i>see</i>	1	445.90
8	REAR BOOT INNER TRIM X <i>see</i>	1	
9	REAR BOOT ABSORBER L + R X <i>see</i>	2	
10	REAR BUMPER — <i>Paint</i>	1	627.20
11	REAR BUMPER RETAINER L + R X <i>see</i>	2	
12	REAR BUMPER BRACKET L + R X <i>see</i>	2	
13	REAR BUMPER LAMP L + R X <i>see</i>	2	
14	REAR BUMPER TOWING CAP — <i>cut</i>	1	30.40
15	REAR BUMPER LOWER — <i>cut</i>	1	180.70
16	REAR BUMPER REINFORCEMENT ✓ <i>Paint</i>	1	360.60
17	REAR BUMPER CENTER GARNISH (INNER) — <i>con</i>	1	30.70
18	REAR BUMPER CLIP — <i>see</i>	10	60.00
19	REAR BUMPER SPONGE X <i>see</i>	1	212.00
20	REAR BUMPER UNDER COVER ✓ <i>cut</i>	1	22.00
21	REAR END PANEL X <i>Repair</i>	1	
22	REAR END PANEL TOP GARNISH ✓ <i>con</i>	1	198.50
23	REAR END PANEL TOP GARNISH CLIP 2 ✓ <i>see</i>	10	50.00
24	REAR SPARE WHEEL PANEL X <i>repair</i>	1	
25	REAR SPARE WHEEL PANEL TOP BOARD X <i>see</i>	1	
26	REAR FENDER PROTECTOR L + R X <i>see</i>	2	
27	REAR FENDER COWLING L + R X <i>see</i>	2	
28	REAR FENDER COWLING CLIP L + R X <i>see</i>	2	
29	REAR EXHAUST PIPE ? — ✓ <i>Paint</i>	1	644.08
30	REAR EXHAUST PIPE MTG ? X X <i>see</i>	1	33.85
31	REAR EXHAUST PIPE HEAT SEAL — <i>torq</i>	1	54.30
32	REAR EXHAUST PIPE GASKET ✓ <i>see</i>	1	20.00
33	FRONT BONNET — <i>Paint</i>	1	958.30

34	FRONT BONNET LOGO	/	new	1	59.10
35	FRONT BONNET CHROME (FRONT)	/	on	1	91.00
36	FRONT BONNET HEADLAMP CHROME L + R	/	on	2	193.90
37	FRONT BONNET HINGE L + R	/	Rep	2	108.10
38	FRONT BONNET LOCK L + R	/	Rep	2	114.10
39	FRONT BONNET ABSORBER L + R	X	see	2	
40	FRONT BONNET CHROME (REAR)	X	see	1	
41	FRONT GRILLE ASSY	/	on	1	137.85
42	HEADLAMP L + R	/	on	2	1689.20
43	FRONT BUMPER	/	Rep	1	554.25
44	FRONT BUMPER RETAINER L + R	X	see	2	
45	FRONT BUMPER BRACKET L + R	X	see	2	
46	FRONT BUMPER SPONGE L + R	X	see	2	
47	FRONT BUMPER REINFORCEMENT L + R	X	repair	2	
48	FRONT BUMPER GRILLE	/	on	1	71.85
49	FRONT BUMPER GRILLE GARNISH	/	on	1	91.50
50	FRONT BUMPER FOG LAMP L + R	X	Left Right see	2	
51	FRONT BUMPER FOG LAMP BRACKET L + R	X	see	2	
52	FRONT BUMPER LOWER	X	see	1	
53	FRONT BUMPER CLIP	/	on	1	50.00
54	FRONT FENDER L + R	X	Repair	2	
55	FRONT FENDER PROTECTOR L + R	X	see	2	
56	FRONT FENDER COWLING L + R	X	see	2	
57	FRONT FENDER COWLING CLIP L + R	X	see	2	
58	HORN	X	see	1	
59	FRONT SUPPORT PANEL	/	Rep	1	513.40
60	AIR CON CONDENSER	/	Rep	1	910.90
61	AIR CON CONDENSER SIDE GARNISH L + R	X	see		55.60
62	AIR CON CONDENSER LIQUID PIPE	? ✓	see	1	
63	AIR CON CONDENSER SUCTION PIPE	? ✓	see	1	
64	AIR CON CONDENSER DISCHARGE PIPE	? ✓	see	1	
65	RADIATOR	/	Rep	1	538.85
66	RADIATOR ELECTRIC FAN COWLING ASSY	/	on	1	649.10
67	RADIATOR TOP HOSE	? ✓	Rep	1	39.05
68	RADIATOR SPARE TANK	? ✓	on	1	34.75
69	RADIATOR SPARE TANK HOSE	? ✓	Rep	1	69.43
70	AIR CLEANER BOX	? ✓	on	1	436.75
71	AIR CLEANER BOX AIR DUCT	? ✓	on	1	134.70
72	AIR RESONATOR BOX	? ✓	on	1	108.10
73	WASHER TANK	/	on	1	158.50

74	EXHAUST MANIFOLD	?	✓	but	1	2038.10
75	EXHAUST MANIFOLD COVER	✓		but	1	191.00
76	ENGINE SOLENOID VAVLE	?	✓	part	1	237.15
77	ENGINE SOLENOID WIRE SWITCH	?	✓	turn	1	691.85
78	ENGINE DIP STICK	?	✓	Bent	1	38.45
79	ENGINE DIP STICK HOLDER	?	✓	cut	1	59.95
80	ENGINE MTG	?	✓	turn	1 SET	478.80
						13984.52
SUBTOTAL						\$ -
LESS 10%						\$ -
PARTS TOTAL						\$ -
SPECIAL NETT					QTY	PRICE
81	REAR BOOT W/S GLASS SEALANT	✓		new	1	\$ 80.00 60
82	REAR NO PLATE	X		sun	1	\$ 50.00
83	REVERSE SENSOR	✓		shut	1	\$ 250.00 200
84	FRONT NO PLATE	✓		cut.	1	\$ 50.00 35
SPECIAL NETT TOTAL						\$ 430.00
LABOUR					QTY	PRICE
1	TO RNR ACCIDENT AFFECTED AREAS (REAR)					\$ 600 800.00
2	TO RNR ACCIDENT AFFECTED AREAS (FRONT)					\$ 1,600.00 1200
3	TO RESPRAY ACCIDENT AFFECTED AREAS					\$ 2,200.00 1800
4	TO RUST PROOF ACCIDENT AFFECTED AREAS					\$ 150.00 50
5	TO RNR REAR BOOT W/S GLASS					\$ 150.00 100
6	TO RNR REAR BOOT MECHANISM					\$ 180.00 50
7	TO RNR REAR LUGGAGE COMPARTMENT					\$ 150.00 50
8	TO RNR REAR EXHAUST PIPE					\$ 120.00 60
9	TO RNR REVERSE SENSOR AND CHECK FUNCTIONS					\$ 80.00 20
10	TO CHECK WATER SEEPAGE					\$ 80.00 20
11	TO CHECK WIRING LAYOUT & HEADLAMP FOCUS					\$ 100.00 20
12	TO RNR AIRCON CONDENSER AND REFILL GAS					\$ 100 150.00 50.50
13	TO RNR ENGINE AND AUTO TRANS ASSY					\$ 400.00 244
14	TO RNR AIR CLEANER BOX, EXHAUST MANIFOLD, ENGINE MTG AND ATTACH PARTS					\$ 380.00 160 11
LABOUR TOTAL						\$ 6,540.00
GRAND TOTAL COST						\$ 6,970.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Kalvin LKK

16/5/18 100 hrs.
8 Repair Pys.
Lump Sum Repair
After Repair photo

Limit Repair

\$13-14K

96719399

Kalvin@LKKAuto.com

PAGE 2 OF 2

MK - \$43K

Nett \$13K

Offer LKs \$13K
Request for After Repair photo
Defect finalise with Harry



Ethicarz Pte. Ltd. 56 Loyang Way, Singapore (508775) #04-04
Loyang Enterprise Building, Email: kelvinwo@ethicarz.sg
Tel: 63844404, FAX: 63840444

VEHICLE NUM:	SGN 8882 L
MAKE & MODEL:	MINI ONE
CHASSIS NUM:	WMWSR32080TY59829
DATE OF ACCIDENT:	14.05.2018
DATE:	14.05.2018

ATTN:				
NO.	DESCRIPTION - PARTS	QTY	PRICE	QUOTED PRICE
1	BOOTLID	1	\$ 985.30	
2	BOOTLID LOGO	1	\$ 59.90	
3	BOOTLID EMBLEM -ONE	1	\$ 53.20	
4	BOOTLID W/S GLASS MOLD	1	\$ 445.90	
5	REAR BUMPER	1	\$ 627.20	
6	REAR BUMPER TOWING CAP	1	\$ 30.40	
7	REAR BUMPER LOWER	1	\$ 180.70	
8	REAR BUMPER REINFORCEMENT	1	\$ 360.60	
9	REAR BUMPER CENTRE GARNISH (INNER)	1	\$ 30.70	
10	REAR BUMPER CLIPS	1 SET	\$ 60.00	
11	REAR BUMPER SPONGE	1	\$ 212.00	
12	REAR BUMPER UNDER COVER	1	\$ 22.00	
13	REAR END PANEL TOP GARNISH	1	\$ 198.50	
14	REAR END PANEL CLIPS	1 SET	\$ 50.00	
15	REAR EXHAUST PIPE	1	\$ 644.08	
16	REAR EXHAUST PIPE MOUNTING	1	\$ 33.85	
17	REAR EXHAUST PIPE HEAT SEAL	1	\$ 54.30	
18	REAR EXHAUST PIPE GASKET	1	\$ 20.00	
19	BONNET	1	\$ 958.30	
20	BONNET LOGO	1	\$ 59.10	
21	BONNET CHROME	1	\$ 91.00	
22	BONNET HEADLAMP CHROME	2	\$ 193.90	
23	BONNET HINGE	2	\$ 108.10	
24	BONNET LOCK	2	\$ 114.10	
25	FRONT GRILLE ASSY	1	\$ 137.85	
26	HEADLAMP	2	\$ 1,689.20	
27	FRONT BUMPER	1	\$ 554.25	
28	FRONT BUMPER GRILLE	1	\$ 71.85	
29	FRONT BUMPER GRILLE GARNISH	1	\$ 91.50	
30	FRONT BUMPER CLIPS	1 SET	\$ 50.00	
31	FRONT SUPPORT PANEL	1	\$ 513.40	
32	AIR CON CONDENSER	1	\$ 910.90	
33	AIR-CON CONDENSER SIDE GARNISH	2	\$ 55.60	
34	RADIATOR	1	\$ 538.85	
35	RADIATOR ELECTRIC FAN COWLING ASSY	1	\$ 649.10	
36	RADIATOR TOP HOSE	1	\$ 39.05	
37	RADIATOR SPARE TANK	1	\$ 34.75	
38	RADIATOR SPARE TANK HOSE	1	\$ 69.43	
39	AIR CLEANER BOX	1	\$ 436.75	
40	AIR CLEANER BOX AIR DUCT	1	\$ 134.70	
41	AIR RESONATOR BOX	1	\$ 108.10	

Nivitha (LKK Auto)

From: ERIC WOO JUN KIAT <ericwoo@lonpac.com>
Sent: Tuesday, 15 May 2018 5:19 PM
To: assignments@lkkauto.com
Cc: skgan@ethicarz.sg; MT_Claim_SG
Subject: FW: Our Ref: 18/18/18/VP05/020603 Accident involving SJG2916P,SGN8882L & SKZ5252P along Yishun Ave 1 on 14/5/18 GIA Report - SGN8882L
Attachments: SGN8882L MINI ONE.PDF

5.25pm @ 15/5/2018
person @ Khim
vehicle in
amerge on 16/5/18

Dear Catherine / Nivitha,

Kindly refer to our attachment and email below.

Please proceed to appoint Ma Chin Fook to conduct a survey of the vehicle SGN 8882L on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

Best Regards,
Eric Woo
Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

-----Original Message-----

From: skgan@ethicarz.sg [mailto:skgan@ethicarz.sg]
Sent: Tuesday, 15 May, 2018 5:10 PM
To: ERIC WOO JUN KIAT
Cc: MT_Claim_SG
Subject: Re: Our Ref: 18/18/18/VP05/020603 Accident involving SJG2916P,SGN8882L & SKZ5252P along Yishun Ave 1 on 14/5/18 GIA Report - SGN8882L

Dear Sir/Mdm,

Please arrange Ma Chin Fook to survey the vehicle.

Thank you

Best regards,
Khim

ETHICARZ PTE LTD
56 Loyang Way, Loyang Enterprise Building
#04-04 S(508775)
Tel : 6384 4404 Fax : 6384 0444

On 2018-05-15 16:50, ERIC WOO JUN KIAT wrote:
> Dear Khim,

>
> We refer to your email below.
>
> We will proceed to conduct a pre-repair survey of the damage to your
> client's vehicle jointly with your workshop. We propose to use one of
> the motor surveyors named in the attached list to conduct the joint
> pre-repair survey as a single joint expert. (Please see attached).
>
> Please let us know within 2 working days whether you are agreeable to
> the appointment of any of the motor surveyors provided to you as a
> single joint expert. You may select one of the listed motor surveyors.
>
> Thank you.
>
> Best Regards,
> Eric Woo
> Claims Executive | Lonpac Insurance Bhd
> 300 Beach Road, #17-04/07 The Concourse, Singapore 199555
> Tel: (65) 6279 9253 | Fax: (65) 6296 3767
>
> -----Original Message-----
> From: skgan@ethicarz.sg [mailto:skgan@ethicarz.sg]
> Sent: Tuesday, 15 May, 2018 4:31 PM
> To: MT_Claim_SG
> Subject: GIA Report - SGN8882L
>
> Dear LONPAC,
>
>
> Please refer to GIA report.
>
>
> Please provide us panel surveyor list to choose from.
>
>
>
> Best regards,
> Khim
>
> ETHICARZ PTE LTD
> 56 Loyang Way, Loyang Enterprise Building
> #04-04 S(508775)
> Tel : 6384 4404 Fax : 6384 0444

Mei Kwan (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Friday, 18 May, 2018 11:13 AM
To: Mei Kwan (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: Our Ref: 18/18/18/VP05/020603 Accident involving SJG2916P,SGN8882L & SKZ5252P along Yishun Ave 1 on 14/5/18 GIA Report - SGN8882L
Attachments: 18052018110933.pdf
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK

Dear Mei Kwan,

Attached copy of insured's GIA report for your attention.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]

Sent: Friday, 18 May, 2018 10:43 AM

To: ERIC WOO JUN KIAT

Cc: MT_Claim_SG; GERALD POH WEE BIN; ONG LI LI; Thin Thin (LKKAUTO); Vivian Lau (LKKAUTO); Admin A

Subject: RE: Our Ref: 18/18/18/VP05/020603 Accident involving SJG2916P,SGN8882L & SKZ5252P along Yishun Ave 1 on 14/5/18 GIA Report - SGN8882L

EQI ref: 18/18/18/VP05/020603

LKK REF: CC4/LPC18008994/K1ua3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: SGN 8882L

Date of survey: 16.05.2018

We have not authorized repairs.

Enclosed for your perusal is:

- Estimated cost of repair - incomplete (pending for parts price)
- TP GIA report
- Photographs of TP vehicle in its damaged condition

Kindly let us have a copy of your insured's GIA report for our necessary action.

300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

-----Original Message-----

From: skgan@ethicarz.sg [mailto:skgan@ethicarz.sg]
Sent: Tuesday, 15 May, 2018 5:10 PM
To: ERIC WOO JUN KIAT
Cc: MT_Claim_SG
Subject: Re: Our Ref: 18/18/18/VP05/020603 Accident involving
SJG2916P,SGN8882L & SKZ5252P along Yishun Ave 1 on 14/5/18 GIA Report -
SGN8882L

Dear Sir/Mdm,

Please arrange Ma Chin Fook to survey the vehicle.

Thank you

Best regards,
Khim

ETHICARZ PTE LTD
56 Loyang Way, Loyang Enterprise Building
#04-04 S(508775)
Tel : 6384 4404 Fax : 6384 0444

On 2018-05-15 16:50, ERIC WOO JUN KIAT wrote:

> Dear Khim,
>
> We refer to your email below.
>
> We will proceed to conduct a pre-repair survey of the damage to your
> client's vehicle jointly with your workshop. We propose to use one of
> the motor surveyors named in the attached list to conduct the joint
> pre-repair survey as a single joint expert. (Please see attached).
>
> Please let us know within 2 working days whether you are agreeable to
> the appointment of any of the motor surveyors provided to you as a
> single joint expert. You may select one of the listed motor surveyors.
>
> Thank you.
>
> Best Regards,
> Eric Woo
> Claims Executive | Lonpac Insurance Bhd
> 300 Beach Road, #17-04/07 The Concourse, Singapore 199555
> Tel: (65) 6279 9253 | Fax: (65) 6296 3767
>
> -----Original Message-----
> From: skgan@ethicarz.sg [mailto:skgan@ethicarz.sg]
> Sent: Tuesday, 15 May, 2018 4:31 PM
> To: MT_Claim_SG

Joy Irene (LKKAUTO)

From: kelvinchew@ethicarz.sg
Sent: Thursday, 13 June 2019 11:56 AM
To: Joy Irene (LKKAUTO); katherinechan@ethicarz.sg
Cc: CS A Team; Admin A; heng@ethicarz.sg; skng@ethicarz.sg
Subject: RE: [LPC]: SGN 8882 L FINALISED // LKK Ref: CC4/LPC18008994/K1ua3 DOA: 14 MAY 2018

Dear Joy,

Refer to your offer, we confirmed accept the amount of S\$13,547.45 all in.

Please issue and mail the cheque to the following address :

Block 9004, Tampines Industrial Park A
#03-92, Street 93
Singapore 528838

Thank you.

Best Regards,

Kelvin Chew



Ethicarz Pte. Ltd.

Tel: (65) 6384 4404 | **Fax:** (65) 6384 0444 | **Email:** kelvinchew@ethicarz.sg | **Website:** www.ethicarz.sg

Address: 56 Loyang Way #04-04 Loyang Enterprise Building Singapore 508775

From: Joy Irene (LKKAUTO) <JoyIrene@lkkauto.com>
Sent: Wednesday, 12 June 2019 5:04 PM
To: katherinechan@ethicarz.sg
Cc: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; heng@ethicarz.sg; skng@ethicarz.sg; kelvinchew@ethicarz.sg
Subject: RE: [LPC]: SGN 8882 L FINALISED // LKK Ref: CC4/LPC18008994/K1ua3 DOA: 14 MAY 2018

WITHOUT PREJUDICE

Dear Katherine,

Kindly confirm acceptance on our offer at \$13,547.45 all-in.

Thank you.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18008994/K1ha3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 04-07-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJG 2916P	Veh. Inspected	SGN 8882L
Policy No.	Z18VP05018247	Coverage (\$)	0.00
Claim No.	18/18/18/VP05/020603	Excess (\$)	0.00
Assign From	GERALD	Assign Date	15/05/2018

2. Vehicle Particulars & Condition

Make & Model	MINI ONE	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WMWSR32080TY59829	Colour	WHITE
Odometer	85165	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/65 R15	BRIDGESTONE	7 mm
L/H Front Tyre	175/65 R15	BRIDGESTONE	7 mm
R/H Rear Tyre	175/65 R15	BRIDGESTONE	7 mm
L/H Rear Tyre	175/65 R15	BRIDGESTONE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	14/05/2018	Inspection Date	16/05/2018
Survey held at	ETHICARZ PTE LTD 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING SINGAPORE 508775		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGN 8882L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOT	DENTED	985.30	985.30
1	REAR BOOT LOCK (NPA)	SERVICEABLE	-	-
1	REAR BOOT W/STRIP (NPA)	SERVICEABLE	-	-
2	REAR BOOT HINGE L+R (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BOOT LOGO	NECESSARY	59.90	59.90
1	REAR BOOT EMBLEM -ONE	NECESSARY	53.20	53.20
1	REAR BOOT W/S GLASS MOLD	NECESSARY	445.90	445.90
1	REAR BOOT INNER TRIM (NPA)	SERVICEABLE	-	-
2	REAR BOOT ABSORBER L+R (NPA)	SERVICEABLE	-	-
1	REAR BUMPER	DEFORMED	627.20	627.20
2	REAR BUMPER RETAINER L+R (NPA)	SERVICEABLE	-	-
2	REAR BUMPER BRACKET L+R (NPA)	SERVICEABLE	-	-
2	REAR BUMPER LAMP L+R (NPA)	SERVICEABLE	-	-
1	REAR BUMPER TOWING CAP	CUT	30.40	30.40
1	REAR BUMPER LOWER	CUT	180.70	180.70
1	REAR BUMPER REINFORCEMENT	BENT	360.60	360.60
1	REAR BUMPER CENTER GARNISH (INNER)	CRACKED	30.70	30.70
10	REAR BUMPER CLIP	NECESSARY	60.00	60.00
1	REAR BUMPER SPONGE	SERVICEABLE	212.00	-
1	REAR BUMPER UNDER COVER	CUT	22.00	22.00
1	REAR END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR END PANEL TOP GARNISH	CRACKED	198.50	198.50
10	REAR END PANEL TOP GARNISH CLIP	NECESSARY	50.00	50.00
1	REAR SPARE WHEEL PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR SPARE WHEEL PANEL TOP BOARD (NPA)	SERVICEABLE	-	-
2	REAR FENDER PROTECTOR L+R (NPA)	SERVICEABLE	-	-
2	REAR FENDER COWLING L+R (NPA)	SERVICEABLE	-	-
2	REAR FENDER COWLING CLIP L+R (NPA)	SERVICEABLE	-	-
1	REAR EXHAUST PIPE	BENT	644.08	644.08

Report Ref No. CC4/LPC18008994/K1ha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST PIPE MTG	SERVICEABLE	33.85	-
1	REAR EXHAUST PIPE HEAT SEAL	TORN	54.30	54.30
1	REAR EXHAUST PIPE GASKET	NECESSARY	20.00	20.00
1	FRONT BONNET	DENTED	958.30	958.30
1	FRONT BONNET LOGO	NECESSARY	59.10	59.10
1	FRONT BONNET CHROME (FRONT)	CRACKED	91.00	91.00
2	FRONT BONNET HEADLAMP CHROME L+R	CRACKED	193.90	193.90
2	FRONT BONNET HINGE L+R	BENT	108.10	108.10
2	FRONT BONNET LOCK L+R	BENT	114.10	114.10
2	FRONT BONNET ABSORBER L+R (NPA)	SERVICEABLE	-	-
1	FRONT BONNET CHROME (REAR) (NPA)	SERVICEABLE	-	-
1	FRONT GRILLE ASSY	CRACKED	137.85	137.85
2	HEADLAMP L+R	CRACKED	1,689.20	1,689.20
1	FRONT BUMPER	DEFORMED	554.25	554.25
2	FRONT BUMPER RETAINER L+R (NPA)	SERVICEABLE	-	-
2	FRONT BUMPER BRACKET L+R (NPA)	SERVICEABLE	-	-
2	FRONT BUMPER SPONGE L+R (NPA)	SERVICEABLE	-	-
2	FRONT BUMPER REINFORCEMENT L+R (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT BUMPER GRILLE	CRACKED	71.85	71.85
1	FRONT BUMPER GRILLE GARNISH	CRACKED	91.50	91.50
2	FRONT BUMPER FOG LAMP L+R (NPA)	SERVICEABLE	-	-
2	FRONT BUMPER FOG LAMP BRACKET L+R (NPA)	SERVICEABLE	-	-
1	FRONT BUMPER LOWER (NPA)	SERVICEABLE	-	-
1	FRONT BUMPER CLIP	NECESSARY	50.00	50.00
2	FRONT FENDER L+R (NPA)	TO REPAIR SEE LABOUR	-	-
2	FRONT FENDER PROTECTOR L+R (NPA)	SERVICEABLE	-	-
2	FRONT FENDER COWLING L+R (NPA)	SERVICEABLE	-	-
2	FRONT FENDER COWLING CLIP L+R (NPA)	SERVICEABLE	-	-
1	HORN (NPA)	SERVICEABLE	-	-
1	FRONT SUPPORT PANEL	BENT	513.40	513.40
1	AIR CON CONDENSER	BENT	910.90	910.90
2	AIR CON CONDENSER SIDE GARNISH L+R	SERVICEABLE	55.60	-

Report Ref No. CC4/LPC18008994/K1ha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIR CON CONDENSER LIQUID PIPE (NPA)	SERVICEABLE	-	-
1	AIR CON CONDENSER SUCTION PIPE (NPA)	SERVICEABLE	-	-
1	AIR CON CONDENSER DISCHARGE PIPE (NPA)	SERVICEABLE	-	-
1	RADIATOR	BENT	538.85	538.85
1	RADIATOR ELECTRIC FAN COWLING ASSY	CRACKED	649.10	649.10
1	RADIATOR TOP HOSE	BENT	39.05	39.05
1	RADIATOR SPARE TANK	CRACKED	34.75	34.75
1	RADIATOR SPARE TANK HOSE	BENT	69.43	69.43
1	AIR CLEANER BOX	CRACKED	436.75	436.75
1	AIR CLEANER BOX AIR DUCT	CRACKED	134.70	134.70
1	AIR RESONATOR BOX	CRACKED	108.10	108.10
1	WASHER TANK	CRACKED	158.50	158.50
1	EXHAUST MANIFOLD	DENTED	2,038.10	2,038.10
1	EXHAUST MANIFOLD COVER	DENTED	191.00	191.00
1	ENGINE SOLENOID VALVE	DENTED	237.15	237.15
1	ENGINE SOLENOID WIRE SWITCH	TORN	691.85	691.85
1	ENGINE DIP STICK	BENT	38.45	38.45
1	ENGINE DIP STICK HOLDER	CUT	59.95	59.95
1	SET ENGINE MTG	TORN	478.80	478.80
	LESS 10% DISCOUNT		-	-1,527.08
			15,572.21	13,743.68
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BOOT W/S GLASS SEALANT (SN)	NECESSARY	80.00	60.00
1	REAR NO PLATE (SN)	SERVICEABLE	50.00	-
1	REVERSE SENSOR (SN)	SHORTED	250.00	200.00
1	FRONT NO PLATE (SN)	CUT	50.00	35.00
			430.00	295.00
	<u>LABOUR</u>			
	TO RNR ACCIDENT AFFECTED AREAS (REAR).INCLUSIVE OF THE REPAIR OF REAR BOOT HINGE L+R,REAR END PANEL AND REAR SPARE WHEEL PANEL.		800.00	600.00

Report Ref No. CC4/LPC18008994/K1ha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RNR ACCIDENT AFFECTED AREAS (FRONT).INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT L+R AND FRONT FENDER L+R.		1,600.00	1,200.00
	TO RESPRAY ACCIDENT AFFECTED AREAS.		2,200.00	1,400.00
	TO RUST PROOF ACCIDENT AFFECTED AREAS.		150.00	50.00
	TO RNR REAR BOOT W/S GLASS.		150.00	100.00
	TO RNR REAR BOOT MECHANISM.		180.00	50.00
	TO RNR REAR LUGGAGE COMPARTMENT.		150.00	50.00
	TO RNR REAR EXHAUST PIPE.		120.00	60.00
	TO RNR REVERSE SENSOR AND CHECK FUNCTIONS.		80.00	20.00
	TO CHECK WATER SEEPAGE.		80.00	20.00
	TO CHECK WIRING LAYOUT & HEADLAMP FOCUS.		100.00	20.00
	TO RNR AIRCON CONDENSER AND REFILL GAS.		150.00	50.00
	TO RNR ENGINE AND AUTO TRANS ASSY.	NOT NECESSARY	400.00	-
	TO RNR AIR CLEANER BOX ,EXHAUST MANIFOLD ,ENGINE MTG AND ATTACH PARTS.	NOT NECESSARY	380.00	-
			6,540.00	3,620.00
GRAND TOTAL			22,542.21	17,658.68
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				12,000.00

Report Ref No. CC4/LPC18008994/K1ha3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.