



Ethicarz Pte. Ltd. 56 Loyang Way, Singapore (508775) #04-04
Loyang Enterprise Building, Email: kelvinwo@ethicarz.sg
Tel: 63844404, FAX: 63840444

VECHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE: FRONT
TYRE: REAR
CHASSIS NUM:

SGN8882L
MINI ONE
WMWSR32080TY59829

ATTN:			
NO.	DESCRIPTION - PARTS	QTY	PRICE
1	REAR BOOT ✓	1	
2	REAR BOOT LOCK X	1	
3	REAR BOOT W/STRIP X	1	
4	REAR BOOT HINGE L + R X	2	
5	REAR BOOT LOGO ✓	1	
6	REAR BOOT EMBLEM - ONE ✓	1	
7	REAR BOOT W/S GLASS MOLD X ✓	1	
8	REAR BOOT INNER TRIM X	1	
9	REAR BOOT ABSORBER L + R X	2	
10	REAR BUMPER ✓	1	
11	REAR BUMPER RETAINER L + R X	2	
12	REAR BUMPER BRACKET L + R X	2	
13	REAR BUMPER LAMP L + R X	2	
14	REAR BUMPER TOWING CAP ✓	1	
15	REAR BUMPER LOWER ✓	1	
16	REAR BUMPER REINFORCEMENT ?	1	
17	REAR BUMPER CENTER GARNISH (INNER) ✓	1	
18	REAR BUMPER CLIP ✓	10	
19	REAR BUMPER SPONGE ?	1	
20	REAR BUMPER UNDER COVER ?	1	
21	REAR END PANEL X <i>Myat</i>	1	
22	REAR END PANEL TOP GARNISH ?	1	
23	REAR END PANEL TOP GARNISH CLIP ?	10	
24	REAR SPARE WHEEL PANEL X	1	
25	REAR SPARE WHEEL PANEL TOP BOARD X	1	
26	REAR FENDER PROTECTOR L + R X	2	
27	REAR FENDER COWLING L + R X	2	
28	REAR FENDER COWLING CLIP L + R X	2	
29	REAR EXHAUST PIPE ?	1	
30	REAR EXHAUST PIPE MTG ?	1	
31	REAR EXHAUST PIPE HEAT SEAL ✓	1	
32	REAR EXHAUST PIPE GASKET ?	1	
33	FRONT BONNET ✓	1	

34	FRONT BONNET LOGO /	1	
35	FRONT BONNET CHROME (FRONT) /	1	
36	FRONT BONNET HEADLAMP CHROME L + R /	2	
37	FRONT BONNET HINGE L + R /	2	
38	FRONT BONNET LOCK L + R /	2	
39	FRONT BONNET ABSORBER L + R X	2	
40	FRONT BONNET CHROME (REAR) X	1	
41	FRONT GRILLE ASSY /	1	
42	HEADLLAMP L + R /	2	
43	FRONT BUMPER /	1	
44	FRONT BUMPER RETAINER L + R X	2	
45	FRONT BUMPER BRACKET L + R X	2	
46	FRONT BUMPER SPONGE L + R X	2	
47	FRONT BUMPER REINFORCEMENT L + R X	2	
48	FRONT BUMPER GRILLE /	1	
49	FRONT BUMPER GRILLE GARNISH /	1	
50	FRONT BUMPER FOG LAMP L + R X	2	
51	FRONT BUMPER FOG LAMP BRACKET L + R X	2	
52	FRONT BUMPER LOWER X	1	
53	FRONT BUMPER CLIP /	1	
54	FRONT FENDER L + R X Repair	2	
55	FRONT FENDER PROTECTOR L + R X	2	
56	FRONT FENDER COWLING L + R X	2	
57	FRONT FENDER COWLING CLIP L + R X	2	
58	HORN X	1	
59	FRONT SUPPORT PANEL /	1	
60	AIR CON CONDENSER /	1	
61	AIR CON CONDENSER SIDE GARNISH L + R /		
62	AIR CON CONDENSER LIQUID PIPE ?	1	
63	AIR CON CONDENSER SUCTION PIPE ?	1	
64	AIR CON CONDENSER DISCHARGE PIPE ?	1	
65	RADIATOR /	1	
66	RADIATOR ELECTRIC FAN COWLING ASSY /	1	
67	RADIATOR TOP HOSE ?	1	
68	RADIATOR SPARE TANK ?	1	
69	RADIATOR SPARE TANK HOSE ?	1	
70	AIR CLEANER BOX ?	1	
71	AIR CLEANER BOX AIR DUCT ?	1	
72	AIR RESONATOR BOX ?	1	
73	WASHER TANK /	1	

74	EXHAUST MANIFOLD ?	1	
75	EXHAUST MANIFOLD COVER ✓	1	
76	ENGINE SOLENOID VAVLE ?	1	
77	ENGINE SOLENOID WIRE SWITCH ?	1	
78	ENGINE DIP STICK ?	1	
79	ENGINE DIP STICK HOLDER ?	1	
80	ENGINE MTG ?	1 SET	
		SUBTOTAL	\$ -
		LESS 10%	\$ -
		PARTS TOTAL	\$ -
	SPECIAL NETT	QTY	PRICE
81	REAR BOOT W/S GLASS SEALANT ✓	1	\$ 80.00 60
82	REAR NO PLATE X	1	\$ 50.00
83	REVERSE SENSOR ✓	1	\$ 250.00 200
84	FRONT NO PLATE ✓	1	\$ 50.00 35
		SPECIAL NETT TOTAL	\$ 430.00
	LABOUR	QTY	PRICE
1	TO RNR ACCIDENT AFFECTED AREAS (REAR)		\$ 600 800.00
2	TO RNR ACCIDENT AFFECTED AREAS (FRONT)		\$ 1,600.00 1200
3	TO RESPRAY ACCIDENT AFFECTED AREAS		\$ 2,200.00 1400
4	TO RUST PROOF ACCIDENT AFFECTED AREAS		\$ 150.00 50
5	TO RNR REAR BOOT W/S GLASS		\$ 150.00 100
6	TO RNR REAR BOOT MECHANISM		\$ 180.00 50
7	TO RNR REAR LUGGAGE COMPARTMENT		\$ 150.00 50
8	TO RNR REAR EXHAUST PIPE		\$ 120.00 60
9	TO RNR REVERSE SENSOR AND CHECK FUNCTIONS		\$ 80.00 20
10	TO CHECK WATER SEEPAGE		\$ 80.00 20
11	TO CHECK WIRING LAYOUT & HEADLAMP FOCUS		\$ 100.00 20
12	TO RNR AIRCON CONDENSER AND REFILL GAS		\$ 150.00 100
13	TO RNR ENGINE AND AUTO TRANS ASSY		\$ 400.00 ?
14	TO RNR AIR CLEANER BOX, EXHAUST MANIFOLD, ENGINE MTG AND ATTACH PARTS		\$ 380.00 ?
		LABOUR TOTAL	\$ 6,540.00
		GRAND TOTAL COST	\$ 6,970.00

Kalvin LKK

16/5/18 1005hrs

8 Repair Pags.

Lump Sum Repair

After Repair photo

Lump Repair

96719399

Kalvin ang @ LKKauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: