

PASS TO

LAI



Ethicarz Pte. Ltd. 56 Loyang Way, Singapore (508775) #04-04

Loyang Enterprise Building, Email: kelvinwo@ethicarz.sg

Tel: 63844404, FAX: 63840444

VEHICLE NUM:

SGN8882L

MAKE & MODEL:

MINI ONE

MILEAGE:

TYRE: FRONT

TYRE: REAR

CHASSIS NUM:

WMWSR32080TY59829

ATTN:

NO.	DESCRIPTION - PARTS	QTY	PRICE
1	REAR BOOT — <i>Paint</i>	1	985.30
2	REAR BOOT LOCK X <i>see</i>	1	
3	REAR BOOT W/STRIP X <i>see</i>	1	
4	REAR BOOT HINGE L + R X <i>repair</i>	2	
5	REAR BOOT LOGO — <i>see</i>	1	59.90
6	REAR BOOT EMBLEM - ONE — <i>see</i>	1	53.20
7	REAR BOOT W/S GLASS MOLD — <i>see</i>	1	445.90
8	REAR BOOT INNER TRIM X <i>see</i>	1	
9	REAR BOOT ABSORBER L + R X <i>see</i>	2	
10	REAR BUMPER — <i>Paint</i>	1	627.20
11	REAR BUMPER RETAINER L + R X <i>see</i>	2	
12	REAR BUMPER BRACKET L + R X <i>see</i>	2	
13	REAR BUMPER LAMP L + R X <i>see</i>	2	
14	REAR BUMPER TOWING CAP — <i>cut</i>	1	30.40
15	REAR BUMPER LOWER — <i>cut</i>	1	180.70
16	REAR BUMPER REINFORCEMENT ✓ <i>Paint</i>	1	360.60
17	REAR BUMPER CENTER GARNISH (INNER) — <i>see</i>	1	30.70
18	REAR BUMPER CLIP — <i>see</i>	10	60.00
19	REAR BUMPER SPONGE X <i>see</i>	1	212.00
20	REAR BUMPER UNDER COVER ✓ <i>cut</i>	1	22.00
21	REAR END PANEL X <i>Repair</i>	1	
22	REAR END PANEL TOP GARNISH ✓ <i>see</i>	1	198.50
23	REAR END PANEL TOP GARNISH CLIP ✓ <i>see</i>	10	50.00
24	REAR SPARE WHEEL PANEL X <i>repair</i>	1	
25	REAR SPARE WHEEL PANEL TOP BOARD X <i>see</i>	1	
26	REAR FENDER PROTECTOR L + R X <i>see</i>	2	
27	REAR FENDER COWLING L + R X <i>see</i>	2	
28	REAR FENDER COWLING CLIP L + R X <i>see</i>	2	
29	REAR EXHAUST PIPE ? — ✓ <i>Paint</i>	1	644.08
30	REAR EXHAUST PIPE MTG ? X <i>see</i>	1	33.85
31	REAR EXHAUST PIPE HEAT SEAL — <i>torq</i>	1	54.30
32	REAR EXHAUST PIPE GASKET ✓ <i>see</i>	1	20.00
33	FRONT BONNET — <i>Paint</i>	1	958.30

X

34	FRONT BONNET LOGO	/	new	1	59.10
35	FRONT BONNET CHROME (FRONT)	/	new	1	91.00
36	FRONT BONNET HEADLAMP CHROME L + R	/	new	2	193.90
37	FRONT BONNET HINGE L + R	/	Best	2	108.10
38	FRONT BONNET LOCK L + R	/	Best	2	114.10
39	FRONT BONNET ABSORBER L + R	X	see	2	
40	FRONT BONNET CHROME (REAR)	X	see	1	
41	FRONT GRILLE ASSY	-	new	1	137.85
42	HEADLAMP L + R	-	new	2	1689.20
43	FRONT BUMPER	/	Best	1	554.25
44	FRONT BUMPER RETAINER L + R	X	see	2	
45	FRONT BUMPER BRACKET L + R	X	see	2	
46	FRONT BUMPER SPONGE L + R	X	see	2	
47	FRONT BUMPER REINFORCEMENT L + R	X	repair	2	
48	FRONT BUMPER GRILLE	-	new	1	71.85
49	FRONT BUMPER GRILLE GARNISH	-	new	1	91.50
50	FRONT BUMPER FOG LAMP L + R	X	LLHX RHX see	2	
51	FRONT BUMPER FOG LAMP BRACKET L + R	X	see	2	
52	FRONT BUMPER LOWER	X	see	1	
53	FRONT BUMPER CLIP	-	new	1	50.00
54	FRONT FENDER L + R	X	repair	2	
55	FRONT FENDER PROTECTOR L + R	X	see	2	
56	FRONT FENDER COWLING L + R	X	see	2	
57	FRONT FENDER COWLING CLIP L + R	X	see	2	
58	HORN	X	see	1	
59	FRONT SUPPORT PANEL	/	Best	1	513.40
60	AIR CON CONDENSER	/	Best	1	910.90
61	AIR CON CONDENSER SIDE GARNISH L + R	X	see		55.60
62	AIR CON CONDENSER LIQUID PIPE	?	✓ see	1	
63	AIR CON CONDENSER SUCTION PIPE	?	✓ see	1	
64	AIR CON CONDENSER DISCHARGE PIPE	?	✓ see	1	
65	RADIATOR	/	Best	1	538.85
66	RADIATOR ELECTRIC FAN COWLING ASSY	/	new	1	649.10
67	RADIATOR TOP HOSE	?	✓ Best	1	39.05
68	RADIATOR SPARE TANK	?	✓ new	1	34.75
69	RADIATOR SPARE TANK HOSE	?	✓ Best	1	69.43
70	AIR CLEANER BOX	?	✓ new	1	436.75
71	AIR CLEANER BOX AIR DUCT	?	✓ new	1	134.70
72	AIR RESONATOR BOX	?	✓ new	1	108.10
73	WASHER TANK	/	new	1	158.50

74	EXHAUST MANIFOLD	?	✓	cut	1	2038.10
75	EXHAUST MANIFOLD COVER	—	✓	cut	1	191.00
76	ENGINE SOLENOID VAVLE	?	✓	part	1	237.15
77	ENGINE SOLENOID WIRE SWITCH	?	✓	turn	1	691.85
78	ENGINE DIP STICK	?	✓	Bent	1	38.45
79	ENGINE DIP STICK HOLDER	?	✓	cut	1	59.95
80	ENGINE MTG	?	✓	turn	1 SET	478.80
						13784.52
SUBTOTAL						\$ -
LESS 10%						\$ -
PARTS TOTAL						\$ -
SPECIAL NETT					QTY	PRICE
81	REAR BOOT W/S GLASS SEALANT	—	✓	new	1	\$ 80.00 60
82	REAR NO PLATE	X	✓	sun	1	\$ 50.00
83	REVERSE SENSOR	—	✓	shut	1	\$ 250.00 200
84	FRONT NO PLATE	—	✓	cut.	1	\$ 50.00 35
SPECIAL NETT TOTAL						\$ 430.00
LABOUR					QTY	PRICE
1	TO RNR ACCIDENT AFFECTED AREAS (REAR)					\$ 600 800.00
2	TO RNR ACCIDENT AFFECTED AREAS (FRONT)					\$ 1,600.00 1200
3	TO RESPRAY ACCIDENT AFFECTED AREAS					\$ 2,200.00 1800
4	TO RUST PROOF ACCIDENT AFFECTED AREAS					\$ 150.00 50
5	TO RNR REAR BOOT W/S GLASS					\$ 150.00 100
6	TO RNR REAR BOOT MECHANISM					\$ 180.00 50
7	TO RNR REAR LUGGAGE COMPARTMENT					\$ 150.00 50
8	TO RNR REAR EXHAUST PIPE					\$ 120.00 60
9	TO RNR REVERSE SENSOR AND CHECK FUNCTIONS					\$ 80.00 20
10	TO CHECK WATER SEEPAGE					\$ 80.00 20
11	TO CHECK WIRING LAYOUT & HEADLAMP FOCUS					\$ 100.00 20
12	TO RNR AIRCON CONDENSER AND REFILL GAS					\$ 100 150.00 50
13	TO RNR ENGINE AND AUTO TRANS ASSY					\$ 400.00 214
14	TO RNR AIR CLEANER BOX, EXHAUST MANIFOLD, ENGINE MTG AND ATTACH PARTS					\$ 380.00 11
LABOUR TOTAL						\$ 6,540.00
GRAND TOTAL COST						\$ 6,970.00

Kalvin (LKK)

16/5/18 1005hrs

8 Repair Pags.

Lump Sum Repair

After Repair photo

Limit Repair

\$13-14k

96719399

Kalvin ang @ LKkauto.com

PAGE 2 OF 2

Mk - \$43K

Nett \$13k

offer works \$13K
Request for After Repair photo
Limit Repair
Defect finalise with them



Ethicarz Pte. Ltd. 56 Loyang Way, Singapore (508775) #04-04

Loyang Enterprise Building, Email: kelvinwo@ethicarz.sg

Tel: 63844404, FAX: 63840444

VEHICLE NUM:

SGN 8882 L

MAKE & MODEL:

MINI ONE

CHASSIS NUM:

WMWSR32080TY59829

DATE OF ACCIDENT:

14.05.2018

DATE:

14.05.2018

ATTN:

NO.	DESCRIPTION - PARTS	QTY	PRICE	ADJUSTED PRICE
1	BOOTLID	1	\$ 985.30	
2	BOOTLID LOGO	1	\$ 59.90	
3	BOOTLID EMBLEM -ONE	1	\$ 53.20	
4	BOOTLID W/S GLASS MOLD	1	\$ 445.90	
5	REAR BUMPER	1	\$ 627.20	
6	REAR BUMPER TOWING CAP	1	\$ 30.40	
7	REAR BUMPER LOWER	1	\$ 180.70	
8	REAR BUMPER REINFORCEMENT	1	\$ 360.60	
9	REAR BUMPER CENTRE GARNISH (INNER)	1	\$ 30.70	
10	REAR BUMPER CLIPS	1 SET	\$ 60.00	
11	REAR BUMPER SPONGE	1	\$ 212.00	
12	REAR BUMPER UNDER COVER	1	\$ 22.00	
13	REAR END PANEL TOP GARNISH	1	\$ 198.50	
14	REAR END PANEL CLIPS	1 SET	\$ 50.00	
15	REAR EXHAUST PIPE	1	\$ 644.08	
16	REAR EXHAUST PIPE MOUNTING	1	\$ 33.85	
17	REAR EXHAUST PIPE HEAT SEAL	1	\$ 54.30	
18	REAR EXHAUST PIPE GASKET	1	\$ 20.00	
19	BONNET	1	\$ 958.30	
20	BONNET LOGO	1	\$ 59.10	
21	BONNET CHROME	1	\$ 91.00	
22	BONNET HEADLAMP CHROME	2	\$ 193.90	
23	BONNET HINGE	2	\$ 108.10	
24	BONNET LOCK	2	\$ 114.10	
25	FRONT GRILLE ASSY	1	\$ 137.85	
26	HEADLAMP	2	\$ 1,689.20	
27	FRONT BUMPER	1	\$ 554.25	
28	FRONT BUMPER GRILLE	1	\$ 71.85	
29	FRONT BUMPER GRILLE GARNISH	1	\$ 91.50	
30	FRONT BUMPER CLIPS	1 SET	\$ 50.00	
31	FRONT SUPPORT PANEL	1	\$ 513.40	
32	AIR CON CONDENSER	1	\$ 910.90	
33	AIR-CON CONDENSER SIDE GARNISH	2	\$ 55.60	
34	RADIATOR	1	\$ 538.85	
35	RADIATOR ELECTRIC FAN COWLING ASSY	1	\$ 649.10	
36	RADIATOR TOP HOSE	1	\$ 39.05	
37	RADIATOR SPARE TANK	1	\$ 34.75	
38	RADIATOR SPARE TANK HOSE	1	\$ 69.43	
39	AIR CLEANER BOX	1	\$ 436.75	
40	AIR CLEANER BOX AIR DUCT	1	\$ 134.70	
41	AIR RESONATOR BOX	1	\$ 108.10	

