

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHA 4535Y

DATE 16/5/2018 10:10

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper X <i>Repair</i>			\$ 603.60	
	Rear Bumper Reinforcement ?			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket ?			\$ 49.00	
	Rear Bumper Clips X			\$ 22.00	
	Rear Bumper Sponge ?			\$ 143.40	
	Rear Bumper Under Cover X			\$ 225.00	
	SUB TOTAL			\$ 1,907.35	
	LESS 20%			\$ 381.47	
	DISCOUNTED TOTAL			\$ 1,525.88	
	Rear Bumper Reverse Sensor X			\$ 135.70	Nett
	Rear Bumper Rubber Mat X			\$ 50.00	Nett
	Rear Bumper Advertisement Logo —			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) —		\$ 100.00	\$ 200.00	Nett
				\$ 435.70	
	Labour Charge				
	Panel Beating			\$ 280.00 <i>100</i>	
	Spray Painting Charge			\$ 200.00 <i>180</i>	
	Wiring Charge			\$ 50.00 <i>X</i>	
	R/Refix Reverse Sensor			\$ 120.00 <i>X</i>	
	TOTAL LABOUR			\$ 650.00	
	ESTIMATE TOTAL			\$ 2,611.58	
<i>Kehru 16/5/18 1505hrs.</i> <i>2 Days.</i> <i>45</i> <i>After Repair photo</i> LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					