




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18008999/K1ja3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 17-05-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLK 1991H	Veh. Inspected	SHB 8047H	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M00HCC	Excess (\$)	0.00	
Assign From		Assign Date	17/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	15/05/2018	Inspection Date	16/05/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

16-May-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHB 8407 H

1 pc	Rear bumper	\$ 811.11
1 pc	Rear bumper sponge	\$ 79.20
1 pc	Rear bumper reinforcement	\$ 815.64
1 pc	Rear bumper reinforcement centre	\$ 79.20
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	\$ 104.40
2 pcs	Rear bumper n/s & o/s reflector @ \$107.50	\$ 215.00
		\$ 2,104.55
Less 20%		\$ 420.91
		\$ 1,683.64

S/NETT

1 set	Rear bumper clips	\$ 48.00
1 set	Reverse sensor	\$ 288.00 200
Sundry		\$ 50.00 + 21
To dismantle and replace reverse sensor and test system		\$ 80.00 20
To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the end panel, etc.		\$ 550.00 200
To putty and spray painting on the rear bumper, end panel		\$ 500.00 200
To apply rustproofing on the repaired and replaced panels		\$ 150.00 X 21
Total		\$ 3,341.64

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin KKK
16/5/18 15 40 hrs.
2 Pgs.
P/P
Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

8/6/18
whl 4/10/18

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

16-May-17

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHB 8^{OK}407 H

1 pc	Rear bumper	\$	811.11
1 pc	Rear bumper sponge X	\$	79.20
1 pc	Rear bumper reinforcement X	\$	815.64
1 pc	Rear bumper reinforcement centre X	\$	79.20
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20 X	\$	104.40
2 pcs	Rear bumper n/s & o/s reflector @\$107.50 X	\$	215.00
			<hr/>
			\$ 2,104.55
Less 20%			\$ 420.91
			<hr/>
			\$ 1,683.64

S/NETT

1 set	Rear bumper clips	\$	48.00
1 set	Reverse sensor	\$	280.00 2.00
Sundry			\$ 50.00 +
To dismantle and replace reverse sensor and test system			\$ 80.00 20
To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the end panel, etc.			\$ 550.00 2.00
To putty and spray painting on the rear bumper, end panel X			\$ 500.00 2.00
To apply rustproofing on the repaired and replaced panels			\$ 150.00 X
Total			<hr/>
			\$ 3,341.64

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin CKK
16/5/18 1540 hrs.
2 days
PIP
Before part photo

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Auto
Consultants
Pte Ltd

Company Registration No. 139607198R

81 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 21/05/2018

Survey Details:

Date of loss	15-May-18
Date of appointment	16-May-18
Date of survey	16-May-18
Location of survey	Premier Automotive Services Pte Ltd

Vehicle Details:

Claim Type:	Third party
Vehicle number	SHB 8047H
Make and Model	HYUNDAI I30 GDH 1.6 TCI - 1582cc
Date of registration	12/10/2016
Excess	
Market Value	\$ -
Part Rebate	\$ -
Nett Loss	\$ -

Repair details:

Initial Estimate	\$ 3,341.64
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 896.89
Check items (estimate)	\$ -
Labour	\$ 420.00
Total	\$ 1,316.89
Lump Sum(if applicable)	TBA

Number of days for repair	<u>2 days</u>
---------------------------	---------------



Re:IA FOR QUANTUM UPLOADED- FOR APPROVAL

Type

🔗 Question

Message

CLEARED, PLS PROCEED FOR DS QUANTUM AS PROPOSED.

Reply



Auto
Consultants
Pte Ltd

Company Registration No: 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 40903 TEL : (65) 62963561 FAX : (65) 62964315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 14/9/2018

Survey Details:

Date of loss	15-May-18
Date of appointment	16-May-18
Date of survey	16-May-18
Location of survey	PREMIER AUTOMOTIVE SERVICES PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SHB 8047H
Make and Model	HYUNDAI I30 1852CC
Date of registration	12-Oct-16
Excess	
Market Value	
Part Rebate	
Nett Loss	

Repair details:

Initial Estimate	\$	3,341.64
------------------	----	----------

Proposed/Revised repair cost:

Parts	\$	896.89
Check items (estimate)		
Labour	\$	420.00
Total	\$	1,316.89
Lump Sum(if applicable)	\$	1,050.00

Number of days for repair	<u>2</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

Company Registration No. 199607188R

11 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (65) 62563561 FAX : (65) 62564315

Remarks:

BOLA 27-HEAD TO REAR-100%

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 1,123.50	INC. GST
Loss of rental	\$ 329.82	3days x 109.94
Loss of income	\$ 120.00	3days x \$40.00
GIA Search Fee	\$ 2.00	
Proposed Total	\$ 1,575.32	

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H
 Owner ID Type: Company
 Owner Name: PREMIER TAXIS PTE. LTD.
 Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
 Mailing Address: -
 Birth Date: -

Vehicle Particulars

Vehicle No.: SHB8047H
 Previous Vehicle No.: -
 Effective Date of Ownership: 12 Oct 2016
 Original Regn Date: 12 Oct 2016
 Registration Date: 12 Oct 2016
 Year of Manufacture: 2016
 Vehicle Type: Public Transport Taxi (Motor Car)
 Vehicle Scheme: Taxi (Company)
 Vehicle Attachment 1: Air-Con (Taxi)
 Vehicle Attachment 2: -
 Vehicle Attachment 3: -
 Vehicle Make: HYUNDAI
 Vehicle Model: I30 GDH 1.6 TCI 5DR DCT
 Primary Colour: Silver
 Secondary Colour: -
 Passenger Capacity: 4
 Chassis No.: TMAD281UVHJ124414
 Engine No.: D4FBGZ114420
 Engine Capacity/Power Rating: 1582 cc / -
 Maximum Power Output: 100.0 kW (134 bhp)
 Propellant: Diesel
 Max Unladen Weight: 1496 kg
 Maximum Laden Weight: 1940 kg
 Open Market Value: \$20,110.00
 PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 11 Oct 2024
 Minimum PARF Benefit: \$7,592.00
 No. of Transfers: 0
 IU Label No.: -
 COE No.: 2016101201004072E
 COE Expiry Date: 11 Oct 2024
 COE Category: A - Car (up to 1600cc & 97kW (130bhp))
 COE Registration Category: A - Car (up to 1600cc & 97kW (130bhp))
 Quota Premium (QP) / Prevailing Quota Premium: - / \$52,108.00
 PQP Paid: \$41,687.00
 QP (Regn Cat): -
 OPC Cash Rebate Eligibility: No

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5095103893

Cover : Third Party

1. Index mark and Registration Number of Vehicle

: **SH88047H**

Chassis Number

: TMAD281UVHJ124414

2. Name of Policyholder

: PREMIER TAXIS PTE. LTD.

3. Effective Date of Insurance

: 20 Oct 2017

4. Expiry Date of Insurance

: 19 Oct 2018

5. Persons or Classes of Persons entitled to drive*

(a) The Policyholder.

(b) Any licensed taxi driver driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use*

(a) Use as a Taxi.

(b) Use for social domestic and pleasure purposes.

This Policy does not cover

(a) Use for racing, pace-making, reliability trial or speed-testing.

(b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION I)

: N/A

EXCESS (SECTION II)

: S\$3,500

INSURE WITH COE

: N/A

HIRE PURCHASE COMPANY

: N/A

SUM INSURED

: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : HL SUNTEK INSURANCE BROKERS PTE LTD (00000690672)

Date of Issue : 16 Oct 2017 17:13 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:



Authorised Officer



Chief Executive

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVE 2 #01-02
SINGAPORE 486443
TEL:65446671 FAX:62141511
CO. REG:200707743D GST REG:200707743D

Our Ref: SHB8047H/GS

WITHOUT PREJUDICE

21st June 2018

(By Email Only)

Attn: The Motor Claims Department
AXA Insurance Pte Ltd
No.8 Shenton Way
#27-01
Singapore 068811

Dear Sir/Madam

ACCIDENT INVOLVING SHB8047H & SLK1991H ALONG SLIP ROAD OF TOA PAYOH RISE INTO THOMSON ROAD ON 15.05.18

We have been authorized by Premier Taxis Pte Ltd, the owner of Taxi vehicle number: SHB8047H, to claim against the party/parties responsible for the damages arising from the above-mentioned accident.

Our records show that you are the insurers of vehicle number: SLK1991H at the material time of the accident with the driver of our client's vehicle, Mr Tang Guan Hock

As a result of the accident caused by your Insured Driver's negligent driving and/or management of your insured's Vehicle Number: SLK1991H, our client's vehicle was damaged and we have been put to loss and damage as follows:

(1) Cost of repair	\$ 1 123.50 (Incl. GST)
(2) Loss of Rental - 3Days @\$109.94per day	\$ 329.82
(3) Loss of Income – 3Days @\$100.00per day	\$ 300.00
(4) GIA Search Fee	\$ 2.00
	<u>\$ 1755.32</u>

A copy of each of the following supporting documents is enclosed:

- (1) Final Repair Bill, GIA report & sketch plan of SHB8047H
- (2) Driver's I/C and Driving Licence
- (3) Vehicle Registration card, Certificate of Insurance
- (4) Check In/Out Voucher, GIA search

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVE 2 #01-02
SINGAPORE 486443
TEL:65446671 FAX:62141511
CO. REG:200707743D GST REG:200707743D

Our Ref: SHB8047H/GS

We would appreciate if you could look into the subject matter and let us have your favorable offer within 14 days. If you are agreeable to the settlement of the above said claims, please forward us your discharge voucher as for our client's signature and payment made to "Premier Automotive Services Pte Ltd".

Please note that if we do not hear from you within the stipulated 14 days, we will have no alternative but to appoint our solicitor to act on our behalf to commence proceedings against you without further notice to you.

Yours faithfully,

A circular stamp with the text "PREMIER AUTOMOTIVE SERVICES PTE LTD" around the perimeter and "ARC" in the center. A handwritten signature is written over the stamp.

Claims Department – Gary Shi

Email: gary.shi@premiertaxi.com

NB: We encourage all parties to liaise with us via email to expedite all matters

PS: Please quote our reference no when replying

c.c. Client – Premier Taxis Pte Ltd

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Friday, 14 September 2018 10:03 AM
To: 'johnnicholas.si.ahs@gmail.com'
Cc: Admin A
Subject: ACCIDENT INVOLVING SLK 1991H AND SHB 8047H ALONG SLIP ROAD COMING OUT TO THOMSON ROAD ON 15.05.2018

JOHN NICHOLAS SI TUCK MENG

Policy Holder

Dear Sir/Madam,

OUR REF : CC4/ASM18008999/K1ja3
YOUR REF : SLK 1991H

ACCIDENT INVOLVING SLK 1991H AND SHB 8047H ALONG SLIP ROAD COMING OUT TO THOMSON ROAD ON 15.05.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from **PREMIER AUTOMOTIVE SERVICES PTE LTD**, acting on behalf of the owner of **SHB 8047H** against your motor insurance policy.

Based on the accident report, accident scenario, it was reported that you have hit **SHB 8047H** from the rear. As such, we are of the opinion that liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to joyirene@lkkauto.com within 7 days from the date of this letter if not provided at AXA's reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should not be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact the undersigned.

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

Joy Irene | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

AUTHORISATION TO ACT

I/We, PREMIER TAXIS PTE LTD ("the third party claimant") of 23 CHANGI SOUTH AVENUE 2 #03-02 SINGAPORE 486443 (address), owner of SHB 8047H (vehicle no.) hereby authorize PREMIER AUTOMOTIVE SERVICES PTE LTD ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no SHB 8047H that was damaged pursuant to the accident which occurred on 15/05/2018 (date) along SLIP OF TOA PAYOH RISE INTO THIMSON ROAD (location) involving vehicle no/s SLK 1991H ("the accident").

I/We further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of "the workshop".

I/We further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 2 (day) of Oct (month) 2018 (year)

A handwritten signature in black ink, appearing to be a stylized 'P' or similar, written over a horizontal line.

Signed by "the third party claimant"
(with chop if applicable)

A handwritten signature in black ink, appearing to be a stylized 'P' or similar, written over a horizontal line. A circular stamp is visible in the background, partially obscured by the signature.

Signed by "the workshop"
(with chop)

LETTER OF AUTHORITY

To: Premier Taxis Pte Ltd
23 Changi South Avenue 2
#03-02
Singapore 486443

And

Premier Automotive Services Pte Ltd
23 Changi South Avenue 2
#01-02
Singapore 486443

ACCIDENT INVOLVING SHB8047H & SLK 1991H
ON 15/5/18 AT/ALONG Tanjong Pagar Rise into Thomson Road

1. I, TANG GUAN HOCK, NRIC No. S1597360I

am the registered Hirer / Relief Driver of motor taxi No. SHB8047H at the time of the above accident.

2. Hereby you have my authority to:

- (a) send a letter of demand on my behalf;
- (b) negotiate a settlement on my behalf;
- (c) confirm a settlement / accept any offer on my behalf;
- (d) sign any Discharge Voucher (if necessary) on my behalf;
- (e) receive payment of the settlement sum / compensation monies on my behalf including to request that the cheque for the settlement sum be made payable to you.

TABH S1597360I
Signature with NRIC No.

16/5/18
Date

Name: TABH GUAN HOCK

Blk 102 Bukit Purmei Road, #10-76, S(0409)
Address

Contact No.: 87992132

Email:



redefining / insurance

This Settlement excludes my liability in respect of any bodily injuries arising out of the above said accident and property damage.

CLAIM REF : S8M00HCC
INSURED : JOHN NICHOLAS SI TUCK MENG

DISCHARGE VOUCHER

We, **PREMIER AUTOMOTIVE SERVICES PTE LTD** confirm that by letter of authorisation dated 21/01/18, we are authorised to and do hereby give this discharge for ourselves and on behalf of **PREMIER AUTOMOTIVE SERVICES PTE LTD** and the Hirer, Larry Guan Hock of vehicle no. SHB 8047H.

Now we **PREMIER AUTOMOTIVE SERVICES PTE LTD** for ourselves and the said Hirer and the driver jointly and severally:-

- agree to accept the sum of Singapore Dollars One Thousand Five Hundred Seventy Five and Cents Thirty Two Only (S\$1,575.32) in the aggregate in full and final settlement of all claims of whatever kind including damages for personal injuries and/or damage to property that all and any of us may have against **AXA INSURANCE PTE LTD** and/or their Insured and/or the driver of vehicle no. SLK 1991H arising out of an accident with SHB 8047H on 15/05/2018.
- declare that **AXA INSURANCE PTE LTD** and/or their Insured and/or the driver of the Insured vehicle shall not be liable for any further claim(s) whatsoever or howsoever present or future that any of us may have against **AXA INSURANCE PTE LTD** and/or their Insured and/or the driver of vehicle no. SLK 1991H arising directly/indirectly as a consequence of the accident and hereby give our full and final discharge.
- We hereby declare that I/we am/are the person(s) entitled to receive the above settlement and hereby undertake to indemnify **AXA INSURANCE PTE LTD** against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made in favour of **PREMIER AUTOMOTIVE SERVICES PTE LTD** is made without any admission of liability whatsoever on the part of **AXA INSURANCE PTE LTD** and/or their Insured and/or the driver of vehicle no. SLK 1991H.

Dated this 2 day of Oct 2018

Signed by _____
(AUTHORISED SIGNATORY)

Company Stamp _____

Witness : _____

Name : Shefali

IC No : 583047248

Address : _____



PREMIER AUTOMOTIVE SERVICES PTE LTD
OFFICE: 23 Changi South Avenue 2 #01-02 S(486443)
TEL: 65436676 / 65436689 FAX: 62141511
CO. REG NO.: 200707743D GST. REG. NO.: 200707743D

TAX INVOICE

PREMIER TAXIS PTE LTD
23 CHANGI SOUTH AVENUE 2 #03-02
SINGAPORE 486443

DATE 21-Jun-2018
PAGE 1 OF 1

ITEM	Description	QTY	U.PRICE	AMOUNT
	FINAL REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8047 H			\$ 1,050.00
TOTAL LUMP SUM REPAIR COSTS AS RECOMMENDED BY SURVEYOR				\$ 1,050.00
GST @ 7%				\$ 73.50
GRAND TOTAL				\$ 1,123.50



for Premier Automotive Services Pte Ltd

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)



24 May 2018

To Whom It May Concern

Dear Sir/Madam

CERTIFICATION LETTER

This letter serves to inform that Tang Guan Hock of NRIC Number S15973601 is a registered driver of SHB8047H. Tang Guan Hock is paying daily rental rate of \$109.94 (Inclusive of GST).

Should you require further information, please contact us at 6214 8880.

Thank you.

Yours sincerely

A handwritten signature in black ink, appearing to read "Chin Bee Lian".

Chin Bee Lian (Ms)
Assistant Vice President
Taxis Administration

Prepared By: Heanah

PREMIER TAXIS PTE LTD
23 Changi South Avenue 2
#03-02
Singapore 486443
Telephone: +65 6214 8880 Fax: +65 6214 8330
www.premiertaxi.com
Co. Reg. No. 200304975H



REPLACEMENT VEH GIVEN YES / NO

VEH NO. _____

JOB NO. _____

CHECK IN / OUT VOUCHER

DRIVER'S NAME <u>Tang Guan Hock</u>	
NRIC <u>S 1597366 I</u>	HANDPHONE <u>87992132</u>
TAXI REGN NO. <u>S H B8047 H</u>	MAKE / MODEL <u>Hyundai I30(A)</u>
DATE IN <u>180518</u> TIME IN <u>1050</u>	DATE OUT <u>180518</u> TIME OUT <u>1525</u>
KILOMETRES IN _____ FUEL IN <u>E 1/4 1/2 3/4 F</u>	KILOMETRES OUT _____ FUEL OUT <u>E 1/4 1/2 3/4 F</u>

TAXI METER DOWNLOADED

YES

NO

DATE / TIME TOWED IN TO WORKSHOP

D D M M Y Y H H M M

DATE / TIME CALL TO DRIVER FOR VEHICLE COLLECTION

D D M M Y Y H H M M

I ACKNOWLEDGE AND CONFIRM THAT I HAVE EXAMINED THE ABOVE SAID VEHICLE AND THAT THE SAME IS IN GOOD CONDITION AND TO MY SATISFACTION IN EVERY RESPECT TOGETHER WITH THE ACCESSORIES / ITEMS LIST ABOVE. THIS VOUCHER IS USED IN CONJUNCTION WITH THE TERM RENTAL AGREEMENT.

CHECK IN

Tang Guan Hock

DRIVER'S NAME

x Tang

DRIVER'S SIGNATURE / DATE / TIME

CHECK OUT

Tang Guan Hock


DRIVER'S NAME

Tang

DRIVER'S SIGNATURE / DATE / TIME

CHECKED IN BY
(PREMIER'S AUTHORISED WORKSHOP)CHECKED OUT BY
(PREMIER'S AUTHORISED WORKSHOP)

INDICATE AREA OF DAMAGE HERE:



BODY MARKINGS

- | | |
|---------------------|-------------|
| 1 - Light Dent | 5 - Damaged |
| 2 - Serious Dent | 6 - Chip |
| 3 - Light Scratch | 7 - Crack |
| 4 - Serious Scratch | 8 - Peeling |

SERVICE / REPAIRS DONE	DRIVER'S REMARKS
<input type="checkbox"/> SERVICING <input type="checkbox"/> OTHERS: <input type="checkbox"/> T / BELT <input type="checkbox"/> AIRCON SYSTEM <input type="checkbox"/> ACCIDENT: DATE / TIME of ACCIDENT: <input type="checkbox"/> TURBO D D M M Y Y H H M M <input type="checkbox"/> BRAKE SYSTEM <input type="checkbox"/> CLUTCH SYSTEM <input type="checkbox"/> BULB <input type="checkbox"/> UNDER CARRIAGE <input type="checkbox"/> CPF <input type="checkbox"/> BATTERY	<u>TP/G</u>



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-074458

Date of Request: 16/05/2018

Your Ref No: Online Purchase

Premier Automotive Services Pte Ltd
23 Changi South Ave 2
#01-02
Singapore 486443

Dear Sir/Madam,

Enquiry Date 16/05/2018
Enquiry By GARY SHI GUO RONG
TP Vehicle No. SLK1991H
Accident Date 15/05/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-074458

Date of Request: 16/05/2018

Your Ref No: Online Purchase

Premier Automotive Services Pte Ltd
23 Changi South Ave 2
#01-02
Singapore 486443

Dear Sir/Madam,

Enquiry Date 16/05/2018

Enquiry By GARY SHI GUO RONG

TP Vehicle No. SLK1991H

Accident Date 15/05/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLK1991H	Direct Asia Insurance (Singapore) Pte Ltd	28/02/2012-15/05/2018	65322888
SLK1991H	AXA Insurance Pte Ltd	19/12/2017-18/12/2018	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLK 1991H (Insd veh)	Model:	HYUNDAI I30
	SHB 8047H (TP veh)		
Date of Accident:	15/05/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	3,575.55
Final Repair Cost	:	\$	1,123.50
Loss of Token Sum	:	\$	120.00
			3days at \$40.00 per day
Rental (if any)	:	\$	329.82
			3 days
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum	:	\$	1,575.32

Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability ____ 100 ____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	PREMIER AUTOMOTIVE SERVICES PTE LTD	:	\$ 1,575.32

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

09/10/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18008999/K1ja3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KIAN CHUAN		Date : 09-10-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLK 1991H	Veh. Inspected	SHB 8047H	
Policy No.	VPA/P2047216	Coverage (\$)	0.00	
Claim No.	S8M00HCC	Excess (\$)	0.00	
Assign From		Assign Date	16/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I30	c.c	1582	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	TMAD281UVHJ124414	Colour	SILVER	
Odometer	127751	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MAXXIS	7 mm	
L/H Front Tyre	195/65 R15	MAXXIS	7 mm	
R/H Rear Tyre	195/65 R15	MAXXIS	7 mm	
L/H Rear Tyre	195/65 R15	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/05/2018	Inspection Date	16/05/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8047H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (CONSISTENT)	CUT	811.11	811.11
1	REAR BUMPER SPONGE (CONSISTENT)	SERVICEABLE	79.20	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	SERVICEABLE	815.64	-
1	REAR BUMPER REINFORCEMENT CENTRE (CONSISTENT)	SERVICEABLE	79.20	-
2	REAR BUMPER N/S & O/S SIDE BRACKET @\$52.20 (CONSISTENT)	SERVICEABLE	104.40	-
2	REAR BUMPER N/S & O/S REFLECTOR @\$107.50 (CONSISTENT)	SERVICEABLE	215.00	-
	LESS 20% DISCOUNT		-420.91	-162.22
			1,683.64	648.89
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	48.00	48.00
1	SET REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	280.00	200.00
1	SUNDRY (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
			378.00	248.00
LABOUR				
	TO DISMANTLE AND REPLACE REVERSE SENSOR AND TEST SYSTEM.		80.00	20.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS INCLUDING TO KNOCK - OUT ,STRAIGHTEN ,REPAIR,RESHAPE OF THE END PANEL ,ETC.		550.00	200.00
	TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER,END PANEL.		500.00	200.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	150.00	-
			-	-
			-	-
			-	-
			1,280.00	420.00
GRAND TOTAL			3,341.64	1,316.89

Report Ref No. CC4/ASM18008999/K1ja3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,050.00
-------------------------------------------------------------------------	--	--	----------

Report Ref No. CC4/ASM18008999/K1ja3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.