

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 247P**AAD1805-135**

1615118

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 247P

VF1ABL15AUC282384

RENAULT

LATITUDE

11.5.2018

AIG

PART		LIST	
1	BUMPER COVER FRT ✓	\$	1,259.42
1	BUMPER SPOILER FRT ✗	\$	181.75
1	BUMPER ABSORBER FRT ✗	\$	394.68
1	BUMPER RETAINER FRT RH ✗	\$	150.77
1	BUMPER SUPPORT FRT ✗	\$	123.88
1	BUMPER UNDERTRAY FRT ✗	\$	472.83
1	BUMPER GRILLE LOWER FRT ✗ ✗	\$	266.80
1	BUMPER FOG LAMP GRILLE RH	\$	207.21
1	BUMPER BEAM FRT ✗	\$	914.08
1	HEADLAMP RH ✗	\$	1,184.43
1	HEADLAMP PANEL FRT RH ✗	\$	152.15
1	FENDER PANEL FRT RH ✗ Repair	\$	783.83
1	WHEELARCH FRT RH ✗	\$	278.84
1	FENDER BRACKET LOWER RH ✗	\$	15.79
1	FENDER INSULATOR RH ✗	\$	130.84
1	DOOR PANEL FRT RH ✗	\$	2,844.66
1	RADIATOR GRILLE ✗	\$	1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT' ✗	\$	225.36
1	RADIATOR GRILLE FRAME ✗	\$	1,353.75
1	RADIATOR FAN COWLING ✗	\$	820.54
1	RADIATOR FAN MOTOR LH ✗	\$	967.36
1	RADIATOR FAN MOTOR RH ✗	\$	1,479.46

TOTAL	\$	15,916.22
10%	\$	1,591.62
	\$	14,324.60

Trans-cab Auto Services Pte Ltd

AAD1805-135

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 247P

Specical Nett

1SET	BUMPER CLIP FRT	✓	\$	66.00
1	BUMPER BRACKET CLIP FRT RH	✗	\$	12.00
1	BUMPER SUPPORT CLIP FRT RH	✗	\$	10.50
1SET	BUMPER GRILLE LOWER CLIP	✗	\$	69.00
1SET	FRAME FULL SUPPORT PANEL CLIP	✗	\$	70.00
2	FRAME FULL SUPPORT PANEL NUT	✗	\$	20.00
2	FRAME FULL SUPPORT PANEL STUD	✗	\$	30.00
1SET	WHEELARCH CLIP FRT RH	✗	\$	30.50
1	FRONT DOOR STICKER 'Trans-cab'	✗	\$	80.00
1	FRONT DOOR STICKER 'Chassis'	✗	\$	50.00
1	RIGHT REAR TYRE	✗	\$	380.00

TOTAL	\$	818.00
--------------	-----------	---------------

TOTAL PARTS	\$	15,142.60
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	400 3,500.00
Putty and spray painting of the affected portion.	\$	400 3,000.00
To rust-proofing of the affected areas.	\$	170.00 ✗
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 ✗
To check steering geometry and computer wheel alignment	\$	220.00 ✗
To transfer of tire, rim and on wheel balancing.	\$	170.00 ✗
To Check Electrical Lighting Concerned.	\$	170.00 ✗

Trans-cab Auto Services Pte Ltd**AAD1805-135**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 247PTo transfer of front fender fittings, attachment
and perform water seepage test.\$ ~~380.00~~ XTo vacuum, replace, refix and recharge air
condenser\$ ~~380.00~~ X

To replace, refix and top up coolant for radiator

\$ ~~170.00~~ XTo vacuum, replace, refix and recharge Air
Intercooler\$ ~~170.00~~ X**TOTAL \$ 8,710.00****Over All Total \$ 23,852.60****PART-BY-PART (REPAIR DAY)****10 DAYS***Kalin rckk**16/5/18 1410 hrs.**3 Rep.**P/P**Before Point photo*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: