



(08/11/13)

Surveyor: Kalvin

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspected Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHF 759T Yr Regn: 3<sup>rd</sup> Jan 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Latitude c.c. 1995...Colour: Red A/C: Insured / Std / NI / NASp. Reading: 220130 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VFIABLI5A4C283369

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD/Rim or

Tyre Size: F: 215 / 60 R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 12/5/18 D.O.I. 16/5/18Survey held at Transcab

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S R/L

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

9/5/19 @ 4070.19 Confirm Tarnish (2 x 103.60 + 100)

Global @ 2340 Confirm Tarnish

(CED) - 2529.81 (8%)

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format: \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18009002/K1ea3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 17-05-2018		
		Code : AIG		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SDL 7462T	Veh. Inspected	SHF 759T	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	17/05/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	12/05/2018	Inspection Date	16/05/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

**Trans-cab Auto Services Pte Ltd**

AAD1805-117

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHF 759T

161518 -19

PIP \$4070-19 / 3072.  
B4 paint photo?

Vehicle No.:

SHF 759T

Chassis No.:

VF1ABL15AUC283369

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE

Date of Accident:

12.5.2018

Third Party Insurer:

AIG

PART		LIST	
1	DOOR PANEL REAR RH <i>— 161</i>	\$	2,844.66
1	DOOR GUIDE REAR RH <i>X sec</i>	\$	176.82
1	DOOR HINGE UPPER RH <i>X sec</i>	\$	274.50
1	DOOR HINGE LOWER RH <i>X sec</i>	\$	300.55
1	DOOR CHECK REAR LH/RH L70Y <i>X sec</i>	\$	203.06
1	DOOR LOCK REAR RH <i>X sec</i>	\$	908.75
1	DOOR HANDLE OUTER REAR RH <i>X sec</i>	\$	126.49
1	DOOR HANDLE CAP REAR RH <i>X sec</i>	\$	35.52
1	DOOR HANDLE SEAL REAR RH <i>X sec</i>	\$	7.89
1	DOOR HANDLE COVER REAR RH <i>X sec</i>	\$	13.22
1	DOOR HANDLE MODULE REAR RH <i>X sec</i>	\$	133.60
1	DOOR REGULATOR REAR RH <i>X sec</i>	\$	1,135.10
1	DOOR REGULATOR MOTOR REAR RH <i>X sec</i>	\$	893.75
1	DOOR REGULATOR NUT REAR L70Y <i>X sec</i>	\$	12.43
1	DOOR FINISHER REAR RH <i>X sec</i>	\$	423.10
1	DOOR MOULDING REAR RH <i>X sec</i>	\$	176.82
1	DOOR CASING REAR RH <i>X sec</i>	\$	1,509.06
1	DOOR WATER SHIELD REAR RH <i>X sec</i>	\$	30.39
1	DOOR CASING LIGHT L70Y <i>X 9</i>	\$	48.74
1	DOOR FINISHER INNER REAR RH <i>X sec</i>	\$	323.44
1	DOOR FINISHER BRACKET INNER REAR RH <i>X sec</i>	\$	46.97
1	DOOR FINISHER BRACKET INNER REAR RH <i>X sec</i>	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR RH <i>X sec</i>	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR RH <i>X sec</i>	\$	20.33
1	DOOR GRAB HANDLE REAR RH <i>X sec</i>	\$	210.96
1	DOOR BLIND REAR RH <i>X sec</i>	\$	741.80
1	DOOR WHEATHESTRIIP REAR RH <i>X sec</i>	\$	410.66
1	DOOR SEAL REAR RH <i>X 77</i>	\$	162.02
1	DOOR GLASS RUNNER SEAL REAR RH <i>X 77</i>	\$	229.31

**Trans-cab Auto Services Pte Ltd**

AAD1805-117

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 759T

1	DOOR WAIST SEAL OUTER REAR RH	X sec	\$	334.69
1	DOOR WAIST SEAL INNER REAR RH	X sec	\$	115.64
1	FENDER PANEL REAR RH	X 1/4" 2"	\$	3,299.13
1	FENDER PANEL INNER TRIM REAR	X sec	\$	671.45
1	WHEELARCH REAR RH	X sec	\$	543.47
1	ROCKER PANEL INNER GARNISH RH	X 1/4" 2"	\$	466.51
1	ROCKER PANEL INNER RH	X sec	\$	1,024.79
1	ROCKER PANEL CENTER RH	X sec	\$	990.25

Front RH Door X 1/4" 2"

	\$	18,886.52
10%	\$	1,888.65
	\$	16,997.87

**Special Nett**

1SET	FRAME FULL SUPPORT PANEL CLIP	X 44	\$	70.00
2	FRAME FULL SUPPORT PANEL NUT	X 44	\$	20.00
2	FRAME FULL SUPPORT PANEL STUD	X 44	\$	30.00
1SET	WHEELARCH CLIP FRT LH	X 44	\$	30.50
1	FRONT DOOR STICKER 'Trans-cab'	— sec	\$	80.00
1	FRONT DOOR STICKER 'Chassis'	— sec	\$	50.00
1	REAR DOOR STICKER '6555 3333'	— sec	\$	80.00
1	DOOR CHECK BOLT	X 44	\$	22.69
1	DOOR GUIDE SCREW	X 44	\$	10.85
1	DOOR HINGE BOLT	X 44	\$	10.85
1	DOOR HINGE NUT RH	X 44	\$	14.60
1	DOOR CHECK BOLT	X 44	\$	22.69
1	DOOR CHECK NUT	X 44	\$	3.75
1	DOOR LOCK SCREW L70Y	X 44	\$	6.12
1	DOOR CATCH SCREW L70Y	X 44	\$	10.06

TOTAL \$ 462.13

TOTAL PARTS \$ 17,460.00

**Trans-cab Auto Services Pte Ltd**

AAD1805-117

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 759T

**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	<del>4,500.00</del> 400
Putty and spray painting of the affected portion.	\$	<del>4,200.00</del> 800
To rust-proofing of the affected areas.	\$	<del>170.00</del> 50
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<del>380.00</del> X 11
To check steering geometry and computer wheel alignment	\$	<del>220.00</del> X 11
To transfer of tire, rim and on wheel balancing.	\$	<del>170.00</del> X 11
To Check Electrical Lighting Concerned.	\$	<del>170.00</del> X 11
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<del>380.00</del> X 11
To transfer of front door fittings, attachment and perform water seepage test.	\$	<del>380.00</del> X 11
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	<del>380.00</del> 50
Towing Fees.	\$	<del>120.00</del> X 11
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<del>380.00</del> X 11
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<del>380.00</del> X 11

**Trans-cab Auto Services Pte Ltd**

AAD1805-117

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 759T

TOTAL	\$	11,830.00
-------	----	-----------

Over All Total	\$	29,290.00
----------------	----	-----------

PART-BY-PART (REPAIR DAY)

15 DAYS

Kalam 11/11/14

16/5/18 1330hrs

3 P.M.

P/P

Before Part photo

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Trans-Cab Services Pte Ltd**

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Our Ref : AAD1805-117

Your Ref : SDL7462T

Date : 12.April 2019

**AIG ASIA PACIFIC INSURANCE**

Dear Sir/Madam,

**ACCIDENT INVOLVING SHF0759T AND SDL7462T ON 12/05/18 05:15 PM ALONG JALAN EUNOS**

It appears that the above accident was caused by your insured's negligence. We, therefore seeking compensation from you for our financial loss as itemized below :-

1.	Cost of Repair (inclusive of 7% GST)	\$	4,355.10
2.	Loss of Rental for <u>2</u> days @ \$ <u>103.6</u> per day	\$	207.20
3.	Loss of Income for <u>2</u> days @ \$ <u>50</u> per day	\$	100.00
4.	LTA Search Fee	\$	7.49
5.	Survey Fee	\$	0.00
	Total	\$	4,669.79

We enclose a copy of the following documents for your consideration :-

GIA report lodged by our driver

Rental rate and mileage records

Certificate of Insurance

Authorization To Act

Original final repair bill

LTA Search Fee

**Kindly let us have the discharge voucher within the next 14 days, failing which we shall proceed to hand over the conduct of this matter to our solicitors without further reference to you.**

Yours Faithfully

Trans-Cab Services Pte Ltd



Jasmine Tan

General Manager

Tel No. : 6603 1250 (DID)

Note : Please email any further correspondence to claims@transcab.com.sg (6603 1259)



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company  
Owner ID: 3878K

Vehicle Details

Vehicle No.: SHF759T  
Vehicle to be Exported: Yes  
Intended De-registration Date: 14 May 2018  
Vehicle Make: RENAULT  
Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR  
Primary Colour: Red  
Manufacturing Year: 2015  
Engine No.: M9R8839C003269  
Chassis No.: VF1ABL15AUC283369  
Maximum Power Output: 127.0 kW (170 bhp)  
Open Market Value: \$19,998.00  
Original Registration Date: 30 Jun 2016  
First Registration Date: 30 Jun 2016  
Transfer Count: 0  
Actual ARF Paid: \$19,998.00

Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 29 Jun 2024  
PARF Rebate Amount: \$14,998.00

Intended COE Rebate Details

COE Expiry Date: 29 Jun 2024  
COE Category: A - Car up to 1600cc & 97kW (130bhp)  
COE Period(Years): 8  
PQP Paid: \$37,164.00  
COE Rebate Amount: \$28,453.00  
Total Rebate Amount: \$43,451.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 14 May 2018

OK



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

**Our Ref: CC3/AIG18009002/K1ea3**

22 MAY 2018

**LEE YANG JOON**  
2 GATEWAY DRIVE  
#19-03  
SINGAPORE 608533

Dear Sir/Madam,

**ACCIDENT INVOLVING SDL 7462T AND SHF 759T ON 12/05/2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Kindly note that we have reviewed this matter and would like to advise that you and/or your authorized driver may not be absolved from blame for this accident.

If you have evidence/information to prove that we should not settle the third party claim, kindly let us have them in writing within the next 10 days, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Asher  
Case Handler  
DID: 6841 6051  
FAX: 6741 4108  
Email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

**Trans-Cab Services Pte Ltd**

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

**Authorization To Act**

We, Trans-cab Services Pte Ltd of Company Registration No. 200303878K hereby authorize Trans-cab Auto Services Pte Ltd to act on behalf to claim for all losses incurred for the accident involving SHF0759T and SDL7462T along JALAN EUNOS on 12/05/18 05:15 PM.

In addition, we also hereby authorize the above payment to be made in favour of Trans-cab Auto Services Pte Ltd upon settlement.

Dated this 12 (day) of April 2019

Yours Faithfully

Trans-Cab Services Pte Ltd



Jasmine Tan

General Manager

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, **TRANS-CAB AUTO SERVICES PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$2,340.00** (Global Sum) for vehicle no. **SHF 759T** that was damaged pursuant to the accident which occurred on **12/05/2018** (date) along **JALAN EUNOS** involving vehicle no/s **SDL 7462T**.

This is pursuant to the inspection conducted on **16/05/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **TRANS-CAB SERVICES PTE LTD** ("the third party claimant") of vehicle no. **SHF 759T** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SHF 759T** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 11 (day) of 06 (month) 2019 (year)

  
Signed by appointed surveyor

  
Signed by "the workshop" (with chop)

**Trans-Cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel: 6287 6666

Fax: 6287 7764

Co. Reg. No.: 201019626G

GST Reg. No.: 201019626G

**Tax Invoice / Debit Note**

<b>TO:</b> <b>AIG ASIA PACIFIC INSURANCE PTE LTD</b> 78 Shenton Way #07-16 CHARTIS Building 079120 Singapore  ATTENTION:	<b>INVOICE NO.</b> : INV1904-008 <b>DATE</b> : 12, April 2019 <b>REFERENCE NO</b> : AAD1805-117 <b>TERMS</b> : Net 30 Days <b>DUE DATE</b> : 12, May 2019 <b>PAGE</b> : 1
--	--

NO.	CODE	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1.	6050101	REPAIR-SHF0759T DOA: 12.05.18 (PART BY PART-19)	1	4,355.10	4,355.10

<b>Total SGD Excl. GST :</b>	<b>4,070.19</b>
<b>7% GST :</b>	<b>284.91</b>
<b>Total SGD Incl. GST :</b>	<b>4,355.10</b>

**\*\*\*\* FOUR THOUSAND THREE HUNDRED FIFTY FIVE AND TEN SGD ONLY \*\*\*\***

- 1) All cheques should be crossed and made payable to "Trans-Cab Auto Services Pte Ltd"
- 2) Please quote our Invoice Number during payment.
- 3) We reserve the right to charge interest @ 1.5% per month on overdue invoice.
- 4) Any dispute as to the accuracy, charges etc of this invoice must be communicated within 10 days from the date hereof failing which it shall be deemed to have been unconditionally accepted.

**E. & O. E.****THIS IS A COMPUTER GENERATED INVOICE WHICH REQUIRES NO SIGNATURE**

**Trans-Cab Services Pte Ltd**

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

12 April, 2019

To Whom It May Concern

Dear Sir / Madam,

Accident on 12/05/18 05:15 PM at JALAN EUNOS

1. We refer to the above-mentioned accident and wish to inform that Trans-Cab Services Pte Ltd is the registered owner of the taxi bearing vehicle registration no. SHF0759T. The taxi was hired to LYE POH WAH a registered hirer-operator of Trans-Cab Services Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate ~~\$105.74~~ per day (inclusive of GST).
2. Please be advised that the Taxi is insured with AXA INSURANCE PTE LTD on a third party basis at the material time of the accident.
3. Please liaise with us directly for any settlement of claims in respect of the said accident.

Yours faithfully,

Jasmine Tan

General Manager

**Trans-Cab Services Pte Ltd**

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

12-05-2018

Dear Sir/Madam,

Please be informed that the taxi was undergo accident repair in the workshop as follow:

Date In	Date Out	Vehicle No.
<b>Accident No.</b>	<b>AAD1805-117</b>	<b>Accident Date</b> 12-05-2018
16/5/2018 09:40	16/5/2018 14:00	SHF0759T
29/11/2018 10:44	30/11/2018 17:00	SHF0759T

Yours Faithfully,

**Trans-Cab Services Pte Ltd**



**Jasmine Tan**

**General Manager**

[> Back to OneMotoring](#)

## Vehicle Insurance Particulars Result

Vehicle No.	Incident Date/Time	Insurance Company Name
SDL7462T	12 May 2018 / 17:15:00	AIG ASIA PACIFIC INSURANCE PTE. LTD.

[Print](#)[OK](#)[Save as PDF](#)



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

## CLAIM SUBFOLDER TRACKING









































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 May 2018 <a href="#">Edit Reg</a>		16 May 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$4,070.19</b> <a href="#">Edit Estimates</a>	<b>S\$4,070.19</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	LEE YANG JOON, ID: S2551262F								
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K								
Vehicle Reg. No.:	SHF759T	Date of Loss:	12/05/2018 17:00 - :59 [22 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3684623761SG	Policy/Cover Note No.:	2100363580 (Comprehensive) Coverage: 06/02/2018 - 05/02/2019						
Vehicle Reg. No. (Insured):	SDL7462T	Policy No. (Claimant):	VPX/P1680520						
		Excess:							
Repairer:	Trans-cab Auto Services Pte Ltd ( ) No 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 28/05/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (18/05/2018): Request To Upload TP GIA Report</li> <li>AIG_SG (18/05/2018): Request To Upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SHF759T (3684623761SG)  
[SDL7462T]  
TP  
TRANS-CAB SERVICES PTE LTD  
May 12 2018 5:00PM  
[LEE YANG JOON]  
Trans-cab Auto Services Pte Ltd

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>   <a href="#">Upload Video</a>   <a href="#">Upload Audio</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Video</b>				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	22/05/18 09:46	<b>Video - Accident</b> <small>From: OD - Reg. No: SDL7462T, Claimant: LEE YANG JOON</small>	Load MP4	
<b>Letters/Correspondences</b>				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	[Draft]	<b>Third Party Express Settlement - Payment Breakdown</b>	Edit	
<b>Photos/Images</b>				
			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
2	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
15	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
16	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
17	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
18	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
19	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
20	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
21	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
22	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
23	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
24	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
25	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
26	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
27	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
28	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
29	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
30	18/05/18 08:16	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
31	03/06/19 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
32	03/06/19 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
33	03/06/19 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
34	03/06/19 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
35	03/06/19 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
36	03/06/19 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
37	03/06/19 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
38	03/06/19 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
39	03/06/19 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
40	03/06/19 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
41	03/06/19 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
42	03/06/19 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
43	03/06/19 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
44	03/06/19 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
45	03/06/19 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
46	03/06/19 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
47	03/06/19 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
48	03/06/19 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
49	03/06/19 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
50	03/06/19 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
51	03/06/19 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
52	03/06/19 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
53	03/06/19 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
54	03/06/19 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
55	03/06/19 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
56	03/06/19 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
57	03/06/19 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
58	03/06/19 17:32	General View	 Load JPG	<input checked="" type="checkbox"/>
59	03/06/19 17:32	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
60	03/06/19 17:32	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/05/18 01:30	TP ESTIMATE - MARKED	 Load PDF	
2	26/05/18 01:30	TP GIA REPORT.	 Load PDF	
3	03/06/19 17:32	LETTER TO OI	 Load PDF	
4	26/06/19 15:46	WORKSHOP INVOICE	 Load PDF	
5	26/06/19 15:46	AUTHORISATION TO ACT FORM	 Load PDF	
6	26/06/19 15:46	Release Voucher	 Load PDF	
7	26/06/19 15:46	RENTAL RECEIPT	 Load PDF	
8	26/06/19 15:46	RENTAL MILEAGE	 Load PDF	
9	26/06/19 15:46	LTA SEARCH	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	18/05/18 09:36	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SDL7462T (Insd veh)	Model:	RENAULT LATITUDE 2.0 DCI
	SHF759T (TP veh)		AUTO D/AB 4DR (A)
Date of Accident:	12/05/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	31,340.29
Final Repair Cost	:	\$	2,340.00
Loss of Use	:	\$	2.00 days at \$50.00 per day
Rental (if any)	:	\$	2 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	2,340.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_\_ 50 \_\_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Trans-cab Auto Services Pte Ltd	: \$	2,340.00
2)		: \$	
3)		: \$	
4)		: \$	
5)		: \$	

JOANNE LEE KHANG MIN

26 Jun  
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18009002/K1EA3Q2

Date: 26/06/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 2100363580
<b>Claimant Vehicle No :</b> SHF759T	<b>Insured Vehicle No :</b> SDL7462T
Date of Loss: 12/05/2018	Nature of Claim: TP Claim No: 3684623761SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHF759T		
Make & Model:	RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C003269
Reg. Date:	30/06/2016 (Man. Year: 2015)	Chassis No:	VF1ABL15AUC283369
Colour:	Red	Odometer:	220130 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Giti 7 mm	Rear Left Side:	Giti 7 mm
Front Right Side:	Giti 7 mm	Rear Right Side:	Giti 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,459.99	2,770.19	14,689.80	84.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,830.00	1,300.00	10,530.00	89.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>29,289.99</b>	<b>4,070.19</b>	<b>25,219.80</b>	<b>86.10</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,050.30</b>	<b>284.91</b>	<b>1,765.39</b>	<b>86.10</b>
<b>Nett Amount (S\$)</b>	<b>31,340.29</b>	<b>4,355.10</b>	<b>26,985.19</b>	<b>86.10</b>
<b>+ Loss of Use (2.0 x S\$50.00/day) (S\$)</b>		100.00		
<b>+ Car Rental (2.0 x S\$103.60/day) (S\$)</b>		207.20		
		<b>(S\$) 4,662.30</b>		
<b>Liabile Amount (50.00%) (S\$)</b>		<b>2,331.15</b>		
<b>+ Doc/Search Fee (S\$)</b>		7.49		
<b>Nett Liability (S\$)</b>		<b>2,338.64</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,340.00</b>		

### INSPECTION

Date of Assignment: 16/05/2018

Date Inspected: 16/05/2018 Inspected At: Trans-cab Auto Services Pte Ltd  
No 2 Ang Mo Kio Street 63  
Singapore 569111

Estimated Period of Repair: 3.0 days

---

**Adjuster:** KALVIN ANG WEI KUN

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR PANEL REAR RH	Dented	2,844.66 FL	*2,844.66 FL
2	1		*DOOR GUIDE REAR RH	Serviceable	176.82 FL	*- FL
3	1		*DOOR HINGE UPPER RH	Serviceable	274.50 FL	*- FL
4	1		*DOOR HINGE LOWER RH	Serviceable	300.55 FL	*- FL
5	1		*DOOR CHECK REAR LH/RH L70Y	Serviceable	203.06 FL	*- FL
6	1		*DOOR LOCK REAR RH	Serviceable	908.75 FL	*- FL
7	1		*DOOR HANDLE OUTER REAR RH	Serviceable	126.49 FL	*- FL
8	1		*DOOR HANDLE CAP REAR RH	Serviceable	35.52 FL	*- FL
9	1		*DOOR HANDLE SEAL REAR RH	Serviceable	7.89 FL	*- FL
10	1		*DOOR HANDLE COVER REAR RH	Serviceable	13.22 FL	*- FL
11	1		*DOOR HANDLE MODULE REAR RH	Serviceable	133.60 FL	*- FL
12	1		*DOOR REGULATOR REAR RH	Serviceable	1,135.10 FL	*- FL
13	1		*DOOR REGULATOR MOTOR REAR RH	Serviceable	893.75 FL	*- FL
14	1		*DOOR REGULATOR NUT REAR L70Y	Serviceable	12.43 FL	*- FL
15	1		*DOOR FINISHER REAR RH	Serviceable	423.10 FL	*- FL
16	1		*DOOR MOULDING REAR RH	Serviceable	176.82 FL	*- FL
17	1		*DOOR CASING REAR RH	Serviceable	1,509.06 FL	*- FL
18	1		*DOOR WATER SHIELD REAR RH	Serviceable	30.39 FL	*- FL
19	1		*DOOR CASING LIGHT L70Y	Not Necessary	48.74 FL	*- FL
20	1		*DOOR FINISHER INNER REAR RH	Serviceable	323.44 FL	*- FL
21	1		*DOOR FINISHER BRACKET INNER REAR RH	Serviceable	46.97 FL	*- FL
22	1		*DOOR FINISHER BRACKET INNER REAR RH	Serviceable	20.33 FL	*- FL
23	1		*DOOR FINISHER BRACKET INNER REAR RH	Serviceable	20.33 FL	*- FL
24	1		*DOOR FINISHER BRACKET INNER REAR RH	Serviceable	20.33 FL	*- FL
25	1		*DOOR GRAB HANDLE REAR RH	Serviceable	210.96 FL	*- FL
26	1		*DOOR BLIND REAR RH	Serviceable	741.80 FL	*- FL
27	1		*DOOR WEATHERSTRIP REAR RH	Serviceable	410.66 FL	*- FL
28	1		*DOOR SEAL REAR RH	Not Necessary	162.02 FL	*- FL
29	1		*DOOR GLASS RUBBER SEAL REAR RH	Not Necessary	229.31 FL	*- FL
30	1		*DOOR WAIST SEAL OUTER REAR RH	Serviceable	334.69 FL	*- FL
31	1		*DOOR WAIST SEAL INNER REAR RH	Serviceable	115.64 FL	*- FL
32	1		*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
33	1		*FENDER PANEL INNER TRIM REAR	Serviceable	671.45 FL	*- FL
34	1		*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
35	1		*ROCKER PANEL INNER GARNISH RH	Repair	466.51 FL	*- FL
36	1		*ROCKER PANEL INNER RH	Serviceable	1,024.79 FL	*- FL
37	1		*ROCKER PANEL CENTER RH	Serviceable	990.25 FL	*- FL
38	1		*FRONT RH DOOR (NPA)	Repair	0.00 FL	*- FL
39	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
40	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
41	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
42	1		*SET WHEELARCH CLIP FRT LH	Not Necessary	30.50 FS	*- FS
43	1		*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*80.00 FS
44	1		*FRONT DOOR STICKER CHASSIS	Necessary	50.00 FS	*50.00 FS
45	1		*REAR DOOR STICKER 65555 3333	Necessary	80.00 FS	*80.00 FS
46	1		*DOOR CHECK BOLT	Not Necessary	22.69 FS	*- FS
47	1		*DOOR GUIDE SCREW	Not Necessary	10.85 FS	*- FS
48	1		*DOOR HINGE BOLT	Not Necessary	10.85 FS	*- FS
49	1		*DOOR HINGE NUT RH	Not Necessary	14.60 FS	*- FS

Report was unsubmitted during this print-out.



No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*DOOR CHECK BOLT	Not Necessary	22.69 FS	*- FS
51	1		*DOOR CHECK NUT	Not Necessary	3.75 FS	*- FS
52	1		*DOOR LOCK SCREW L70Y	Not Necessary	6.12 FS	*- FS
53	1		*DOOR CATCH SCREW L70Y	Not Necessary	10.06 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>19,348.64</b>	<b>3,054.66</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>1,888.65</b>	<b>284.47</b>

<b>Total Parts (\$\$)</b>	<b>17,459.99</b>	<b>2,770.19</b>
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	4,500.00	400.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,200.00	800.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	50.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
6	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
8	TO TRANSFER OF FRONT FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
9	TO TRANSFER OF FRONT DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
10	TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	50.00
11	TOWING FEES	New	120.00	0.00
12	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK	New	380.00	0.00
13	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>11,830.00</b>	<b>1,300.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >