

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 759T**AAD1805-117**

1615118 -19

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF 759T

VF1ABL15AUC283369

RENAULT

LATITUDE

12.5.2018

AIG

PART		LIST	
1	DOOR PANEL REAR RH ✓	\$	2,844.66
1	DOOR GUIDE REAR RH ✕	\$	176.82
1	DOOR HINGE UPPER RH ✕	\$	274.50
1	DOOR HINGE LOWER RH ✕	\$	300.55
1	DOOR CHECK REAR LH/RH L70Y ✕	\$	203.06
1	DOOR LOCK REAR RH ✕	\$	908.75
1	DOOR HANDLE OUTER REAR RH ✕	\$	126.49
1	DOOR HANDLE CAP REAR RH ✕	\$	35.52
1	DOOR HANDLE SEAL REAR RH ✕	\$	7.89
1	DOOR HANDLE COVER REAR RH ✕	\$	13.22
1	DOOR HANDLE MODULE REAR RH ✕	\$	133.60
1	DOOR REGULATOR REAR RH ✕	\$	1,135.10
1	DOOR REGULATOR MOTOR REAR RH ✕	\$	893.75
1	DOOR REGULATOR NUT REAR L70Y ✕	\$	12.43
1	DOOR FINISHER REAR RH ✕	\$	423.10
1	DOOR MOULDING REAR RH ✕	\$	176.82
1	DOOR CASING REAR RH ✕	\$	1,509.06
1	DOOR WATER SHIELD REAR RH ✕	\$	30.39
1	DOOR CASING LIGHT L70Y ✕	\$	48.74
1	DOOR FINISHER INNER REAR RH ✕	\$	323.44
1	DOOR FINISHER BRACKET INNER REAR RH ✕	\$	46.97
1	DOOR FINISHER BRACKET INNER REAR RH ✕	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR RH ✕	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR RH ✕	\$	20.33
1	DOOR GRAB HANDLE REAR RH ✕	\$	210.96
1	DOOR BLIND REAR RH ✕	\$	741.80
1	DOOR WHEATHESTRIIP REAR RH ✕	\$	410.66
1	DOOR SEAL REAR RH ✕	\$	162.02
1	DOOR GLASS RUNNER SEAL REAR RH ✕	\$	229.31

Trans-cab Auto Services Pte Ltd**AAD1805-117**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 759T

1	DOOR WAIST SEAL OUTER REAR RH	X	\$	334.69
1	DOOR WAIST SEAL INNER REAR RH	X	\$	115.64
1	FENDER PANEL REAR RH	X Rep. 2	\$	3,299.13
1	FENDER PANEL INNER TRIM REAR	X	\$	671.45
1	WHEELARCH REAR RH	X	\$	543.47
1	ROCKER PANEL INNER GARNISH RH	X Rep. 2	\$	466.51
1	ROCKER PANEL INNER RH	X	\$	1,024.79
1	ROCKER PANEL CENTER RH	X	\$	990.25

Front RH door X Rep. 2

	\$	18,886.52
10%	\$	1,888.65
	\$	16,997.87

Special Nett

1SET	FRAME FULL SUPPORT PANEL CLIP	X	\$	70.00
2	FRAME FULL SUPPORT PANEL NUT	X	\$	20.00
2	FRAME FULL SUPPORT PANEL STUD	X	\$	30.00
1SET	WHEELARCH CLIP FRT LH	X	\$	30.50
1	FRONT DOOR STICKER 'Trans-cab'	/	\$	80.00
1	FRONT DOOR STICKER 'Chassis'	/	\$	50.00
1	REAR DOOR STICKER '6555 3333'	/	\$	80.00
1	DOOR CHECK BOLT	X	\$	22.69
1	DOOR GUIDE SCREW	X	\$	10.85
1	DOOR HINGE BOLT	X	\$	10.85
1	DOOR HINGE NUT RH	X	\$	14.60
1	DOOR CHECK BOLT	X	\$	22.69
1	DOOR CHECK NUT	X	\$	3.75
1	DOOR LOCK SCREW L70Y	X	\$	6.12
1	DOOR CATCH SCREW L70Y	X	\$	10.06

TOTAL	\$	462.13
--------------	----	---------------

TOTAL PARTS	\$	17,460.00
--------------------	----	------------------

Transcab Auto Services Pte Ltd

AAD1805-117

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 759T

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00 400
Putty and spray painting of the affected portion.	\$	4,200.00 800
To rust-proofing of the affected areas.	\$	170.00 50
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 X
To check steering geometry and computer wheel alignment	\$	220.00 X
To transfer of tire, rim and on wheel balancing.	\$	170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00 X
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00 X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00 50
Towing Fees.	\$	120.00 X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 X

Trans-cab Auto Services Pte Ltd

AAD1805-117

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 759T

TOTAL	\$	11,830.00
Over All Total	\$	29,290.00

PART-BY-PART (REPAIR DAY)

15 DAYS

Kahin 10/10/18

16/5/18 1330hrs
3 Days.

P/P

Before Part photo

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: