

Trans-cab Auto Services Pte Ltd**AAD1805-130**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 558G

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF 558G

VF1ABL15AUC278119

RENAULT

LATITUDE

13.5.2018

AIG

	PART		LIST
1	DOOR PANEL FRT RH <i>x/rep</i>	\$	2,844.66
1	DOOR HINGE UPPER RH <i>x</i>	\$	261.28
1	DOOR HINGE LOWER RH <i>x</i>	\$	300.55
1	DOOR CHECK FRT RH <i>x</i>	\$	194.77
1	DOOR LOCK FRT RH <i>x</i>	\$	908.75
1	DOOR CATCH FRT RH <i>x</i>	\$	131.23
1	DOOR HANDLE OUTER FRT RH <i>x</i>	\$	477.76
1	DOOR HANDLE COVER FRT RH <i>x</i>	\$	13.22
1	DOOR HANDLE MODULE FRT RH <i>x</i>	\$	133.60
1	DOOR REGULATOR FRT RH <i>x</i>	\$	505.19
1	DOOR REGULATOR MOTOR FRT RH <i>x</i>	\$	796.46
1	DOOR REGULATOR GUIDE FRT RH <i>x</i>	\$	120.97
1	DOOR PANEL REAR RH <i>/</i>	\$	2,844.66
1	DOOR GUIDE REAR RH <i>x</i>	\$	176.82
1	DOOR HINGE UPPER RH <i>x</i>	\$	274.50
1	DOOR HINGE LOWER RH <i>x</i>	\$	300.55
1	DOOR CHECK REAR LH/RH L70Y <i>x</i>	\$	203.06
1	DOOR LOCK REAR RH <i>x</i>	\$	908.75
1	DOOR HANDLE OUTER REAR RH <i>x</i>	\$	126.49
1	DOOR HANDLE CAP REAR RH <i>x</i>	\$	35.52
1	DOOR HANDLE COVER REAR RH <i>x</i>	\$	13.22
1	DOOR HANDLE MODULE REAR RH <i>x</i>	\$	133.60
1	DOOR REGULATOR REAR RH <i>x</i>	\$	1,135.10
1	DOOR REGULATOR MOTOR REAR RH <i>x</i>	\$	893.75
1	DOOR REGULATOR NUT REAR L70Y <i>x</i>	\$	12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y <i>x</i>	\$	6.31
1	DOOR FINISHER REAR RH <i>x</i>	\$	423.10
1	DOOR MOULDING REAR RH <i>x</i>	\$	176.82
1	DOOR MOULDING CLIP L70Y <i>x</i>	\$	5.92

Trans-cab Auto Services Pte Ltd**AAD1805-130**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 558G

1	DOOR MOULDING SCREW L70Y X	\$	6.91
1	DOOR CASING REAR RH X	\$	1,509.06
1	DOOR WATER SHIELD REAR RH X	\$	30.39
1	DOOR CASING CLIP X	\$	12.63
1	DOOR CASING LIGHT L70Y X	\$	48.74
1	DOOR FINISHER INNER REAR RH X	\$	323.44
1	DOOR FINISHER BRACKET INNER REAR RH X	\$	46.97
1	DOOR FINISHER BRACKET INNER REAR RH X	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR RH X	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR RH X	\$	20.33
1	DOOR GRAB HANDLE REAR RH X	\$	210.96
1	DOOR BLIND REAR RH X	\$	741.80
1	DOOR WHEATHESTRIIP REAR RH X	\$	410.66
1	DOOR SEAL REAR RH X	\$	162.02
1	DOOR GLASS RUNNER SEAL REAR RH X	\$	229.31
1	DOOR WAIST SEAL OUTER REAR RH X	\$	334.69
1	DOOR WAIST SEAL INNER REAR RH X	\$	115.64
1	FENDER PANEL REAR RH X rep	\$	3,299.13
1	FENDER PANEL INNER TRIM REAR X	\$	671.45
1	WHEELARCH REAR RH X	\$	543.47
1	DOOR MIRROR ASSY RH X	\$	1,483.40
1	TAILLAMP RH X	\$	552.55
1	BUMPER COVER REAR X	\$	1,108.46
1	BUMPER LOWER REAR X	\$	768.84
1	BUMPER BRACKET CTR REAR X	\$	113.47
1	BUMEPR BRACKET SIDE RH REAR X	\$	135.97
1	BUMEPR RETAINER RH REAR X	\$	44.99
1	BUMPER REFLECTOR RH X	\$	43.61
1	BUMEPR BRACKET SIDE LH REAR X	\$	135.97
1	BUMEPR RETAINER LH REAR X	\$	44.99
1	BUMPER REFLECTOR LH X	\$	43.61
1	BUMPER BEAM REAR X	\$	777.52
1	BUMPER BEAM BRACKET LH REAR X	\$	225.95
1	BUMPER BEAM BRACKET RH REAR X	\$	225.95
1	ROCKER PANEL INNER GARNISH RH X	\$	466.51
1	ROCKER PANEL INNER RH X	\$	1,024.79
1	ROCKER PANEL CENTER RH X	\$	990.25

Trans-cab Auto Services Pte Ltd

AAD1805-130

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 558G

	\$	31,304.14
10%	\$	3,130.41
	\$	28,173.73

Special Nett

1SET	FRAME FULL SUPPORT PANEL CLIP	X	\$	70.00
2	FRAME FULL SUPPORT PANEL NUT	X	\$	20.00
2	FRAME FULL SUPPORT PANEL STUD	X	\$	30.00
1SET	WHEELARCH CLIP FRT LH	X	\$	30.50
1	FRONT DOOR STICKER 'Trans-cab'	/	\$	80.00
1	FRONT DOOR STICKER 'Chassis'	/	\$	50.00
1	REAR DOOR STICKER '6555 3333'	/	\$	80.00
1	DOOR CHECK BOLT	X	\$	22.69
1	DOOR GUIDE SCREW	X	\$	10.85
1	DOOR HINGE BOLT	X	\$	10.85
1	DOOR HINGE NUT RH	X	\$	14.60
1	DOOR CHECK BOLT	X	\$	22.69
1	DOOR CHECK NUT	X	\$	3.75
1	DOOR LOCK SCREW L70Y	X	\$	6.12
1	DOOR CATCH SCREW L70Y	X	\$	10.06

TOTAL	\$	462.13
--------------	----	---------------

TOTAL PARTS	\$	28,635.86
--------------------	----	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	4,500.00 600
----	-------------------------

Putty and spray painting of the affected portion.

\$	4,200.00 800
----	-------------------------

To rust-proofing of the affected areas.

\$	170.00 50
----	----------------------

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	380.00 X
----	---------------------

Trans-cab Auto Services Pte Ltd

AAD1805-130

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 558G

To check steering geometry and computer wheel alignment	\$	220.00 X
To transfer of tire, rim and on wheel balancing.	\$	170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00 X
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00 X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00 50
Towing Fees.	\$	120.00 X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 X

TOTAL	\$	11,830.00
--------------	-----------	------------------

Over All Total	\$	40,465.86
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)**15 DAYS**

Ka Lin LKK
16/5/18 1730 hrs.
4 Pys.
L/s
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: