



Signature

Fame

REF:

III

9010

J63-01

01C  
H522

## ASSIGNMENT

From:

Date

24/5/18

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBG 1034K

at Workshop m/s

TC Autoclinic

of

25 Long Kee Rd

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

10 am - 12 pm


Make of Veh:

owner reach around 12pm

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'w/p'

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBG 1034K

Yr Regn:

2017 / May

Type: M.Car / M.Cycle / Bus ☒ Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan Urvan NV20015 c.c 1461

Colour:

BLUE

A/C: Insured / Std / NI / NA

Sp. Reading

43928

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VSK4BAM2020145683

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

175/70R14

R:

BS / DUN / EXNOVA / ☒ GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

11/05/18

D.O.I.

24/05/18

Survey held at

TC Autoclinic

Des. of Damages: Frt / Rear / ☒ O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$

3,997.40

(CRD: \$2,973.60 / 42%)

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS \$

) Photo

) Other:

)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607188R GST Reg. No. 10 0607188-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CC4/III18009010/3

64 CECIL STREET  
#05-02 IOB BUILDING SINGAPORE 049711

Date : 17-05-2018



Code : III2

## 1. Policy Particulars :-

Insured Veh.	SUA 4241U	Make, Inspection	UBI 1034K
Policy No.		Insurance No.	1034K
Claim No.		Excess (\$)	2000
Assign From		Assign To	17-05-2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.		Year of Reg.	
Chassis No.		Engine	
Oil motor			
Oil filter			
Oil pan			
Oil pump			

## 3. Condition

Front Left Tyre		Front Right Tyre	
Left Front Tyre		Right Front Tyre	
Right Rear Tyre		Left Rear Tyre	
L/R Rear Tyre			

## 4. Description of Vehicle

--	--

## 5. General

Insured Date		Insured By	
Policy held at	INDIA INTERNATIONAL PTE LTD		
	25, LEMMAE RD		
	SINGAPORE 150097		

## 5a. Remarks

ALL INFORMATION WAS OBTAINED ON A/VITUAL BASIS. NO PHYSICAL INSPECTION WAS CONDUCTED. WE ARE NOT AUTHORIZED TO ISSUE POLICIES.
--

787  
TC AUTOCLINIC PTE LTD  
25 LENG KEE ROAD  
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : LENG KEE  
CONTACT NO : 67038511  
REFERENCE : 109/IC/TCAC/CCR/2018  
DATE : 12-MAY-2018

INDIA INT'L INSURANCE PTE LTD  
64 CECIL STREET  
#04-05 108 BUILDING  
S(049711)  
TEL : 63478100  
FAX : 62244174  
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : M/S SOON SENG ELECTRIC PTE LTD  
ADDRESS : 11 WOODLANDS CLOSE  
#06-26 WOODLANDS 11  
S(737853)  
TELEPHONE NO : 96424465/98137700

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : 1700013018  
VEHICLE NO : G8G1034K  
MODEL CODE : YTKARUM20TWL-CAAC  
MODEL/YEAR : NISSAN NV200 1.5L DIESEL VAN (11)  
ENGINE NO : K9KC4000057253  
CHASSIS NO : VSKYBAM20Z0145683  
MILEAGE : 42591 KM  
DATE IN : 12/05/2018  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : SHAWN CHUA CHU RONG  
ACCIDENT DATE : 11/05/2018

TC AUTOCLINIC PTE LTD  
25 LENG KEE ROAD  
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO G8G1D34K

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RP1	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	240.00	/ 120
2 RS1	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	/
3 SSAL1	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	200.00	/ 100
4 WAC1	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION - COMMERCIAL	120.00	/
5 ZZ/001	RENEW REAR BUMPER, REAR RIGHT FENDER, RIGHT SLIDING DOOR, REAR RIGHT RIM COVER, RIGHT OUTER SILL ETC		
6 ZZ/002	PANELS & REPAIR	1250.00	/ 1120
7 ZZ/003	TRANSFER RIGHT SLIDING DOOR MECHANISMS TO FACILITATE REPAIR	120.00	/ 80
8 ZZ/004	RESPRAY REAR RIGHT FENDER, RIGHT SLIDING DOOR, RIGHT OUTER SILL, B-PILLAR	1250.00	/ 750
9 ZZ/005	QC, RETUNE & CONSULT CHECK		
10 ZZ/006	COMPLIMENTARY WASH & VACUUM		

TOTAL LABOUR CHARGES

3235.00

TC AUTOCLINIC PTE LTD  
25 LENG KEE ROAD  
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO: GBS1034K

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	RIGHT SLIDING DOOR	H2100-BJ1AC	1165.20	fine ✓
2	RIGHT BUMPER HBACKET	B522B-BJ00A	22.70	no? x sue
3	REAR BUMPER	H5022-3LGEH	624.80	no ✓
4	REAR RIGHT RIM COVER	40315-BJ01A	93.40	sue ✓
5	REAR RIGHT FENDER	78100-3LS0A	1554.30	repair
6	RIGHT OUTER SILL	76410-BJ00C	1209.60	repair
SUB TOTAL			4670.00	0.00 0.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			934.00	0.00 0.00
GRAND TOTAL			3736.00	0.00 0.00
OVERALL TOTAL			3736.00	

LEGEND: REMARKS[ OK ] = APPROVED. REMARKS[ X ] = NOT APPROVED

TC AUTOCLINIC PTE LTD  
25 LENG KEE ROAD  
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO GBG1034K

TOTAL LABOUR CHARGES	3235.00
TOTAL SPARE PARTS CHARGES	3736.00
GRAND TOTAL	6971.00 *

\* All charges do not include GST.

SURVEYOR'S PARTICULARS

NAME	RASUL - HP 90010068
SURVEYED DATE	24/05/18 P1240
AUTHORIZED DATE	
EXCESS CLAUSE	0.00
LIABILITY	0.00
REMARKS	6 days

Resurvey by paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TC AUTOCLINIC PTE LTD  
25 LENG KEE ROAD  
SINGAPORE 159097

FINALIZED : ACCIDENT/BODY REPAIRS  
WORKSHOP : LENG KEE  
CONTACT NO : 67038511  
REFERENCE : 109/IC/TCAC/CCR/2018  
DATE : 12-MAY-2018

INDIA INT'L INSURANCE PTE LTD  
64 CECIL STREET  
#04-05 IOB BUILDING  
S(049711)  
TEL : 63476100  
FAX : 62244174  
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : M/S SOON SENG ELECTRIC PTE LTD  
ADDRESS : 11 WOODLANDS CLOSE  
#06-26 WOODLANDS 11  
S(737853)  
TELEPHONE NO : 96424466/98137700

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM  
POLICY NO : 1700013018  
VEHICLE NO : GBG1034K  
MODEL CODE : YTKARUM20TWL-CAAC  
MODEL/YEAR : NISSAN NV200 1.5L DIESEL VAN (11)  
ENGINE NO : K9KC4000057253  
CHASSIS NO : VSKYBAM20Z0145683  
MILEAGE : 42591 KM  
DATE IN : 12/05/2018  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : SHAWN CHUA CHU RONG  
ACCIDENT DATE : 11/05/2018



TC AUTOCLINIC PTE LTD  
25 LENG KEE ROAD  
SINGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBG1034K

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	240.00	120.00 ✓
2 RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	55.00 ✓
3 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	200.00	100.00 ✓
4 WACI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION - COMMERCIAL	120.00	120.00 ✓
5 ZZ/001	RENEW REAR BUMPER, RIGHT SLIDING DOOR, REAR RIGHT RIM COVER. REPAIR REAR RIGHT FENDER & SILL	1250.00	1170.00 ✓
6 ZZ/003	TRANSFER RIGHT SLIDING DOOR MECHANISMS TO FACILITATE REPAIR	120.00	80.00 ✓
7 ZZ/004	RESPRAY REAR RIGHT FENDER, RIGHT SLIDING DOOR, RIGHT OUTER SILL	1250.00	750.00 ✓
8 ZZ/005	QC, RETUNE & CONSULT CHECK		
9 ZZ/006	COMPLIMENTARY WASH & VACUUM		
TOTAL LABOUR CHARGES		3235.00	2395.00

TC AUTOCLINIC PTE LTD  
25 LENG KEE ROAD  
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBG1034K

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	FUEL LID (SUPPLEMENTARY)	78830-JX00B	119.60		OK
2	RIGHT SLIDING DOOR	H2100-BJ1AC	1165.20		OK
3	RIGHT BUMPER RBRACKET	B522B-BJ00A	22.70		X
4	REAR BUMPER	H5022-3LGEH	624.80		OK
5	REAR RIGHT RIM COVER	40315-BJ01A	93.40		OK
6	REAR RIGHT FENDER	78100-3LS0A	1554.30		X
7	RIGHT OUTER SILL	75410-BJ00C	1209.60		X
SUB TOTAL			2003.00	0.00	0.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			400.60	0.00	0.00
GRAND TOTAL			1602.40	0.00	0.00
OVERALL TOTAL			1602.40		

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

TC AUTOCLINIC PTE LTD  
25 LENG KEE ROAD  
SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO 68G1034K

NETT ITEM 2003.00  
LESS 20.00%) -400.60  
NETT AMOUNT 1602.40

LIST ITEM 0.00  
LESS 30.00%) 0.00  
LIST AMOUNT 0.00

SPECIAL NETT ITEM 0.00  
LESS .00%) 0.00  
SPECIAL NETT AMOUNT 0.00

TOTAL LABOUR CHARGES 2395.00  
TOTAL SPARE PARTS CHARGES 1602.40

TOTAL CHARGES 3997.40  
ADD 7 % GST 279.82

GRAND TOTAL 4277.22

TC AUTOCLINIC PTE LTD  
25 LENG KEE ROAD  
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : LENG KEE  
CONTACT NO : 67038511  
REFERENCE : 109/IC/TCAC/CCR/2018  
DATE : 12-MAY-2018

INDIA INT'L INSURANCE PTE LTD  
64 CECIL STREET  
#04-05 IOB BUILDING  
S(049711)  
TEL : 63476100  
FAX : 62244174  
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : M/S SOON SENG ELECTRIC PTE LTD  
ADDRESS : 11 WOODLANDS CLOSE  
#06-26 WOODLANDS 11  
S(737853)  
TELEPHONE NO : 96424466/98137700

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : 1700013018  
VEHICLE NO : G8G1034K  
MODEL CODE : YTKARURM20TWL-CAAC  
MODEL/YEAR : NISSAN NV200 1.5L DIESEL VAN (11)  
ENGINE NO : K9KC4000057253  
CHASSIS NO : VSKYBAM20Z0145683  
MILEAGE : 42591 KM  
DATE IN : 12/05/2018  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : SHAWN CHUA CHU RONG  
ACCIDENT DATE : 11/05/2018

TC AUTOCLINIC PTE LTD  
25 LENG KEE ROAD  
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBG1034K

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RP1	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	<del>240.00</del>	120
2	RS1	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	/
3	SEAL1	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	<del>200.00</del>	100
4	WAC1	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION - COMMERCIAL	120.00	/
5	ZZ/001	RENEW REAR BUMPER, REAR RIGHT FENDER, RIGHT SLIDING DOOR, REAR RIGHT RIM COVER, RIGHT OUTER SILL ETC		
6	ZZ/002	PANELS & REPAIR	<del>1250.00</del>	1120
7	ZZ/003	TRANSFER RIGHT SLIDING DOOR MECHANISMS TO FACILITATE REPAIR	<del>120.00</del>	80
8	ZZ/004	RESPRAY REAR RIGHT FENDER, RIGHT SLIDING DOOR, RIGHT OUTER SILL, B-PILLAR	<del>1250.00</del>	750
9	ZZ/005	QC, RETUNE & CONSULT CHECK		
10	ZZ/006	COMPLIMENTARY WASH & VACUUM		
TOTAL LABOUR CHARGES			3235.00	

TC AUTOCLINIC PTE LTD  
25 LENG KEE ROAD  
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBG1034K

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	RIGHT SLIDING DOOR	H2100-BJ1AC	1165.20	Due ✓
2	RIGHT BUMPER RBACKET	B522B-BJ00A	22.70	m? ✓
3	REAR BUMPER	H5022-3LGEH	624.80	res ✓
4	REAR RIGHT RIM COVER	40315-BJ01A	93.40	res ✓
5	REAR RIGHT FENDER	78100-3LS0A	1554.30	Repair
6	RIGHT OUTER SILL	76410-BJ00C	1209.60	Repair
SUB TOTAL			4670.00	0.00 0.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			934.00	0.00 0.00
GRAND TOTAL			3736.00	0.00 0.00
OVERALL TOTAL			3736.00	

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

TC AUTOCLINIC PTE LTD  
25 LENG KEE ROAD  
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO GBG1034K

TOTAL LABOUR CHARGES	3235.00
TOTAL SPARE PARTS CHARGES	3736.00
GRAND TOTAL	6971.00 *

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	: Rasul - Hp 90010068
SURVEYED DATE	: 24/05/18 P1240
AUTHORIZED DATE	:
EXCESS CLAUSE	: 0.00
LIABILITY	: 0.00
REMARKS	: 6 days

Resurvey by paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Nivitha (LKK Auto)

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Tuesday, 15 May 2018 4:52 PM  
**To:** Shawn Chua; 'sur@lkkauto.com'; Nivitha (LKK Auto)  
**Cc:** Heng Kwang Liang; Zuhaidah Samsuri  
**Subject:** RE: Accident Involving GBG1034K & SHA4241U On 11/05/18  
**Attachments:** GBG1034K GIA Report.pdf; Estimate Before Survey.pdf

5.09pm @ 15/5/18  
person @ Shawn  
vehicle not in

Dear Sir / Mdm,

Please conduct a survey on TP vehicle GBG1034K and let us have your report urgently.

This claim will be handled by Ms Aida.

\*Kindly upload this survey request email to merimen.

Thank You.

*Best Regards,*

**Gabriel Wee**

Motor Claims Dept.

**India International Insurance Pte Ltd**

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

---

**From:** Shawn Chua [mailto:shawnychua@tanchong.com]  
**Sent:** 15 May, 2018 1:39 PM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>  
**Cc:** Heng Kwang Liang <kelvinheng@tanchong.com>  
**Subject:** RE: Accident Involving GBG1034K & SHA4241U On 11/05/18

III Insured: **SHA4241U**

Claimant: **GBG1034K**


Good afternoon.

May I appoint LKK Auto Consultants?

Regards,

Shawn Chua  
Service Executive  
TC AutoClinic Pte Ltd  
25 Leng Kee Road  
Singapore 159097  
DID: +65 67038515  
HP: +65 96450023  
Fax: +65 64795019





**From:** Motor Claim - III [mailto:motorclaim@iii.com.sg]  
**Sent:** Tuesday, 15 May, 2018 1:36 PM  
**To:** Shawn Chua <shawnychua@tanchong.com>  
**Cc:** Heng Kwang Liang <kelvinheng@tanchong.com>  
**Subject:** RE: Accident Involving GBG1034K & SHA4241U On 11/05/18

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

*Best Regards,*

**Gabriel Wee**

Motor Claims Dept.

**India International Insurance Pte Ltd**

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

---

**From:** Shawn Chua [mailto:shawnychua@tanchong.com]  
**Sent:** 15 May, 2018 11:30 AM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>  
**Cc:** Heng Kwang Liang <kelvinheng@tanchong.com>  
**Subject:** Accident Involving GBG1034K & SHA4241U On 11/05/18

Dear Sir/Madam,

Our customer holds your insured driver, **SHA4241U** liable for the accident on **11/05/18** and would like to claim against your insured driver. We hereby inquire whether you would like to have a direct settlement with our customer, **GBG1034K**.

If you minded to reach an amicable direct settlement with our customer, please let us have your substantive reply strictly by **18/05/18**. Otherwise our customer will proceed in a manner that he deems fit.

Kindly let me know when can I arrange for a survey so that I'll be able to arrange an appointment with my customer.

Attached herewith the **GIA Report** and **estimate of repair cost** for **GBG1034K**.

Regards,

Shawn Chua  
Service Executive  
TC AutoClinic Pte Ltd  
25 Leng Kee Road  
Singapore 159097  
DID: +65 67038515  
HP: +65 96450023  
Fax: +65 64795019

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be

intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

## Print Received Message

This mail is associated with :

**\*GBG1034K (MCT18050259)**

**[SHA4241U]**

TP

SOON SENG ELECTRIC PTE LTD

May 11 2018 10:00AM

[-]

TC AutoClinic Pte Ltd

**From** India International Insurance Pte Ltd (HQ) (III\_SG), sent on 03/06/2019 10:39 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$4592.22) - GBG1034K - Claim Handler: Zuhaidah Bte Samsuri

Approved:4592.22.

## Shawn Chua

---

**From:** Rasul (LKKAuto) <Rasul@lkkauto.com>  
**Sent:** Thursday, December 27, 2018 5:35 PM  
**To:** Shawn Chua  
**Subject:** RE: GBG1034K Finalized Claim

**Follow Up Flag:** Follow up  
**Flag Status:** Flagged

Hi Shawn,

Finalised amount confirmed


Best Regards,

Rasul | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

---

**From:** Shawn Chua [mailto:[shawnychua@tanchong.com](mailto:shawnychua@tanchong.com)]  
**Sent:** Wednesday, 31 October, 2018 8:15 AM  
**To:** Rasul (LKKAuto)  
**Cc:** SUR  
**Subject:** GBG1034K Finalized Claim

LKK Ref: CC4/III18009010/Ja3

Our Ref: GBG1034K

Good morning.

Attached is GBG1034K finalized claim.

Kindly reply so that I can close the case soon.

Thank you very much for your time & assistance.

Regards,

Shawn Chua  
Service Executive  
TC AutoClinic Pte Ltd  
25 Leng Kee Road  
Singapore 159097  
DID: +65 67038515  
HP: +65 96450023  
Fax: +65 64795019

## Letter of Claim for Third Party

Insurance Company: India Int'l Insurance Pte Ltd

Date: 31-10-18

Address : 64 Cecil St  
#04-05 IOB Building  
S049711

Attention : Claims Department - Motor Claims Manager

Dear Sir/Madam,

Subject: Accident involving vehicle number GBG 1034 X & SHA 4241 U at Marina  
Boulevard after Marina View Link on 11-05-18.

I am the owner of vehicle number GBG 1034 X which was involved with the accident as mentioned above. As the accident was solely caused by your insured vehicle bearing registration number SHA 4241 U, I hereby submit my claim against your company for the uninsured loss which are as follows:

Excess Payment for OD Claim	\$ _____
Loss of Use (\$\$ _____) for _____ days	\$ _____
Car Rentals as per invoice attached	\$ <u>190.00</u>
Search Fee	\$ _____
Cost of Repair	\$ <u>4277.22</u>
Others <u>Grab receipts</u>	\$ <u>125</u>
Total Claim Amount	\$ <u>4592.22</u>

Enclosed please find copies of GIA report, invoices & certificate of insurance for your necessary review.

Kindly reply me within 14 days from the date hereof or alternatively let me have the full & final settlement for all uninsured loss which amounted to \$ 4592.22, failing which I will have to recover all losses via legal action. Please also note your prompt action will help to reduce the claim cost.

Yours sincerely



Name : \_\_\_\_\_

Address: \_\_\_\_\_

Tel No : \_\_\_\_\_

Letter of Authority

1. Accident involving vehicle number GBG 1034 K & SHA 4241 U at Marina Boulevard after Marina View Link on 11-05-18
2. I, Soon Seng Electric Pte Ltd NRIC 20151052Z, owner of motor Vehicle no. GBG 1034 K hereby authorize my repair workshop, namely TC AutoClinic Pte Ltd 25 Leng Kee Rd S159097 to act for me with respect to the following
  - a) To submit my claims for all losses including uninsured loss, rental car charges, medical fees, excess payment and cost of repairs.
  - b) To resolving my claim as they deem fit, including settling the matter on basis of my contributing negligence if any.
  - c) To receive payment for settlement of my claim and all payment be made payable to the workshop for cost of repairs and other uninsured losses
  - d) To sign discharge voucher on my behalf
3. I understand that the claim for loss of use of my vehicle will be based on the number of days estimated by the surveyor in his report to be required for repair. The actual number of days may be more due to unavailability of parts, weekend, holidays and other operational exigencies and I accept that it may not be possible to claim for the extra days. In addition, any contributory negligence part of my claim can also affect portion of my claim for loss of usage.
4. I further acknowledge that any settlement that workshop may reach on my behalf is on a without prejudice basis and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle is concerned.
5. For successful recovery of upfront Excess payment by claimant, the workshop shall effect refund accordingly to the mode of upfront payment.
  - a) For upfront Excess payment by credit card, the refund shall be credited to the respective Credit Card Account via Credit Card Company handling the transaction.
  - b) For Excess payment by cash, the workshop shall refund the amount to the claimant via cheque payment.

Dated this 31 (Day) of Oct (Month) 2018 (Year)

Claimant Particulars

Name: \_\_\_\_\_  
Address: \_\_\_\_\_

Tel No: \_\_\_\_\_

Signature: \_\_\_\_\_



Authorized Workshop

Workshop: TC AutoClinic Pte Ltd  
Claim Officer: Shawn Chua

Signature  
& Co. Stamp. \_\_\_\_\_



Email: \_\_\_\_\_

## EXPRESS SETTLEMENT

### DISCHARGE VOUCHER

#### III- Direct Settlement (PODS)

India Ref: MCT18050259  
Claimant Ref: GBG 1034K

We/I, TC AUTOCLINIC PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 4,277.22 (repair cost), S\$ 190.00 (loss of use/rental), S\$ 125.00 <sup>DISBURSEMENT</sup> (~~search fee~~), vehicle no. GBG 1034K that was damaged pursuant to the accident which occurred on 11/05/18 (date) at MARINA BOULEVARD (location) involving vehicle no. SHA 4241U (insured vehicle). This is pursuant to the inspection conducted on 24/05/18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner SOON SENG ELECTRIC PTE LTD ("the third party claimant") of vehicle no. GBG 1034K to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to GBG 1034K (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 4,592.22 to TC AUTOCLINIC PTE LTD

Dated this 31 day of July 20 19

CLAIMANT:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:

Signed by "the workshop" (with chop)

Soon Chua

25 Long Kee Rd  
S159047

WITNESS:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:

Signed by appointed Surveyor

LKK AUTO CONSULTANTS PTE LTD

199607198R

51 UBI AVENUE 1 #01-25

PAYA UBI INDUSTRIAL PARK (S) 408933



WSP



**TAX INVOICE**

CO. REG: 19-9105199-R

NAME : INDIA INT'L INSURANCE PTE LTD  
ADDRESS : 64 CECIL STREET  
TELEPHONE : #04-05 IOB BUILDING S(049711)  
MODEL : 63476100  
ENGINE NO : YTKARUM20TWL-CAAC  
CHASSIS NO : K9KC400D057253  
VEHICLE NO : VSKYBAM20Z0145683  
GBG1034K

INVOICE NO : WE2102715  
INVOICE DATE : 31-DEC-2018  
TERMS : CREDIT  
DATE REC'D : 29-JUN-2018  
SA/SE : CCR  
JOB NO : EG142058  
MILEAGE : 042591  
YOUR REFERENCE : 109/IC/TCAC/CCR/2018

ITEMS	JOB DESCRIPTION	AMOUNT
1	LABOUR PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00
2	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00
3	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00
4	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION - COMMERCIAL	120.00
5	RENEW REAR BUMPER, RIGHT SLIDING DOOR, REAR RIGHT RIM COVER. REPAIR REAR RIGHT FENDER & SILL	1170.00
6	TRANSFER RIGHT SLIDING DOOR MECHANISMS TO FACILITATE REPAIR	80.00
7	RESPRAY REAR RIGHT FENDER, RIGHT SLIDING DOOR, RIGHT OUTER SILL	750.00
	<b>SUBTOTAL :</b>	<b>2395.00</b>
1	PARTS REAR RIGHT RIM COVER Qty:1 @ \$93.40 each (Disc:20.00% After Disc:\$74.72each)	74.72
2	FUEL LID (SUPPLEMENTARY) Qty:1 @ \$119.60 each (Disc:20.00% After Disc:\$95.68each)	95.68

DOLLARS:

WORKSHOP MANAGER

The General Terms and Conditions of Service (the "Conditions") printed overleaf or attached to this invoice shall apply to all Services set out above. Any claims relating the Services shall be subject to the Conditions. Any objections to the charges in this invoice must be made within seven (7) days from the date of this invoice, otherwise it shall be assumed that this invoice has been accepted as correct and conclusive.

CUSTOMER

TO SECURITY GUARD

PLEASE TEAR ALONG PERFORATED LINE

DATE

TIME

RELEASE BY

VEHICLE NO :

**TAX INVOICE**

NAME :  
ADDRESS : INDIA INT'L INSURANCE PTE LTD  
64 CECIL STREET  
TELEPHONE : #04-05 IOB BUILDING S(049711)  
MODEL : 63476100  
ENGINE NO : YTKARURM20TWL-CAAC  
CHASSIS NO : K9KC400D057253  
VEHICLE NO : VSKYBAM20Z0145683  
GBG1034K

CO. REG: 19-9105199-R  
INVOICE NO :  
INVOICE DATE : WE2102715  
TERMS : 31-DEC-2018  
DATE REC'D : CREDIT  
SA/SE : 29-JUN-2018  
JOB NO : CCR  
MILEAGE : EG142058  
YOUR REFERENCE : 042591  
109/IC/TCAC/CCR/2018

ITEMS	JOB DESCRIPTION	AMOUNT
3	RIGHT SLIDING DOOR Qty:1 @ \$1165.20 each (Disc:20.00% After Disc:\$932.16each)	932.16
4	REAR BUMPER Qty:1 @ \$624.80 each (Disc:20.00% After Disc:\$499.84each)	499.84
	SUBTOTAL :	1602.40
1	REMARKS ACCIDENT INVOLVING GBG1034K & SHA4241U ON 11/05/18 AT MARINA BOULEVARD AFTER MARINE VIEW LINK	
2	3RD PARTY & LOU/RENTAL CLAIM AGAINST III VIA TCAC LKK REF: CC4/III1800901/JA3	
3	OUR REF: GBG1034K	
4	ATTACHED DIRECT SETTLEMENT EMAIL BY MS JOY IRENE FROM LKK	
5	ATTACHED LETTER OF AUTHORITY ATTACHED LETTER OF CLAIM FOR THIRD PARTY ATTACHED SATISFACTORY NOTE: 109/IC/TCAC/CCR/2018	
	Insurance Co : INDIA INT'L INSURANCE PTE LTD Policy No.....: 1700013018 Claim Type ...: DIRECT SETTLEMENT / THIRD PARTY CLAIM DOA.....: 11-MAY-2018	

DOLLARS:

WORKSHOP MANAGER

The General Terms and Conditions of Service (the "Conditions") printed overleaf or attached to this invoice shall apply to all Services set out above. Any claims relating the Services shall be subject to the Conditions. Any objections to the charges in this invoice must be made within seven (7) days from the date of this invoice, otherwise it shall be assumed that this invoice has been accepted as correct and conclusive.

CUSTOMER

TO SECURITY GUARD

PLEASE TEAR ALONG PERFORATED LINE

DATE

TIME

VEHICLE NO :

RELEASE BY

**TAX INVOICE**

NAME :  
ADDRESS : INDIA INT'L INSURANCE PTE LTD  
TELEPHONE : 64 CECIL STREET  
MODEL : #04-05 IOB BUILDING S(049711)  
ENGINE NO : 63476100  
CHASSIS NO : YTKARURM20TWL-CAAC  
VEHICLE NO : K9KC400D057253  
VSKYBAM20Z0145683  
GBG1034K

CO. REG: 19-9105199-R  
INVOICE NO :  
INVOICE DATE : WE2102715  
TERMS : 31-DEC-2018  
DATE REC'D : CREDIT  
SA/SE : 29-JUN-2018  
JOB NO : CCR  
MILEAGE : EG142058  
YOUR REFERENCE : 042591  
109/IC/TCAC/CCR/2018

ITEMS	JOB DESCRIPTION	AMOUNT
	Our Ref.....: 109/IC/TCAC/CCR/2018 Surveyor.....: M/S LKK ENGINEERING & MANAGEMENT SERVICES	
	LABOUR :	2395.00
	PARTS :	1602.40
	SUBTOTAL :	3997.40
	TOTAL :	3997.40
	GST(7%) :	279.82
	AMOUNT DUE :	4277.22

(NB : NC=No Charge;P=Included in Package;W=Warranty;G=Goodwill)  
DOLLARS: FOUR THOUSAND TWO HUNDRED SEVENTY  
SEVEN AND CENTS TWENTY TWO ONLY.

WORKSHOP MANAGER

The General Terms and Conditions of Service (the "Conditions") printed overleaf or attached to this invoice shall apply to all Services set out above.  
Any claims relating the Services shall be subject to the Conditions. Any objections to the charges in this invoice must be made within seven (7) days  
from the date of this invoice, otherwise it shall be assumed that this invoice has been accepted as correct and conclusive.

CUSTOMER

TO SECURITY GUARD

PLEASE TEAR ALONG PERFORATED LINE

DATE

TIME

RELEASE BY

VEHICLE NO : GBG1034K (EG142058/WE2102715)

# B 萬豐利汽車服務

## BAN HONG LEE MOTOR SERVICES

BH 5033, Ang Mo Kio Industrial Park 2 #01-279 (off Ang Mo Kio Ave. 3)  
Singapore 569536 Tel: 6482 5577 (3 Lines) Fax: 6482 5000  
Reg No: 263102/00M  
TOWING SERVICE: 6858 4067 (After 10.30pm)

Truck Rental  
Motor Repair  
Motor Insurance Claims  
Insurance Agent  
Dealer in Used Car  
Authorised Carpool Service Centre

甲及羅車出租  
汽車修理  
保險賠償  
代辦保險  
買賣汽車  
車務服務中心



### 車輛出租合同

### VEHICLE RENTAL AGREEMENT

Date: 30/10/18  
Owner: BAN HONG LEE MOTOR SERVICES ("the owner")  
Hirer: Sam Seng Slatric  
Address: 81M84 Woodlands 8482 #11-73 (73-74)  
NRIC / Co. Reg. No: \_\_\_\_\_  
Tel: 6315 2277 Fax: \_\_\_\_\_ H/P: 96424466

Owner and Hirer have agreed to enter into this Vehicle Rental Agreement for the motor vehicle described below and upon the terms and conditions contained on both sides of this document. Hirer acknowledges having read and understood all the terms and conditions and signifies acceptance upon signing.

Vehicle Reg. No: SKW4795		Agreement No.: 139405	
Driver's Particulars		Odometer: _____	
Name: Chew Yean Cheung		Date & Time Out: 30/10/18 8:00A	
Address: _____		Date & Time In: _____	
I/C No: 8377678A	Dr/Licence No: 8377678A	Hour @\$ _____	
Date of Issue: 24/11/07	Occupation: Co-A	2 Days @\$ 87 ✓ R1801 ✓	
Date of Birth: 17/10/1983	Tools: OL Spare Tyre: owner	Wks @\$ _____	
		Mths @\$ _____	

#### Third Party Claim

In respect of each third party insurance claim arising from the date of hire to date of return of the vehicle (both dates inclusive), Hirer unconditionally agrees to pay Owner S\$ 3000 ✓  
comprising excess payable and compensation to Owner for impact of claim on future motor insurance premiums.

#### Own Vehicle Damage

Hirer is responsible for the first \$ 3000 ✓ excess for collision/damage to first party, (i.e.) BAN HONG LEE MOTOR SERVICES (including windscreen) plus loss of earning while damaged vehicle is under repair.

#### Authorised Driver

Hirer shall pay additional excess of S\$1500 if the Authorised Driver is below the age of 25 or is above 65 years old or has less than 2 years driving experience.

#### Driver Not Cover By Insurance

General Exception: Insurance policy does not cover against any driver aged below 22 and/or above 70 years old and/or with driving experience of 1 year and below.

Deposit (Refundable): 2200 ✓

Sub-Total: 2394 ✓

Balance To Pay: \_\_\_\_\_

PETROL/DIESEL AT YOUR OWN EXPENSE  
FOR LOCAL USE ONLY

BAN HONG LEE MOTOR SERVICES

Authorised Signature

Hirer's Signature

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement




































## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 May 2018 <a href="#">Edit Reg</a>		15 May 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$3,997.40</b> <a href="#">Edit Estimates</a>	<b>S\$3,997.40</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	SOON SENG ELECTRIC PTE LTD, Co. Reg. No.: 201510152Z								
Vehicle Reg. No.:	GBG1034K	Date of Loss:	11/05/2018 10:00 - :59 [12 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18050259	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHA4241U	Policy No. (Claimant):	1700013018						
		Excess:							
Repairer:	TC AutoClinic Pte Ltd (Leng Kee) 25 Leng Kee Road, 159097 Leng Kee - Tel: 67038511								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 28/05/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>• III_SG (03/06/2019): Alert - Adj Mandate Approved (S\$4592.22) - GBG1034K - Claim Handler: Zuhaidah Bt...</li> <li>• III_SG (16/04/2019): Alert - Adj Mandate Maintained - GBG1034K - Claim Handler: Zuhaidah Bte Samsuri</li> <li>• III_SG (05/03/2019): Alert - Adj Mandate Approved (S\$4467.22) - GBG1034K - Claim Handler: Zuhaidah Bt...</li> <li>• III_SG (24/05/2018): Alert - Adj Mandate Approved (S\$0.00) - GBG1034K - Claim Handler: Zuhaidah Bte S...</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*GBG1034K (MCT18050259)  
[SHA4241U]  
TP  
SOON SENG ELECTRIC PTE LTD  
May 11 2018 10:00AM  
[COMFORT TRANSPORTATION PTE LTD]  
TC AutoClinic Pte Ltd

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/03/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
2	04/03/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
3	04/03/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
4	04/03/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
5	04/03/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
6	04/03/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
7	04/03/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
8	04/03/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
9	04/03/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
10	04/03/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
11	04/03/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
12	04/03/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
13	04/03/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
14	04/03/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
15	04/03/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
16	04/03/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
17	04/03/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
18	04/03/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
19	04/03/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
20	04/03/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
21	04/03/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
22	04/03/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
23	04/03/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
24	04/03/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
25	04/03/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
26	04/03/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
27	04/03/19 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
28	04/03/19 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	04/03/19 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	04/03/19 15:09	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/05/18 19:33	TP ESTIMATE	 Load PDF	
2	17/05/18 19:33	TP GIA REPORT	 Load PDF	
3	17/05/18 19:33	ACKNOWLEDGEMENT EMAIL TO 15.05.2018	 Load PDF	
4	27/05/18 10:08	TP ESTIMATE - MARKED	 Load PDF	
5	18/02/19 11:35	WORKSHOP INVOICE	 Load PDF	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
6	18/02/19 11:35	RENTAL RECEIPT		Load PDF
7	18/02/19 11:35	LOD		Load PDF
8	16/04/19 11:27	GRAB RECEIPTS		Load PDF
9	13/08/19 12:58	AUTHORIZATION LETTER		Load PDF
10	14/08/19 08:26	DISCHARGE VOUCHER		Load PDF
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	18/05/18 08:35	Singapore Accident Statement		Load PDF

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18009010/R1HA3Q2

Date: 14/08/2019

## REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle  
No : GBG1034K

Insured Vehicle No : SHA4241U

Date of Loss: 11/05/2018

Nature of Claim: TP

Claim No: MCT18050259

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **GBG1034K**

Make &amp; Model: NISSAN NV200, 1.5 D MT ABS AIRBAG 2WD 6DR (A)

Engine No: K9KC400D057253

Reg. Date: 01/05/2017 (Man. Year: 2017)

Chassis No: VSKYBAM20Z0145683

Colour: Blue

Odometer: 43928 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

No

Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 175/70 R14

Rear Tyre Size:

175/70 R14

Front Left Side: Goodyear 6 mm

Rear Left Side:

Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side:

Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,831.68	1,602.40	2,229.28	58.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,235.00	2,395.00	840.00	25.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,066.68</b>	<b>3,997.40</b>	<b>3,069.28</b>	<b>43.43</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>494.67</b>	<b>279.82</b>	<b>214.85</b>	<b>43.43</b>
<b>Nett Amount (S\$)</b>	<b>7,561.35</b>	<b>4,277.22</b>	<b>3,284.13</b>	<b>43.43</b>
<b>+ Car Rental (2.0 x S\$95.00/day) (S\$)</b>		190.00		
<b>+ Other Doc Fees (S\$)</b>		125.00		
<b>Nett Liability (S\$)</b>		<b>4,592.22</b>		

## INSPECTION

Date of Assignment: 15/05/2018

Date Inspected: 24/05/2018

Inspected At:

TC AutoClinic Pte Ltd (Leng Kee)

25 Leng Kee Road

Singapore 159097

Estimated Period of Repair: 6.0 days



---

**Adjuster:** MOHD RASUL**Manager:** VIC ALPEH

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 18 Feb 2019)	
<b>Parts:</b>	N/A	NISSAN NV200 1.5 D MT ABS AIRBAG 2WD 6DR (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBG1034K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RIGHT SLIDING DOOR	Buckled	1,165.20 FN	*1,165.20 FN
2	1		*RIGHT BUMPER BRACKET	Serviceable	22.70 FN	*- FN
3	1		*REAR BUMPER	Necessary	624.80 FN	*624.80 FN
4	1		*REAR RIGHT RIM COVER	Scratched	93.40 FN	*93.40 FN
5	1		*REAR RIGHT FENDER	Repair	1,554.30 FN	*- FN
6	1		*RIGHT OUTER SEAL	Repair	1,209.60 FN	*- FN
7	1		*FUEL LID	Necessary	119.60 FN	*119.60 FN
<b>Sub Total (S\$)</b>					<b>4,789.60</b>	<b>2,003.00</b>
<b>- Nett Item Discount on N Items 20.00/20.00% (S\$)</b>					<b>957.92</b>	<b>400.60</b>
<b>Total Parts (S\$)</b>					<b>3,831.68</b>	<b>1,602.40</b>

F=Franchise part, N=NetItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	New	240.00	120.00
2	REPLACE REVERSE SENSOR ,NECESSARY ADJUSTMENT & FUNCTION TEST	New	55.00	55.00
3	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	New	200.00	100.00
4	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION -COMMERCIAL	New	120.00	120.00
5	RENEW REAR BUMPER ,REAR RIGHT FENDER ,RIGHT SLIDING DOOR ,REAR RIGHT RIM COVER ,RIGHT OUTER SILL ETC PANELS & REPAIR	New	1,250.00	1,170.00
6	TRANSFER RIGHT SLIDING DOOR MECHANISMS TO FACILITATE REPAIR	New	120.00	80.00
7	RESPRAY REAR RIGHT FENDER ,RIGHT SLIDING DOOR,RIGHT OUTER SILL ,B-PILLAR	New	1,250.00	750.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,235.00</b>	<b>2,395.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >