

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 109/IC/TCAC/CCR/2018
DATE : 12-MAY-2018

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-05 IOB BUILDING
S(049711)
TEL : 63476100
FAX : 62244174
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : M/S SOON SENG ELECTRIC PTE LTD
ADDRESS : 11 WOODLANDS CLOSE
#06-26 WOODLANDS 11
S(737853)
TELEPHONE NO : 96424466/98137700

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700013018
VEHICLE NO : GBG1034K
MODEL CODE : YTKARURM20TWL-CAAC
MODEL/YEAR : NISSAN NV200 1.5L DIESEL VAN (II)
ENGINE NO : K9KC400D057253
CHASSIS NO : VSKYBAM20Z0145683
MILEAGE : 42591 KM
DATE IN : 12/05/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 11/05/2018

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBG1034K

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	240.00	
2	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	200.00	
4	WACI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION - COMMERCIAL	120.00	
5	ZZ/001	RENEW REAR BUMPER, REAR RIGHT FENDER, RIGHT SLIDING DOOR, REAR RIGHT RIM COVER, RIGHT OUTER SILL ETC		
6	ZZ/002	PANELS & REPAIR	1250.00	
7	ZZ/003	TRANSFER RIGHT SLIDING DOOR MECHANISMS TO FACILITATE REPAIR	120.00	
8	ZZ/004	RESPRAY REAR RIGHT FENDER, RIGHT SLIDING DOOR, RIGHT OUTER SILL, B-PILLAR	1250.00	
9	ZZ/005	QC, RETUNE & CONSULT CHECK		
10	ZZ/006	COMPLIMENTARY WASH & VACUUM		
		TOTAL LABOUR CHARGES	3235.00	

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBG1034K

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	RIGHT SLIDING DOOR	H2100-BJ1AC	1165.20			
2	RIGHT BUMPER RBACKET	85228-BJ00A	22.70			
3	REAR BUMPER	H5022-3LGEH	624.80			
4	REAR RIGHT RIM COVER	40315-BJ01A	93.40			
5	REAR RIGHT FENDER	78100-3LS0A	1554.30			
6	RIGHT OUTER SILL	76410-BJ00C	1209.60			
SUB TOTAL			4670.00	0.00	0.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			934.00	0.00	0.00	
GRAND TOTAL			3736.00	0.00	0.00	
OVERALL TOTAL			3736.00			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO GBG1034K

TOTAL LABOUR CHARGES	3235.00
TOTAL SPARE PARTS CHARGES	3736.00
GRAND TOTAL	6971.00 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.