

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : QBE INSURANCE (SINGAPORE) PTE LTD
 1 RAFFLES QUAY
 29-10 SOUTH TOWER
 SINGAPORE 048583

TEL: 62246633
 ATTN: Motor Claim Department

WS Ref: TP/QBE/AMK

Claim Type: Third Party

Accident Date: 24/04/2018

TP Veh Reg No: GBA7969E

FAX: 65345356

Not Authorized
Recovery B4 pain
3 days

Claim No: ES1890508

Estimate No: ES1890508/AMK

Date: 09 May 2018

Policy No: 5099191068

Veh Reg No: SJB308J

Make/Model: BMW 730LI

Chassis No: WBA YE22060DZ20931

Engine No: 10548326N52B30AF

Reg. Date: 25/06/2013

Estimate Repair Cost to Vehicle No : SJB308J

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Cost Plus				
1 REAR BUMPER	1,070.00	1 PC	1,070.00	✓
2 REAR BUMPER RH SIDE RETAINER	155.00	1 PC	155.00	X
3 REAR BUMPER RUBBER STRIP CENTRE (CHROME)	85.00	1 PC	85.00	✓
4 RH TAILLAMP	560.00	1 PC	560.00	✓
			1,870.00	
	Add 20%		374.00	2,244.00
Labour				
5 REMOVE & REFIX REAR BUMPER, TAILLAMP; KNOCKING & REPAIR REAR RH FENDER & REALIGN THE SAME	450.00	1 LA	450.00	✓
6 PUTTY & RESPRAY REAR BUMPER, REAR RH FENDER & ALL AFFECTED AREAS	500.00	1 LA	500.00	✓
				950.00

Total S\$ 3,194.00

Add GST @ 7% 223.58

Total Amount payable S\$ 3,417.58

VEHICLE LYING AT:
 NO.10 ANG MO KIO INDUSTRIAL PARK 2A
 #01-04 AMK AUTOPOINT
 SINGAPORE 568047
 TEL : 64812001

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplier must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE